

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204220

Record Title & Contents

**GEOTECHNICAL REPORT FOR
ALAMEDA DE LAS PULGAS - 418 ALBION AVENUE**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
1	misc ca. 1970 fault data	NO	07/06/70	William R. Dickenson	Comentary and Reconnaissance Photogeologic Map, San Andreas Rift Belt
	misc ca. 1975 fault data	NO	06/15/75	Jon C. Cummings, Town Geologist	Memorandum to Olive Mayer re: Fault Traces
			08/01/75	Ken Kodama	An Investigation of a Fault Trace in Woodside, California by the VLP Electromagnetic Technique
			09/23/75	Thomas H. Moses, Mayor	Letter to George Gunias re: "Areas 39" report
			09/26/75	Jon C. Cummings, Town Geologist	Memorandum to Robert Myers, Town Manager re: review of "Areas 39" report.
			10/07/75	Thomas H. Moses, Mayor	Letter to George Gunias re: transmitting Town Geologist's report on "Areas 39" report
			11/03/75	George Gunias	Letter to Thomas H. Moses, Mayor re: 9/23/75 letter
			11/07/75	George Gunias	Letter to Thomas H. Moses, Mayor re: 10/7/75 letter
			02/09/76	George Gunias	Letter to Thomas H. Moses, Mayor re: response to Town Geologist's 6/15/75
					Memorandum and 9/26/75/review of "Areas 39" report
no	Geology and Geologic Hazards	NO	05/29/05	Jon C. Cummings, Town Geologist	Geology and Geologic Hazards report fo the Town
1	Geologic Map	NO	01/07/88	William Cotton and Associates	Geologic Map Revisions/Supplemental Geologic Hazard Mapping
ALAMEDA DE LAS PULGAS					
1	2452 Alameda de las Pilgas	X	08/07/06	Earth Investigations Consultants	Geotechnical Investigation, proposed Residential Addition
ALBION AVENUE					
1	129 Albion Avenue	X	09/24/86	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed-Story Garage
	139 Albion Avenue	X	04/08/02	Nielsen Geotechnical Incorporated	Soil Report
			11/22/04	Murray Engineers Inc	New Engineer of Record, Residence Improvements
	179 Albion Avenue	X	09/19/94	Michelucci & Associates, Inc.	Geotechnical Investigation, Planned Improvements
			12/15/00	Nielsen Geotechnical Incorporated	Soil Report

			02/15/01	Nielsen Geotechnical Incorporated	Soil Report
			06/23/05	Murray Engineers, Inc.	New Engineer of Record and Woodside Comment List, Gorden Residence
			04/16/08	Murray Engineers, Inc.	Supplemental Recommendations, New Swimming Pool
			05/18/11	Murray Engineers, Inc.	Supplemental Drilled Pier Foundation Design Criteria, Gordon Swimming Pool
			05/27/11	Murray Engineers, Inc.	Supplemental Recommendations, Gordon Pool Equipment Vault
			08/03/11	Murray Engineers, Inc.	Geotechnical Plan Review, Gordon Pool Spa & Equipment Vault
196 Albion Avenue	X		07/03/79	J. Michael Cleary and Associates	Percolation Investigation, Residence
			07/06/79	J. Michael Cleary and Associates	Geotechnical Investigation, Proposed Home
			07/23/79	Walker & Moody Architects	Site Plan, with annotations
			07/26/79	William Cotton and Associates	Geotechnical Review Sheet
			07/27/79	William Cotton and Associates	Schreiber - Geotechnical Review
			07/22/15	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
219 Albion Avenue	X		09/06/00	Bay Area Geotechnical Group	Geotechnical Consultation, Proposed Additions, Quist Residence
222 Albion Avenue	X		07/10/09	Murray Engineers, Inc.	Geotechnical Investigation, Werbe Residence
			01/19/10	Murray Engineers, Inc.	Supplemental Driveway Recommendations, Werbe Residence
			02/01/10	Murray Engineers, Inc.	Supplemental Spa Recommendations, Werbe Residence
			04/12/11	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Site Retaining Wall, Werbe Residence
250 Albion Avenue	X		09/15/03	Nielsen Geotechnical Incorporated	Soil Report, Coast Oak Maintenance Facility & Greenhouse
			10/20/10	Murray Engineers, Inc.	Geotechnical Investigation, Covered Equipment Storage Shed
			01/27/06	Town	Aerial Photographs
			10/14/10	Murray Engineers, Inc.	Geotechnical Investigation, Residence Addition
278 Albion Avenue	X		03/21/97	Michelucci & Associates, Inc.	Geotechnical Investigation, Planned Improvements
			03/29/05	Michelucci & Associates, Inc.	Geotechnical Investigation, Planned New Building
			05/11/09	Murray Engineers, Inc.	Geotechnical Investigation, Burgess Residence Improvements
			05/15/09	Murray Engineers, Inc.	Supplemental Information Regarding 35% or Greater Slopes, Burges Property
Fleishaker Estate Subdivision	X		06/13/79	Cooper & Clark	Soil Investigation, Proposed Residential Lots and Earth Dam. Fleishaker Property
329, 331, and 333 Albion Avenue			10/27/80	William Cotton and Associates	Geotechnical Review Sheet

			01/29/81	William Cotton and Associates	Geologic Review, Fleishacker Subdivision #139
			03/09/81	William Cotton and Associates	Geologic Review, Fleishacker Subdivision #139
			11/16/81	Cooper & Clark	Site Geologic Evaluation, proposed Residential Subdivision, Fleishacker Property
			12/02/81	William Cotton and Associates	Review of Slope Stability Analyses for Proposed Residential Lots and Earth Dam, Fleishacker Property
			12/07/81	William Cotton and Associates	Review
			01/05/82	William Cotton and Associates	Geologic Review, Fleishacker Subdivision #139
			01/05/82	William Cotton and Associates	Response to letter dated 1/18/82 from D. Ramer
			03/26/82	Brian Kangas Foulk & Associates	Tentative Map, Fleishacker Estates Subdivision
			03/30/82	Cooper & Clark	Consultation - Responses to Town Geologist's Review Comments on Soil Investigation dated 11/16/81
			04/12/82	County of San Mateo, Department of Public Health & Welfare	SD #139 (Fleishacker) Tentative Map Revised 4/12/82
			04/12/82	William Cotton and Associates	Geologic Review
			05/11/82	Brian Kangas Foulk & Associates	Estimated Cut and Fill Quantities - Fleishacker Estate Subdivision
			06/01/82	Brian Kangas Foulk & Associates	Inundation Map - Fleishacker Reservoir
			06/08/82	Dames & Moore	Third Party Review of Dam Embankment Analysis, Fleishacker Property
			07/12/82	R. I. Whaley, Town Engineer	Review of Tentative Map and Supporting Data, Fleishacker Estates Subdivision
			07/23/10	William Cotton and Associates	Geologic Review
329 Albion Avenue	X		03/01/00	Nielsen Geotechnical Incorporated	Soil Report
			02/08/02	Nielsen Geotechnical Incorporated	Construction Report, Swimming Pool
331 Albion Avenue	X		02/28/06	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Residential Remodel and Addition
354 Albion Avenue	X		07/24/90	JCP Geologists - Engineers	Additional Soil and Foundation Study, Proposed New Location of Residence, Barn and Swimming Pool
			12/05/90	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence
				William Cotton and Associates	Geotechnical Review Sheet
			12/31/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review. Fagin, PA #8136
			04/24/91	William Cotton and Associates	Supplemental Geotechnical Review, Fagin, PA #8136-R
			12/04/91	William Cotton and Associates	Supplemental Geotechnical Review, Fagin, PA #8136-R

	418 Albion Avenue	X	08/23/94	Clearly Consultants, Inc.	Soil and Geologic Investigation for Living Room Expansion
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204221					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 499 ALBION AVENUE - ALTA VISTA COURT					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
ALBION AVENUE					
1A	499 Albion Avenue	x	07/25/00	Clearly Consultants, Inc.	Geotechnical Investigation, Farm
			11/14/00	Clearly Consultants, Inc.	Evaluation of Leachfield Stability
			08/02/01	Clearly Consultants, Inc.	Supplemental Soil Engineering Recommendations and Plan Review Letter, Farm
			10/17/00	Clearly Consultants, Inc.	Review of Revised Architectural Plans
			08/21/02	Clearly Consultants, Inc.	Soil Engineering Observation and Testing Services During Construction, Accessory Buildings A, B, C
			11/20/03	Clearly Consultants, Inc.	Geotechnical Investigation, Lower Garden Improvements
			09/15/07	Clearly Consultants, Inc.	Evaluation of Natural Slope Gradient, Lower Garden Retaining Wall Improvements
	500 Albion Avenue	x	12/05/80	Clearly Consultants, Inc.	Soil Engineering Investigation, Proposed House Addition
			10/08/93	Clearly Consultants, Inc.	Geotechnical Evaluation, Proposed Additions to Existing House
	545 Albion Avenue	x	05/15/85	Clearly Consultants, Inc.	Geotechnical Engineering Investigation, Single-Family Residence
			08/14/90	Clearly Consultants, Inc.	Topographic Plan with annotations
				Clearly Consultants, Inc.	Geotechnical Review Sheet
			09/20/91	Clearly Consultants, Inc.	Geologic and Geotechnical Review, Douglas Residence, PA-8501
			09/25/10	Clearly Consultants, Inc.	Comment on Seismic Design
			04/29/02	Clearly Consultants, Inc.	Geotechnical Investigation, Proposed Residential Additions, Gessow Property
	550 Albion Avenue	x	10/31/05	Clearly Consultants, Inc.	Geotechnical Investigation, Dorsey Residence Addition
	555 Albion Avenue	x	07/20/99	Clearly Consultants, Inc.	Geotechnical Engineering Evaluation, Proposed Alterations and Addition, Portion of Existing Garage
	580 Albion Avenue	x	07/14/78	Clearly Consultants, Inc.	Soil Investigation, Proposed Home, APN 072-060-160
			07/14/78	Clearly Consultants, Inc.	Engineering Geologic Study (APN 072-060-160)
	585 Albion Avenue	x	07/27/96	Clearly Consultants, Inc.	Geotechnical Investigation, Planned Pool, Guest House and Additions
			04/23/07	Clearly Consultants, Inc.	Geotechnical Investigation, Campbell Residence Additions

	590 Albion Avenue	x	03/30/99	Clearly Consultants, Inc.	Geotechnical Investigation, Stirn Residence
			08/04/04	Clearly Consultants, Inc.	Geotechnical Plan Review
	595 Albion Avenue	x	06/14/83	Clearly Consultants, Inc.	Geotechnical Investigation, Land Division of Kaisel Property
			05/31/84	Clearly Consultants, Inc.	Geotechnical Investigation, Proposed Residence
			11/06/91	Clearly Consultants, Inc.	Soil and Foundation Investigations, Additions to Residence
				Clearly Consultants, Inc.	Geotechnical Review Sheet
			05/15/92	Clearly Consultants, Inc.	Site Plan
			06/04/92	Clearly Consultants, Inc.	Geologic and Geotechnical Review, Addition, PA-8809
			01/07/01	Clearly Consultants, Inc.	Geotechnical Engineering Consultation Services, Landscape Water Features
			12/04/09	Clearly Consultants, Inc.	Geotechnical Investigation, New Solar Array Foundations
ALTA MESA ROAD					
1A	107 Alta Mesa Road	x	10/31/95	Nicholas Engineering Consultants	Geotechnical Investigation. Proposed Residence Addition
			06/30/04	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence Addition
	111 Alta Mesa Road	x	07/01/03	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	112 Alta Mesa Road	x	05/02/91	John Sarmiento & Associates	Preliminary Groundwater Seepage Investigation, Peck Residence
			06/12/97	PGSoils, Inc.	Geotechnical Conditions, Proposed Residential Addition
	119 Alta Mesa Road		05/24/15	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Addition
	120 Alta Mesa Road	x	04/18/95	Nielsen Geotechnical Incorporated	Soil Report
	144 Alta Mesa Road	x	04/24/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Additions
	171 Alta Mesa Road	x	06/12/05	Town of Woodside	various documents associated with permit, fees and initial review by Town Geologist
			11/30/89	GeoForensics, Inc.	A Causation Investigation of the Reported Distress at the Crocker Residence
			02/05/90	GeoForensics, Inc.	Report Supplement, Crocker Residence
			07/17/90	GeoForensics, Inc.	Subsurface Exploration, Crocker Residence
				Sian Hwi Njo	Foundation Calculations, Crocker Residence
				William Cotton Associates	Geotechnical Review Sheet
			06/02/90	Sian Hwi Njo	Concrete Foundation Plan, Crocker Residence with notes
	175 Alta Mesa Road	x	08/17/90	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Addition to Residence
	181 Alta Mesa Road	x	06/18/96	Michelucchi & Associates, Inc.	Geotechnical Investigation, Fitzpatrick/Kingman Residence, Planned Additions and Remodeling
	188 Alta Mesa Road		11/27/18	Romig Engineers, Inc.	Geotechnical Investigation Garage Expansion

	190 Alta Mesa Road	x	10/16/92	Nielsen Geotechnical Incorporated	Geotechnical Report
ALTA VISTA ROAD					
	103 Alta Vista Road	x	02/21/09	Frank Lee & Associates	Foundation Recommendations, Proposed One-Story Single Family Residence
			03/23/10	Frank Lee & Associates	Soil and Foundation Investigation, Proposed One-Story Single Family Residence
	123 Alta Vista Road	x	04/23/93	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, O'Hara Residence
	128 Alta Vista Road	x	08/19/05	Romig Engineers, Inc.	Geotechnical Services, Residence Addition
	135 Alta Vista Road		02/09/18	GeoForensics, Inc.	Geotechnical Investigation, Proposed Cottage Remodel
	138 Alta Vista Road	x	06/21/92	GeoForensics, Inc.	Foundation Study, Proposed Residential Additions, Hennig Residence
			06/15/10	GeoForensics, Inc.	Geotechnical Investigation Update, Proposed New Residence, Bet Property
	131 Alta Vista Road	x	09/22/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
	142 Alta Vista Road	x	07/11/96	Terrasearch, Inc.	Geotechnical Investigation, Proposed Single Family Residence
	148 Alta Vista Road	x	06/17/97	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Addition
	148 Alta Vista Road		09/22/17	PGSoils, Inc.	Geotechnical Conditions, Proposed Deck Replacement and House Addition
	156 Alta Vista Road	x	09/08/00	Sigma Prime Geosciences, Inc.	Engineering Geologic and Geotechnical Engineering Report
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204222					
Record Title & Contents					
GEOTECHNICAL REPORT FOR ARBOR COURT - BIG TREE WAY					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
ARBOR COURT					
2	105 Arbor Court	x	10/09/90	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed Additions, Existing Maahs Residence
			06/24/92	Tejima and Associates, Inc.	Existing Problems, Maahs Residence
			12/29/93	Jo Crosby & Associates	Geotechnical Investigation, Maahs Residence
			04/24/07	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed 2 Car Garage, Retaining Walls, and New Driveway
	115 Arbor Court	x	03/03/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development

			06/06/01	Earth Investigations Consultants	Geotechnical Design Parameters, Proposed Lap Pool
			11/03/17	Earth Investigations Consultants	Geotechnical Report Update, Residential Remodel and Addition
	135 Arbor Court	x	04/30/02	Romig Engineers, Inc.	Geotechnical Investigation, Johnson Studio Addition
	145 Arbor Court	x	10/29/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
AUDIFFRED LANE					
2	116 Audiffred Lane	x	12/16/99	Nielsen Geotechnical Incorporated	Soil Report
	122 Audiffred Lane	x	02/18/93	GeoForensics, Inc.	Geotechnical Observations, Reported Residential Distress, Yancy Residence
			01/07/00	Engineered Soil Repairs, Inc.	Yancy Residence Underpinning Structural Calculations
			06/15/00	Fowler & Associates	Engineering Geology Investigation, Yancey Residence
			08/10/01	Engineered Soil Repairs, Inc.	Construction Observation Letter
			08/10/01	Engineered Soil Repairs, Inc.	"AS-Built Report, Yancy Residence
	122 / 124 Audiffred Lane	x	10/28/87	Terrasearch, Inc.	Geotechnical Investigation, Proposed Two-Lot Residential Development, Parcel 4 A and B
	122 / 124 Audiffred Lane		04/03/95	Levine-Fricke	Geotechnical Investigation, Yancey and Schwabacher Residences
	124 Audiffred Lane	x	03/22/95	Levine-Fricke	Memo - Field and Laboratory Activities
			03/23/95	Levine-Fricke	Boring Logs and Locations
	136 Audiffred Lane	x	10/15/04	Milstone Geotechnical	Geotechnical Investigation, Foundation Distress, Weiss Residence
			06/13/07	Murray Engineers, Inc.	Geotechnical Investigation, Weiss Swimming Pool
			01/09/08	Murray Engineers, Inc.	Supplemental Recommendations, Adams Swimming Pool
BARDET ROAD					
2	131 Bardet Road	x	11/14/05	Murray Engineers, Inc.	Geotechnical Investigation, Madden Residence
	148 Bardet Road	x	02/14/01	PGSoils, Inc.	Soils Conditions, Proposed Guest House Addition
	155 Bardet Road	x	03/21/03	Romig Engineers, Inc.	Geotechnical Consultation, Deck Addition
			03/15/18	Geosphere Consultants, Inc.	Geotechnical Investigation, Proposed Residential Development
	164/168 Bardet Road	x	05/26/97	Earth Systems Consultants, N. C.	Soil Engineerign Study, Voiss Landslide
	168 Bardet Road	x	10/12/92	Earth Systems Consultants, N. C.	Geologic and Geotechnical Engineering Study, Addition to Novitsky Residence
			02/12/93	Earth Systems Consultants, N. C.	Addendum to Geologic and Geotechnical Engineering Study, Addition to Novitsky Residence
			08/30/16	Michelucci & Associates, Inc.	Proposed New Guest House, Addition to Main Residence and Driveway Renovations
BARRETT DRIVE					

2	1 Barrett Drive	x	03/12/02	Jo Crosby & Associates	Geotechnical Investigation, Planned Residence Addition
			04/02/02	Jo Crosby & Associates	Response to Engineering Geology Review Comments
	2 Barrett Drive		04/28/17	Romig Engineers, Inc.	Geotechnical Investigation, Residence Improvements
BEAR GULCH ROAD					
2	100 Bear Gulch Road	x	09/05/91	Applied Earth Sciences Consultants	Geotechnical Investigation, Proposed Addition, Martin Residence
			05/30/96	Applied Earth Sciences Consultants	Geotechnical Investigation, Proposed Addition, Martin Residence
			01/12/07	Applied Earth Sciences Consultants	Geotechnical and Geologic Investigation, Proposed Pool House
2	185 Bear Gulch Road	x	04/05/88	Earth Systems Consultants	Geotechnical Evaluation Report, Proposed Residential Addition
			04/06/89	Earth Systems Consultants	Supplemental Recommendations, Proposed Addition
			12/24/92	Earth Systems Consultants	Report Update and Foundation Plan Review, Proposed Additions
			06/03/93	Earth Systems Consultants	Addendum to Geotechnical Evaluation Report, Proposed Residential Additions
BIG TREE ROAD					
2	5 Big Tree Road	x	06/05/01	GeoForensics Inc.	Geotechnical Investigation, Proposed Residential Additions, Gottfried Property
			06/26/01	Steven F. Connelly	Engineering Geologic Investigation, Proposed Remodel, Gottfried Residence
			10/28/01	GeoForensics Inc.	Report Supplement, Gottfried Property
			03/15/05	GeoForensics Inc.	Construction Observations, Driveway
			09/07/05	GeoForensics Inc.	Response to Town Comments on 8/4/05 GFI letter
			09/19/05	A.C.&H. Civil Engineers, Inc.	Response to 9/9/05 Town Comments
	6 Big Tree Road	x	03/28/73	W.A. Wahler & Associates	Site and Foundation Investigation, Proposed Campbell Residence
BIG TREE WAY					
2	45 Big Tree Way	x	06/15/73	Dunham and Associates	Preliminary Soil and Geologic Investigation, Proposed Three-Lot Subdivision
			02/01/74	Dunham and Associates	Preliminary Soil and Geologic Investigation, Proposed Building Site
			03/19/85	Earth Systems Consultants	Soil Engineering Report, Proposed Single Family Residence, Haimson Property
				William Cotton and Associates	Geotechnical Review Sheet
			07/31/85	Earth Systems Consultants	Foundation Plan Review, Haimson Residence
			08/07/85	Joseph M. Bauer	Calculations, Proposed Haimson Residence

			09/05/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Haimson Property
				?	Site Plan, with annotations
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204223					
Record Title & Contents					
GEOTECHNICAL REPORT FOR BLUE RIDGE WAY - BROOKWOOD ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
BLUE RIDGE LANE					
2A	6 Blue Ridge Lane	x	01/26/76	Dunham & Associates	Geologic and Soil Engineering Evaluation, Parcel 2, End of Blue Ridge Lane
			02/27/76	Town of Woodside	Review of Dunham & Associates Report
			11/10/75	Brian Kangas Foulk & Associates	Land Division Map No. 222, Tentative Parcel Map, Subdivision of Parcel B, Land Division Map No. 210
			06/30/87	Terratech, Inc.	Geotechnical Investigation, Clark Residence
			03/10/97	Nielsen Geotechnical Incorporated	Soil Report
	8 Blue Ridge Lane		01/03/12	Murray Engineers, Inc.	Geotechnical Investigation, Cottage Improvements
	11 Blue Ridge Lane	x	03/15/99	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Addition & Remodeling
			10/23/14	Romig Engineers, Inc.	Geotechnical Investigation, Sullivan Residence
	19 Blue Ridge Lane	x	08/31/93	Clearly Consultants, Inc.	Geotechnical Investigation, New Residence
			09/30/94	Nielsen Geotechnical Incorporated	Soil Report, Swimming Pool and Pool House
			06/12/07	Clearly Consultants, Inc.	Geotechnical Investigation, Guest House
BRIDGE LANE					
2A	Bridle Lane	x	08/20/73	William Cotton and Associates	Review of Tentative Map
			8/0/74	Edwin H. Smith	Subdivision Map
			04/16/74	Geolabs-Northern California, Inc.	Magnetometer Survey, Proposed Forerst Glade Estates
			06/21/74	Geolabs-Northern California, Inc.	Subsurface Investigation of Splinter Fault Trace, Proposed Forest Glade Estates
			07/15/74	Geolabs-Northern California, Inc.	Evaluation of Landslide Located Southwest of Site and Liquefaction Potential of On-Site Soils, Proposed Forest Glade Estates
			08/11/74	William Cotton and Associates	Review Letter ?

			10/08/74	Mr. George Gunias, Woodside Citizen	Questions in Regard to Forest Glade Estates
			10/08/74	Town of Woodside	Minutes of Town Council Meeting
			10/25/74	Jo Crosby & Associates	Letter of Resignation - Forest Glade Estates
			07/30/75	Board of Registration for Geologists and Geophysicists	Complaint
1, 2, 3 Bridle Lane	x		11/10/69	Crosby & Associates	
			04/16/74	Geolabs - Northern California, Inc.	Magnetometer Survey, Proposed Forest Glade Estates
			06/21/74	Geolabs - Northern California, Inc.	Subsurface Investigation of Splinter Fault Trace
			07/25/77	Richard E. Rowland	Geologic Report on a portion of the Hume Property
1 Bridle Lane	x		11/11/69	Crosby & Associates	Soil & Geologic Investigation, Forest Glade Estates, Hooper property
			03/06/87	Perry R. Wood	Soil Conditions, Lot 3, Bridle Lane, Forest Glade Estates
			03/16/87	Crosby & Associates	Lot 3, Forest Glade Estates
			04/01/87	William Fredrick Heijn Architect	Plans with annotations
				William Cotton and Associates	Geotechnical Review Sheet
			06/03/87	Crosby & Associates	Lot 3, Forest Glade Estates
			06/11/87	William Cotton and Associates	Geologic and Geotechnical Review, Bosse, Lot 3 Forest Glade Estates, P.A. #4078
			9/0/89		site photographs
			05/20/93	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation, Lands of First Franklin
			04/28/94	Terrasearch, Inc.	Geotechnical Investigation, Proposed Additions, Tennis Court & Swimming Pool
2 Bridle Lane	x		03/22/88	Perry R. Wood	Soil Percolation Tests and Recommended Spetic Drainfield, Parcel 2/Bridle Lane
			03/18/88	Terrasearch, Inc.	Soil Investigation, Parcel 2 / Bridel Lane, Proposed Residence
3 Bridle Lane	x		07/20/01	Harlan Tait Associates	Geotechnical Investigation, Residence
			03/15/03	Harlan Tait Associates	Geotechnical Consultation, Residence
			09/15/05	Connell Geotechnical, Inc.	Geotechnical Consultation, Underground Water Storage Tank
4 Bridle Lane	x		03/08/89	Terrasearch, Inc.	Geotechnical Engineering Investigation, Parcel 4, Bridle Lane, Proposed Residence
				William Cotton and Associates	Geotechnical Review Sheet
			06/21/89	J. Thomas Jakaby	Structural Calculations, Miller Residence
			09/13/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Miller, PA-7466

			09/20/89	Terrasearch, Inc.	Response to Geotechnical Consultant Review and Grading and Foundation Plan Review
			10/03/89	William Cotton and Associates	Supplemental Geotechnical Review, Miller, PA-7466
			10/30/89	William Cotton and Associates	Supplemental Geotechnical Review
			04/18/00	Romig Engineers, Inc.	Geotechnical Engineering Investigation, Miller Guest House
			03/19/07	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Mees Residential Additions and Swimming Pool
	5 Bridle Lane	x	00/00/97	Lowney Associates	?

BROOKWOOD ROAD

2A	110 Brookwood Road	x	01/22/03	Carl W. Garbe	Geotechnical Consultation, Proposed Deck
			03/09/06	Romig Engineers, Inc.	Geotechnical Investigation, Bergeron Residence Additions
	130 Brookwood Road	x	07/02/10	ADCO Engineering	Soil an Foundation Investigation, Proposed Addition
			08/05/10	ADCO Engineering	Revised Soil an Foundation Investigation, Proposed Addition
			10/15/10	Ali M. Oskoorouchi	Foundation & Soil Investigations, Proposed Addition to Makel Residence
	135 Brookwood Road	x	06/25/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed House and Garage Addition
	165 Brookwood Road	x	03/31/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	180 Brookwood Road	x	04/19/01	Bay Area Geotechnical Group	Foundation Invstigation Report, Proposed Residential Addition
	185 Brookwood Road	x	10/02/96	SIA Consulting Engineers	Geotechnical Investigation
	215 Brookwood Road	x	02/23/00	Romig Consulting Engineers	Geotechnical Investigation, Salpeter Residence Improvements
			07/13/01	Romig Consulting Engineers	Geotechnical Plan Review, Residence Improvements
			03/15/05	Romig Engineers, Inc.	Supplemental Recommendations, Residence Addition
	220 Brookwood Road		03/21/14	Romig Engineers, Inc.	Geotechnical Investigation, Coleman Property Improvements
	235 Brookwood Road		08/14/13	Romig Engineers, Inc.	Geotechnical Investigation, Residence Improvements
			08/06/14	Romig Engineers, Inc.	Geotechnical Investigation, Site Retaining Walls and Swimming Pool

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204224

Record Title & Contents

**GEOTECHNICAL REPORT FOR
BUCK COURT - 1025 CANADA ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
-------	---------	------------------	------	-------------	-------

BUCK COURT

3	Buck Estates Subdivision	x	10/0/80	Frahm Elder Cannis	First Study Plan, Lands of Hagen
			12/29/80	William Cotton and Associates	Geotechnical Review Sheet
			01/20/81	William Cotton and Associates	Geologic Review - Lands of Hagan, Buck Estates
			01/29/81	William Cotton and Associates	Review
			02/26/81	Jo Crosby & Associates	Geotechnical Investigation, 11+ Acres, Buck Estates
			07/13/81	Donald A. Woolfe and Associates	Environmental Setting Survey, Buck Estate
			08/05/81	Frahm Elder Cannis	Preliminary Map
			08/12/81	William Cotton and Associates	Review - Buck Estates/B & P Subdivision, SD #140
	Briggs Subdivision		07/30/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Briggs Subdivision
			07/16/86	William Cotton and Associates	Geotechnical Review Sheet
			08/21/86	Toen of Woodside	Results of Meeting with Subdivision Review Committee, Subdivision #147
			09/23/86	Tillson-Bliss & Associates	Replies to Results of Subdivision Review Committee Notes
			10/08/86	Jo Crosby & Associates	Geotechnical Investigation, Briggs Estate
			02/18/87	Charles M. Salter Associates, Inc.	Briggs Estate - Accoustical Consulting
	10 Buck Court	x	07/02/98	Nielsen Geotechnical Incorporated	Soil Report, Lots 2, 3 & 7, Buck Estate, Northgate Drive
			05/14/00	Nielsen Geotechnical Incorporated	Plan Review, New House, Lot 3
			09/13/00	Nielsen Geotechnical Incorporated	Plan Review 3rd Review, New House, Lot 3, Buck Estate
			11/09/00	Nielsen Geotechnical Incorporated	Review of Revised Retaining Wall Plan, New House
			12/03/01	Nielsen Geotechnical Incorporated	Construction Report, Lot 3
	20 Buck Court	x	07/02/98	Nielsen Geotechnical Incorporated	Soil Report, Lots 2, 3 & 7, Buck Estate, Northgate Drive
			08/29/02	Nielsen Geotechnical Incorporated	Construction Report, Residential Project, 20 Buck Court (Lot 2, Buck Estate)
			04/11/08	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Swimming Pool
	30 Buck Court	x	05/08/01	Nielsen Geotechnical Incorporated	Soil Report
	40 Buck Court	x	07/02/98	Nielsen Geotechnical Incorporated	Soil Report, Lots 2, 3 & 7, Buck Estate, Northgate Drive
			01/04/00	Bay Area Geotechnical Group	Foundation Investigation, Proposed Single Family Residence, Lot 7, Buck Court

	50 Buck Court		07/16/98	Bay Area Geotechnical Group	Foundation Investigation, Proposed Single Family Residence, Lot 6, Buck Court
		x	11/07/02	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Swimming Pool, Lot 6, Buck Estates
			12/04/03	Nielsen Geotechnical Incorporated	Review of Plans & Structural Calculations, Retaining Wall
			04/20/04	Nielsen Geotechnical Incorporated	Construction Report, Pool and Retaining Wall
	60 Buck Court	x	07/22/98	Bay Area Geotechnical Group	Geotechnical Investigation, Lot 5 / Buck Court, Proposed Single Family Residence
CANADA LANE					
3	1515 Canada Lane	x	05/22/00	GeoForensics, Inc.	Geotechnical Investigation Update, Proposed Residential Addition, Griffen Property
			11/08/00	GeoForensics, Inc.	Response to Review Comments, Proposed Addition
	1577 Canada Lane		03/15/18	Murray Engineers, Inc.	Geotechnical Investigation, Holmstrom Accessory Structures
	1580 Canada Lane	x	03/21/86	Howard F. Donley & Associates	Soil and Foundation Investigation, Proposed Addition to Office Building
	1583 Canada Lane	x	04/07/06	Romig Engineers, Inc.	Geotechnical Study, Foundation Improvements
			04/24/08	Romig Engineers, Inc.	Updated Design Parameters, Dickinson Residence Upgrade
	1589/1591 Canada Lane	x	06/30/82	PSC Associates, Inc.	Geotechnical Engineering Investigation, Proposed Residence, Parcels (1589) and C (1591)
				William Cotton and Associates	Geotechnical Review Sheet
			12/27/89	PSC Associates, Inc.	Geotechnical Report Update, Lot C (1591)
			12/05/90	Edward W. Baca	Topographical Survey
			03/28/91	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Vanos, SD #35 and Exc to SD #72
			04/23/91	PSC Associates, Inc.	Supplemental Geotechnical Investigation and Response to Cotton Review Letter for Proposed Residence on Parcel C
			11/08/91	William Cotton and Associates	Geologic and Geotechnical Review, Vanos, SD #39
			06/30/92	William Cotton and Associates	Geologic and Geotechnical Review, Vanos, PA #8830 and 8832
			08/24/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Vanos, #8830 and #8832
	1595 Canada Lane	x	07/10/02	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence
			07/07/05	GeoForensics Inc.	Geotechnical Recommendations, Proposed New Pool, Canada Lane Property
			07/18/16	Murray Engineers, Inc.	Geotechnical Investigation, Mikkelsen Pool House & Swimming Pool

	3030 Canada Lane	x	03/21/86	Howard F. Donley & Associates	Soil and Foundation Investigation, Proposed Addition to Office Building
			01/08/86	Charlie Chu, Jr. & Associates	Existing Site Plan with New Addition, with annotations
			04/17/86	William Cotton and Associates	Geotechnical Review Sheet
			04/23/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Gadbois Office Addition
			05/05/86	Howard F. Donley & Associates	Response to Cotton's Letter dated 4/23/86, Proposed Office Addition
			05/14/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Gadbois Office Addition
CANADA ROAD					
3	811 Canada Road	x	07/10/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Two Lot Subdivision
	833 Canada Road	x	03/19/85	Howard F. Doneley & Associates	Geotechnical Investigation
			06/04/85	Lea Engineering	Structural Calculations
			06/28/85	Howard F. Doneley & Associates	Foundation Plan Review, Proposed Residence
					Septic System Plan
			08/26/85	William Cotton and Associates	Geotechnical Review Sheet
			09/04/85	William Cotton and Associates	Preliminary Geologic Review and Geotechnical Investigation Evaluation, Soma, Parcel #068-253-100
			09/27/85	Howard F. Doneley & Associates	Soil Expansivity
			10/11/85	William Cotton and Associates	Supplemental Geotechnical Review, Soma, Parcel #068-253-100
	839 Canada Road	x	07/28/97	Nielsen Geotechnical Incorporated	Soil Report
	937 Canada Road	x	10/01/07	PGSoil, Inc.	Geotechnical Investigation, Proposed House Addition
			11/30/07	PGSoil, Inc.	Supplement to Geotechnical Investigation, Proposed House Additions
	1025 Canada Road	x	08/18/77	Cooper -Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
		x	08/13/87	Cooper Engineers, Inc.	Geotechnical Investigation, Parcel A/Land Division 243, Proposed Single-Family Residence
	1028 Canada Road		04/22/15	Romig Engineers, Inc.	Geotechnical Investigation, Werdegard Residence
	1030 Canada Road	x	05/02/05	Cleary Consultants, Inc.	Geotechnical Investigation, New Accessory Buildings (2), Greenhouses (2), and Lath House
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204225					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 1034 CANADA ROAD - 1308 CANADA ROAD					

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
CANADA ROAD					
3A	1034 Canada Road	x	01/29/96	Earth Investigations Consultants	Fault Investigation Waiver, Proposed Improvements
	1036 Canada Road	x	04/07/78	Jo Crosby & Associates	Geologic and Soils Investigation (APN 072-060-406)
			05/23/78	Joe Crosby & Associates	Addendum to Geologic and Soils Investigation
			06/20/02	Cleary Consultants, Inc	Geotechnical Investigation, New Barns (2) on Indian House Ranch (APN 072-060-390)
	1166 Canada Road	x	04/07/06	Romig Engineers, Inc.	Geotechnical Investigation, Addicott Barn, Pool House and Residence Improvements
	1177 Canada Road	x	03/08/98	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Foundation Improvements and Detached New Garage
			01/25/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Cabana
	1185 Canada Road	x	04/26/92	GeoForensics, Inc.	Foundation Study, Mattman Residence
				William Cotton and Associates	Geotechnical Review Study
			06/15/92	William Cotton and Associates	Geologic and Geotechnical Review, Mattman Addition, BP-8810
	1210 Canada Road	x	04/06/77	Terrasearch, Inc	Soil and Geologic Investigation, Lands of Chamberlain
			12/09/76	Perry R. Woods	Percolation Test Results and Logs
			03/18/77	Fram Elder Cannis	Preliminary Map, Land Division, Lands of Chamberlain, showing Parcel B with percolation test pit locations
			03/19/01	Terrasearch, Inc	Geotechnical Investigation, Proposed Wine Cellar
			05/15/14	Murray Engineers, Inc	Ryan Horse Barn
	1221 Canada Road	x	06/17/91	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
				William Cotton and Associates	Geotechnical Review Sheet
			01/10/91	William Cotton and Associates	Supplemental Geotechnical Review, Pugh Residence, PA-8491
			10/07/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
			12/05/91	GeoForensics, Inc.	Geotechnical Plan Review, Proposed New Residence
	1240 Canada Road	x	01/12/70	Reynolds & Associates	Foundation Investigation, Chamberlain Residence
	1250 Canada Road	x	07/30/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Residence
			08/04/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Guest House and Retaining Wall, Brouscomb Property
			01/20/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool, Brouscomb Property
	1260 Canada Road	x	02/05/85	PSC Associates, Inc.	Geotechnical Engineering Report

			07/15/85	PSC Associates, Inc.	Geologic and Geotechnical Engineering Investigation, Proposed Residence, Lot 1 near Glenwood Avenue
			05/22/95	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
			06/29/95	Earth Investigations Consultants	Geotechnical Investigation, Response to Town Review, Proposed Residential Development
	1281 Canada Road		11/30/16	Murray Engineers, Inc	Geotechnical Investigation, Altick Residence
	1300 Canada Road	x	07/15/85	PSC Associates, Inc.	Geologic and Geotechnical Engineering Investigation, Proposed Residence, Lot 1 near Glenwood Avenue
	1302 Canada Road	x	06/17/81	Terrasearch Inc.	Geologic Feasibility Evaluation, Proposed Servants's Dwelling
			06/17/86	Purcell, Rhodes & Associates	Soil Engineering and Geotechnical Report, Proposed Cabana, McNaughton Residence
	1308 Canada Road	x	10/11/99	John W. Leonard	Geotechnical Engineering Investigation, Coast Oak Property, Single-Family Residential Property
			08/31/04	Murray Engineers, Inc	Geotechnical Evaluation Residence Distress
	1311 Canada Road		06/04/12	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Remodel & Detached Accessory Building
	1339 Canada Road		12/05/14	Michelucci & Associates, Inc	Geotechnical Investigation, Proposed Sunroom Floor Replacement
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204226					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 1385 CANADA ROAD - CREST ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
CANADA ROAD					
4	1385 Canada Road	x	04/15/97	Associated Terra Consultants, Inc.	Geologic Investigation
			09/02/97	Michelucchi & Associates, Inc.	Geotechnical Investigation of Landslide, Proposed 3-Lot Subdivision
			10/25/02	Romig Engineers, Inc.	Geotechnical Investigation, Edwards Garage Addition
			02/02/10	Murray Engineers, Inc.	Geotechnical Investigation, Edwards Residence
	1395 Canada Road	x	04/21/95	Lee Engineers, Inc.	Soil Investigation, Noyes Residence Addition & Swimming Pool Site Development
	1450 Canada Road	x	05/13/09	Neil O. Anderson and Associates	Geotechnical Investigation, Solomon Residence Swimming Pool
	1470 Canada Road	x	12/09/93	Fowler & Associates	Geological and Geotechnical Investigation, Proposed Single Family Residence
			01/24/94	Fowler & Associates	Supplemental Geological and Geotechnical Investigation, Proposed Single Family Residence

			04/08/98	Fowler & Associates	Supplemental Geotechnical Investigation, Proposed Barn
			11/16/01	Fowler & Associates	Geotechnical Consultation, Proposed Barn
	1491 Canada Road	x	03/28/00	Nielsen Geotechnical Incorporated	Soil Report
			09/21/12	Murray Engineers, Inc.	Geotechnical Investigation, Zaky Residence Improvements
CEDAR LANE					
4	2 Cedar Lane	x	11/24/97	Nielsen Geotechnical Incorporated	Soil Report
	3 Cedar Lane	x	07/28/95	Fowler & Associates	Geotechnical Investigation, Proposed Two New Accessory Structures
			04/01/02	Fowler & Associates	Geotechnical Consultation and Plan Review
	4 Cedar Lane	x	08/09/07	Romig Engineers, Inc.	Geotechnical Investigation, Lacob Residence
	5 Cedar Lane	x	04/17/95	Nielsen Geotechnical Incorporated	Soil Report
			11/30/97	Nielsen Geotechnical Incorporated	Supplemental Soil Report
CHURCHILL AVENUE					
4	198 Churchill Avenue	x	02/28/87	J. V. Lowney & Associates	Geotechnical Investigation, Distressed Garage and Residence Addition
				William Cotton and Associates	Geotechnical Review Sheet
			11/23/87	Stoeker and Northway Architects incorporated	Site Plan, Residential Remodel
			07/06/05	Romig Engineers, Inc.	Geotechnical Investigation, Front Porch and Foundation Repair
CINNABAR ROAD					
4	Cinnabar Road	x	09/12/66	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Woodside Hills Unit No. 6
	240 Cinnabar Road	x	04/24/89	J. V. Lowney & Associates	Geotechnical Investigation, McCarthy Residence
			09/20/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Swimming Pool, McCarthy Property
			06/16/06	Bay Area Geotechnical Group	Geotechnical Consultation, Proposed Residential Improvements
	245 Cinnabar Road	x	12/29/77	Jo Crosby & Associates	Geology and Soils Investigation Report, 48 Acres/Harcross Road
			10/17/97	Dibble - Wright Associates	Geologic Inspection (APN 069-380-120)
			09/20/99	Jo Crosby & Associates	Geotechnical Investigation, Proposed Tennis Court Development
			05/16/00	Jo Crosby & Associates	Response to Town Comments on 9/20/99 Report
CORTO LANE					
4	35 Corto Lane	x	11/07/03	Romig Engineers, Inc.	Geotechnical Investigation, Werdegarr Residence Addition
	50 Corto Lane	x	06/05/96	Lee Engineers, Inc.	Soil Investigation Report, Proposed Swimming Pool Reconstruction

			06/10/03	Lee Engineers, Inc.	Sunroom Site Condition Reconnaissance and Recommendations
	70 Corto Lane	x	06/28/99	GeoForensics Inc.	Limited Geotechnical Investigation, Proposed New Residential Additions
			06/06/01	GeoForensics Inc.	Construction Observations, Residence Additions
			09/28/05	GeoForensics Inc.	Report Supplement, Cleary Residence
CREST ROAD					
4	115 Crest Road	x	06/17/97	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Addition
	120 Crest Road	x	06/13/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Pool House and Patios, Johnson Property
	140 Crest Road		07/28/14	Murray Engineers, Inc.	Geotechnical Investigation, Haller Residential Improvements
	145 Crest Road		04/17/02	Carl W. Garbe	Soil/Foundation Investigation, Proposed Remodelling
		x	12/14/05	Hydro-Geo Consultants, Inc.	Geotechnical Assessment, Addition to Existing Alexander Nemirovsky Residence (APN 069-142-010)
	150 Crest Road	x	06/29/10	Romig Engineers, Inc.	Geotechnical Investigation, Legros Residence Addition & Deck
			02/01/11	Romig Engineers, Inc.	Geotechnical Recommendations, Spa, Pool, and Pool Deck
	160 Crest Road	x	02/15/05	Advance Soil Technology, Inc.	Geotechnical / Soil and Foundation Investigation, Proposed Single Family Residence
	Crest Road		09/12/66	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Woodside Hills Unit No. 6
	170 Crest Road		05/31/12	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Addition
	187 Crest Road		05/18/18	Romig Engineers	Geotechnical Investigation Robinson Residence
	189 Crest Road	x	04/10/87	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed D'Amico Residence
	191 Crest Road		4/9/2015	GeoForensics, Inc.	Geotechnical Investigation for Proposed New Pool House, Retaining Walls, Driveway, and Flatwork
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204227					
Record Title & Contents					
GEOTECHNICAL REPORT FOR CROYDEN WAY - 265 ELEANOR DRIVE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
CROYDEN WAY					
4A	120 Croydon Way	x	01/09/04	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence Additions, Harris Property
			04/10/08	GeoForensics, Inc.	Updated Recommendations Letter for Proposed Landscape Improvements

	121 Croyden Way	x	01/28/93	Carl W. Garbe	Soils and Foundation Report, Proposed Improvements
DEAN ROAD					
4A	120 Dean Road	x	02/21/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Residence
	130 Dean Road	x	03/18/03	Romig Engineers, Inc.	Geotechnical Investigation
	140 Dean Road	x	01/25/01	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Residence
			06/19/03	Terrasearch, Inc.	Geotechnical Recommendations, New Swimming Pool
			10/29/03	Terrasearch, Inc.	Response to Town Comments
DRY CREEK LANE					
4A	180 Dry Creek Lane	x	04/08/00	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence Addition, Foley Property
EAST VIEW WAY					
4A	507 East View Way	x	07/23/93	Steve Dal Associates	Limited Geotechnical Study Remodel/Addition, Existing Adams Residence
	522 East View Way	x	10/29/98	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
			05/06/05	J. Yang and Associates	Geotechnical Site Investigation, Swimming Pool
			09/23/06	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
	535 East View Way	x	06/23/94	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Single Family Residence and Vineyard, Lands of Rogers
	538 East View Way	x	10/30/98	J. Yang and Associates	Geotechnical Site Investigation, Proposed Residence
4A	575 East View Way	x	07/30/90	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Rogers
			04/30/01	Upp Geotechnology, Inc.	Geotechnical Report Update and Plan Review, Proposed Basement Addition, Rogers Residence
			11/18/17	Geosphere Consultants, Inc.	Limited Geotechnical Investigation, Proposed Solar Module
	623 East View Way	x	08/23/90	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Rogers
ECHO LANE					
4A	15 Echo Lane	x	02/21/06	Romig Engineers, Inc.	Geotechnical Review, Van Rheeman Residence
			04/18/16	Sigma Prime Geosciences, Inc.	Geotechnical Report, Proposed Work, Shaffer Property
			11/03/20	Sigma Prime Geosciences, Inc.	Geotechnical Report, Proposed Addition
ELEANOR DRIVE					
4A	115 Eleanor Drive	x	02/13/09	United Soil Engineering, Inc.	Geotechnical and Slope Investigation, Proposed New Residence
			05/18/09	United Soil Engineering, Inc.	Revised Geotechnical and Slope Investigation, Proposed New Residence

			06/22/09	United Soil Engineering, Inc.	Supplemental Geotechnical and Slope Investigation, Proposed New Residence
			07/06/09	United Soil Engineering, Inc.	Additional Geotechnical Recommendations (2), Proposed New Residence
131 Eleanor Drive	x		12/21/09	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Deck
			11/12/10	Earth Investigations Consultants	Supplemental Geotechnical Parameters, Proposed Landscape Wall
139 Eleanor Drive	x		01/28/11	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Remodeling
140 Eleanor Drive	x		09/01/80	Edwin H. Smith	Preliminary Map, Subdivision of Lot 6 and Portion Lot 5, Block 1, Woodside Heights with annotations
			11/12/80	Purcell, Rhoades & Associates	Geotechnical Hazards Assessment, APN's 069-222-050 and -070, Eleanor Drive and Northgate Drive
			12/29/80	William Cotton and Associates	Geotechnical Review Sheet, LD #270
			01/08/81	Town of Woodside	Review Letter Summarizing Requirements
			01/14/81	Town of Woodside	Review of PRA Hazards Report dated 11/12/80
			01/23/81	Edwin H. Smith	Response to Review Letter Summarizing Requirements dated 1/8/81
			01/27/81	William Cotton and Associates	Geologic Review of PRA Hazards Report dated 11/12/80
			02/26/81	Town of Woodside	Review Letter Summarizing Requirements
			03/10/81	Edwin H. Smith	Preliminary Map, LD # 270 - Request for Exception to Water Flow Requirements
			05/21/81	Purcell, Rhoades & Associates	Soil and Geologic Study, Parcel 8, APN's 069-222-050 and -070
			07/15/81	William Cotton and Associates	Geologic Review, Gafke, LD #270
			09/12/03	Fowler & Associates	Engineering Geology Investigation, Proposed Single Family Residence
			09/15/03	David Jones Associates	Geotechnical Investigation, Proposed Single Family House
			10/03/07	Michelucci & Associates, Inc.	Front Entry Area - Proposed Temporary Releveling/Underpinning
			05/09/16	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Guest House
155 Eleanor Drive	x		06/14/00	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residence
			03/21/01	Bay Area Geotechnical Group	Addendum to Geotechnical Investigation, Proposed Residence
			04/09/01	Geomatrix Consultants	Geotechnical Review, Smith Residence
			04/12/01	Geomatrix Consultants	Basement Height
			06/04/01	Bay Area Geotechnical Group	Second Addendum to Geotechnical Investigation Report, Proposed Smith Residence
			10/09/02	Bay Area Geotechnical Group	Geotechnical Observation/Testing Services During Construction of Residence
161 Eleanor Drive	x		07/28/95	Tom Hui	Visual Structural Inspection Report
167 Eleanor Drive	x		05/15/18	Sigma Prime Geosciences, Inc.	Geotechnical Report for Proposed Single Family Home
			01/15/19	Sigma Prime Geosciences, Inc.	Geotechnical Report for Proposed Single Family Home

	168 Eleanor Drive	x	01/24/05	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Swimming Pool
			02/24/15	Michelucci & Associates, Inc.	Proposed Addition and Modifications to Residence and Guest House
	175 Eleanor Drive	x	02/14/90	JCP Geologists Engineers	Geologic and Soil & Foundation Services, Distressed Home
				William Cotton and Associates	Geotechnical Review Sheet
			05/14/90	Lea Engineering	Structural Calculations
			07/02/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence
			06/03/94	Harlan Tait Associates	Letter of Transmittal
	200 Eleanor Drive	x	04/01/86	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Addition to Home
	205 Eleanor Drive	x	01/30/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Additions at 205 Eleanor Drive
			09/07/05	GeoForensics Inc.	Geotechnical Investigation, Spa and Replacement Retaining Walls, Jimerson Property
			12/02/05	GeoForensics Inc.	Limited Geotechnical Evaluation, Proposed Additions
	228 Eleanor Drive	x	09/28/98	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation
	233 Eleanor Drive	x	12/09/96	J. Yang and Associates	Geotechnical Site Investigation, Poland Residence Addition
			07/14/01	J. Yang and Associates	Geotechnical Site Investigation, Proposed Kahn Residence
			07/24/01	Steven F. Connelly	Engineering Geology Investigation, Proposed Residence, Kahn Property
			09/22/06	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Swimming Pool
	238 Eleanor Drive	x	09/09/75	Berlogar, Long & Associates	Engineering Geologic Investigation, Proposed Parcel Split
			01/22/76	Berlogar, Long & Associates	Soil Investigation, Proposed Residence
			02/27/76	Town of Woodside	Review of Berlogar, Long & Associates
			04/15/96	Nielsen Geotechnical Incorporated	Soil Report
	265 Eleanor Drive	x	06/09/94	Rutherford & Chekene	Geotechnical Investigation and Design Recommendations, Starr Residence Remodel
			08/14/17	Murray Engineers Inc.	Geotechnical Investigation, Jensen Site Improvements
	268 Eleanor Drive		6/28/2012	Romig Engineers, Inc.	Geotechnical Investigation, Castellino Garage Additions
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204228					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 270 ELEANOR DRIVE - ESPINOSA ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
ELEANOR DRIVE					

5	270 Eleanor Drive	x	12/02/98	Nielsen Geotechnical Incorporated	Soil Report
			02/15/99	Nielsen Geotechnical Incorporated	Supplemental Soil Report,
			03/31/99	Nielsen Geotechnical Incorporated	Review - Geotechnical Investigation Report, Proposed Additions and Retaining Wall
			05/17/99	Nielsen Geotechnical Incorporated	Plan Review, Addition and Remodel
			06/01/01	Nielsen Geotechnical Incorporated	Response to Inquiry, Retaining Walls
			06/19/01	Geomatrix Consultants	Geotechnical Review, Rossi Retaining Walla and Site Improvements
			10/02/01	Nielsen Geotechnical Incorporated	Foundation Observations, Rear-Yard Retaining Wall
			02/07/02	Nielsen Geotechnical Incorporated	Foundation Pier Bore Observations, Driveway Retaining Wall
			12/06/02	Nielsen Geotechnical Incorporated	Construction Report
	275 Eleanor Drive	x	07/25/11	GeoQuest	Geotechnical Investigation, Addition to Roizen Residence
			07/25/11	GeoQuest	Plan Review - Geotechnical Investigation, Addition to Roizen Residence
	289 Eleanor Drive	x	12/17/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Second Story Addition
	292 Eleanor Drive	x	09/04/07	Romig Engineers, Inc.	Geotechnical Investigation, Canessa Residence Improvements
			11/03/08	Romig Engineers, Inc.	Supplemental Recommendations, Garage Conversion
	315 Eleanor Drive	x	02/10/10	Romig Engineers, Inc.	Geotechnical Slope Review, McLaughlin Garage Addition
			03/15/10	Romig Engineers, Inc.	Geotechnical Investigation, McLaughlin Detached Garage and Guest House
	353 Eleanor Drive	x	05/18/99	Romig Consulting Engineers	Geotechnical Investigation, Barrocas Residence Addition
	372 Eleanor Drive		01/13/87	Associated Geotechnical Engineers	Foundation Engineering Investigation for Proposed House Additions, Carter Residence
	380 Eleanor Drive	x	01/29/00	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions and Future Pool
			10/06/00	PGSoils, Inc.	Geotechnical Investigation, Proposed Deck, MacDonald Property
			03/02/05	PGSoils, Inc.	Geotechnical Report Update, Proposed House Addition
	408 Eleanor Drive	x	09/12/08	Romig Engineers, Inc.	Geotechnical Investigation, Residential Subdivision
			07/29/10	Romig Engineers, Inc.	Geotechnical Investigation, Wonnacott Residence
	410 Eleanor Drive		10/18/16	Romig Engineers, Inc.	Geotechnical Investigation, Ungerman Residence Addition & Distress Evaluation

	447 Eleanor Drive	x	04/14/86	JCP Geologist-Engineers	Review of Soil Engineering Aspects, Foundation Plan, Proposed Addition
			07/02/05	Raymond J. Dodson	Dressing Room Addition
			09/01/05	Raymond J. Dodson	Dressing Room Addition
	461 Eleanor Drive	x	04/11/06	Murray Engineers, Inc.	Geotechnical Investigation, Pollack Residence
			04/06/07	Murray Engineers, Inc.	Supplemental Recommendations, Spa Addition to Pool
	465 Eleanor Drive	x	07/19/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
			07/30/02	Romig Engineers, Inc.	Geotechnical Plan Review, Residence Addition
	475 Eleanor Drive		04/08/04	Nielsen Geotechnical Incorporated	Foundation Recommendations
	469 Eleanor Drive	x	03/21/02	PGSoils, Inc.	Geotechnical Conditions, Proposed Carport Upgrade and Addition
			12/01/04	Earth Investigations Consultants	Geotechnical Investigation, Proposed Concrete Block Culvert
	485 Eleanor Drive	x	04/14/08	Neil O. Anderson and Associates	Forensic Investigation, Hausman Residence Swimming Pool
			12/02/10	Earth Investigation Consultants	Geotechnical Investigation, Proposed New Retaining Wall
			05/30/12	Earth Investigation Consultants	Geotechnical Investigation, Proposed Residential Development
	528 Eleanor Drive	x	08/19/99	Nielsen Geotechnical Incorporated	Soil Report
			12/17/01	Nielsen Geotechnical Incorporated	Construction Report, House, Retaining Walls and Pool
	538 Eleanor Drive	x	02/22/87	William M. McMorrow & Associates	Geotechnical Engineering Investigation, Relative Distress to Single-Family Residence, Beisler Property
			03/28/88	William M. McMorrow & Associates	Review of Design Documents, proposed Repairs to Beisler Residence
			06/10/88	William M. McMorrow & Associates	Geotechnical Engineering Consultation & Observation Services, Repairs to Beisler Residence
			09/21/01	Romig Engineers, Inc.	Geotechnical Investigation, Mone-Choplin Residence
			06/08/06	Romig Engineers, Inc.	Supplemental Recommendations, Residence Additions
	571 Eleanor Drive		08/27/13	Earth Systems Pacific	Geotechnical Engineering Study, Proposed Two-Story Residence and Guest House
	572 Eleanor Drive		12/11/12	Romig Engineers, Inc.	Geotechnical Investigation, Teter Residence
	580 Eleanor Drive	x	05/28/98	NielsenGeotechnical Incorporated	Soil Report, Lot 4, Buck Estate
			11/30/01	NielsenGeotechnical Incorporated	Construction Report, Residential project, Lot 4, Buck Estate
			07/06/07	Charles H. Hartsog	Soils Report, Bacolini Project

ESPINOSA ROAD

5	750 (?) Espinosa Road	x	03/31/95	Milstone Geotechnical	Geotechnical Reconnaissance Investigation, Schilling Lake Spillway, Thornewood Open Space Preserve
	750/764 Espinosa Road	x	08/23/83	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Espinosa Road Landslide
			?	?	Detailed Map of Landslide and Associated Features with Section Sketch on Back
			06/24/83	Skyline County Water District	Letter to Mr. Bock
			06/29/83	Town of Woodside	Stop Work Notice
			06/29/08	Mr. Bock	Letter to Town Council
			07/12/83	Town Engineer	Report to Town Council - Item #8 - Appeal of Requiring Investigation and Permit for Landslide Repair
			07/12/83	Tim J. Manzagol	Temporary Slide Repair for Dropped Portion of Espinosa Road - Bock Property
			07/12/83	Homewoners	Letter to Town Council - Repair of Private Road
			07/18/83	William Cotton and Associates	Geologic Review, Boch Landslide
			09/13/83	William Cotton and Associates	Geologic Review - Esponosa Road (Boch) Landslide Complex
			10/17/83	Freeman-Kern Associates, Inc.	Completion Report, Espinosa Road Landslide Repair
	810 Espinosa Road	x	09/15/04	Micheluci & Associates	Geotechnical Consultation, Planned Modifications to Residence
	885 Espinosa Road	x	01/23/03	Romig Engineers, Inc.	Geotechnical Services, Residence Addition
	895 Espinosa Road	x	01/20/00	Micheluci & Associates	Preliminary Geotechnical Evalustion, Planned Swimming Pool
			06/19/00	Micheluci & Associates	Review of Plans, Planned Swimming Pool
			09/14/01	Micheluci & Associates	Engineering Observations of Landscape Improvements
	905 Espinosa Road	x	11/10/72	Jo Crosby & Associates	Geologic and Foundation Investigation, Varian Lot
			12/22/76	Purcell, Rhodes & Associates	Soil and Geologic Investigation, Portion of Lot 31/Portola Hills
			01/19/77	Purcell, Rhodes & Associates	Addendum to Soil, Geologic and Percolation Investigation Report 12/22/76
			01/20/77	Leighton and Associates	Review
			04/25/77	Leighton and Associates	Proposed Building Addition
			03/01/78	Purcell, Rhodes & Associates	Addendum to Soil and Geologic Investigation, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
			04/03/78	Leighton and Associates	Request for Additional Information
			04/19/78	Purcell, Rhodes & Associates	Additional Geotechnical Data, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
			05/10/78	Purcell, Rhodes & Associates	Project Status, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
			06/06/78	Purcell, Rhodes & Associates	Clarification of Previously Submitted Geotechnical Data, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
			06/16/78	Leighton and Associates	review

			07/11/78	J. Walter Hoskins	Grading Plan and Proposed Residence, with annotations
			09/06/78	Purcell, Rhodes & Associates	Supplemental Information, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
			05/28/79	Purcell, Rhodes & Associates	(Plan Review) Gano Residence
			04/28/03	Michelucci & Associates, Inc.	Geotechnical Consultation, Planned Subfloor Modification to Residence
	920 Espinosa Road	x	08/05/83	William F. Jones, Inc.	Geotechnical Investigation, Donath Property
			09/16/83	William Cotton and Associates	Geotechnical Review Sheet
			09/27/83	William Cotton and Associates	Review - Donath Landslide
			09/23/14	Upp Geotechnology	Limited Geotechnical Study, Proposed Garage
	950 Espinosa Road	x	04/11/01	Romig Engineers, Inc.	Geotechnical Investigation, Dubbs Residence
			02/12/03	Romig Engineers, Inc.	Supplemental Recommendations, Driveway Retaining Wall
	980 Espinosa Road		08/28/13	PGSoils, Inc.	Geotechnical Conditions, McDonald Property Slope Cut & Retaining Wall
	Espinosa Road @ Grandview Drive	x	12/05/74	Berlogar, Long & Associates	Soils Engineering and Engineering Geologic Investigation, Single Family Residence, cr. Grandview Drive
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204229					
Record Title & Contents					
GEOTECHNICAL REPORT FOR EUCALYPTUS COURT - FAMILY FARM ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
EUCALYPTUS COURT					
5A	1 Eucalyptus Court	x	08/18/77	Cooper-Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
			12/31/03	Romig Engineers, Inc.	Geotechnical Investigation, Sammut Pool House
			03/24/11	Michelucci & Associates, Inc.	Drainage Evaluation, Existing Residence and Adjacent Lawn Areas and Installation of Two Groundwater Monitoring Piezometers
			07/12/11	Michelucci & Associates, Inc.	Review of Plans and Supplemental Design Recommendations, Proposed New Landscape Retaining Walls
	2 Eucalyptus Court	x	08/18/77	Cooper-Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
	3 Eucalyptus Court	x	08/18/77	Cooper-Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
EUGENIA LANE					
5A	20 Eugenia Lane	x	04/28/97	Jo Crosby & Associates	Geotechnical Investigation
	25 Eugenia Lane	x	03/10/90	Purcell, Rhodes & Associates	Geotechnical Study, Addition

	31 Eugenia Lane	x	03/23/05	GeoForensics, Inc.	Geotechnical Investigation, Proposed Spa, Kibble Property
			10/17/05	GeoForensics, Inc.	Driveway Reconstruction
FAMILY FARM ROAD					
5A	Family Farm Road Bridge	x	02/07/00	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Proposed Bridge at Sausal Creek
			04/30/00	Upp Geotechnology, Inc.	Supplemental Information, Geotechnical Evaluation, Proposed Bridge
	200/201 Family Farm Road	x	02/09/82	William Cotton and Associates	Review - Smith Land Division
			1/0/82	Skierka & Fisher Land Surveys	Preliminary Map
	200 Family Farm Road	x	04/13/87	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Detached Garage, Swimming Pool, and Retaining Wall
	218 Family Farm Road	x	12/16/94	Clearly Consultants, Inc.	Fault Location Investigation Report
			05/10/95	Clearly Consultants, Inc.	Geotechnical Investigation Report, New Residence
			06/30/96	Clearly Consultants, Inc.	Fault Location Investigation Report, Guest Home/Pool and Caretakers Cottage
	(195 Farm Road)		09/20/96	Clearly Consultants, Inc.	Geotechnical Investigation, Caretakers Cottage
			06/12/98	Clearly Consultants, Inc.	Proposed Caretakers Cottage Project
	220 Family Farm Road	x	12/21/00	Romig Engineers, Inc.	Geotechnical Investigation, Sullivan Residence Addition
	230 Family Farm Road	x	06/20/00	John Coyle & Associates, Inc.	Fault Location Map, Existing Pool House
			06/25/99	Nielsen Geotechnical Incorporated	Soil Report
			08/07/02	Nielsen Geotechnical Incorporated	Basement Recommendations, Remodel Existing Suesthouse
			05/19/03	Nielsen Geotechnical Incorporated	Soil Report, Basement and Attached Garage
			04/28/06	Murray Engineers, Inc.	Supplemental Recommendations, Driveway Retaining Wall
	250 Family Farm Road	x	04/19/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Soil Foundation Investigation, Proposed New Structures
				William Cotton and Associates	Geotechnical Review Sheet
			09/20/83	Vincent F. Kong	Structural Calculations, Markkula Residence Addition
			09/23/83	Leonard E. Limcoln	Site Plan, with annotations
			11/04/83	William Cotton and Associates	Review- Markkula Residential Addition
			11/14/83	Purcell, Rhodes & Associates	Plan Review, Addition
			11/23/83	William Cotton and Associates	Review- Markkula Residential Addition
			06/28/01	Terrasearch, Inc.	Preliminary Geotechnical Recommendations Regarding Foundation Design, Proposed Room Addition
			07/25/01	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Addition and Remodel for Existing Residence
			06/28/01	Terrasearch, Inc.	Preliminary Geotechnical Recommendations Regarding Foundation Design, Proposed Room Addition

			03/12/02	Earth Investigations Consultants	Soil and Foundation Investigation & Plan Review, Proposed Dry-stack Landscape Retaining Walls. Craft-Malcolm Property
260 Family Farm Road	x		03/01/78	Fischer Land Surveys	Tentative Map, Proposed Resubdivision of APN 75-293-110, with annotations
			06/19/78	Purcell, Rhoades & Associates	Geotechnical Hazard Investigation, Parcel 2, Proposed Resubdivision of APN 75-293-110
			09/10/78	William Cotton and Associates	Geologic Review, Eyer Land Division
270 Family Farm Road	x		10/03/97	Upp Geotechnology, Inc.	Geotechnical Investigation, New House, Pool and Pool House, Lands of Bonora
			11/18/97	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation, Proposed Leachfield, Bonora Property
			05/21/98	Upp Geotechnology, Inc.	Responses to Geotechnical Review, Proposed House, Pool House, and Pool, Lands of Bonora
			07/02/98	Upp Geotechnology, Inc.	Supplemental Plan Review, Proposed House and Pool House, Lands of Bonora
			08/10/98	Upp Geotechnology, Inc.	Construction Monitoring, Drilled Pier Excavation and Grade Beam Voids, Lands of Bonora
			08/20/98	Upp Geotechnology, Inc.	Supplemental Plan Review, Revisions to Foundation Plan, Lands of Bonora
			08/24/98	Upp Geotechnology, Inc.	Foundation Revisions
			09/17/98	Upp Geotechnology, Inc.	Construction Monitoring, Grade Beam Voids, Bonora Residence and Pool House
			01/30/01	Upp Geotechnology, Inc.	Construction Observation, Pool House, Swimming Pool and Site Retaining Wall
			02/29/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Swimming Pool Extension
			06/03/16	Upp Geotechnology, Inc.	Limited Geologic & Geotechnical Study Proposed Studio Accessory Structure
290 Family Farm Road	x		11/08/82	Perry R. Wood	Proposed On-Site Septec Drainfield, Parcel 2, Lands of Cooper
			04/27/83	Site Characteristics, Inc.	Lands of Cooper Fault Investigation
			05/04/83	William Cotton and Associates	Geotechnical Review Sheet
			05/23/83	William Cotton and Associates	Review, Proposed Land Division, Cooper Parcel
300 Family Farm Road	x		07/29/03	Romig Engineers, Inc.	Geotechnical Investigation, Stanton Residence Improvements
			10/04/04	Romig Engineers, Inc.	Responses to Town's Review Comments
			08/15/05	Source 1	Well Permit and Well Log
			04/27/06	Romig Engineers, Inc.	Geotechnical Plan Review Letter, Water Tank and Vault
310 Family Farm Road			02/03/77	Berloger Long & Associates	Geologic Faulty Investigation
320 Family Farm Road	x		07/06/95	Nielsen Geotechnical Incorporated	Foundation Recommendations, Remodel and Second Story Addition

			07/18/95	Nielsen Geotechnical Incorporated	Supplemental Foundation Information, Remodel and Second Story Addition
			07/16/01	Associated Terra Consultants, Inc.	Soils and Foundation Investigation, Retaining Walls
			08/06/02	Associated Terra Consultants, Inc.	Addendum to Soils and Foundation Investigation for Retaining Walls
			08/29/03	Associated Terra Consultants, Inc.	Plan Review of Front and Rear Retaining Walls and Small Landscaping Wall Designs
			09/18/03	Associated Terra Consultants, Inc.	Project Geotechnical Soils Investigation
			10/09/03	Cotton, Shires & Associates	Geotechnical Engineering Review, Corrigan Residence
			10/28/03	Associated Terra Consultants, Inc.	Responses to Commnets from Town's Geotechnical Consultant
350 Family Farm Road	x		08/24/89	J. V. Lowney & Associates	Geotechnical Investigation, Huggins Residence Addition
				William Cotton and Associates	Geotechnical Review Sheet
			08/09/89	Rinne & Peterson	Structural Calculations
			09/12/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Huggins, Residentil Addition PA #7470
370 Family Farm Road	x		06/06/02	GeoForensics, Inc.	Geotechnical Consultation, Proposed Garage
			07/03/04	Town	Engineering Geology and Plan Review
			08/02/04	GeoForensics, Inc.	Review of Plans
			08/08/04	Town	Permit Approval
			12/17/04	GeoForensics, Inc.	Construction Observations (#2)
			06/06/05	GeoForensics, Inc.	Geotechnical Evaluation, Proposed Kitchen Expansions
381 Family Farm Road	x		03/29/79	Geoconsultants, Inc.	Fault Location Investigation, McKean Property
			04/10/79	Howard Donely Associates, Inc.	Fault Location Investigation, McKean Property
			05/18/79	William Cotton and Associates	Review
			07/10/79	Howard Donely Associates, Inc.	Geologic and Fault Location Investigation, McKean Property
			08/04/79	William Cotton and Associates	Review
			08/21/79	Howard Donely Associates, Inc.	Fault Setback Locations, McKean Property
			12/28/79	William Cotton and Associates	Review
420 Family Farm Road	x		10/09/01	Kern Consulting, Inc.	Geologic and Geotechnical Evaluation, Sandhe/Henry Residence
			10/17/04	Geomatrix Consultants	Geotechnical Review
			10/19/04	Town	Plan Review
			10/30/04	Town	Plan Review
425 Family Farm Road	x		07/22/05	PGSoils, Inc.	Geotechnical Conditions, Proposed Residential Remodeling

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204230

Record Title & Contents

**GEOTECHNICAL REPORT FOR
FARM HILL ROAD - FOX HOLLOW ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
FARM HILL ROAD					
6	Barkley Park/Fields	x	?		Report to Planning Commission - Peninsula Christian Center
			05/18/79	Harding-Lawson Associates	Soil and Geological Investigation, Proposed Peninsula Christian Center
			08/30/79	Donald A. Woolfe and Associates	Dreft Environmental Impact Report, Peninsula Christian Center
			11/07/79	William Cotton and Associates	Geotechnical Review Sheet
			11/20/79	Harding-Lawson Associates	Consultation Regarding Soils and Geology, Peninsula Christian Center
			08/25/80	Harding-Lawson Associates	Retaining Wall Design
			11/13/79	William Cotton and Associates	Review of Environmental Impact Report
			0/0/80	Oleg V. Miram, Structural Engineer	Retaining Wall Design
			02/09/81	William Cotton and Associates	Review of Soils and Geological Investigation, Proposed Peninsula Christian Center
			03/05/81	Harding-Lawson Associates	Additional Consultation, Retaining Wall Design
			04/07/81	William Cotton and Associates	Review of 3/5/81 HLA letter
FARM ROAD					
6	110 Farm Road	x	09/17/75	Rhoades and Associates	Soil and Geologic Investigation, Earl Residence
			10/20/75	Town of Woodside	Review of 9/17/75 Rhoades and Associates Soil and Geologic Investigation, Earl Residence
			10/20/75	Purcell Rhoades & Associates	Addendum to Soil and geologic Report of September 17, 1975
			10/20/75	Purcell Rhoades & Associates	Determination of Drain Field for Lot 5, Hidden Valley Farms
			10/21/75	Purcell Rhoades & Associates	Utility Fault Crossing Recommendations
			11/13/75	Town of Woodside	Legal Notice
			01/07/76	Purcell Rhoades & Associates	Soil and Geologic Investigation, Lot 5 Hidden Valley Farms
			05/26/76	Purcell Rhoades & Associates	Inspection of Foundation Pier Drilling, Wayne Earl Property
			07/31/85	Leonard E. Lincoln, Architect	Site Plan, with annotations
			08/08/85	Purcell Rhoades & Associates	Soil Report Update, Additions to Existing Foundations
			08/15/85	Town of Woodside	Geotechnical Review Sheet
			08/20/85	William Cotton and Associates	Preliminry Geologic/Geotechnical Review, Earl Residential Addition
			11/01/85	William Cotton and Associates	Geologic Review Billing Breakdown, Earl Residential Addition
			01/29/86	Wayne L. Earl	Small Claims Court Claim and Summons
	115 Farm Road (113 Farm Road)	x	09/17/86	Perry R. Wood	Fault Exploration Trench, Parcel 076-294-01

			03/16/87	Stoecker and Northway Architects Incorporated	Request for Variance Plans
	(113 Farm Road)		06/22/87	Perry R. Wood	Fault Exploration Trench, Near Stables
			11/10/87	Dunham & Associates	Foundation Recommendations, Proposed House Addition
			11/16/09	Dunham & Associates	Plan Review, Proposed Addition
				William Cotton and Associates	Geotechnical Review Sheet
			12/28/87	William Cotton and Associates	Geologic and Geotechnical Review, Jacobson Residential Addition, PA #4425
			04/28/97	Steven F. Connelly, C.E.G.	Fault Investigation, Jacobson Property
			07/31/97	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Dwelling Unit
	120 Farm Road	x	08/07/06	Earth Investigations Consultants	Geotechnical Investigations, Proposed Residential Remodel
	135 Farm Road	x	09/17/86	Perry R. Wood	"Fault Investigation"
	140 Farm Road		01/31/16	Earth Investigations Consultants	Geotechnical Investigation, Proposed Barn Remodel
	165 Farm Road	x	05/22/02	GeoForensics Inc.	Geotechnical Investigation, Proposed New Deck Supports, Gifford Property
			04/16/03	GeoForensics Inc.	Geotechnical Investigation, Evaluation of New Basement and Retaining Walls
			01/29/04	GeoForensics Inc.	Geotechnical Investigation, Evaluation of the New Accessory Structure, Basement, and Retaining Walls (revised)
			08/18/08	GeoForensics Inc.	Geotechnical Investigation, Proposed Barn, Gifford Property
	170 Farm Road	x	11/04/74	Berlogar, Long & Associates	Fault Investigation, Lot No. 15, Gerstley Property
			05/15/95	Clearly Consultants, Inc.	Preliminary Geological Investigation, Lot 15, APN 076-029-040
			06/14/96	Lowney Associates	Geotechnical and Geologic Investigation, Volckmann Residence
			03/27/97	Lowney Associates	Supplemental Geotechnical Recommendations
			09/29/97	Lowney Associates	Proposed Swimming Pool
	180 Farm Road		06/17/13	Romig Engineers, Inc.	Geologic and Geotechnical Investigation, Brett Residence and Site Improvements
	185 Farm Road	x	04/30/81		Structural Calculations for Loustaunou Guest House
				William Cotton and Associates	Geotechnical Review Sheet
			09/03/81	Terratech	Foundation Inspection, Loustaunou Property
			11/05/08	Murray Engineers, Inc.	Geotechnical Services, Harvey Barn & Caretaker Residence
	195 Farm Road	x	09/20/96	Clearly Consultants, Inc.	Geotechnical Investigation, Caretakers Cottage
FERNside STREET					
6	1700 Fernside Street	x	10/09/01	Harlan Tait Associates	Geotechnical Investigation, Lovazzano Residence Addition
			06/05/03	Charles H. Hartsog	Soils/Geotechnical Report

			07/14/04	Charles H. Hartsog	Final Delineated Geotechnical Conditions, Proposed Pool, Response to Comments
			07/14/04	Charles H. Hartsog	Final Delineated Geotechnical Conditions, Proposed Pool, Plan Review
	1730 Fernside Street	x	05/20/94	Upp Geotechnology, Inc.	Limited Soils Investigation, Additions to Allen Residence and New Pool Cabana
FOX HOLLOW ROAD					
6	105 Fox Hollow Road	x	11/09/96	Nielsen Geotechnical Incorporated	Soil Report
			02/28/00	Nielsen Geotechnical Incorporated	Soil Report
			11/05/01	Nielsen Geotechnical Incorporated	Construction Report
	120 Fox Hollow Road	x	01/28/07	Earth Investigations Consultants	Geotechnical Investigation Update, Proposed Residential Development
			04/04/07	Earth Investigations Consultants	Supplemental Geotechnical Parameters, Basement, Proposed Residential Development
			06/08/09	Earth Investigations Consultants	Geotechnical Investigation Update, Proposed Residential Development
	121 Fox Hollow Road	x	02/05/09	Romig Engineers, Inc.	Geotechnical Investigation, Caldwell Swimming Pool
			01/14/11	Romig Engineers, Inc.	Geotechnical Investigation, Caldwell Residence Addition
	125 Fox Hollow Road	x	09/26/07	Murray Engineers, Inc.	Geotechnical Investigation, Creek Bank Stabilization
			08/13/08	Murray Engineers, Inc.	Supplemental Geotechnical Evaluation, Creek Bank Stabilization, Sterling Property
			10/08/08	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Creek Bank Stabilization, Sterling Property
	130 Fox Hollow Road	x	10/28/04	Murray Engineers Inc.	Limited Geotechnical Study, Pool House Improvements
	131 Fox Hollow Road	x	04/20/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed New House
			10/16/95	Earth Investigations Consultants	Geotechnical Investigation, Proposed Creek Repair
			11/27/96	Earth Investigations Consultants	Geotechnical Services, Proposed Creek Repair
			07/25/01	Earth Investigations Consultants	Geotechnical Investigation
			03/28/02	Earth Investigations Consultants	Engineering Geologic Review
	180 Fox Hollow Road	x	11/19/68	Crosby and Associates	Preliminary Geologic & Soil Investigation, Play Pen Subdivision
			06/26/95	Jo Crosby & Associates	Addendum to the Geotechnical Investigation for the Planned Guest Cottage
			02/27/06	Michelucci & Associates, Inc.	Geotechnical Consultation
	190 Fox Hollow Road	x	11/05/90	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed One-Story Guest House, Existing Herzig/Wohlers Residence
			03/16/93	Carl W. Garbe, P.E.	Soils and Foundation Report, Proposed Outbuilding

			05/23/06	Murray Engineers, Inc.	Geotechnical Investigation, Wohlers/Herzig Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204231					
Record Title & Contents					
GEOTECHNICAL REPORT FOR FRIARS LANE - GODETIA DRIVE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
FRIARS LANE					
6A	2, 4, 6, 8 Friars Lane	x	6/0/75	Paul E. Nowack	Preliminary Map, Lands of Tsugawa
			04/19/76	Dunham & Associates	Soil and Geologic Investigation, Proposed 4-Lot Subdivision, Lands of Tsukagawa, La Honda Road
			05/12/76	Town of Woodside	Review of Soil and Geologic Investigation Report
			05/27/76	Town of Woodside	Review of Preliminary Map of Proposed Curtain Drains as Mitigation Measure to Control Potential Slope Instability in Leach Field areas
			06/14/76	Town of Woodside	Review of Modified Preliminary Map
			06/16/76	Town of Woodside	Summary of Review and Recommendations Concerning Tsukagawa
			06/22/76	Town of Woodside	Planning Commission Minutes
			07/20/76	Dunham & Associates	Addendum, Proposed 4-Lot Subdivision, Lands of Tsukagawa, La Honda Road
			08/09/76	Town of Woodside	Review of Supplemental Geologic Report
			08/19/76	F. A. Stejer	Supplementary Geologic Report No. 2 - Proposed 4-Lot Subdivision, Lands of Tsukagawa
			08/25/76	Town of Woodside	Review of Supplemental Geologic Report No. 2
			01/23/77	Allan E. Newlands	Letter to Town Council
			?	?	Site Plan, Plate 1
			?	?	Cross Section A-A', Plate 2
			02/08/77	Town of Woodside	Review of Revised Preliminary Map dated 2/4/77
	2 Friars Lane		07/04/77	?	Site Plan, with annotations
			07/13/77	Town of Woodside	Review of Revised Building Site on Plot Plan dated 7/4/77
			07/20/77	Town of Woodside	Discussion of Cut Slopes, Land Division No. 224, Tsukagawa (Cooper-Hamilton)
	2 Friars Lane		03/23/78	Walter Boike	Letter to Woodside Planning Commission
	2 Friars Lane		03/23/78	Fred Banning	Letter to Woodside Planning Commission
	2 Friars Lane		03/28/78	Town of Woodside	Report to the Planning Commission
	4 Friars Lane		06/24/15	Romig Engineers, Inc.	Geotechnical Investigation, Detached Garage and Site Improvements

	8 Friars Lane	x	05/01/97	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, proposed Tennis Court, Shaw Property
GLENCRAG WAY					
6A	626 Glencrag Way	x	03/13/78	Howard Donley Associates	Geotechnical and Drainfield Investigation, Proposed Single Family Residence, Lots 11-15, Block 204, APN 68-142-190, Nance
			03/12/78	Howard Donley Associates	Summary Slope Stability
			04/18/78	Leighton and Associates	call to applicant re: consultant charges
			04/24/78	County of San Mateo	Proposed Variance #229 (Nance)
			06/14/78	Leighton and Associates	Review of 3/13/78 Report
			11/15/78	Howard Donley Associates	Response to 10/30/78 Memorandum from Town Geologist
			1/0/78	Fred Blomquist & Associates	Site Plan & Topographic Map
	650 Glencrag Way	x	07/16/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition and Detached Studio
			07/05/17	Earth Investigations Consultants	Limited Geotechnical Investigation, Proposed Solar Panel Foundation Support
	655 Glencrag Way	x	03/25/85	J. V. Lowney & Associates	Geotechnical Investigation, Harrington Residence
	700 Glencrag Way	x	12/05/08	Murray Engineers, Inc.	Limited Geotechnical Investigation, Carport/Deck Reconstruction, Krensky
			09/29/09	Murray Engineers, Inc.	Supplemental, Limited Geotechnical Investigation, Retaining Wall Reconstruction, Krensky Property
	799 Glencrag Way	x	07/07/78	Dunham & Associates	Soil Investigation, Proposed Land Division, Lots 14-23, Block 200 - Cowan
			08/25/78	Edward A. Danehy	Engineering Geologic Investigation of Septic Drain-Field Sites, Proposed Resubdivision of Lots 14-23, Block 200, Emerald Lake Estates, SD2
			9/0/78	Redmond Walsh	Proposed Lot Line Adjustment, Lots 14-23, Block 200, Emerald Lake Estates, Subdivision 2, one with annotations
			12/12/78	William Cotton and Associates	Summary of Field Review of Casey Land Division 255 and Soil and Geologic Report
			05/18/79	William Cotton and Associates	Review of above
			01/18/82	Dunham & Associates	Soil Investigation, Proposed Home, Parcel "B", Block 200, Estates of Emerald Lake No. 2 (APN 068-292-180)
			10/16/07	Carl W. Garbe	Soil Conditions, Landscaped Area (below and adjacent to house)
			03/07/08	Carl W. Garbe	Landscaping
			05/20/08	Carl W. Garbe	Proposed Landscaping
			11/18/13	Romig Engineers, Inc.	Construction Observation Landscape Improvements and Driveway Deck Repair
	810 Glencrag Way		09/24/12	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence Remodel
	841 Glencrag Way	x	07/16/97	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Foundation Improvements

GLENWOOD AVENUE					
6A	104 Glenwood Avenue	x	11/10/92	JCP Geologists - Engineers	Soil and Foundation Service, Proposed Additions to Home
	128 Glenwood Avenue		11/21/11	Earth Systems Pacific	Soild Engineering Study, Proposed Residence
	139 Glenwood Avenue		10/10/89	GeoForensics, Inc.	Geotechnical Review, Pardini Foundation Reconstruction
	140 Glenwood Avenue	x	05/31/96	Upp Geotechnology, Inc.	Geotechnical Investigation, Proposed Residence, Pinkerton Property
			07/06/04	Upp Geotechnology, Inc.	Geotechnical Update, Proposed New Garage, Pinkerton Property
	207 Glenwood Avenue	x	4/0/88	Applied Earth Sciences Consultants	Soil and Geologic Investigation
				William Cotton and Associates	Geotechnical Review Sheet
			09/14/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Chivington Addition, VAR-438
			02/22/08	Applied Earth Sciences Consultants	Geotechnical Investigation, Driveway Improvements, Chivington Residence
			undated	various	Package Containing Various Documents Pertaining to Driveway Remediation Plan
			08/14/09	Milstone Geotechnical	Geotechnical Design Memorandum - Retaining Wall Design Parameters
			02/22/08	Applied Earth Sciences Consultants	Cross Section A-A' Showing Existing and Original Ground Surfaces
	232 Glenwood Avenue	x	08/13/09	GeoForensics, Inc.	Geoyechnical Investigation, New Residence and Relocated Detached Garage
	235 Glenwood Avenue	x	07/09/93	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Foundation Modifications
	240 Glenwood Avenue	x	10/10/05	Romig Engineers, Inc.	Foundation Recommendations, Proposed Bath Room
	243 Glenwood Avenue	x	04/20/89	Richard Hanson, Civil Engineer	Structural Calculations
			04/25/89	Upp Geotechnology, Inc.	Geotechnical Investigation
			06/09/89	Upp Geotechnology, Inc.	Review of Foundation Plans, Russo Residence
				William Cotton and Associates	Geotechnical Review Sheet
	255 Glenwood Avenue		01/27/05	Michelucci & Associates, Inc.	Geotechnical Consultation, Proposed Foundation Partial Releveling
			03/14/05	Michelucci & Associates, Inc.	Review of Foundation Underpinning Plans
			05/09/05	Michelucci & Associates, Inc.	Engineering Observation of Hand Dug Pier Excavations
			02/23/05	Harlan Tait Associates	Geotechnical Review, Planned Foundation Mitigation for Existing House
			10/14/16	McEvoy Engineering	Structural Calculations for BLDG2016-0475
			02/22/17	McEvoy Engineering	Structural Calculations for REV2017-0024

	271 Glenwood Avenue	x	09/30/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel and Second-Story Addition
			10/02/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Detached Deck, Burson Residence
	303 Glenwood Avenue	x	11/19/02	J. Yang and Associates	Geotechnical Site Inspection, Proposed Remodel of House
			02/05/03	J. Yang and Associates	Review Comments
			02/10/03	J. Yang and Associates	Geologic Cross Section
	304 Glenwood Avenue		03/01/12	Lee Engineers, Inc.	Soil Investigation Report, Single Family Residence Reconstruction
	308 Glenwood Avenue	x	12/29/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Additions
			01/06/04	Earth Investigations Consultants	Supplemental Foundation Recommendations
	421 Glenwood Avenue	x	05/23/94	Michelucci & Associates, Inc.	Geotechnical Investigation, Gerhardt Residence
			01/26/05	Romig Engineers, Inc.	Geotechnical Update, Gerhardt Residence Addition
	475 Glenwood Avenue	x	09/19/79	PSC Associates, Inc.	Soil and Geologic Investigation, Proposed Residence on Parcels 073-063-190 and 073-063-200
			08/22/80	William Cotton, Town Geologist	Geotechnical Review, Ratcliff
			10/06/80	PSC Associates, Inc.	Additional Work, Soil and Geologic Investigation, Proposed Residence on Parcels 073-063-190 and 073-063-200
GODETIA DRIVE					
6A	988 Godetia Drive	x	12/20/00	Upp Geotechnology, Inc.	Geotechnical Feasibility Investigation, Three-Parcel Subdivision, Lands of Alexanyan
			06/19/02	Upp Geotechnology, Inc.	Limited Soils and Foundation Investigation, Proposed Addition to Residence, Alexanyan Property
			05/02/03	Upp Geotechnology, Inc.	Supplemental Limited Soil and Foundation Investigation, Alexanyan Property
	999 Godetia Drive	x	05/22/09	JF Consulting, Inc.	Geotechnical Investigation, New Residence
			11/23/09	JF Consulting, Inc.	Revision of Seismic Parameters, Basement Retaining Walls, New Residence
	1000 Godetia Drive	x	09/10/03	Carl W. Garbe, P.E.	Soil/Foundation Report, Proposed Retaining Wall
			09/11/07	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Improvements
	1001 Godetia Drive		04/04/13	Foundation Engineering Consultants, Inc.	Geotechnical Engineering Report, Room addition and Landscape Walls
			08/06/14	GeoForensics, Inc.	Geotechnical Investigation, New Spa
			04/01/16	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Remodel
	1104 Godetia Drive	x	04/02/79	William Cotton and Associates	Review Comments - Lot Line Adjustment
			04/11/79	J. R. Mackay	Site Plan
			04/30/79	William Cotton and Associates	Geotechnical Review Sheet
	1011 Godetia Drive	x	10/11/78	Dunham & Associates	Soil Investigation, Proposed Home

	1020 Godetia Drive	x	12/29/06	Earth Investigations Consultants	Geotechnical Investigations
	1075 Godetia Drive	x	06/25/78	Purcell, Rhodes & Associates	Soil Investigation, Proposed Swimming Pool
			11/19/02	Earth Investigations Consultants	Soil and Foundation Investigation
			07/06/16	CalGeotech Engineering Consultants, Inc.	Final Geotechnical Engineering Investigation Report, New Improvements
	Godetia Road/Summerset Place	x	09/09/81	Cleary Consultants, Inc.	Preliminary Geotechnical Investigation, 6.9 Acre Parcel at Canada Road and Godetia Road
	Subdivision		09/28/10	William Cotton and Associates	Godetia School Site/Redwood City School District Property
	1225 Godetia Road	x	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision
				William Cotton and Associates	Geotechnical Review Sheet
			05/26/89	Kwan & Associates	Structural Calculations
			09/15/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Bianchini, PA #7382
			09/25/89	Cleary Consultants, Inc.	Review of Grading and Foundation Plans, Lot 2
			09/26/89	Cleary Consultants, Inc.	Review of Landscape Plans, Lot 1
			09/27/89	Cleary Consultants, Inc.	Supplemental Geotechnical Review, Bianchini, PA #7382
			07/07/89	The Russell Group, Architects	Sire Plan, with geologic annotations
	1250 Godetia Drive	x	04/25/05	Romig Engineers, Inc.	Geotechnical Investigation, Gregory Pool House
			02/13/09	Romig Engineers, Inc.	Supplemental Recommendations, New Deck
			10/12/09	Romig Engineers, Inc.	Supplemental Recommendations, New Retaining Wall and Patio
	1270 Godetia Drive	x	03/01/76	Geo-Ekta Laboratories / Gross & Associates, Inc.	Foundation Soils Investigation and Geologic Investigation, Lot 1 and Lot 5
			02/23/94	J. Yang and Associates	Geotechnical Site Investigation - draft
			05/09/94	Darwin Meyers Associates	Geologic Hazards Reconnaissance
			06/02/94	J. Yang and Associates	Geotechnical Site Investigation
			06/24/04	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
			08/13/04	Steven F. Connelly, C.E.G.	Feasibility Investigation, Proposed Subdivision

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204232

Record Title & Contents

**GEOTECHNICAL REPORT FOR
GRANDVIEW DRIVE - 291 GREER ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
GRANDVIEW DRIVE					

7	125 Grandview Drive	x	05/05/92	JCP Geologists - Engineers	Geotechnical Services for Distressed Home
			04/10/96	Hoexter Consulting, Inc. / Romig Consulting Engineers	Engineering Geologic Reconnaissance and Feasibility Evaluation, Proposed Renovation and Additions
	136 and 166 Grandview Drive	x	03/11/74	Geolabs - Northern California, Inc.	Foundation Engineering and Engineering Geology Investigation, 4.65-Acre Parcel
			03/16/74	William Cotton	Review of GNC 3/11/74 Foundation Engineering and Engineering Geology Investigation, 4.65-Acre Parcel Report
			01/20/77	Leighton and Associates	Review of GNC 3/11/74 Foundation Engineering and Engineering Geology Investigation, 4.65-Acre Parcel Report
			01/27/77	Gordon Dowsett, Architect	Proposed Residence
			02/09/77	Purcell, Rhodes & Associates	Geologic Review and Reconnaissance, 4.65-Acre Parcel 1
			02/18/77	Leighton and Associates	Review of 2/9/77 PRA Geologic Review and Reconnaissance, 4.65-Acre Parcel 1
			04/04/77	Purcell, Rhodes & Associates	Foundation Plan Review
			08/01/77	Watry Engineering, Inc.	Structural Calculations
			08/18/77	Leighton and Associates	Review of PRA 8/4/77 Foundation Plan Review
	277 Grandview Drive	x	04/05/02	Upp Geotechnology, Inc.	Reconnaissance Geologic Investigation, Lands of Denko/Hudson APN 75-220-240
			05/22/03	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Denko/Hudson
	280 Grandview Drive	x	02/20/90	Earth Systems Consultants	Soil Report, Davison Residence Addition
			02/09/05	Earth Systems Consultants	Update Soil Engineering Study, Davison Residence Addition (Proposed)
			06/03/05	Earth Systems Consultants	update Soil Engineering Study Supplement, Proposed Davison Residence Additions
	300 Grandview Drive	x	10/14/97	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residential Addition
			07/27/07	Murray Engineers, Inc.	Geotechnical Investigation, Retaining Wall Improvements
			07/29/10	Romig Engineers, Inc.	Geotechnical Status Report, Retaining Wall Improvements
	303 Grandview Drive	x	08/15/85	Tim J. Manzagol	Letter and Deposit requesting Town Geologist Field Inspection of LD Boring in Landslide
			8/16, 19/85	William Cotton and Associates	Internal Memo on Field Inspection Request
			08/20/85	William Cotton and Associates	Phone Notes on call with Tim Manzagol
GREENWAYS DRIVE					
7	2132 Greenways Drive	x	07/19/04	Romig Engineers, Inc.	Geotechnical Investigation, Foundation Improvements
			06/04/08	Romig Engineers, Inc.	Supplemental Geotechnical Investigation, Nieva Dteached Garage and Swimming Pool
			09/22/08	Romig Engineers, Inc.	Geotechnical Investigation, Nieva Residence, Garage, and Pool
	2185 Greenways Drive	x	04/03/08	Michelucci & Associates, Inc.	Preliminary Geotechnical Investigation, Existing Single-Family Residence

	2195 Greenways Drive		05/19/14	Earth Investigations Consultants	Geotechnical Investigation, Proposed Lap Swimming Pool and Patio
GREER ROAD					
7	151 Greer Road	x	08/12/08	Milstone Geotechnical	Geotechnical Investigation, Proposed Kitchen Addition, Barry Residence
	161 Greer Road	x	09/02/93	Dunham & Associates	Geotechnical Engineering Evaluation, Proposed Addition and Carport
	190 Greer Road	x	11/09/00	Earth Investigations Consultants	Engineering Geologic Evaluation, Active Faulting Across Property
			03/14/02	Romig Engineers, Inc.	Geotechnical Investigation, Barger Residence
	195 Greer Road		05/26/83	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Guest House
			05/03/12	Murray Engineers, Inc.	Geotechnical Plan Review, Feirman Residence Improvements
	220 Greer Road	x	12/15/72	Jo Crosby & Associates	Geologic Investigation. Parcel B, Land Division Map No. 111
			12/06/73	Jo Crosby & Associates	Geologic Exploration, Auchincloss Property
			12/04/98	Nordmo Associates	Geotechnical Report, Proposed Studio and Conservatory
			12/08/98	Hydro-Geo Consultants, Inc.	Preliminary Geologic Conditions, proposed Conservatory and Studio
			01/13/99	Hydro-Geo Consultants, Inc.	Addendum to 12/8/98 Geologic Report, Modified Plot Plan
			06/07/99	Nordmo Associates	Geotechnical Plan Review, proposed New Studio Building
			01/31/00	Upp Geotechnology, Inc.	Engineering Geologic Investigation, Kepecs Property
			02/28/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Information, Kepecs Property
			03/17/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Information (Number 2), Kepecs Property
			04/17/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Information, Kepecs Property
			05/18/00	Nordmo Associates	3rd Geotechnical Plan Review, Proposed New Studio Building
			11/19/01	Romig Engineers, Inc.	Geotechnical Investigation, New pool and Tea House
	223 Greer Road	x	05/20/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property
			05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Proposed Walker Homesite
			05/24/74	Applied Soil Mechanics	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
			11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Walker Residence (APN 072-051-140)
			08/30/89	Lea Engineering	Structural Calculations
			09/07/89	Lea Engineering	Cantilever Retaining Wall Program
			11/16/89	Roger Kelley Kohler Architect	Site Plan with annotation
				William Cotton and Associates	Geotechnical Review Sheet
			02/21/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Coe Additions, PA #7624
			04/04/90	Applied Soil Mechanics	Update Geologic Evaluation, Proposed Addition to Existing Mitchell-Coe Residence

			04/25/90	Applied Soil Mechanics	Foundation Plan Review, Proposed Addition to Existing Mitchell -Coe Residence
			04/27/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Coe Additions, PA #7624
			05/15/00	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Garage and Addition
239 Greer Road	x		05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
			11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Residence (APN 072-051-140)
250 Greer Road	x		12/21/71	Jo Crosby & Associates	Geologic and Feasibility Investigation, Proposed Greer Highlands
			01/19/72	Jon C. Cummings, Town of Woodside	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
			08/13/98	Michelucci & Associates, Inc.	Geotechnical Consultation, Creek Bank Collapse
			06/09/09	Murray Engineers, Inc.	Fault Exploration Trenching, McCown Property
			06/11/09	Murray Engineers, Inc.	Fault Evaluation Investigation
			02/25/13	GeoForensics, Inc.	Geotechnical Investigation for Proposed Basement Replacement at Sallin Residence
265 Greer Road	x		05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
			11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Residence (APN 072-051-140)
	x		12/21/71	Jo Crosby & Associates	Geologic and Geasibility Investigation, Proposed Greer Highlands
280 Greer Road also known as/includes 300, 331A, and 381			01/19/72	Jon C. Cummings	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
			12/26/78	Cooper-Clark & Associates	Geologic Hazards Evaluation, Phase 1, Residential Subdivision
			01/27/81	William Cotton, Town of Woodside	Geologic Review of above
			06/05/81	Cooper-Clark & Associates	Geotechnical Investigation, Proposed 23-Acre Subdivision
			11/11/88	Upp Geotechnology, Inc.	Reconnaissance Investigation, Proposed Road Alignment, Lands of Pearson, 23 acre Parcel
			12/16/88	Upp Geotechnology, Inc.	Reconnaissance Geotechnical Investigation, Proposed Building Site, Lands of Pearson, 23 acre Parcel
			01/10/89	Upp Geotechnology, Inc.	Reconnaissance Investigation, Proposed Road Alignment, Lands of Pearson, 23 acre Parcel
			01/15/89	Churchill & Associates	Site Development Application
			09/30/91	Applied Earth Sciences Consultants	Summary of Water Well Drilling and Testing near West Union Creek, Lands of Pearson
			11/26/91	Upp Geotechnology, Inc.	Geotechnical Reconnaissance, Proposed Bridge for Creek Crossing, Lands of Pearson

			02/10/95	Upp Geotechnology, Inc.	Geotechnical Update Letter, Proposed Bridge for Creek Crossing, Lands of Pearson
			05/30/95	Upp Geotechnology, Inc.	Geotechnical Update Letter, Proposed Bridge for Creek Crossing, Lands of Pearson
			09/06/95	Upp Geotechnology, Inc.	Update Reconnaissance Investigation, Proposed Access Way, Lands of Pearson
	291 Greer Road	x	05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
			11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Residence (APN 072-051-140)
			05/01/95	Nielsen Geotechnical Incorporated	Geotechnical Report
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204233					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 300 GREER ROAD - HARDWICK ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
GREER ROAD					
7A	300 Greer Road	x	0/0/04	Various	File with Drawings, Photographs, and Repair Scheme for Landslide Repair
	331 Greer Rd		12/17/18	Murray Engineers Inc	Fault Investigation, 331B Greer Caretaker's Residence
	381 Greer Road	x	12/21/71	Jo Crosby & Associates	Geologic and Feasibility Investigation, Proposed Greer Highlands
			01/19/72	Jon C. Cummings	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
HACIENDAS DRIVE					
7A	38 Haciendas Drive	x	01/10/75	Berloger, Long & Associates	Soil Engineering and Engineering Geologic Investigation, Lots 19, 20, and 21, Las Haciendas Tract
			04/28/77		Plot Plan with annotations
			08/15/78	William Cotton and Associates (?)	Results of Review
			08/28/78	william Cotton and Associates	Geotechnical Review
			03/13/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Swimming Pool
HARCROSS DRIVE					
7A	165 Harcross Road	x	02/17/98	Romig Consulting Engineers	Geotechnical Study, Residence Addition
			08/20/01	Romig Consulting Engineers	Geotechnical Investigation, Retaining Walls

	185 Harcross Road	x	12/19/89	Hallenbeck & Associates	Preliminary Geotechnical Engineering Inspection
			03/31/90	JR Engineering & Structures	Foundation Plan & Details, Proposed Reveleving of First Floor Level
				William Cotton and Associates	Geotechnical Review Sheet
			04/03/90	JR Engineering & Structures	Floor Re-Leveling Operation, Skarston Residence
	320 / 450/ 460 Harcross Road	x	12/29/77	Joe Crosby & Associates	Geologic and Soil Investigation, 48 Acres (Rancho De Las Pulgas)
			01/07/78	Perry R. Wood	Soil Percolation Tests, Lots 1-20, Parcel No. 2, Land Division Map No. 162
	320 Harcross Road	x	01/10/00	Ting & Associates, Inc.	Geotechnical Investigation, Proposed Pool House and Loggia
			03/04/00	Ting & Associates, Inc.	Foundation Plan Review and Supplemental Foundation Drain Recommendations, Proposed Pool House/Loggia
HARDWICK ROAD					
7A	110 Hardwick Road	x	01/30/02	Romig Engineers, Inc.	Geotechnical Study, Residence Addition
			08/20/08	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Additions
	150 Hardwick Road	x	11/22/94	Nielsen Geotechnical Incorporated	Soil Report
			09/29/03	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Addition and Pool House
			06/02/04	Nielsen Geotechnical Incorporated	Revised Geotechnical Recommendations, Addition and Pool House
			04/14/06	Murray Engineers, Inc.	Supplemental Recommendations, Kitchen-Dining Room Addition
			04/13/11	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Entry Trellis Improvements
	155 Hardwick Road	x	08/16/90	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Second-Story Addition
	160 Hardwick Road	x	02/11/05	Murray Engineers, Inc.	Geotechnical Investigation, Barhoum Residence Improvements
			05/17/05	Murray Engineers, Inc.	Supplemental Retainig Wall Recommendations & Geotechnical Plan Review, Residence Improvements
	187 Hardwick Road	x	07/11/02	Earth Systems Consultants, Northern California	Geologic Hazards Evaluation and Soil Engineering Study, Tesfaya Residence (Proposed Remodel and Additions)
			09/12/02	Cotton, Shires & Associates, Inc.	Geotechnical Engineering Review, Tesfaya Residence
			01/13/03	Earth Systems Consultants, Northern California	Additional Geotechnical Engineering Study fo Drainage Dissipater Trench, Tesfaya Residence
			01/13/03	Earth Systems Consultants, Northern California	Response to Geotechnical Engineering Comments
			10/01/07	ES Geotechnologies	Supplement to Soil Engineering Study, Proposed Spa, Tesfaya Residence
	197 Hardwick Road	x	05/05/06	J. Yang and Associates	Geotechnical Site Investigation, House Addition and Remodel House

			06/03/08	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Sullivan Property
			09/05/08	GeoForensics, Inc.	Geotechnical Slope Evaluation, Sullivan Property
			06/01/09	GeoForensics, Inc.	Geotechnical Slope Evaluation (#3), Sullivan Property
	199 Hardwick Road	x	07/28/04	GeoForensics, Inc.	Geotechnical Investigation, Proposed Swimming Pool, Kutay Property
	210 Hardwick Road		04/12/18	Romig Engineers, Inc.	Geotechnical Investigation, Fedorov-Wang Residence Addition
			03/01/19	Romig Engineers, Inc.	Slopes Steeper than 35%, Fedorov-Wang Septic Expansion
			03/06/20	Romig Engineers, Inc.	Geotechnical Investigation, He-Odegaard Residence Addition
	220 Hardwick Road	x	02/25/02	Nielsen Geotechnical, Inc.	Soil Report
			11/29/05	Murray Engineers, Inc.	New Engineer-of-Record & Supplemental Recommendations, Site Retaining Walls
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204234					
Record Title & Contents					
GEOTECHNICAL REPORT FOR HIDDEN VALLEY LANE - HIGHLAND TERRACE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
HIDDEN VALLEY LANE					
8	15 Hidden Valley Lane	x	07/12/67	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Proposed Homesite, Lot 12, Tract 104, Hidden Valley Farms Subdivision
			06/21/00	Romig Engineers, Inc.	Geotechnical Recommendations, Planned Tennis Court
			09/14/00	Romig Engineers, Inc.	Geotechnical Investigation, Davison Residence
			02/21/01	Romig Engineers, Inc.	Fault Trenching Investigation, New Residence
			03/07/01	Louis A. Richardson	Addendum to Fault Investigation
			03/14/01	Romig Engineers, Inc.	Supplemental Recommendations, New Residence
			09/26/11	Romig Engineers, Inc.	Geotechnical Study, Detached Garage
	25 Hidden Valley Lane	x	11/02/77	Berlogar, Long & Associates	Geotechnical Investigation, Proposed Residence
	45 Hidden Valley Lane	x	04/10/96	Nielsen Geotechnical Incorporated	Review of Existing Foundation, Conversion of Storage Room to Office Space
			11/07/07	Romig Engineers, Inc.	Geotechnical Investigation, Matsumoto Guest House
			03/12/08	Romig Engineers, Inc.	Liquefaction Analysis, Matsumoto Guest House
HIGH ROAD					
8	High Road @ Woodside Road	x	11/21/72	Geo-Ekta Laboratories	Preliminary Foundation Soils Investigation

			08/01/72	Edward W. Baca	Tentative Map, Lands of Cavaliere
880 High Road	x		07/16/01	Don Hillebrandt Associates	Geotechnical Investigation. Family/Breakfast Room Addition, Master Bathroom Extension and New Front Entry
			09/01/01	Don Hillebrandt Associates	Supplement to 07/16/01 DHA report
			06/13/05	Don Hillebrandt Associates	Geotechnical Investigation, Dining Room Addition & Kitchen Renovation
929 (?) High Road	x		03/01/77	Dunham and Associates	Site Evaluation, Proposed Land Division, Mowry
			03/31/77	Leighton and Associates	Review of above report
			04/25/77	Francis A. Stejer	Engineering Geologic Study, Parcel 4 (Vol. 5, LLS page 144), Mowry
			04/27/77	Leighton and Associates	Review of above report
			05/17/77	Francis A. Stejer	Response to Critique by Leighton and Associates re: Engineering Geologic Study, Parcel 4 (Vol. 5, LL page 144)
			05/27/77	Leighton and Associates	Review of above response
			07/26/77	Dunham and Associates	Soil Engineering Evaluation, Proposed Land Division (2 lots), Parcel 4 (Vol. 5, LLS page 144)
			08/16/77	Leighton and Associates	Review of above report
			08/29/77	Francis A. Stejer	Reply to Leighton and Associates Critique dated May 27, 1977
			10/06/77	Leighton and Associates	Review of above response
			10/19/77	San Mateo County	Proposed Land Division #235 (Mowry)
			11/30/77	Dunham and Associates	Proposed Land Division No. 235, High Road
			12/29/77	Dunham and Associates	Proposed Land Division No. 235, High Road
930 High Road	x		04/30/97	Earth Investigations Consultants	Geotechnical Services, Geotechnical Design Parameters, Proposed New Patio & Cottage Improvements
			05/26/05	Earth Investigations Consultants	Geotechnical Parameters, Proposed Swimming Pool
930 / 1040 High Road	x		08/14/90	Clearly Consultants, Inc.	Geotechnical Investigation, Proposed Property Division and Construction of Two New Residences
961 High Road	x		04/10/90	JCP Geologists - Engineers	Soil and Foundations Study, Proposed Residence, Swimming Pool, Cabana and Guest House
				William Cotton and Associates	Geotechnical Review Sheet
			06/13/90	Lea Engineering	Site Study Plan, with annotation
			06/14/90	Lea Engineering	Structural Calculations
			06/15/90	County of San Mateo, Department of Health Services	Review of Septic System, Sculley Parcel
			06/21/90	JCP Geologists - Engineers	Review of Septic Plans
			07/03/90	JCP Geologists - Engineers	Review of House Plans
			07/09/90	Lea Engineering	Comment of 37% slope.

			08/01/90	Town of Woodside	Staff Report for Planning Commission, 941 (961) High Road
			01/12/07	Romig Engineers, Inc.	Geotechnical Investigation, Basement Addition, Garage Wall Repair, and Swimming Pool
			04/12/07	Romig Engineers, Inc.	Underpinning of Dining Room, Maslak Residence
1031 High Road	x		04/20/01	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Garage, Foundation Retrofit
1040 High Road	x		08/14/90	Cleary Consultants, Inc.	Geotechnical Investigation, Two New Residences
				William Cotton and Associates, inc.	Geotechnical Review Sheet
			03/19/91	William Cotton and Associates, inc.	Supplemental Geotechnical Review, Browne Land Division 313
			04/27/05	Murray Engineers, Inc.	Geotechnical Investigation, Ellis Residence Improvements
1061 High Road	x		08/22/90	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Residence
			03/18/91	JCP Geologists - Engineers	Update Services, Proposed Residence
			07/26/93	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Pool House and Swimming Pool
1065 High Road	x		06/29/94	J. Yang and Associates	Soil and Foundation Study, Proposed Residence
			10/27/94	J. Yang and Associates	Soil and Foundation Study, Proposed Residence
HIGHLAND TERRACE					
8	115 Highland Terrace	x	12/20/07	PGSoils, Inc.	Geotechnical Investigation
	120 Highland Terrace	x	01/21/95	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Two-Story Addition and Garage
	127 Highland Terrace	x	03/30/05	Murray Engineers Inc.	Geotechnical Investigation, Residence Improvements
	150 Highland Terrace	x	02/01/05	Murray Engineers Inc.	Geotechnical Investigation, Residence Improvements
	215 Highland Terrace		02/23/17	PGSoils, Inc.	Geotechnical Investigation, Proposed House Additions
	251 Highland Terrace	x	03/14/97	Nielsen Geotechnical Incorporated	Soil Report
			01/15/03	Romig Engineers, Inc.	Geotechnical Investigation, Large Residence Addition
	255 Highland Terrace	x	01/18/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
			03/24/03	Earth Investigations Consultants	Supplemental Site Characterization & Preliminary Plan Review, Proposed Residential Development
	303 Highland Terrace	x	02/08/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Additions
	320 Highland Terrace	x	02/28/01	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
	325 Highland Terrace	x	05/17/96	PGSoils, Inc.	Subsurface Condition, Proposed Residence
	328 Highland Terrace	x	11/04/88	Michelucci & Associates, Inc.	Geotechnical Study, Proposed Additions to Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204236					

Record Title & Contents					
GEOTECHNICAL REPORT FOR HILLSIDE DRIVE - HOME ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
HILLSIDE DRIVE					
8A	127 Hillside Drive	x	04/29/94	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Proposed Addition/Modifications to Residence
	260 Hillside Drive	x	01/27/99	GeoForensics, Inc.	Keystone Retaining Wall Design, Wenrick Property
			08/10/01	GeoForensics, Inc.	Proposed Reatining Wall, Wenrick Property
	303 Hillside Drive	x	11/19/10	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Detached Garage and Evaluation of Replaced Rear House Foundation
			07/01/11	GeoForensics, Inc.	Review of Plans, Proposed Residential Remodel
	307 Hillside Drive	x	12/10/01	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Exterior Deck
			07/12/02	Michelucci & Associates, Inc.	Review of Plans, Proposed Attached Rear Yard Deck
			11/04/02	Michelucci & Associates, Inc.	Pier Excavation Observation, Attached Elevated Rear Yard Deck
	308 Hillside Drive	x	01/14/02	Nielsen Geotechnical, Inc.	Foundation Detail / Specifications, Taylor Garage
			06/10/02	Nielsen Geotechnical Incorporated	Plan Review, Replacement Garage
			11/05/02	Nielsen Geotechnical Incorporated	Final report, Replacement Garage
	309 Hillside Drive	x	09/08/05	Romig Engineers, Inc.	Geotechnical Investigation, Bouthillette Residence
			12/19/07	Romig Engineers, Inc.	Geotechnical Investigation, Residence Remodel
	320 Hillside Drive	x	05/23/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions and Remodel
	340 Hillside Drive	x	04/02/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Residence and Garage, Gabittas Property
	404 Hillside Drive	x	11/30/95	Fowler & Associates	Geotechnical Investigation, Peterson Residence
			06/04/02	Fowler & Associates	Geotechnical Consultation, Proposed Adition
	428 Hillside Drive	x	08/08/94	Nielsen Geotechnical Incorporated	Modified Soil Report
			04/27/98	Nielsen Geotechnical Incorporated	Plan Review and Supplemental Recommendations
			05/10/04	Nielsen Geotechnical Incorporated	Plan Review

			12/14/07	Murray Engineers, Inc.	Summary of Earthwork Observations, Smith/Leigh Residence & Property Improvements
	444 Hillside Drive	x	04/06/02	Dave Olnes P.E. Inc.	Geotechnical Reconnaissance
	515 Hillside Drive	x	11/16/05	Romig Engineers, Inc.	Geotechnical Investigation, Mainz Deck Replacement
HOBART HEIGHTS ROAD					
8A	155 Hobart Heights Road	x	08/13/96	United Soil Engineering, Inc.	Geotechnical Investigation, Proposed Residence Addition
			07/08/97	Jo Crosby & Associates	Geological Conditions, Proposed Addition
			08/31/06	Romig Engineers, Inc.	Geotechnical Investigation, Swimming Pool
	195 Hobart Heights Road		07/08/15	J. Yang and Engineers	Geotechnical Investigation, Building Addition and Remodel
HOME ROAD					
8A	1 Home Road	x	11/13/92	Applied Earth Sciences Consultants	Geologic Investigation, Site Developemnt Feasibility, 6.1-acre Parcel, Parcel B, Woodside Country Club Properties, Subdivision No.1
	27 Home Road	x	02/19/93	John Coyle & Associates, Inc.	Geologic Investigation, Proposed Addition, Thurlow Property
			05/17/93	Raleigh Engineering	Foundation Investigation, Proposed Single Family Residence Addition
	1439 Home Road	x	07/24/00	Nielsen Geotechnical, Inc.	Soil Report
			07/17/06	Romeig Engineers, Inc.	Geotechnical Investigation, Ross Leclerc Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204237					
Record Title & Contents					
GEOTECHNICAL REPORT FOR JANE DRIVE - JEFFERSON AVENUE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
JANE DRIVE					
9	112 Jane Drive	x	06/17/92	Michelucci & Associates, Inc.	Geotechnical Additions, Proposed Additions
			06/09/93	Haro, Kasunich and Associates, Inc.	Supplemental Geotechnical Investigation and Foundation Design Criteria, Underpinning Two-story Addition
	136 Jane Drive	x	01/09/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Slope Movement, Drainage and Structural Distress, Berghorn Residence
				William Cotton and Associates	Geotechnical Review Sheet
			07/11/87	Upp Geotechnology, Inc.	Review of Retaining Wall Foundation Plans, Finch Property
			04/28/88	Robelo / Kocjan Associates, Inc.	Structural Calculations
			06/13/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Finch Retaining Wall, PA #4666
			07/28/88	William Cotton and Associates	Supplemental Geotechnical Review, Finch Retaining Wall, PA #4666
			09/26/88	Upp Geotechnology, Inc.	Retaining Wall Backfill, Finch Property

	145 Jane Drive		01/21/13	Romig Engineers, Inc.	Geotechnical Investigation, Upson Residence
	148 Jane Drive	x	2/12/10	JF Consulting, Inc.	Geotechnical Investigation
	160 Jane Drive	x	04/28/99	Cleary Consultants, Inc.	Geotechnical Investigation, Planned Additions to Existing Residence
			02/23/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Improvements
			10/22/07	GeoForensics, Inc.	Limited Geotechnical Investigation, Proposed Williams Barn Extension
	165 Jane Drive	x	05/25/06	Romig Engineers, Inc.	Geotechnical Investigation, Upson Residence
	185 Jane Drive	x	05/16/05	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Barn
			10/10/06	GeoForensics, Inc.	Geotechnical Recommendations, Proposed New Pool
			02/11/16	Earth Investigations Consultants	Geotechnical Investigation, Residential Remodel
			10/13/17	Earth Investigations Consultants	Geotechnical Plan Review and 35% Slope Analysis, Residential Remodel and Addition
	190 Jane Drive	x	09/15/92	John P. Nielsen, Ph.D.	Limited Soil Report
			10/22/07	GeoForensics, Inc.	Limited Geotechnical Investigation, Proposed Barn Extension, Williams Property
	212 Jane Drive	x	11/08/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence. Navarro Property
	315 Jane Drive	x	07/11/86	Purcell, Rhodes & Associates	Soils and Foundation Study, Lot 2, Jane Drive, Meadow Vista Subdivision
	320 Jane Drive	x	04/15/74	Town of Woodside	Grading on Gilmore-McDowell Property Without Permits
			03/22/74	Berloger, Long & Associates	Proposed Residential Development, Lands of McDowell
			03/25/74	Town of Woodside	Review of Berloger's Report
			09/20/77	Berloger, Long & Associates	Geotechnical Investigation, Proposed Residential Development, Lands of Gilmoree McDowell
			10/07/85	Applied Earth Consultants, Inc.	Soils and Foundation Investigation, Schinaman Property
			10/15/85	Applied Earth Consultants, Inc.	Supplemental Foundation Recommendations, Proposed Wood-Frame Residential Structure, Schinamam Property
			01/07/86	Mr. Schinman	Letter to Town
			01/20/86	William Cotton and Associates	Geologic Review of Proposed Development
			03/06/86	William Cotton and Associates	Geotechnical Review Sheet
			03/12/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
			04/08/86	Applied Earth Consultants, Inc.	Adequacy of Previous Geologic Report, Schinmam Property
	330 Jane Drive	x	11/25/85	Applied Earth Consultants, Inc.	Soils and Foundation Investigation, Carey Property
			02/11/86	Edward Dominion	Structureal Calculations
			03/15/86	Ling Shen Chen	Site Plan
			04/26/86	Applied Earth Consultants, Inc.	Review of Foundation Plans, Proposed Wood-Frane Residential Structure

			06/10/86	Edward L. Pack Associates, Inc.	Exterior and Future Interior Noise Levels
			8/0/86	William Cotton and Associates	Geotechnical Review Sheet
			08/06/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review. Lands of Carey
			08/11/86	Applied Earth Consultants, Inc.	Addendum - Supplemental Foundation Recommendations, Carey Property
			08/25/86	William Cotton and Associates	Supplemental Review, Lands of Carey
			11/11/86	Applied Earth Consultants, Inc.	Inspection of Pier Drilling for Foundation
			07/26/88	William Cotton and Associates	Notes of Distress to Concrete Retaining Wall and Slabs
			07/29/88	William Cotton and Associates	Geotechnical Review of Distress, with photos
335 Jane Drive	x		08/06/03	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence Addition, Guest House, and Detached Garage
			06/05/05	GeoForensics, Inc.	Existing Approved Fills, Deheb Property
			06/27/05	GeoForensics, Inc.	Response to Review Comments, Proposed New Residence
			07/07/05	GeoForensics, Inc.	Response to Review Comments (#2), Proposed New Residence
340 Jane Drive	x		05/29/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Residence and Swimming Pool, Lot 5, Meadow Vista Subdivision
			05/29/86	Brian Kangas Foulk & Associates	Grading Plan, with annotations
			07/22/86	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Grading Plan, Proposed Residence, Lot 5, Meadow Vista Subdivision
			08/01/86	Vaughn Shahinian Associates	Structural Calculations and Details
			08/05/86	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence, Lot 5, Meadow Vista Subdivision
			08/26/86	William Cotton and Associates	Geotechnical Review Sheet
			08/29/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Juelsgaard, Meadow Vista Subdivision Lot #5
			09/16/86	JCP Geologists - Engineers	Addendum, Soil and Foundation Report, Proposed Residence and Swimming Pool, Lot 5, Meadow Vista Subdivision
			10/06/86	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Juelsgaard, Meadow Vista Subdivision Lot #5
			01/08/96	Terratech, Inc.	Updated Geotechnical Report
345 Jane Drive	x		09/16/87	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed Residence, Lot, Meadow Vista Subdivision
			01/06/88	Tejima and Associates, Inc.	Response to (12/22/87) Letter from Woodside Building Department, Proposed Residence, Lot 8, Meadow Vists Subdivision
				Arvind K. Gupta, P.E.	Structural Calculations
				William Cotton and Associates	Geotechnical Review Sheet
			01/27/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Frederick, Meadow Vista Lot 8, PA #4503

			02/10/88	Arvind K. Gupta, P.E.	Response to Comment of Adequacy of Reinforcement in Piers
			02/22/88	Tejima and Associates, Inc.	Response to (1/27/88) Letter from Town Geologist, Proposed Residence, Lot 8 Meadow Vista Subdivision
			03/17/88	William Cotton and Associates	Supplemental Geotechnical Review, Frederick, Meadow Vista Lot 8, PA #4503
			10/29/96	Jo Crosby & Associates	Geologic and Geotechnical Investigation, Residence
			12/07/00	Jo Crosby & Associates	Addendum to Report dated October 29, 1996
			09/17/01	Jo Crosby & Associates	Response to Geotechnical Review Letter
	350 Jane Drive	x	05/09/86	JCP Geologists Engineers	Soil and Foundation Services, Proposed 6,500 Square Foot Home, Meadow Vista Subdivision
			09/25/86	JCP Geologists Engineers	Addendum, Soil and Foundation Services, Proposed 6,500 Square Foot Home, Meadow Vista Subdivision
			04/17/87	Lea Engineering	Structural Calculations
				William Cotton and Associates	Geotechnical Review Sheet
			07/13/87	JCP Geologists Engineers	Review of Soil Engineering Aspects of Grading and Foundation Plans, proposed Residence on Lot #6, Meadow Vista
			09/24/87	James K. Bell, Archirect	Application Revision
			09/29/10	JCP Geologists Engineers	Review of Soil Engineering Aspects of Grading and Foundation Plans, proposed Residence on Lot #6, Meadow Vista
			11/06/87	William Cotton and Associates	Geologic and Geotechnical Review, Ting Residence, Meadow Vista Lot #6
JEFFERSON AVENUE					
9	Emerald Lake Hills	no	10/18/95	Town of Woodside	Emerald Lake Hills Specific Plan and Geologic Map
	4202 Jefferson Avenue		09/12/13	American Soil Testing, Inc.	Proposed Addition & Remodel
	4219 Jefferson Avenue		08/30/13	Murray Engineers Inc.	Geotechnical Investigation, Su Residence
			12/31/18	Murray Engineers Inc.	Supplemental Recommendations, Zuazo Residence
	4224 Jefferson Avenue	x	08/21/89	Applied Earth Sciences Consultants	Soil and Geologic Investigation, Undeveloped Parcel, APN 068-243-160
			04/11/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Joseph Residence, VAR-479, Site Dev, 40, Lots 28/29
			01/19/01	Bay Area Geotechnical Group	Geotechnical and Geologic Investigation, Proposed Residence
	4253 Jefferson Avenue	x	05/08/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Culvert/Headwall Repair, Hartwig Property
			08/08/05	Lowney Associates	Geotechnical Investigation, Hartwig Residence Improvements
	4262 Jefferson Avenue	x	11/22/95	Nielsen Geotechnical Incorporated	Soil Report
	4275 Jefferson Avenue	x	06/08/04	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Studio

			11/17/05	Bay Area Geotechnical Group	Addendum, Geotechnical Engineering Investigation, Proposed Studo
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204238					
Record Title & Contents					
GEOTECHNICAL REPORT FOR JOSSELYN LANE - KENMORE WAY					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
JOSSELYN LANE					
9A	140 Josselyn Lane	x	02/17/84	Berlogar, Long & Associates	Geotechnical Investigation (APN 072-112-030)
			03/05/84	Berlogar, Long & Associates	Addendum Report No. 1, Geotechnical Investigation, Josselyn Lane Site
			03/27/84	Mattson and Mattson	Site Plan, with annotations
			04/12/84	Berlogar, Long & Associates	Proposed Gun Residence Plan Review
			04/19/84	William Cotton and Associates	Geotechnical Review Sheet
			04/24/84	William Cotton and Associates	Preliminary Geologic Review and Geotechnical Investigation Evaluation, Calvin Gunn, APN 72-112-03
			05/09/84	Berlogar, Long & Associates	Response to Comments
			05/17/84	Berlogar, Long & Associates	Plan Review
			06/05/84	William Cotton and Associates	Supplemental Geotechnical Information Evaluation, Calvin Gunn, APN 72-112-03
			06/30/84	Perry R. Wood	Soil Percolation Tests and Recommended Septec Drainfield, Parcel No. 072-112-030
			07/05/84	Berlogar, Long & Associates	Plan Review
			07/27/84	William Cotton and Associates	Plan Revision Evaluation, Lands of Gunn, APN 72-112-03
	145 Josselyn Lane	x	07/27/95	Terrasearch, Inc.	Geologic and Geotechnical Investigation, Proposed Guest House
			09/03/03	Terrasearch, Inc.	Geotechnical Investigation, Proposed Addition and Remodel
			10/27/03	Terrasearch, Inc.	Response to Peer Review Comments, Proposed Addition and Remodel
			12/18/03	Terrasearch, Inc.	Response to Plan Review Letter, Basement Conversion and Addition
			11/23/04	Admo & Associates, Inc.	Structural Issues Associated with Stairwell Retaining Wall, Basement Addition
			09/10/08	Clearly Consultants, Inc.	Geotechnical Investigation, New Residence
			07/29/11	Murray Engineers, Inc	Geotechnical Investigation, Proposed Garage Bowman Property
	170 Josselyn Lane	x	01/31/78	Dunham & Associates	Foundation Recommendations, Proposed Guest House
			01/31/78	Francis A Stejer	Geologic Setting, Proposed Guest House, Stent Property
			04/23/97	Dunham & Associates	Geotechnical Engineerign Investigation, Proposed Additions

			10/06/97	Fowler & Associates	Geological Investigation, Proposed Remodeling, Stent Residence
175 Josselyn Lane			07/14/17	Murray Engineers, Inc.	Geotechnical Investigation, Feldman Residence
204 Josselyn Lane	x		09/12/94	Geomatrix Consultants	Observations at the Josselyn Site
			09/14/94	Earth Investigations Consultants	Geologic Investigation, Fault Location
			09/30/94	Harlan Tait Associates	Review - Geologic Fault Investigation
			05/17/95	Upp Geotechnology, Inc.	Geotechnical Investigation, Distress to George Residence
			10/09/95	Upp Geotechnology, Inc.	Supplemental Information, Mitigation of Distress, George Residence
			10/31/95	Harlan Tait Associates	Supplementary Review - Geologic/Geotechnical Investigation, Proposed Underpinning, Releveling and Addition
			06/26/95	Upp Geotechnology, Inc.	Addendum, Geotechnical Investigation, Distress to George Residence
210 Josselyn Lane	x		03/30/00	Upp Geotechnology, Inc.	Pre-Sale Reconnaissance Geotechnical Investigation, Heine Property
			03/31/06	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Residential Remodel
			02/02/07	Bay Area Geotechnical Group	Fault Set Back, Proposed Residential Remodel and Garage Addition
215 Josselyn Lane	x		06/25/90	JCP Geologists - Engineers	Geologic and Soil & Foundation Study, Proposed Residence, Detached Garage and Swimming Pool (APN 072-052-140)
				William Cotton and Associates	Geotechnical Review Sheet
			09/06/90	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Services, Proposed Residence, Swimming Pool and Detached Garage
			10/12/90	William Cotton and Associates	Preliminary Geologic Review, Horton, Replacement Residence
			10/29/10	JCP Geologists - Engineers	Slope Stability Sections and Analysis
			01/15/91	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Study, Proposed Residence, Detached Garage and Swimming Pool
			02/13/91	JCP Geologists - Engineers	Alignment of Subsurface Exploration and Stability Analysis Profile, Horton Property
			02/13/91	William Cotton and Associates	Supplemental Geologic Review, Horton, Replacement Residence
				JCP Geologists - Engineers	Logs of Large Diameter Borings
			03/27/91	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Study, Proposed Residence
			03/27/91	JCP Geologists - Engineers	Addendum for Proposed Guest Cottage
			04/29/91	William Cotton and Associates	Geologic and Geotechnical Review, Horton, BP #8290-8295
			05/24/91	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Grading Plans, Proposed Residence and Other Structures
			06/03/91	Lea Engineering	Seismic Design - Lateral Loads
			06/05/91	Lea Engineering	Structural Calculations - Water Tank
			06/15/91	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Study, Proposed Residence, Detached Garage and Swimming Pool

			06/20/91	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans, Proposed Residence and Other Structures
			06/21/91	JCP Geologists - Engineers	Proposed Septic Leach Field
			06/25/91	William Cotton and Associates	Supplemental Geotechnical Review, Horton, BP #8290 to #8295
			07/24/91	JCP Geologists - Engineers	Fault Investigation Study, Proposed Guest House Cottage
			06/24/91	Lea Engineering	Seismic Design
			07/31/91	William Cotton and Associates	Supplemental Geologic Review, Horton Guesthouse, BP #8293
			08/29/91	William Cotton and Associates	Geologic and Geotechnical Review, Horton, BP #8290-8295
			09/18/91	JCP Geologists - Engineers	Supplemental Fault Investigation Study, Proposed Guest House Cottage
			09/27/91	William Cotton and Associates	Supplemental Geologic Review, Horton Guesthouse, BP #8293
				Sinclair Associates, Inc.	Site Plan with annotations
	230 Josselyn Lane	x	11/22/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	275 Josselyn Lane	x	02/27/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Room Additions
			12/19/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
			05/18/10	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Residence
	285 Josselyn Lane	x	09/28/06	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation and Plan Review
KENMORE WAY					
9A	145 Kenmore Way	x	12/11/07	Murray Engineers, Inc.	Geotechnical Investigation, Site Improvements
	130 Kenmore Way	x	02/11/92	JR Engineering & Structures	Structural Verifications of Existing Deck Structure
			08/03/92	GeoForensics, Inc.	Geotechnical Observations of Foundations, Austin Deck
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204246					
Record Title & Contents					
GEOTECHNICAL REPORT FOR					
KINGS MOUNTAIN ROAD - 179 KINGS MOUNTAIN ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
KINGS MOUNTAIN ROAD					
10	Kings Mountain Road Slide		03/31/95	Harlan Tait Associates	project file
	Kings Mountain Road at Squealer	x	03/02/06	Romig Engineers, Inc.	Geotechnical Investigation, Gabion Wall and Road Stabilization
	155 Kings Mountain Road	x	06/14/84	PSC Associates, Inc.	Soil and Geologic Investigation Report, New Single Family Residence
			06/14/84	PSC Associates, Inc.	Soil and Geotechnical Investigation, Proposed Residence
			06/24/84	PSC Associates, Inc.	Site and Geologic Investigation Report, Single Family Residence

			07/03/84	PSC Associates, Inc.	Grading and Foundation Plan Review, New Residence
			07/11/84	William Cotton and Associates	Geotechnical Review Sheet
			07/17/84	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Lands of Maltin
			07/30/84	William Cotton and Associates	Geotechnical Plan Review Evaluation, Lands of Maltin, APN 72-141-06
			08/08/84	PSC Associates, Inc.	Revised Grading and Foundation Plan Review, Proposed Residence
			09/27/84	PSC Associates, Inc.	Geotechnical Observation of Foundation Pir Drilling
			10/29/84	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Maltin Swimming Pool
			06/11/85	PSC Associates, Inc.	Maltin Pool Site
			10/31/96	GeoForensics, Inc.	Geotechnical Investigation, New Barn, Belden Property
			04/30/07	Romig Engineers, Inc.	Geotechnical Investigation, New Garage and Basement
	179 Kings Mountain Road	x	02/01/90	Applied Earth Sciences Consultants	Select Geologic, San Andreas Fault, Ground Water, and Soil Percolation Investigations, Whittell Trust
			11/26/90	Applied Earth Sciences Consultants	Geotechnical Investigation of Subsurface Conditions Adjacent to the Theater Building
			04/22/92	Applied Earth Sciences Consultants	Supplemental San Andreas Fault and Liquefaction Investigations, Markkula Estate
			03/25/91	Applied Earth Sciences Consultants	Supplemental Data for Shallow Ground Water Development
10			04/24/92	Applied Earth Sciences Consultants	Findings of Soil Percolation, Dewatering Trench Installation, and Ground Water Monitoring Investigations
			6/0/91	California Archaeological Consultants	Archaeological Survey Reoport
			08/28/92	Applied Earth Sciences Consultants	Geotechnical Review, Conceptual Subdivision Plans
			09/05/92	Applied Earth Sciences Consultants	Review of Norwak and Associates Tentative Subdivision Maps
			09/15/92	Nowack and Associates, Inc.	Natural Land Features Study, Markkula Estate
			12/15/92	H T Harvey & Associates	Hydrologic Assessment of Pond Performance
			12/16/92	William Cotton and Associates	Geologic and Geotechnical Review
			12/22/92	H T Harvey & Associates	Alternative Analysis for the Presence of Bass and Stream Gates on the Project Site
			01/04/93	H T Harvey & Associates	Delineation of Jurisdictional Waters
			01/15/93	Applied Earth Sciences Consultants	Geotechnical Review of Seismic Related Issues Regarding Proposed New Bridge, Existing Pond and Utilities
			01/18/93	H T Harvey & Associates	Addendum. Kings Mountain Road Project
			01/19/93	Nowack and Associates, Inc.	Natural Land Features Study, Markkula Estate (2nd Revision)

			05/24/93	Applied Earth Sciences Consultants	Geotechnical Investigation for the Main Residence
			07/16/93	Applied Earth Sciences Consultants	Summary Groundwater Report and Siting of On-site Sewage Disposal Systems
			8/0/93	?	Chronology of Events at 179 Kings Mountain Road
			09/10/93	Applied Earth Sciences Consultants	Geotechnical Investigation, Lot 3 Single Family Residence (Caretaker's Residence)
			03/07/94	Applied Earth Sciences Consultants	Response to Town Geologist's Request for Documents Related to 9/10/93 Report
			12/14/94	Applied Earth Sciences Consultants	Preliminary Review of Tentative Grading and Architectural Plans and Septic System, Markkula Estate
			05/09/95	Applied Earth Sciences Consultants	Geotechnical Investigation, Lot 2 Gatehouse Residence
			10/14/96	Applied Earth Sciences Consultants	Supplemental Report, Tentative Plan Review
			03/10/97	Applied Earth Sciences Consultants	On-Site Sewage Disposal System Design, Construction and Maintenance, Lot 3 Main House and Guest House

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204239

Record Title & Contents

**GEOTECHNICAL REPORT FOR
238 KINGS MOUNTAIN ROAD - 700 KINGS MOUNTAIN ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
KINGS MOUNTAIN ROAD					
10A	238 Kings Mountain Road	x	10/20/08	Romig Engineers, Inc.	Geotechnical Investigation, MacDonald Residence, Garage, and Swimming Pool
	288 Kings Mountain Road	x	01/10/85	William Cotton and Associates	Geotechnical Review Sheet
			01/16/85	William Cotton and Associates	Preliminary Geologic Review, Kehoe Residence, APN 072-120-030
			08/10/88	Trans Pacific Geotechnical Consultants, Inc.	Geologic Studies and Geotechnical Investigation, Proposed Single-Family Residence
				William Cotton and Associates	Geotechnical Review Sheet
			01/16/89	William Cotton and Associates	?
			06/14/89	Trans Pacific Geotechnical Consultants, Inc.	Supplemental Information, Geotechnical Investigation, Proposed Single-Family Residence
			08/05/89	Edward Dominiom	Structural Calculations with */31/89 Addendum #1

			08/10/89	William Cotton and Associates	Preliminary Geologic Review, White, Project #7424 - Feasibility Evaluation
			08/17/89	Trans Pacific Geotechnical Consultants, Inc.	Geotechnical Omvestigation, Proposed Single-Family Residence
			09/14/89	Trans Pacific Geotechnical Consultants, Inc.	Review of Design Drawings, Proposed Single-Family Residence
			09/14/89	William Cotton and Associates	FAX showing fill slope
			11/09/89	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, White Residence
289 Kings Mountain Road	x		10/27/87	Watterman and Sun	Site Plan, Addition and Remodel, Levinthal Residence
				William Cotton and Associates	Geotechnical Review Sheet
			11/11/94	Upp Geotechnology, Inc.	Fault Location Study, Richeson Property
			12/06/94	Upp Geotechnology, Inc.	Supplemental Fault Location Investigation, Richeson property
310 Kings Mountain Road	x		05/22/64	Gribaldo, Jacobs, Jones and Associates	Foundation Investigation, James Lagiss Residence
320 Kings Mountain Road	x		03/24/87	Jo Crosby & Associates	Geotechnical Consultation on the Distress to Residence
				William Cotton and Associates	Geotechnical Review Sheet
			04/11/87	Wipson Incorporated	Plans with photo and annotations
			05/11/87	Jo Crosby & Associates	Foundation Repair Plan Review, Residence
			06/08/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Arnsten Foundation Repairs, P.A. #4099
			04/18/89	Jo Crosby & Associates	Geotechnical Investigation, Planned Addition to Residence
			05/09/98	Robelo/Kocjan Associates, Inc.	Structural Calculations
			10/06/98	Town of Woodside	Requirements to Final Project BP #6480
325 Kings Mountain Road	x		02/14/11	Murray Engineers, Inc.	Geotechnical Investigation, Zambezi Creek Residence
335 Kings Mountain Road	x		06/25/10	Earth Investigations Consultants	Geologic Investigation, Fault Location - Draft
			07/09/10	Town of Woodside	Review Comments on 6/25/10 report
			07/13/10	Earth Investigations Consultants	Geologic Investigation, Fault Location
			11/12/17	Geosphere Consultants, Inc.	Geotechnical Investigation, Proposed Residential Remodel
340 Kings Mountain Road	x		05/30/85	William Cotton and Associates	Geotechnical Review Sheet
			06/21/85	Baldwin Consultants	Soil and Foundation Investigation, Proposed Guest House
			06/25/85	Richard Hanson	Calculations - Foundation Design
			07/16/85	Baldwin Consultants	Plan Review, Proposed Guest House
			07/19/85	Baldwin Consultants	Plan Review, Proposed Guest House
			07/29/85	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Keek Guest House
			04/02/03	Earth Investigations Consultants	Geotechnical Review, Proposed Residence Addition
			08/27/10	Murray Engineers, Inc.	Fault Investigation, Schroll Property

			01/12/11	Murray Engineers, Inc.	Supplemental Investigation, Fault Rupture Hazard, Schroll Property
360 Kings Mountain Road	x		11/30/10	Earth Investigations Consultants	Geologic Investigation, Fault Rupture Hazard, Wilmer Property
481 Kings Mountain Road	x		01/11/89	JCP Geologists - Engineers	Engineering Geologic Study, Proposed Residence
			11/30/94	Applied Earth Sciences Consultants	A San Andreas Fault and Groundwater Investigation
			08/16/96	Cyme, Inc.	Geotechnical Engineering Investigation, Jaiswal-Family New Residential Development
			01/27/06	Murray Engineers, Inc.	Geotechnical Investigation, Replacement Vehicle Bridge
521 Kings Mountain Road	x		06/02/03	Earth Systems Consultants	Limited Soil Engineering Study, Proposed House Barns, Mounted Patrol Grounds
661 Kings Mountain Road	x		06/26/95	Earth Investigations Consultants	Preliminary Geologic Hazard Assessment
			07/08/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residence
			08/09/00	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Landscape Retaining Walls
			08/13/03	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Landscape Retaining Walls
680 Kings Mountain Road	x		01/21/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Additions and New Barn
700 Kings Mountain Road	x		12/09/83	Hoskins Engineers, Inc.	Structural Calculations
			03/10/86	William Cotton and Associates	Geotechnical Review Sheet
			03/12/86	William Cotton and Associates	Preliminary Geologic Review, Lands of Goodfellow and Kampcik, Champman Variance 394
			09/04/86	Cleary Consultants, Inc.	Soil & Foundation Engineering Investigation
			09/10/86	Brian Kangas Foulk & Associates	Grading and Drainage Plan, Custom Home for Goodfellow and Kampcil, with annotations
			11/06/86	William Cotton and Associates	Geotechnical Review Sheet
			11/17/86	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Goodfellow and Kampcik, PA #3299
			12/04/86	Cleary Consultants, Inc.	Supplemental Evaluation, Goodfellow-Kampcik Residence
			12/18/86	Cleary Consultants, Inc.	Review of Foundation and Grading Plans, Goodfellow and Kampcik Residence
			01/15/87	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Goodfellow and Kampcik, PA #3299
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204240					
Record Title & Contents					
GEOTECHNICAL REPORT FOR					

LA HONDA ROAD -LANING DRIVE

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
LA HONDA ROAD					
11	La Honda Road	x	04/06/79	Purcell, Rhoades & Associates	Preliminary Geotechnical Hazard Evaluation and Percolation Testing, 60-Acre Parcel Fronting along Old La Honad Road
			10/29/80	Edwin H. Smith	Preliminary Map, Lands of Parnas Corporation in Rancho El Corte Madera and Rancho Canada De Raynundo, with annotations
			02/02/81	William Cotton and Associates	Geotechnical Review Sheet - Macie and Pean LD #272
			03/04/81	William Cotton and Associates	Review of 4/6/79 PRA report
			05/18/81	Purcell, Rhoades & Associates	Preliminary Soil Report, Assessor's Parcel Nos. 75-060-110. 140, and 160, and 75-070-040
			0/0/85	James Guthrie & Associates, Inc.	Preliminary Site Plan
			12/20/85	William Cotton and Associates	Geotechnical Review Sheet - Macie LD #272
			01/02/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Lot Line Adjustment, Macie and Pean
	801 La Honda Road	x	11/15/83	Purcell, Rhoades & Associates	Soils and Foundation Study - Swimming Pool, Welch Residence
				William Cotton and Associates	Geotechnical Review Sheet
			12/05/83	William Cotton and Associates	Review - Welch Swimming Pool, 75-134-01
			10/02/05	Geo Forensics, Inc.	Geotechnical Investigation, Proposed New Residence Addition ans Garage/Shop Addition
	1255 La Honda Road	x	02/27/84	JCP Geologists - Engineers	Geologic and Soil & Foundation Studies for Distressed Home and Proposed Addition
	1391 La Honda Road	x	09/12/95	Ting and Associates	Geotechnical Investigation, Proposed Single Family Residence
			09/12/95	Buckley Engineering Associates	Geologic Investigation, Proposed Addition
	1655 La Honda Road	x	09/30/85	William Cotton and Associates	Geotechnical Review Sheet, with Site Photographs
			10/07/85	William Cotton and Associates	Preliminary Geologic Review, Giarretto Addition
			06/10/86	Applied Earth Sciences Consultants	Geotechnical Evaluation, Proposed Addition
			08/07/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Giarretto Addition AP #2846
			08/26/86	Applied Earth Sciences Consultants	Plan Review, Proposed House Addition

			09/09/86	William Cotton and Associates	Supplemental Geotechnical Review, Giarretto Addition, AP #2846
LAKEVIEW DRIVE					
11	115 Lakeview Drive	x	09/07/95	Harza	Geotechnical Investigation, Black Property
			05/30/96	Harza	Supplemental Basement Retaining Wall and Slab Recommendations, Black Residence
			11/12/96	Harza	Supplemental Swimming Pool Recommendations, Black Residence
			09/07/01	Harza	Geotechnical Investigation, Black Property
	122 Lakeview Drive	x	07/31/01	Nielsen Geotechnical, Inc.	Geotechnical Information (Draft Soils Report dated 7/6/99)
	170 Lakeview Drive	x	01/23/79	Donald E. Banta & Associates	Geotechnical Investigation, Noravian Residence, Parcel 1, Land Division No. 89
			03/27/79	Panco/Sinclair Associates, Inc.	Site Plan with annotations
			06/27/79	William Cotton and Associates	Geotechnical Review
			07/19/79	William Cotton and Associates	Geologic Review Lands of Noravian
			08/19/79	William Cotton and Associates	Geotechnical Review - Lands of Noravian
			01/14/02	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Deck
			04/30/02	American Soil Testing, Inc.	Supplemental Foundation Data, Proposed Deck
			07/26/02	American Soil Testing, Inc.	Supplemental Recommendations, Proposed Deck
			01/28/03	American Soil Testing, Inc.	Supplemental Data and Recommendations, Proposed Addition and Remodel
LANING DRIVE					
11	100 Laning Drive	x	07/28/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Developments, Parcels 1 (100) and 2 (110 and 120)
			07/09/15	Earth Investigations Consultants	Supplemental Geotechnical Investigation, Proposed Addition to Cabana
	110 Laning Drive	x	07/28/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Developments, Parcels 1 and 2, Canada Road at Laning Drive
			02/21/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
			06/24/02	Earth Investigations Consultants	Supplemental Geotechnical Recommendations, Proposed Pool
	115 Laning Drive	x	12/12/00	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence, Shaw Property
			01/05/04	GeoForensics Inc.	Review of Plans and Report Update, Shaw Residence
			05/06/04	GeoForensics Inc.	Report Supplement, Proposed Barn
	120 Laning Drive	x	07/28/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Developments, Parcels 1 and 2, Canada Road at Laning Drive
			02/18/98	Lea& Sung Engineering, Inc.	Tentative Parcel Map, Lands of Dancer
			08/28/01	Earth Investigations Consultants	Supplemental Geotechnical Recommendations, Proposed Basement

	130 Laning Drive	x	06/04/98	Nielsen Geotechnical Incorporated	Soil Report
	155 Laning Drive	x	04/13/95	Earth Mechanics Consulting Engineers	Geotechnical Investigation
			06/12/01	Romig Engineers, Inc.	Geotechnical Investigation, New Residence
	225 Laning Drive	x	05/05/05	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Modifications to Existing Residence
	240 Laning Drive	x	11/12/99	Romig Consulting Engineers	Geotechnical Investigation, King Residence Improvements
			03/22/01	Town of Woodside	Engineering Geology Review
			03/02/01	Romig Consulting Engineers	Geotechnical Plan Review, New Garage and Pool House
			04/09/01	Geomatrix Consultants	Geotechnical Review
			07/31/01	Romig Consulting Engineers	Geotechnical Plan Review, New Garage and Pool House
	240 Laning Drive		10/16/02	Romig Consulting Engineers	Construction Observation, Project Phase I, Garage, Pool House & Pergola
	245 Laning Drive	x	01/29/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Bechtel Residence Additions
			11/22/11	PGSoils, Inc.	Geotechnical Report Update, Proposed Residential Remodeling
			02/29/16	Murray Engineers, Inc.	Geotechnical Investigation, Landscape Improvements

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204241

Record Title & Contents

**GEOTECHNICAL REPORT FOR
LA QUESTA WAY - LAWLER RANCH ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
LA QUESTA WAY					
11A	160 La Questa Way	x	02/08/06	Murray Engineers, Inc.	Geotechnical Investigation, Klein Guesthouse
			06/29/06	Murray Engineers, Inc.	Supplemental Grading Recommendations, Klein Guesthouse
	231 La Questa Road	x	05/15/95	GeoFroensics, Inc.	Geotechnical Investigation, Proposed Residential Addition
	240 La Questa Way	x	06/16/95	Nielsen Geotechnical Incorporated	Soil Report
			03/03/04	Nielsen Geotechnical Incorporated	Plan Review
			11/30/16	Romig Engineers, Inc.	Geotechnical Investigation, McBaine Residence Improvements
	250 La Questa Way	x	06/12/92	Melvin R. Hill, Inc.	Soil Investigation
			09/21/92	Melvin R. Hill, Inc.	Addendum to Soil Report

			11/19/92	Melvin R. Hill, Inc.	Addendum to Soil Report
	271 La Questa Way	x	05/16/11	Romig Engineers, Inc.	Geotechnical Investigation, Marinucchi-Duncan Residence
	351 La Questa Way	x	09/27/74	Berloger, Long & Associates	Soils Engineering Geologic Investigation, Proposed Parcel Split, Single Family Residential Development
			08/06/96	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Remodel and Additions, Proudian Residence
			03/26/02	Upp Geotechnology, Inc.	Soil and Foundation Investigation Report Update and Supplemental Recommendations, Proposed Riding Arena, Barn, and Shop, Ditz Property
			05/29/09	Earth Investigations Consultants	Geotechnical Investigation, Site Mitigation
			09/20/13	Earth Systems Pacific	Geotechnical Engineering Study, Proposed Two-Story Residence, Guest House, and Pool
	375 La Questa Way	x	07/09/91	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Cottage
	400 La Questa Way	x	12/14/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
			05/16/00	Earth Investigations Consultants	Geotechnical Plan Review, proposed Pool Rehabilitation
			09/14/00	Geomatrix Consultants	Geotechnical Review, Proposed Building Addition, Georgakas Residence
			11/27/00	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Remodel
			04/25/01	Earth Investigations Consultants	Geotechnical Review, Proposed Pool Deck
			08/13/01	Earth Investigations Consultants	Geotechnical Final, Pool and Spa
	400 La Questa Way		05/22/02	Earth Investigations Consultants	Geotechnical Construction Observation - Final
	411 La Questa Way	x	09/27/74	Berloger, Long & Associates	
			08/16/78	Berloger, Long & Associates	Supplemental Consultation, Proposed Residence - Parcel 2, Lubin Land Division
			07/01/05	Michelucci & Associates, Inc.	Preliminary Geotechnical Evaluation, Proposed Front Entry Addition
			09/15/05	Michelucci & Associates, Inc.	Supplement to Preliminary Geotechnical Evaluation, proposed Front Entry Addition
			10/23/19	Michelucci & Associates, Inc.	Geotechnical Investigation Proposed New Patio, Deck, Retaining Walls and Addition to Residence
	427 La Questa Way	x	12/18/87	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Lands of Vaccaro
LAS PULGAS DRIVE					
11A	Las Pulgas Drive / Cinnabar Road		04/07/78	Donald A. Woolfe and Associates	Environmental Assessment, Lands of Wirth (Crosby/Coonan)
			06/01/78	Frahm Elder Cannis	Preliminary Map (Aerial Photograph), Rancho De Las Pulgas Subdivision (Lands of Wirth)
			06/07/78	Leighton and Associates	Addendum to Report
			06/15/78	Leighton and Associates	Review

			08/01/78	Donald A. Woolfe and Associates	Draft Environmental Impact Report, Lands of Wirth (Crosby/Coonan), Rancho De Las Pulgas Subdivision
	450 Las Pulgas Drive	x	09/13/06	Jo Crosby & Associates	Geotechnical Investigation, Proposed Residential Development, Lot 2, Las Pulgas Estates
	455 Las Pulgas Drive	x		Jo Crosby & Associates	Geology and Soils Investigation, Rancho De Las Pulgas
	Rancho De Las Pulgas Subdivision				
	455 Las Pulgas Drive	x		William Cotton and Associates	Geotechnical Review Sheet
			09/16/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Hawks, PA-4862, SDP-16
			09/30/88	Town of Woodside	Application Notice
			10/05/88	Jo Crosby & Associates	Review of Foundation and Grading Plans, Lot 3, Las Pulgas Estates Subdivision
			05/07/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Suri Residence, SD #42
			09/21/90	Cannis Consulting Engineers	Grading / Drainage Plan
			10/02/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Suri Residence, SD #42
			01/25/91	Lee Engineers	Geotechnical Investigation, Lot 3
			04/16/91	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Suri Residence, Building Permits #8283 - #8286
			05/18/91	Lee Engineers	Supplemental Geologic and Geotechnical Review, Suri Residence
			06/05/91	Lee Engineers	Supplemental Structural Calculations for Revised Foundation
			06/11/91	Engeotech, Inc.	Testing and Inspection Durig Grading, Proposed Residential Dwelling, Lot 3
			06/14/91	Lee Engineers	Supplemental Recommendations
			06/21/91	Engeotech, Inc.	Compaction Data
			06/24/91	William Cotton and Associates	Supplemental Geotechnical Review, Suri Residence, Building Permits #8283 - #8286
			07/05/91	Engeotech, Inc.	Response to Comments from Geotechnical Consultants, proposed Residential Dwelling, Lot 3, Las Pulgas Estates
			07/29/91	William Cotton and Associates	Supplemental Geotechnical Review, Suri Residence, Building Permits #8283 - #8286
			08/05/91	Engeotech, Inc.	Geotechnical Consultants, Proposed Residential Dwelling, Lot 3, Las Pulgas Estates
			08/06/91	Dominic Chu	Structural Calculations, Suri Residence
			08/22/91	William Cotton and Associates	Supplemental Geologic Review, Suri Residence, Building Permits #8283 - #8286

			08/29/91	Engeotech, Inc.	Response to Comments from Geotechnical Consultants, Proposed Residential Dwelling, Lot 3, Las Pulgas Estates
			09/27/91	William Cotton and Associates	Supplemental Geologic Review, Suri Residence, Building Permits #8283 - #8286
455 Las Pulgas Drive			10/20/94	Harlan Tait Associates	Letter of Transmittal
460 Las Pulgas Drive	x		06/08/93	Jo Crosby & Associates	Progress Report on the Problems
			05/16/94	Tredwell & Rollo	Preliminary Geotechnical Consultation and Construction Summary Report, Molakides Residence
			09/11/95	Ned Clyde Construction, Inc.	Soil Report for Pool and Guest House
470 Las Pulgas Drive	x		05/09/00	Nielsen Geotechnical Incorporated	Soil Report
475 Las Pulgas Drive	x		03/29/79	Frahm Elder Cannis	Percolation Test (Locations), Rancho de Las Pulgas Subdivision (Lands of Wirth)
			12/22/80	Joe Crosby & Associates	Final Report for the Observation and Testing of Site Grading, Las Pulgas Estates
			07/10/86	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Lot 5, Las Pulgas Drive, Las Pulgas Estates
				William Cotton and Associates	Geotechnical Review Sheet
			05/07/87	Brent Cottong, Landscape Architect	Grading Plan, Huang Residence, Lot 5, Las Pulgas Subdivision
			08/05/87	William Cotton and Associates	Preliminary Geologic Review, Huang, Las Pulgas Estates, Lot #5, Permit #4236
			08/14/87	Joe Crosby & Associates	Update of the Geotechnical Report for Lot 5, Las Pulgas Estates Subdivision
			08/21/87	Joe Crosby & Associates	Foundation Plan Review, Proposed Residence, Lot 5, Las Pulgas Estates Subdivision
			08/25/87	Joe Crosby & Associates	Addendum to Geotechnical Report: Recommendations for Retaining Walls, Swimming Pool, and Tennis Court Grading, Lot 5, Las Pulgas Sub.
			09/29/87	Joe Crosby & Associates	Review of Retaining Wall Plans, Lot 5, Las Pulgas Estates Subdivision
			01/27/88	William Cotton and Associates	Supplemental Geotechnical Review, Huang, Las Pulgas Estates Lot #5, PA #4236
			07/29/88	Joe Crosby & Associates	Update of Geotechnical Report, Lot 3, Las Pulgas Estates Subdivision
			08/16/88	Joe Crosby & Associates	Addendum to Geotechnical Report: Recommendations for Retaining Walls and Swimming Pool, Lot 3, Las Pulgas Estates Subdivision
			09/15/89	Joe Crosby & Associates	Swimming Pool Plan Review: Lot 5, Las Pulgas Estates Subdivision
475 Las Pulgas Drive			10/20/94	Harlan Tait Associates	
480 Las Pulgas Drive	x		12/22/95	Upp Geotechnology, Inc.	Geotechnical Investigation and Percolation Testing, Lands of Huang
			08/15/96	Harlan Tait Associates	Peer Review
			10/17/96	Upp Geotechnology, Inc.	Addendum Information and Plan Review, Prinz Residence

			11/07/06	Harlan Tait Associates	Supplementary Peer Review
			07/22/97	Upp Geotechnology, Inc.	Plan Review, Proposed Swimming Pool, Prinz Property
			09/24/97	Upp Geotechnology, Inc.	Status Letter, Construction Monitoring, Prinz
485 Las Pulgas Drive	x		06/18/86	Joe Crosby & Associates	Foundation -Drainage Plan Review, Lot 6, Las Pulgas Estates
			08/12/86	William Cotton and Associates	Geotechnical Review Sheet
			06/09/88	B Clyde Beck Architect	Yen - New Residence
			08/15/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Yen, Las Pulgas Estates, Lot #6
			09/05/88	Joe Crosby & Associates	Review of Swimming Pool Plans, Lot 6, Las Pulgas Estates
			10/07/88	Joe Crosby & Associates	Recommendations for Stitch Pier Retaining System, Lot 6, Las Pulgas Estates Subdivision
			10/25/88	Joe Crosby & Associates	Supplemental Recommendations for Stitch Pier Retaining System, Lot 6, Las Pulgas Estates Subdivision
			11/01/88	Gene S.Shaw, PE	Structural Calculations, Yen's Residence
			11/02/88	Joe Crosby & Associates	Review of Remedial Plans for Fill Slope, Lot 6, Las Pulgas Estates Subdivision
			11/04/88	William Cotton and Associates	Memo to Mr. Yen RE: Project Approval
			11/23/88	Joe Crosby & Associates	Lens Grouting at David Yen Residence, Las Pulgas Estates
			12/03/88	Gene S.Shaw, PE	Structural Calculations
			12/28/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
490 Las Pulgas Drive	x		12/22/98	Fowler & Associates Geotechnical, Inc.	Geotechnical Investigation, Proposed Single Family Residence
			05/31/00	Fowler & Associates Geotechnical, Inc.	Supplemental Geotechnical Investigation, Proposed Single Family Residence
			06/10/06	Fowler & Associates Geotechnical, Inc.	Geotechnical Investigation, Proposed Single Family Residence
LAWLER RANCH ROAD					
11A	Lawler Ranch Road		04/08/80	Earth Sciences Associates	Assessment of Geologic Hazards, Lawler Property
			03/10/82	Donald A. Woolfe and Associates	Environmental Assessment, Proposed Whiskey Hill Subdivision
				Brian Kangas Foulk	Whiskey Hill - Concept Map
			12/19/85	Nordmo Associates, Inc.	Soil Investigation, Proposed House, The Lawler Ranch
			12/04/89	Clearly Consultants, Inc.	Reconnaissance Geologic Investigation, 92 Acres (5 Parcels)
			07/29/91	?	Outline of Geologic Report, Subdivision #150, Lands of Lawler
			09/20/91	Donald Woolfe and Associates	Environmental Constraints/Concept Map, Lawler Ranch - Lot 69
			10/10/91	William Cotton & Associates	Preliminary Geologic and Geotechnical Review, Lawler Subdivision #150, Lawler Ranch Road

			07/09/92	Hawk Engineers, Inc.	Natural Land Features Study, Whiskey Hill Estates
			08/10/92	GeoForensics, Inc.	Geotechnical and Geologic Investigation, Proposed Residential Development, Whiskey Hill Estates
			12/21/92	GeoForensics, Inc.	Responses to Town's Geologic and Geotechnical Consultants' Comments, Whiskey Hill Estates
			02/01/94	Wagstaff and Associates	Draft Environmental Impact Report, Whiskey Hill Estates Subdivision
			07/14/94	Wagstaff and Associates	Final Environmental Impact Report, Whiskey Hill Estates Subdivision - Responses to Comments on the Draft EIR
			07/14/94	Wagstaff and Associates	Final Environmental Impact Report, Whiskey Hill Estates Subdivision
			05/25/95	GeoForensics, Inc.	Geotechnical Report Update, Whiskey Hills Estates
			05/20/95	Berry and Associates	Erosion and Drainage Control Analysis, Sand Hill Estates
			05/20/95	Berry and Associates	Natural Land Features Study, Sand Hill Estates
			05/26/95	Berry and Associates	Statements and Materials to Accompany Vesting Tentative Map, Sand Hill Estates

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204242

Record Title & Contents

**GEOTECHNICAL REPORT FOR
LINDENBROOK ROAD - 230 MANZANITA WAY**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
LINDENBROOK ROAD					
12	205 Lindenbrook Road	x	10/04/83	Robert Mahoney	Landslide Repair Report
			10/25/83	William Cotton and Associates	Geotechnical Review Sheet
			11/16/83	William Cotton and Associates	Geotechnical Review, Matheson Landslide
			01/17/84	Joe Crosby & Associates	Geotechnical Investigation, Landslide Repairs
			02/04/84	Soil Engineering Construction, Inc.	Pile Calculations
			02/24/84	William Cotton and Associates	Geotechnical Review of Landslide Repair, Matheson
			04/09/84	Joe Crosby & Associates	Addendum I, Geotechnical Investigation, Landslide Repairs
			04/02/84	Joe Crosby & Associates	Aerial Geology Map and Site Plan
			04/19/84	Joe Crosby & Associates	Addendum, Geotechnical Investigation for Landslide Repairs
			05/24/84	William Cotton and Associates	Geotechnical Evaluation, Matheson Landslide Repair
			07/10/84	Joe Crosby & Associates	Addendum II, Geotechnical Investigation, Landslide Repairs

			08/01/84	William Cotton and Associates	Geotechnical Evaluation, Matheson Landslide Repair
			08/06/84	William Cotton and Associates	Geotechnical Evaluation, Matheson Landslide Repair
			12/11/84	William Cotton and Associates	Photographs of Matheson Landslide Repair
			12/13/84	William Cotton and Associates	Geologic Inspection of Site Conditions, Matheson Landslide Repair
			03/23/85	Soil Engineering Construction, Inc.	Structural Plans and Calculations for Repair of House Foundation
			05/09/85	Joe Crosby & Associates	Observation and Testing for Landslide Repair
			06/04/85	William Cotton and Associates	Preliminary Geologic Review, Septic Drainfield Site, Hart Residence
			08/24/85	Soil Engineering Construction, Inc.	Landslide Repair Plans, with annotations
			09/11/85	Soil Engineering Construction, Inc.	Design Calculations for Retaining Wall
			09/25/85	William Cotton and Associates	Review of Retaining Wall Design
			09/27/85	William Cotton and Associates	Geotechnical Evaluation, Mahoney Retaining Wall
			10/07/85	William Cotton and Associates	Supplemental Geotechnical Evaluation, Mahoney Landslide Repair and Residence Underpinning
			03/25/86	Joe Crosby & Associates	Geotechnical Evaluation of Repairs
			04/14/86	William Cotton and Associates ?	Preliminary and Final Comments on Various Crosby (?) Submittals
			04/16/86	Joe Crosby & Associates	Comments on the "Checklist" of WCA dated 4/14/86
			04/22/86	Joe Crosby & Associates	Comments on "Amended Checklist" of WCA
			04/26/86	Soil Engineering Construction, Inc.	Structural Calculations for Retaining Wall Below Driveway
			04/28/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Mahoney Distressed Residence and Landslide Repairs and Improvements
			08/26/16	GeoForensics, Inc.	Replacement of Retaining Wall
	240 Lindenbrook Road	x	12/07/16	UPP Geotechnology	Limited Geotechnical Study Proposed Basement Addition And Retaining Wall Replacement
	245 Lindenbrook Road	x	04/30/84	Terrasearch, Inc.	Soil and Geologic Investigation, Lands of Hugo, Two Proposed Residences and Support Structures
			02/10/85	Rick Skierka	Tentative Map
			05/08/85	Rick Skierka	Tentative Map
			03/19/85	William Cotton and Associates	Geotechnical Review Sheet
			03/20/85	William Cotton and Associates	Preliminary Geologic Review, Hugo Lot Line Adjautment, LD 288
			06/09/88	JCP Geologists Engineers	Soil ans Foundation Services, Three Proposed Structures
			05/05/90	Joseph Parello	Structural Calculations
			05/26/90	House of Haws	Plans

				William Cotton and Associates	Geotechnical Review
			06/15/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence and Garage
			07/13/90	William Cotton and Associates	Geologic and Geotechnical Review, Hugo Residence and garage, PA-7884
			08/23/90	JCP Geologists Engineers	Addendum to Soil and Foundation Study, Three Proposed Structures
	250 Lindenbrook Road	x	09/11/90	JCP Geologists - Engineers	Engineering Geologic and Soil & Foundation Study, Proposed Addition and Garage
			11/15/90	JCP Geologists-Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed New Residence and Garage
			01/02/91	William Cotton Associates	Geotechnical Review Sheet
			9 & 11/90	House of Haws	Plan with notes
			11/04/97	GeoForensics, Inc.	Geotechnical Report Update, Proposed New Garage and Addition, Kellenberger Property
	260 Lindenbrook Road	x	01/25/96	Hoexter Consulting, Inc. / Romig Consulting Engineers	Geologic and Geotechnical Investigation, McDowall Residence Renovation
			05/18/11	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Replacment Garage
	300 Lindenbrook Road	x	06/05/85	Brian Kangas Foulk & Associates	Topographic Survey, Portions of Lot II, Meadow Vista Subdivision
			10/04/85	Edward Dominion	Structural Calculations
			09/23/85	Howard F. Donley & Associates	Geotechnical Investigation, Proposed New Residence for Green
			01/07/86	Howard F. Donley & Associates	Review of Design Calculations an Architectural Drawings, Proposed Single Family Residence
			01/17/86	William Cotton and Associates	Geotechnical Review Sheet
			01/23/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Green
	305 Lindenbrook Road	x	08/15/86	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Residence
LOWER LAKE ROAD					
12	110 Lower Lake Road	x	01/12/90	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Guest Cottage
			04/30/02	JF Consulting, Inc.	Geotechnical Update Letter, Proposed Horse Barn, Lands of Watt/Tracy
LYNN WAY					
	115 Lynn Way	x	05/30/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel to Existing Residence
			01/22/07	Alliance Environmental and Soil Engineering	Geotechnical Investigation, Proposed Pool House & Swimming Pool
	125 Lynn Way	x	06/10/04	ARA Engineering Company	Geotechnical Engineering Study, Proposed Residential Development
			04/04/05	ARA Engineering Company	Addendum to Geotechnical Engineering Study, Planned Residential Development
			07/28/06	ARA Engineering Company	Geotechnical Engineering Services, Response to Town Comments

	125 Lynn Way		07/28/06	ARA Engineering Company	Geotechnical Engineering Services, Review of Design Plans & Specifications
	135 Lynn Way	x	04/15/97	Friar Associates, Incorporated	Geotechnical & Geologic Investigation, Addition to Existing Residence
	150 Lynn Way	x	10/20/03	Milstone Geotechnical	Geotechnical Investigation, Proposed Auxiliary Building
			03/05/04	Milstone Geotechnical	Geotechnical Investigation, Proposed Auxiliary Building
MANUELLA AVENUE					
12	309 Manuella Avenue	x	04/08/96	Nielsen Geotechnical Incorporated	Soil Report
			12/06/97	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Addition
	349 Manuella Avenue		12/15/16	Murray Engineers, Inc.	Geotechnical Investigation, New Residence
	395 Manuella Avenue	x			
MANZANITA WAY					
12	105 Manzanita Way	x	04/05/88	Terrasearch, Inc.	Geotechnical Investigation, Proposed Residence
	115 Manzanita Way		11/07/14	Michelucci & Associates Inc.	Geotechnical Investigation, Proposed Interior Remodel
	200 Manzanita Way	x	04/27/87	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Parcel 073-122-150, Manzanita Way near Mountain Home Road
			04/30/87	PSC Associates, Inc.	Geotechnical Engineering Inverstigation, Proposed Residence, Lot 15 Manzanita Way
			06/22/87	Lea Engineering	Site and Drainage Plan
				William Cotton and Associates	Geotechnical Review Sheet
			07/30/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Wadell, PA #4229
			08/10/87	John Coyle & Associates, Inc.	Site Reconnaissance, Searsville Fault Trace, Wedell Property
			07/31/96	GeoForensics, Inc.	Geotechnical Investigations, Proposed Site Improvements, Barth Property
			05/06/97	GeoForensics, Inc.	Review of Plans, Proposed Waterhole/Pond
			05/21/97	Harlan Tait Associates	Review - Geotechnical Investigation, Proposed Addition, Guest House and Waterhole/Pond
	201 Manzanita Way		09/09/15	Romig Engineers, Inc	Residence Renovation
	230 Manzanita Way	x	06/14/99	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residential Addition
	now 101 Winding Way				
	No Site (between 201 and 325 Manzanita)		12/06/11	Cotton, Shires and Associates, Inc.	Geotechnical Investigation, Cal Water Bear Gulch Station 3 Water Diversion
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204243					
Record Title & Contents					

**GEOTECHNICAL REPORT FOR
321 MANZANITA WAY - 555 MANZANITA WAY**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MANZANITA WAY					
12A	321 Manzanita Way	x	07/03/96	Treadwell & Rollo	Geotechnical Investigation
			05/31/05	GFDS Engineers	Preliminary Structural Review, Wooden Bridge
			07/14/05	Gilpin Geosciences, Inc.	Emergency Status, Bridge Restoration Project, Bear Creek
			07/25/05	Treadwell & Rollo	Geologic and Geotechnical Investigation, Bridge Renovation
			11/21/13	Romig Engineers, Inc	Lap Pool
	325 Manzanita Way	x	09/11/85	Adel Nepomuceno	Soil and Foundation Investigation, Guest House Extension
			10/02/85	Adel Nepomuceno	Aquirre's Guest House
			04/24/92	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Residence
	345 Manzanita Way	x	08/27/07	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Site Improvements
	410 Manzanita Way	x	09/14/82	Donald E. Banta & Associates	Geotechnical Investigation, Proposed Garage and Studio
			06/28/13	Earth Investigation Consultants	Proposed Residence and Pool
	426 Manzanita Way	x	09/24/97	Ned Clyde Construction, Inc.	Plans and Specifications, Manzanita Way Property
	440 Manzanita Way	x	03/31/75	Richard E. Rowland	Geologic Investigation, Alden Property (Parcel 1, Lands of Estate of Johnson)
			08/30/83	Terrasearch, Inc.	Geotechnical Investigation, Slope Failure, Alden Residence
			02/15/99	Applied Earth Sciences Consultants	Geotechnical Investigation
			09/15/10	Neil O. Anderson and Associates	Geotechnical Investigation, Alden Residence Swimming Pool Remodel
	445 Manzanita Way	x	11/20/95	Hydro-Geo Consultants, Inc.	Preliminary Geological Evaluation, Canada-Hermit Fault
			12/01/95	Hydro-Geo Consultants, Inc.	Response to Town Review of 11/20/95 Report
			12/07/95	Hydro-Geo Consultants, Inc.	Response to Town Review of 12/1/95 Letter
			05/30/96	Nielsen Geotechnical Incorporated	Soil Report
			06/28/96	Nielsen Geotechnical Incorporated	Perimeter Cut-Off Drain
			09/12/96	Nielsen Geotechnical Incorporated	Building Fault Set-Backs, Johnson Residential Development
			05/30/97	Nielsen Geotechnical Incorporated	Supplemental Geotechnical Information, Proposed New Residence
			01/15/09	Murray Engineers, Inc.	Geotechnical Investigation, Johnson Guesthouse & Studio

	515 Manzanita Way	x	09/03/13	Murray Engineers, Inc.	Residence Improvements
			07/08/12	Murray Engineers, Inc.	Hydrology Study
			03/01/11	Murray Engineers, Inc.	Residence Improvements
	520 Manzanita Way	x	11/07/80	Perry R. Wood	Geologic Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
			09/27/83	Perry R. Wood	Soil Percolation Tests, Proposed Parcel 5, a Subdivision of Parcels 072-221-330, -340, -350, -360, -370, -280, and -390
			04/07/86	PSC Associates, Inc.	Geotechnical Engineering Investigation, Addition to the Guest House
			08/04/99	Upp Geotechnology, Inc.	Preliminary Report, Limited Geotechnical Investigation, Slope Stabilization and Drainage Improvements
			08/12/99	Upp Geotechnology, Inc.	Response to Town Review and Geotechnical Review Comments, Slope Stabilization and Drainage Improvements
			08/18/99	Upp Geotechnology, Inc.	Second Response to Town Review and Geotechnical Review Comments, Slope Stabilization and Drainage Improvements
			08/30/03	Upp Geotechnology, Inc.	Plan Review, Emergency Stabilization Plans (Zone I), Lands of Martin
			08/31/99	Upp Geotechnology, Inc.	Preliminary Report, Limited Geotechnical Investigation, Slope Stabilization and Drainage Improvements
			01/27/00	Upp Geotechnology, Inc.	Addendum Report, Limited Geotechnical Investigation, Slope Stabilization and Drainage Improvements - Zone 2
			07/28/00	Upp Geotechnology, Inc.	Supplemental Information, Slope Stabilization and Drainage Improvements - Zone 2
			11/21/00	Upp Geotechnology, Inc.	Construction Monitoring, Slope Stabilization
	540 Manzanita Way	x	09/21/78	Edwin H. Smith	Preliminary Map, Lands of Stone, with annotations
			09/24/80	William Cotton and Associates	Geotechnical Review Sheet
			10/07/80	William Cotton and Associates	Geologic Review, Lands of Stone/Jensen - SD-138
			11/05/80	PSC Associates, Inc.	Soils Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
			11/07/80	Perry R. Wood	Geologic Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
			01/28/81	William Cotton and Associates	Review Comments - Lands of Stone, Subdivision #138
			06/29/81	Donald A. Woolfe and Associates	Environmental Setting Survey, Stone/Jensen Property
			08/06/81	William Cotton and Associates	Geologic Review, Stone/Jensen, SD-138
				William Cotton and Associates	Geotechnical Review Sheet
			11/22/83	William Cotton and Associates	Geologic Review, Proposed Lot 8, Lands of Mayacamas Corporation
			02/03/84	William Cotton and Associates	Preliminary Geologic Review, Lands of Mayacamas Corporation, SD-145
			03/29/85	Smith, Randlett, Foulk & Stock, Inc.	Concept Map, Subdivision Map, Resubdivision of Manzanita Hills, SD-138

			07/23/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review, Lands of Martin, AD-145, Resubdivision of Manzanita Hills
			07/29/85	PSC Associates, Inc.	Possible Landslide Hazard Area the Northeast Corner, Lot 8
			08/20/85	William Cotton and Associates	Supplemental Geologic / Geotechnical Review, Lands of Martin SD-145, Manzanita Hills Subdivision
			10/15/85	William Cotton and Associates	Geologic Evaluation, Lands of Martin, Lot 7, Manzanita Subdivision, SD-145
	555 Manzanita Way	x	06/23/78	Francis A. Stejer	Engineering Geologic Study, Proposed Guest House
			07/13/78	Dunham & Associates	Soil Investigation, Proposed Guesthouse
			07/27/78	Pennington & Pennington	Site and Plot Plan, Guest House for Carnochan
				William Cotton and Associates (?)	Summary of Office Review, Carnochan
			09/11/78	William Cotton and Associates	Geotechnical Review
			07/12/91	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Gymnasium, Studio and Pump House
			07/17/01	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Barn, Swimming Pool, and Stone House
			3/31/2016	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Basement and Kitchen Remodel, Tennis Court Resurfacing and Future Pool House
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204244					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 580 MANZANITA WAY - MARTINEZ ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MANZANITA WAY					
13	580 Manzanita Way	x	07/08/83	Site Characteristics, Inc.	Faulty Investigation Report - Lands of Mosher
			07/13/83	William Cotton and Associates	Geotechnical Review Sheet
			08/03/83	William Cotton and Associates	Review - Lands of Mosher (Manzanita Hills), SD138
			09/25/84	Town of Woodside	Comments - Revision of Final Subdivision Map - SD-138, Manzanita Hills
			09/30/83	Site Characteristics, Inc.	Geotechnical Evaluation of Proposed Subdivision, Lands of Mayacamas Corporation
			12/10/03	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Thompson Property Improvements
			04/13/05	Pacific Geotechnical Engineering	Addendum Geotechnical Investigation, Thompson Residence Garage

600 Manzanita Way	x	11/07/80	Perry A. Wood	Geologic Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
		07/14/85	Dominion Engineering Co.	Topographic Map, Lands of Gauthier
		08/20/84	William F. Jones, Inc.	Drainage Problem
		09/26/85	PSC Associates, Inc.	Report Update and Plan Review, Proposed Residence, Lot 4
		10/31/85	County of San Mateo	Sewage Disposal System
		05/26/86	William Cotton and Associates	Geotechnical Review Sheet of 11/7/80 Perry R. Wood and 9/26/85 PSC reports
		06/06/86	William Cotton and Associates	Preliminary Geologic and Geotechnical review, Lands of Gauthier, Manzanita Hill Subdivision, Lot 4
		08/03/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Barn
		05/26/99	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Additions to Existing Residence
610 Manzanita Way	x	02/06/86	J. V. Lowney & Associates	Geotechnical Investigation, New Residence
610/618 Manzanita Way	x	11/0/84	Smith, Randlett, Foulk & Stock, Inc.	Tentative Map. Lot Line Change between Lots 3 and 4, Manzanita Hills, SD #138
		04/12/85	William Cotton and Associates	Geotechnical Review Sheet
		04/16/85	William Cotton and Associates	Preliminary Geologic Review, Frantz-Mayacamas Lot Line Change (Lots 3 and 4), LD289
625 Manzanita Way	x	09/23/99	Romig Consulting Engineers	Geotechnical Investigation, Caselton Guest Residence
655 Manzanita Way	x	01/17/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
		05/21/03	Triad/Holmes Associates	500-Year Flood Survey
		06/05/03	Earth Investigations Consultants	Reply to Town Review, Geotechnical Investigation, Proposed Site Improvements
660 Manzanita Way	x	03/18/75	Daniel J. Rhoades & Associates	Soil and Foundation Investigation, Portion of Lots 65 & 66, Block d, Portola Woods
		01/11/86	Earth Systems Consultants	Soil and Geologic Investigation, Proposed Addition to Residence
		03/12/87	Earth Systems Consultants	Soil Study Report, Proposed Residence Addition
		03/16/94	Jo Crosby & Associates	Geologic Investigation Report, Planned Residential Structures
		05/02/94	Jo Crosby & Associates	Addendum, Geologic Investigation, Planned Residential Structures
		07/11/94	Jo Crosby & Associates	Addendum, Geologic Investigation Report, Planned Residential Structures
		12/28/94	Nielsen Geotechnical Incorporated	Soil Report
		09/18/98	GeoForensics, Inc.	Geotechnical Report Update, Ivory Property
		03/06/14	Upp Geotechnology	Limited Geotechnical Study, Proposed Swimming Pool and Associated Improvements

	680 Manzanita Way	x	09/18/00	Nielsen Geotechnical Incorporated	Soil Report
			03/13/03	Romig Engineers, Inc.	Geotechnical Investigation, Pool House & Site Improvements
			05/31/17	Romig Engineers, Inc.	Geotechnical Investigation, Apfel-Reses Residence Addition
MAPLE WAY					
13	415 Maple Way	x	12/09/05	Murray Engineers, Inc.	Geotechnical Investigation, Walker Residence Addition
	420 Maple Way	x	08/10/76	Associated Geotechnical Engineers	Geotechnical Investigation, Proposed Vanderzyl Residence
			02/13/05	GeoFroensics, Inc.	Geotechnical Investigation, proposed Replacement Deck, Balcon Residence
	430 Maple Way	x	09/25/03	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Residential Additions
	470 Maple Way		09/30/16	Romig Engineers, Inc.	Geotechnical Investigation, Coekaerts Residence
	512 Maple Way	x	04/29/09	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Foundation Replacement/Remodel
			12/02/10	Michelucci & Associates, Inc.	Supplemental Geotechnical Recommendations, Proposed Site Retaining Walls
			11/24/10	Michelucci & Associates, Inc.	Structural Calculations
MARTIN LANE					
13	20 Martin Lane	x	07/29/99	Romig Consulting Engineers	Geotechnical Investigation, York Residence Addition
	30 Martin Lane	x	09/23/96	Nielsen Geotechnical Incorporated	Soil Report
	35 Martin Lane	x	02/10/04	Romig Engineers, Inc.	Geotechnical Investigation, Page-Oberg Residence Addition
			07/30/04	Romig Engineers, Inc.	Liquefaction Evaluation, Pge/Oberg Garage Addition
	40 Martin Lane	x	02/10/03	PGSoils, Inc.	Geotechnical Conditions, Proposed Residential Addition
			03/24/03	PGSoils, Inc.	Supplement to Geotechnical Conditions Report, Proposed Residential Addition
	45 Martin Lane	x	03/24/04	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
MARTINEZ ROAD					
13	21 Martinez Road	x	05/01/97	Nielsen Geotechnical Incorporated	Soil Report
			06/21/99	Nielsen Geotechnical Incorporated	Zaccor Grading Study, Zaccor Property

			12/20/99	Nielsen Geotechnical Incorporated	Response to Letter of December 1, 1999 from Town Counsel
			05/23/00	Nielsen Geotechnical Incorporated	Request for Design, Zaccor Retaining Walls
			06/15/00	John Woodruff Geology	Geologic Reconnaissance
			06/27/00	Nielsen Geotechnical Incorporated	Plans and Supporting Documentation, Site Retaining Walls & Drainage
	21 Martinez Road		08/23/00	Nielsen Geotechnical Incorporated	Supplemental Information - Second Submittal, SD97-079 & BP00-394
	25 Martinez Road	x	12/14/07	Jo Crosby & Associates	Geotechnical Investigation, Stability of the Garage Addition
			12/01/10	Jo Crosby & Associates	Update Report, Geotechnical Investigation, Carport-Garage Remodel
			02/17/10	Jo Crosby & Associates	Geotechnical Investigation Update
	50 Martinez Road	x	10/16/90	Upp Geotechnical, Inc.	Geologic Reconnaissance Investigation, Lands of Samuels
				William Cotton and Associates	Geotechnical Review Sheet
			06/13/91	Hoskins Engineering Inc.	Structural Calculations, Single Family Residence
	50 Martinez Road		7/26.91	William Cotton and Associates	Preliminary Geologic Review, Samules Residence Repair, PA #8179
	275 Martinez Road	x	04/26/84	William F. Jones, Inc.	Geotechnical Investigation, Fairman Residence
				William Cotton and Associates	Geotechnical Review Sheet
			09/01/84	William F. Jones, Inc.	Review of Underpinning Plans. Fairman Residence
			09/18/84	William Cotton and Associates	Geotechnical Review Sheet
			09/19/84	William Cotton and Associates ?	Geologic Map of Fairman Residence by PCA
			09/24/84	William Cotton and Associates	Geologic and Geotechnical Review
			7/0/91	R. C. Huttom & Associates	Boundary and Topographic Survey showing >35% slopes
			12/04/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
			12/20/91	William F. Jones, Inc.	Town of Woodside Architect Review, Room Addition
			02/28/92	William F. Jones, Inc.	Supplemental Geotechnical Investigation and Level of Risk Evaluation
			04/20/92	William Cotton and Associates	Geologic and Geotechnical Review, Fairman Residential Additions
			05/11/92	William F. Jones, Inc.	Response to Geologic and Geotechnical Review
			06/29/92	William F. Jones, Inc.	Response to Meeting at Town Hall, Proposed Room Addition
			11/30/92	William F. Jones, Inc.	Plan Review, Proposed Room Additions
			02/18/93	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Fairman Residential Additions, 925-041
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204245					

Record Title & Contents					
GEOTECHNICAL REPORT FOR MARVA OAKS DRIVE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MARVA OAKS DRIVE					
13A	117 Marva Oaks Drive	x	07/15/00	Town of Woodside	Comments
			09/29/00	Romig Engineers, Inc.	DRAFT Geotechnical Investigation, New Residence
			10/16/00	Town of Woodside	Comments
			07/01/06	Romig Engineers, Inc.	Geotechnical Investigation
			10/25/06	Romig Engineers, Inc.	New Residence
			06/05/07	Romig Engineers, Inc.	Supplemental Recommendations, Huhs Residence
			08/14/08	Romig Engineers, Inc.	Supplemental Recommendations, Huhs Detached Carport
	151 / 153 / 155 Marva Oaks Drive	x	12/30/82	Eareth Sciences Associates	Phase I Assesment of Geologic Hazards, lasco Property
			11/01/83	Donald A. Woolfe & Associates	Environmental Assessment, Lands of Jack and lasco for Proposed Subdivision
			08/27/84	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfields, Lands of Jack and lasco
			10/11/84	Earth Sciences Associates	Phase II Soil and Geologic Investigation, lasco Property (2 COPIES)
			09/20/85	Perry R. Wood	Addendum, Soil Percolation Tests and Recommended Septic Drainfields, Lands of Jack and lasco
			08/00/93	ESA Consultants	Geologic and Geotechnical Design Level Investigation, Marva Oaks Drive Cul de Sac and Joint Driveway
			12/03/93	ESA Consultants	Response to Town Comments
			06/15/01	Lowney Associates	Supplemental Geotechnical Recommendations for Landslide Mitigation, Proposed Development
	153 Marva Oaks Drive	x	03/21/90	Upp Geotechnology, Inc.	Percolation Testing, Lands of Jack/lasco
			05/12/98	Applied Earth Sciences Consultants	Geotechnical Review of Conceptual Site Plan, Julia Morgan Residence Restoration Project
			10/09/00	Lowney Associates	Geotechnical and Geologic Investigation
			03/15/00	Lowney Associates	
	155 MARVA OAKD DRIVE		03/06/00	CYME, INC.	
	155 Marva Oaks Drive	x	10/05/00	Lowney Associates	Geotechnical and Geologic Investigation
			04/18/01	Lowney Associates	SUPPLEMENTAL REPORT 4/6/01 REVISED 4/18/01
			09/21/01	Geomatrix Consultants	Permeability Tests Review, Falkenberg Tennis Court

			10/30/01	Lowney Associates	Response to Geomatrix Review, Tennis Court Permeability Results
			10/11/02	Lowney Associates	Geotechnical Recommendations, Tennis Court Preparation
			06/08/06	TRC Lowney	Supplemental Geotechnical Review of Project Plans, Falkenberg Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204247					
Record Title & Contents					
GEOTECHNICAL REPORT FOR MEADOW ROAD - MISSION TRAIL ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MEADOW ROAD					
14	3 Meadow Road	x	08/28/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Foundation Improvements to Existing House, New Guesthouse
			03/11/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed New House
	28 Meadow Road	x	06/25/93	Hydro-Geo Consultants, Inc.	Geotechnical Site Evaluation for Single-Family Residence
			08/06/93	David W. Buckley	Geotechnical Investigation, Proposed Schilling Residence
			09/09/94	Applied Earth Sciences Consultants	Ground Water Investigation and Control Plan, Proposed On-Site Septic System
	28 Meadow Road		11/09/94	Applied Earth Sciences Consultants	As-Built Report for Ground Water Dewatering Trench for On-Site Septic System
	45 Meadow Road	x	05/03/78	William F. Jones, Inc.	Soil Investigation, Hogle Residence
			06/28/78	William F. Jones, Inc.	Swimming Pool Plan Review, Hogle Residence
			07/24/78	Leighton and Associates	Review Comments, Swimming Pool
MEDWAY ROAD					
14	12 Medway Road	x	03/15/02	David Jones Associates	Engineering Geology Investigation, Proposed Andre Residence
			03/20/02	David Jones Associates	Geotechnical Investigation, Proposed Single-Family Residence (APN076-051-050, 076-042-090)
			07/01/02	David Jones Associates	Structural Calculations, Proposed Single Family Residence
			10/10/02	David Jones Associates	Geotechnical Response to Town Comments, Proposed Residence
	16 Medway Road	x	02/09/07	Fowler & Associates Geotechnical, Inc.	Geotechnical Investigation, Proposed Remodel of Guest Cottage
	20 Medway Road	x	04/17/07	Michelucci & Associates, Inc.	Geotechnical Investigation, Area of Existing Addition to Residence
MIDGLEN WAY					

14	822 Midglen Way	x	02/17/00	Earth Systems Consultants	Geotechnical Investigation, Proposed Residential Development
			10/21/03	Earth Systems Consultants	Supplemental Geotechnical Recommendations, Proposed Pool
MIRAMONTES ROAD					
14	141 Miramontes Road	x	09/06/90	William F. Jones, Inc.	Soils Investigation, McPherson Residence
	151 Miramontes Road	x	07/09/07	Romig Engineers, Inc.	Geotechnical Engineers, Inc., Miramontes Residence
			10/12/09	Romig Engineers, Inc.	Swimming Pool Design, Middler Property
	163 Miramontes Road	x	05/06/98	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence
			03/29/10	JF Consulting, Inc.	Geotechnical Investigation, New Swimming Pool, Lands of Mcaniff
			10/12/10	JF Consulting, Inc.	Geotechnical Investigation, Foundation Replacement for Cottage & New Car Port, Lands of McAniff
	203 Miramontes Road	x	02/04/99	Earth Investigations Consultants	Geotechnical Investigation
			04/28/06	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel
	208 Miramontes Road	x	08/15/90	DCM/Joyal Engineering	Preconstruction Geotechnical Engineering Investigation, Mariani Residence
			12/12/90	Soil Engineering Construction, Inc.	Structural Calculations, Stitch Pier Wall
				William Cotton and Associates	Geotechnical Review Sheet
			01/30/91	DCM/Joyal Engineering	Geotechnical Review of StitchPier Wall Design
			04/30/99	Nielsen Geotechnical Incorporated	Soil Report
	239 Miramontes Road	x	04/03/03	Michelucchi & Associates, Inc.	Geotechnical Investigation, Proposed New Residence
			07/16/03	Michelucchi & Associates, Inc.	Supplemental Geotechnical Recommendations, Proposed New Residence
			07/17/03	Michelucchi & Associates, Inc.	Supplemental Geotechnical Recommendations No. 2, Proposed Low Fill Slopes
			09/10/03	Michelucchi & Associates, Inc.	Review of Plans, Propsed Pool Shed abd Supplemental Geotechnical Recommendations No. 4
			10/28/03	Michelucchi & Associates, Inc.	Proposed Rock Retaining Walls
			09/13/04	Michelucchi & Associates, Inc.	Geotechnical Recommendations, Proposed Swimming Pool
	289 Miramontes Road	x	12/04/97	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
	345 Miramontes Road	x	09/15/04	Murray Engineers Inc.	Geotechnical Investigation, Putnam Residence
			03/03/05	Murray Engineers Inc.	Supplemental Recommendations, Hardscape Improvements
	395 Miramontes Road	x	05/23/94	Haro, Kasunich and Associates, Inc.	Geotechnical Investigation

			05/15/95	Haro, Kasunich and Associates, Inc.	Verification of Subsurface Soil Environment, Proposed Main House Addition
			05/15/95	Haro, Kasunich and Associates, Inc.	Verification of Subsurface Soil Profile with Additional Hand Augered Exploratory Borings, Proposed Guesthouse
MISSION TRAIL ROAD					
	15 Mission Trail Road		5/4/2016	Romig Engineers, Inc.	Geotechnical Investigation, Reese Residence
14	25 Mission Trail Road	x	05/21/76	Richard E. Roland	Geologic Investigation of Parcel No. 73-011-150
			11/0/76	Frahm Edler Cannis	Preliminary Map, Land Division, Pands of Herrmann & Klingele
			02/18/77	Leighton and Associates	Review of RER 5/21/76 Geologic Investigation of Parcel No. 73-011-150
	55 Mission Trail Road	x	06/27/89	Cleary Consultants, Inc.	Geotechnical Investigation
			02/02/11	JF Consulting, Inc.	Review of Soil Report, Addition, Putnam Residence and Our Comments
			various	various	Planning Commission Package on Putnam Creek Bank Project
	65?	x	06/17/85	Lee Engineers	Existing Soils Report Confirmation Review and Recommendations
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204248					
Record Title & Contents					
GEOTECHNICAL REPORT FOR MONTECITO ROAD - 505 MOORE ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MONTECITO ROAD					
14A	6 Montecito Road	x	11/13/92	Applied Earth Sciences Consultants	Geologic Investigation, Site Development Feasibility, Parcel "B" Woodside Country Club Properties, Subdivision No. 1
			12/22/92	William Cotton and Associates	Supplemental Geologic Review, Markkula Building Site Feasibility
			04/22/94	Applied Earth Sciences Consultants	Supplemental Geologic Investigation, Parcel "B", Woodside Country Club Properties, Subdivision No. 1
			01/08/01	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Bowers
			07/17/01	Upp Geotechnology, Inc.	Summary Letter, Geotechnical Investigation, Lands of Bowers
			05/12/15	Upp Geotechnology, Inc.	Update of Geotechnical Investigation, Proposed Residential Development
	8 Montecito Road	x	10/15/08	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Swimming Pool
			08/04/09	Wayne Ting & Associates, Inc.	Revised Swimming Pool Recommendations

			08/05/09	Wayne Ting & Associates, Inc.	Update of Geotechnical Investigation, Proposed Addition and Swimming Pool
	21 Montecito Way (Road)	x	07/20/98	Nielsen Geotechnical Incorporated	Leachfield Stability Investigation
			08/19/99	John Coyle & Associates	Geologic Reconnaissance Letter Report, Proposed Leach Field Area
			06/27/05	Murray Engineers, Inc.	Geotechnical Investigation, Ladd Residence Improvements
			02/01/06	Murray Engineers, Inc.	Emergency Landslide Mitigation, Ladd property
			02/06/06	Murray Engineers, Inc.	Supplemental Information, Emergency Landslide Mitigation, Ladd Property
			05/03/06	Murray Engineers, Inc.	Supplemental Information, Landslide Mitigation, Ladd Property
			02/15/07	Murray Engineers, Inc.	Supplemental Recommendations and Plan Review, Landslide Mitigation, Ladd Property
	33 Montecito Road	x	10/12/83	Jo Crosby & Associates	Consultation on Proposed Concrete Filled Drilled Pier Retaining Walls
			05/19/03	Jo Crosby & Associates	Stability Analysis
			12/08/04	Romig Engineers, Inc.	Geotechnical Investigation, Vine Residence Improvements
			12/08/05	Romig Engineers, Inc.	Geotechnical Review, Residence Improvements
			3/28/2013	Romig Engineers, Inc.	Geotechnical Investigation, Water Tanks
MONTELENA COURT					
14A	1, 2, 3 Montelena Court	x	10/19/78	Jo Crosby & Associates	Geologic Investigation, 12+ Acres
			01/16/81	Jo Crosby & Associates	Addendum: Geologic Investigation, 12+ Acres
	1 Montelena Court		09/19/90	Nordmo Associates, Inc.	Geotechnical Review of Construction
		x	03/10/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Equestrian Improvements
	2 Montelena Court	x	06/02/86	Nordmo Associates, Inc.	Soil Investigation, Barnes/Law Property
			12/05/96	Lowney Associates	Foundation Investigation, Butler Residence
			09/15/97	Lowney Associates	Supplemental Geotechnical Information, Butler Residence Guesthouse
			03/28/03	Lowney Associates	Updated Geotechnical Investigation
			04/01/04	Lowney Associates	Geotechnical Response Regarding Liquefaction, Proposed Residence and Caretakers Cottage.
			06/24/04	Triad/Holmes Associates	Engineering Review Comments for BP03-549
MONTICELLO COURT					
14A	4 Monticello Court	x	05/30/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Carport Conversion and Garage, Campbell Property
	6 Monticello Court	x	07/10/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Two Lot Subdivision
	7 Monticello Court	x	06/14/05	PGSoils, Inc.	Soils Conditions, Proposed Swimming Pool

			06/15/05	PGSoils, Inc.	Response to Town Comments
	8 Monticello Court	x	07/10/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Two Lot Subdivision
MOORE ROAD					
14A	137 Moore Road	x	10/01/82	Carl W. Garbe	Geotechnical Study Outline, Proposed Subdivision, 7-Acre Parcel
			03/28/84	Howard F. Donley & Associates	Geotechnical Investigation
			03/29/84	William Cotton and Associates	Geotechnical Review Sheet
			04/06/84	William Cotton and Associates	Preliminary Geologic Review, Lands of Havre, LD-279
			06/26/85	Brian Kangas Foulk & Associates	Grading & Drainage Plan for Jerry Bagnani
			07/30/85	Howard F. Donley & Associates	Plan Review, Proposed Single Family Residence, Lot 7, Parcel B
			08/20/85	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Bagnani, Land Division 279
			01/03/96	Nielsen Geotechnical Incorporated	Soil Report
			12/04/97	Nielsen Geotechnical Incorporated	Supplemental Soil Report
	389 Moore Road	x	01/24/06	Murray Engineers, Inc.	Engineering Geologic & Geotechnical Reconnaissance, Site Development Feasibility
	475 Moore Road	x	03/14/07	Ronig Engineers, Inc.	Geotechnical Investigation, Roberts Residence
	490 Moore Road	x	08/12/76	Terrasearch, Inc	Soil & Geologic Investigation, Three-acre Parcel
			06/01/77	Town of Woodside	Review Comments
			06/23/77	Terrasearch, Inc	Supplemental Soil & Geologic Investigation, Three-acre Parcel
			06/24/77	Terrasearch, Inc	Supplemental Foundation Recommendations, Three-acre Parcel
			07/08/77	Town of Woodside	Review of Responses to Town Comments
			06/26/00	Alliance Environmental & Soil Engineering	Geotechnical Investigation, Proposed Swimming Pool
			07/06/02	GeoForensics Inc.	Geotechnical Investigation, Landslide Mitigation
			10/03/02	GeoForensics Inc.	Drawing Revision, Douglass Property
			08/27/03	Ronig Engineers, Inc.	Geotechnical Investigation, Douglas Residence Addition
			01/29/08	Ronig Engineers, Inc.	Geotechnical Investigation, Douglas Deck, Swimming Pool, and Pool House
			10/01/08	GeoForensics Inc.	Alternative Pool Location, Douglas Property
			11/19/08	GeoForensics Inc.	Retaining Wall Recommendations, Douglas Property

			11/20/08	GeoForensics Inc.	Retaining Wall Recommendations (#2), Douglas Property
			02/12/09	Ronig Engineers, Inc.	Geotechnical Recommendations, Douglas Pool House
	505 Moore Road	x	03/13/90	Melvin R. Hill, Inc.	Soil and Foundation Investigation, Proposed Single Family Residence
			01/12/90	Cannis Consulting Engineers	Concept Map, Parcel 2, Vol. 25, PM 1, Lands of Cardellini
			01/12/90	Cannis Consulting Engineers	Vesting Tentative Map, Parcel 2, Vol. 25, PM 1, Lands of Cardellini
			05/24/90	Cannis Consulting Engineers	Response to Town Planning Comments - LD #311, with annotations
			10/24/90	Cannis Consulting Engineers	Vesting Tentative Map, Parcel 2, Vol. 25, PM 1, Lands of Cardellini
			12/04/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Cardellini Vesting Tentative Map, LD 311
			02/18/00	Nielsen Geotechnical, Inc.	Soil Report
			09/17/00	Nielsen Geotechnical, Inc.	Plan Review
			07/19/02	Nielsen Geotechnical, Inc.	Construction Report
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204249					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 515 MOORE ROAD - MOUNTAIN HOME COURT					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MOORE ROAD					
15	515 Moore Road	x	03/20/08	Murray Engineers, Inc.	Geotechnical Investigation, Mahoney Residence
	524 Moore Road	x	05/06/99	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Guest House and Access Driveway
			03/16/00	Michelucci & Associates, Inc.	Supplemental Letter, UBC Soil Profile Type and Related Criteria, Proposed Guest House
			06/07/00	Michelucci & Associates, Inc.	Supplemental Geotechnical Investigation, Proposed Guest House
	525 Moore Road	x	07/27/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Addition
	525 Moore Road		07/12/05	Romig Engineers, Inc.	Geotechnical Investigation, Soffel Barn
	540 Moore Road	x	06/12/98	Cleary Consultants, Inc.	Soil and Foundation Engineering Investigation, Home Renovation
	505? / 545 Moore Road	x	04/09/74	Berlogar, Long & Associates	Soils and Geologic Investigation, Proposed Two Parcel Single Family Residential Development, 13.5 Acre Parcel
			04/30/74	William Cotton and Associates	Review of Soils and Geologic Investigation Report - Sogemeire Property
			05/02/74	Town of Woodside	Review of Soils Report - Sogemeire Land Division & Remaining Conditions
			05/03/74	Town of Woodside	Comments on Geologic Investigation Report

			07/25/78	Berlogar, Long & Associates	Soils Investigation, Proposed Single Family Residence, Parcel 2
			11/06/78	William Cotton and Associates	Field Review of 7/25/78 report
			11/13/78	William Cotton and Associates	Cardellini - Conformity: Geotechnical Review
				Robert L. Klemmedson, Architect & Planner	Preliminary Plot Plan, Cardellini Residence
560 Moore Road	x		11/17/83	Brian Kangas Foulk & Associates	Tentative Parcel Map - Lands of Hayne
			03/28/84	Louis A. Richardson	Geologic Investigation. Lands of Hayne, APN 73-132-030
			03/28/84	William M. McMorrow & Associates	Geotechnical Engineering Investigation, Lands of Hayne - Proposed Lot Split
			04/20/84	William Cotton and Associates	Geotechnical Review Sheet
				William Cotton and Associates	Photographs
			04/16/84	William Cotton and Associates	Preliminary Geologic Review, Hayne Land Division 285
				Cody Associates	Grading/Drainage Plan, Grossi Pool & Tennis Court
			01/03/90	Earth Systems Consultants	Geotechnical Report, Grossi Residence
			01/24/90	Town of Woodside	Comments on Site Development #36 and Building #7674
			02/14/90	Town of Woodside	Comments on Site Development #36
			02/27/90	Earth Systems Consultants	Revised Geotechnical Report, Grossi Residence
			02/27/90	Earth Systems Consultants	Tennis Court and Swimming Pool Plan Review, Grossi Residence
				William Cotton and Associates	Geotechnical Review Sheet
			04/02/90	William Cotton and Associates	Geologic and Geotechnical Review
			08/16/90	Earth Systems Consultants	Revised Geotechnical Recommendations, Grossi Residence
			08/27/90	Earth Systems Consultants	Plan Review, Grossi Pool and Tennis Court
			05/17/96	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Bedroom Addition, Grossi House
595 Moore Road	x		7/0/82	Brian Kangas Foulk & Associates	Tentative Parcel Map - A Resubdivision of A Portion of Lot 7, with annotations
			10/01/82	Carl W. Garbe	Geotechnical Study Outline, Proposed Subdivision, 7 Acre Parcel
			11/30/82	William Cotton and Associates	Geotechnical Review Sheet
			12/08/82	William Cotton and Associates	Geologic Review, Harve, LD 279
			03/28/84	Howard Donley Asscoaites, Inc.	Geotechnical Investigation, Proposed Single Family Residence, Lot 7, Parcel B
			10/29/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
600 Moore Road	x		08/16/96	Nielsen Geotechnical Incorporated	Geotechnical Report
1142 Moore Road	x		4/0/87	Brian Kangas Foulk Associates	Site Plan and Orthophotograph

				William Cotton and Associates	Geotechnical Review Sheet
			06/17/87	William Cotton and Associates	Preliminary Geologic Review, Zygarewicz, Lot Line Adjustment #296
			03/25/98	Romig Consulting Engineers	Geotechnical Investigation, Machado Residence Pool & Pool House
	1144 Moore Road	x	09/22/95	Upp Geotechnology, Inc.	Geotechnical Investigation, Appurtenant Structures, Hirsch Property
			08/15/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation, New Pool Development, Hirsch Property
MOUNTAIN HOME COURT					
15	370 Mountain Home Court	x	02/22/00	Michelucchi & Associates, Inc.	Geotechnical Investigation, Proposed Creek Bank Stabilization, Sonsini Property
			08/30/00	Michelucchi & Associates, Inc.	Response to Town Geologist Comments
			11/01/00	Michelucchi & Associates, Inc.	Response to Town Geologist Comments
	372 Mountain Home Court	x	07/26/83	Perry R. Wood	Soil Percolation Tests, Proposed Parcel A, Subdivision of Parcel 072-190-790
			3/0/83	Edwin H. Smith	Preliminary Map, Resubdivision of Parcel 2A of Land Division Map No. 241, with annotations
			01/06/84	PSC Associates, Inc.	Geotechnical Engineering Investigation, Proposed Residence, Parcel A
			02/13/84	William Cotton and Associates	Geotechnical Review Letter
			02/14/84	William Cotton and Associates	Preliminary Geotechnical Review, Mayacamas, LD-282
			08/25/86	PSC Associates, Inc.	Grading and Foundation Plan Review, Proposed Georgakas Residence on Parcel A
			10/12/87	Perry R. Wood	Additional Soil Percolation Tests and Recommended Septic Drain Field, APN 072-190-790
			04/18/88	PSC Associates, Inc.	Proposed Driveway Retaining Wall, Georgakas Residence, Parcel A
			03/16/94	Rick Skierka	Lot Line Adjustment
	376 Mountain Home Court	x	06/22/94	Earth Systems Consultants	Updated Geotechnical Report, Proposed Landscape Improvements, Gilhuly Property
			03/31/08	Peters & Ross	Geotechnical Investigation, Gilhuly Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204250					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 181 MOUNTAIN HOME ROAD - 360 MOUNTAIN HOME ROAD					

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MOUNTAIN HOME ROAD					
15A	181 Mountain Home Road	x	12/17/02	Earth Mechanics Consulting Engineers	Geotechnical Investigation Report, Planned Residence
			09/03/04	Murray Engineers Inc	Geotechnical Services, Edwards Residence
			09/24/04	Murray Engineers Inc	Supplemental Information, Geotechnical Investigation, Edwards Residence
			02/22/06	Murray Engineers Inc	Supplemental Geotechnical Recommendations, New Residence
	186 Mountain Home Road	x	05/11/98	John Coyle & Associates, Inc.	Geologic Reconnaissance Letter Report
			05/13/98	Nielsen Geotechnical Incorporated	Soil Report
			07/08/98	John Coyle & Associates, Inc	Addendum Geologic Letter Report
			07/10/98	Nielsen Geotechnical Incorporated	Plan Review
			05/07/07	Murray Engineers, Inc.	Geotechnical Recommendations, New Tennis Court
	187 Mountain Home Road	x	07/21/94	Baker - CEG	Engineering Geologic Investigation, Possible Future Additions to Existing Residence
			07/31/94	GeoForensics, Inc.	Geotechnical Recommendations, Proposed Residential Additions
			06/16/95	Baker - CEG	Responses to Town Geologists' Review Comments on 7/21/94 Baker-CEG Report
			07/03/95	Michelucci & Associates, Inc.	Geotechnical Recommendations, Proposed Addition and Remodel Project
		x	12/22/11	PGSoils, Inc.	Geotechnical Investigation for Proposed Barn Replacement
	189 Mountain Home Road	x	02/04/08	Murray Engineers, Inc.	Geotechnical Investigation, Burke Residence
			09/30/09	Murray Engineers, Inc.	Geotechnical Report Update, New Residence
			11/30/09	Murray Engineers, Inc.	Supplemental Foundation Recommendations, New Residence
			10/04/10	Murray Engineers, Inc.	Supplemental Foundation Recommendations, New Residence
	190 Mountain Home Road	x	08/14/07	Lea & Braze Engineering, Inc.	Hydrology Study, Matta Residence
	225 Mountain Home Road	x	10/01/85	William Cotton and Associates	Geotechnical Review Sheet - Miller LD #291
			9/0/85	Reimer Associates	Tentative Map, with annotations
			10/09/85	William Cotton and Associates	Preliminary Geologic Review
			10/10/85	Town of Woodside	Subdivision Review Committee Comments
			09/26/13	Murray Engineers Inc	
			10/28/16	Murray Engineers, Inc.	Geotechnical Investigation, Miller Guesthouse

	240 Mountain Home Road	x	04/30/07	Murray Engineers, Inc.	Geotechnical Investigation, Yohanan Residence
			09/27/07	Lea and Braze Engineering, Inc.	Hydrology Study, Yohanan Residence
			10/10/07	Murray Engineers, Inc.	Supplemental Recommendations, Landscaping Improvements & Immersion Room Foundation
			04/07/09	Murray Engineers, Inc.	Geotechnical Investigation, White Residence
			12/07/10	Murray Engineers, Inc.	Geotechnical Investigation, New Residence
	246 Mountain Home Road	x	02/15/13	Earth Systems Pacific	Geotech Engineering Study-Proposed Two Story Residence
	255 Mountain Home Road		02/11/08	Earth Investigations	
			09/10/08	Earth Investigations	
	290 Mountain Home Road	x	02/25/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New garage and Patio, Millichap Property
	330 Mountain Home Road	x	07/11/00	Harlan Tait Associates	Geotechnical Investigation, Sherer Property
			03/18/03	Harlan Tait Associates	Geotechnical Investigation, Pettit Residence
			04/07/09	Murray Engineers, Inc.	Geotechnical Investigation, Dransfield/Bridger Residence
			08/03/09	Murray Engineers, Inc.	Geotechnical Plan Review, Dransfield/Bridger Residence
			03/18/03	Harlan Tait Associates	Geotechnical Investigation, Pettit Residence
	360 Mountain Home Road	x	06/01/99	Milstone Geotechnical	Geotechnical Investigation, Proposed Friedman Residence
			07/29/99	Milstone Geotechnical	Geotechnical Investigation, Proposed Residence
			10/08/01	Milstone Geotechnical	Geotechnical Investigation, Proposed Relocation and Remodel of Existing Residence
			07/10/02	Milstone Geotechnical	Geotechnical Report Update, Proposed Friedman Residence

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204273

Record Title & Contents

**GEOTECHNICAL REPORT FOR
375 MOUNTAIN HOME ROAD - 568 MOUNTAIN HOME ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MOUNTAIN HOME ROAD					
15B	375 Mountain Home Road	x	06/17/85	Lee Engineers	Existing Soils Report Confirmation Review and Recommendations
	382 Mountain Home Road	x	10/02/97	Earth Investigations Consultants	Soil & Foundation Investigation, Proposed Pool and Spa
			07/10/09	Romig Engineers, Inc.	Geotechnical Investigation, Ricci Guest House, Pool House and Stable/Barn
			12/18/19	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition

	384 Mountain Home Road		09/30/74	Geolabs - Northern California, Inc.	Foundation Engineering Investigation, Parcel 4 West of Mountain Home Road and North of Mountain Wood Lane
			07/13/81	JCP Geologists	Soil and Foundation Study, Proposed Homesite located on Mountain Home Road
	386 Mountain Home Road	x	05/18/87	Terrasearch, Inc.	Geotechnical Investigation, Proposed Residence and Addition to Existing Residence
			10/26/92	DES Architects / Engineers	Structural Calculations
			10/27/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Stables, Swimming Pool and Cabana
			07/25/01	GeoForensics Inc.	Geotechnical Investigation, Proposed Site Improvements
			08/21/02	GeoForensics Inc.	Geotechnical Report Supplement, Cook/Ostby Property
	411 Mountain Home Road	x	02/18/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
			07/10/06	Applied Earth Sciences Consultants	Geotechnical Investigation, Pool Pavilion, Pasquesi Family
	450 Mountain Home Road	x	09/17/01	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Residence
			11/26/02	Earth Mechanics Consulting Engineers	Geotechnical Consultation
			07/08/02	Earth Mechanics Consulting Engineers	Geotechnical Responses to Plan Review Comments
	460 Mountain Home Road	x	01/15/13	Murray Engineers, Inc	Geotech Investigation, Water Tower Building Improvements
			01/14/15	Lea & Braze Engineering, Inc	Hydrology Study
	515 Mountain Home Road	x	07/22/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Additions to Miller Residence
	550 Mountain Home Road	x	09/18/98	Romig Consulting Engineers	Geotechnical Investigation, Ludwig Residence Addition
			02/29/00	Romig Consulting Engineers	Supplemental Geotechnical Investigation, Ludwig Residence
	556 Mountain Home Road	x	08/08/08	Jo Crosby & Associates	Results of the Exploratory Fault Investigation
	560 Mountain Home Road	x	10/05/77	Purcell, Rhoades & Associates	Fault & Geotech Invest., Portion of Parcel 2, Land Division No. 129, Vol. 4, for Mr. Campbell
			11/18/77	Leighton and Associates	review of above
			12/02/77	Town of Woodside	Inter-Office Memo on Liquefaction Potential
			02/21/78	Leighton and Associates	Review of Land Division Map #240
			03/28/78	Town of Woodside	Report to the Planning Commission with several data attachments
			0/0/81	William Cotton and Associates	Geotechnical Review Sheet
			05/21/81	Edwin H. Smith	Land Division Map #240, Preliminary Map, Parcel 2 of Land Division Map # 129
			05/29/81	Town of Woodside	Cover Transmitting Earlier LD Correspondence
	566 Mountain Home Road	x	03/14/08	Jo Crosby & Associates	Geotechnical Investigation, Proposed Residential Development
			08/08/08	Jo Crosby & Associates	Results of the Exploratory Fault Investigation & plan
			10/29/08	Jo Crosby & Associates	Response to Town Review Comments

	568 Mountain Home Road	x	02/28/95	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Structure, Scoren Property
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204251					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 578 MOUNTAIN HOME ROAD - 925 MOUNTIAN HOME ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MOUNTAIN HOME ROAD					
16	578 Mountain Home Road	x	08/17/92	Cleary Consultants, Inc.	Geotechnical Investigation, Residence Additions
			06/08/93	Cleary Consultants, Inc.	Supplemental Geologic Letter, Residence Additions
			06/19/95	Cleary Consultants, Inc.	Geotechnical Investigation, New Pool and Associated Landscaping
			09/13/00	Cleary Consultants, Inc.	Geotechnical Investigation, Planned Guest House, Maintenance Building and Garage
	580 Mountain Home Road	x	12/18/96	Jo Crosby & Associates	Geotechnical Investigation, Planned Structures
			09/15/97	Jo Crosby & Associates	Response to Review Comments on 12/18/96 Report
			10/27/00	Jo Crosby & Associates	Fault Investigation, Tea House
	607 Mountain Home Road	x	06/08/93	Terrasearch, Inc.	Geotechnical Investigation, Proposed Additions
			08/04/93	Terrasearch, Inc.	Response to Town of Woodside Consultant's Review of 6/8/93 TI report
	618 Mountain Home Road	x	01/30/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Improvements
			12/15/04	Romig Engineers, Inc.	Landscape Retaining Wall, O'Leary Tennis Court
			08/12/04	Romig Engineers, Inc.	Supplemental Recommendations, New Swimming Pool
			05/23/05	Romig Engineers, Inc.	Geotechnical Recommendations, Generator Building and Pool Storage Building
			08/09/05	Romig Engineers, Inc.	Geotechnical Guidelines, Water Tank and Vault
	620 Mountain Home Road	x	11/19/96	Cleary Consultants, Inc.	Geotechnical Investigation, Residence Addition
			08/02/06	Cleary Consultants, Inc.	Geotechnical Investigation, Kitchen/Sitting Room Addition
	675 Mountain Home Road	x	04/08/01	GeoForensics Inc.	Limited Geotechnical Investigation, Proposed New Barn
	680 Mountain Home Road	x	10/00/97	Rick Skierka	Lot Line Adjustment
	725 Mountain Home Road	x	05/31/01	Signet Testing Labs, Inc.	Geotechnical Investigation
			03/06/02	Signet Testing Labs, Inc.	Review of Geotechnical Elements of Design Drawings, Gate House
			05/20/02	Signet Testing Labs, Inc.	Response to Comments From Town of Woodside, BP02-131, Gate House
			04/02/04	Applied Earth Sciences Consultants	Feasibility Assessment, Proposed Site Improvements

			05/05/04	D&M Consulting Engineers, Inc.	Geotechnical Investigation Report, New Buildings
			02/11/05	Applied Earth Sciences Consultants	Geotechnical Investigation, Tennis Court
			03/13/06	Applied Earth Sciences Consultants	Geotechnical Investigation and Recommendations, Proposed Gate House Maintenance Shed
			03/16/06	Applied Earth Sciences Consultants	Geotechnical Investigation & Recommendations, Proposed Tennis Court Trellis
			05/01/06	Applied Earth Sciences Consultants	Geotechnical Investigation & Recommendations, Proposed Pond Pavilion, Upper and Lower Stables
			06/19/06	Applied Earth Sciences Consultants	On-site Sewage Disposal Systems, Gatehouse Maintenance Shed and Lower Stable
			08/16/06	Applied Earth Sciences Consultants	Tennis Court Surface and Drainage Relative to Impervious Surface Calculations
745 Mountain Home Road	x		05/01/95	Upp Geotechnology, Inc.	Fault Investigation, King Property
			06/02/95	Upp Geotechnology, Inc.	Addendum Fault Location Investigation, King Property
			03/12/96	Applied Earth Sciences Consultants	Geologic, Geotechnical Engineering, Seismologic and Hydrologic Investigation, Estate Redevelopment Feasibility
			06/20/96	Applied Earth Sciences Consultants	Supplemental Data Regarding the Old King Estate Well Identified as K-1
			12/15/96	Applied Earth Sciences Consultants	Geotechnical Foundation Investigation and Recommendations
			?	TS Nowack Consultants	Hydrology Calculations
			12/06/99	Applied Earth Sciences Consultants	A Geotechnical Report for Pond Bottom Lining
			09/06/00	Applied Earth Sciences Consultants	Monitor Well Readings
			05/04/01	Applied Earth Sciences Consultants	Monitor Well Readings
			07/05/01	Applied Earth Sciences Consultants	Production and Monitor Well Location Map Transmittal
			01/30/02	Applied Earth Sciences Consultants	Monitor Well readings
			02/17/02	Town of Woodside	Conditions of Approval
			0/0/02	Town Of Woodside	Memo from Town Geologist to Planning Director
			07/07/02	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2001-2002 Report
			06/01/03	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2002-2003 Report

			12/19/03	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2003-2004 Report
			09/21/07	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2006-2007 Report
			10/24/08	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2007-2008 Report
			0/0/09	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2008-2009 Report
			10/15/10	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels, and Water Quality Analysis, Annual 2009-2010 Report
			08/20/20	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels, and Water Quality Analysis, Annual 2019-2020 Report
	750 Mountain Home Road	x	01/18/01	Romig Engineers, Inc	Geotechnical Investigation, Barnett Residence
	780 Mountain Home Road	x	09/22/88	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Additions and New Structures
			03/10/89	Raymond E. Lindahl, Inc.	Structural Calculations
				William Cotton and Associates	Geotechnical Review Sheet
			06/19/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Bossen Additions, PA #7285
	890 Mountain Home Road	x	06/21/91	Tejima and Associates, Inc.	Geotechnical Investigation Report, Proposed Accessory Quarters, Existing Declert Residence
	915 Mountain Home Road	x	03/25/05	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Carriage House Reconstruction
	925 Mountain Home Road	x	08/24/81	Purcell, Rhoades & Associates	Preliminary Soils Report, Assessor's Parcel 92-221-180, Sand Hill Road and Mountain Home Road
			12/02/83	J. V. Lowney & Associates	Geotechnical Investigation, Residence Addition
			12/09/93	Town of Woodside	Use of Permeable Asphalt at 925 Mountain Home Road
			08/27/96	Town of Woodside	Construction and Use of a Permeable Asphalt Tennis Court
				Town of Woodside	Deposit Account Print-Out dated 11/14/01
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204252					
Record Title & Contents					
GEOTECHNICAL REPORT FOR					
959 MOUNTAIN HOME ROAD - 215 MOUNTAIN WOOD LANE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MOUNTAIN HOME ROAD					
16A	959 Mountain Home Road	x	6/0/83	Edwin H. Smith	Preliminary Map, Land Division, Lands of Hoffman

			09/30/83	Louis A. Richardson	Geologic Investigation Report, Lands of Hoffman, APN 072-221-150
			09/30/83	Dunham & Associates	Soils Engineering Evaluation, Potential Building Site and Land Division, Lands of Hoffman
			02/03/84	William Cotton and Associates	Geotechnical Review Sheet
			02/07/84	William Cotton and Associates	Preliminary Geotechnical Review, Lands of Hoffmanm LD 284
			12/19/86	Perry R. Wood	Soil Percolation Tests, Lot 2
			12/27/86	Perry R. Wood	Soil Percolation Tests and recommended Septic Drainfield, Lot 2 (Parcel 072-221-410)
			01/29/87	Carl W. Grabe	Soils & Foundation Report, Proposed Residence, APN 072-221-150, Lot 2
			07/09/87	Carl W. Grabe	Soils & Foundation Report, Proposed Residence, APN 072-221-150, Lot 2
			08/03/87	Carl W. Grabe	Soils Test Data (Expansion, Strength), Proposed Residence
			08/07/87	Carl W. Grabe	Soils & Foundation Report, Proposed Swimming Pool
			08/07/87	Carl W. Grabe	Geotechnical Review of Plans, Proposed Residence
				William Cotton and Associates	Geotechnical Review Sheet
			07/02/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Tse, AP #4080
			09/11/97	William Cotton and Associates	Supplemental Geotechnical Review, lands of Tse, Permit #4080
			06/29/92	Louis A. Richardson	Proposed Raab Residence
			06/30/92	Lowney Associates	Geotechnical Investigation and Geologic Reconnaissance, Raab Residence
999 Mountain Home Road	x		09/30/83	Louis A. Richardson	Geologic Investigation Report, Lands of Hoffman (APN 072-221-150)
			06/29/92	Louis A. Richardson	Proposed Rabb Residence (update of 9/30/83 report)
			06/30/92	Lowney Associates	Geotechnical Investigation and Geologic Reconnaissance, Rabb Residence
1000 Mountain Home Road	x		04/07/86	Upp Geotechnology	Geotechnical Investigation, Lands of Kirkwood (APN 072-211-450)
			4/0/86	John S. Bradbury	Structural Calculations
			04/24/86	Lubin Associates, Architects	Site Plan
			05/19/86	William Cotton and Associates	Geotechnical Review Sheet
			05/22/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kirkwood Residential Reconstruction
			01/22/99	Applied Earth Sciences Consultants	A San Andreas Fault Investigation
			05/30/99	Applied Earth Sciences Consultants	A Geotechnical Foundation Investigation
			07/28/99	Applied Earth Sciences Consultants	A Geotechnical Review of Garage Plans, Phillips Residence
			09/14/99	Applied Earth Sciences Consultants	A Geotechnical Review , Phillips, Residence Remodel Plans

			02/23/01	Applied Earth Sciences Consultants	Geotechnical Construction Observation and Testing and Recent Site Review, Main Residence Remodel
			08/08/01	Applied Earth Sciences Consultants	Geotechnical Construction Observation and Recent Site Review, Residence Remodel
			01/03/19	Geosphere Consultants, Inc.	Limited Supplemental Geotechnical Study, Proposed Landscape Improvements
1005 Mountain Home Road	x		07/07/77	Perry R. Wood	Soil Percolation Rates in Areas Suitable for Septic Drain Facilities, Baldwin Property
			12/14/77	Leighton and Associates	daily report of site visit
			01/01/78	Frahm Elder Cannis	Preliminary Map, Meadowood (Lands of Baldwin)
			01/09/78	Terratech, Inc.	Geologic/Geotechnical Investigation, Lands of Baldwin
			02/10/78	Town of Woodside	Review of Preliminary Map, Meadowood, Landlock Corporation
			02/14/78	Town of Woodside	Summary of Subdivision Review Committee, Meadowood Subdivision
			03/10/78	Terratech, Inc.	Comments on Wood Report
			04/12/78	Leighton and Associates	Request for Additional Information
			04/19/78	Terratech, Inc.	Response to Request for Additional Information
			05/17/78	Leighton and Associates	Review of Preliminary Map, Meadowood, Landlock Corporation
			05/30/99	Applied Earth Sciences Consultants	A soil & geological investigation for reconstruction of single family residence
			09/16/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development, (APN 072-380-050)
1015 Mountain Home Road	x		02/21/86	William Cotton and Associates	Geotechnical Review Sheet
			02/25/86	William Cotton and Associates	Preliminary Geologic Review, Diller Antenna/Tower, Variance 392
			03/22/17	Earth Investigations Consultants	Geotechnical Investigation, Proposed Swimming Pool Remodel
1025 Mountain Home Road	x		various	Terratech, Inc.	various construction observation letters, Wendell Residence
			06/15/86	Perry R. Wood	Modified Septic Drainfield for New Residence
			06/26/95	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Kagle Property
			02/27/96	Town of Woodside / Kagles	Covenant and Agreement of pool house use
1035 Mountain Home Road	x				
1100 Mountain Home Road	x		09/12/05	Romig Engineers, Inc.	Geotechnical Review, Residence Improvements
			03/30/07	Town of Woodside	Memo on faulting issues and past development
			05/09/07	Murray Engineers, Inc.	Fault Location Investigation
			05/09/07	Town Of Woodside	Fault Location Investigation Review Letter
			02/19/08	Romig Engineers, Inc.	Geotechnical Investigation, Le Claire Residence Additions
MOUNTAIN WOOD LANE					
16A	155 Mountain Wood Lane	x	04/06/06	Murray Engineers, Inc.	Geotechnical Investigation, Hodge Residence

			09/18/06	Murray Engineers, Inc.	Geotechnical Investigation, Hodge Residence
			04/10/18	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Improvements
	160 Mountain Wood Lane	x	02/17/93	John W. Leonard, Civil Engineer	Preliminary Geologic and Geotechnical Engineering Study
			02/28/96	Lowney Associates	Geotechnical Investigation, Pool, Pool House, Guest House and Exercise Facility
			03/11/98	Nielsen Geotechnical Incorporated	Soil Report
			12/04/00	Nielsen Geotechnical Incorporated	Design Recommendations, Accessory Structure at the Tennis Court
			03/05/01	Nielsen Geotechnical Incorporated	Plan Review, Phase 4, Tennis Court Building
	205 Mountain Wood Lane		04/19/17	Murray Engineers, Inc.	Geotechnical Investigation, Marks Residence
	215 Mountain Wood Lane		08/18/85	JCP Geologists - Engineers	Soil and Foundation Study, Swimming Pool and Spa
			9/0/85	William Cotton and Associates	Geotechnical Review Sheet
			09/05/85	William Cotton and Associates	Preiminary Geologic Review, Watkins Pool
			01/29/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Watkins Pool
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204253					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 235 MOUNTAIN WOOD LANE - OAKFORD ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
MOUNTAIN WOOD LANE					
	235 Mountain Wood Lane	x	12/09/91	Lowney Associates	Geotechnical Investigation and Geologic Reconnaissance, Perkins Residence
			02/21/94	Applied Earth Sciences Consultants	Interm Summary Report, A San Andreas Fault Investigation
			03/24/94	Applied Earth Sciences Consultants	A San Andreas Fault Investigation
			07/14/94	Applied Earth Sciences Consultants	San Andreas Fault Investigations and Associated Setback Recommendations, Perkins Property
	245 Mountain Wood Lane		12/07/16	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Remodel
	255 Mountain Wood Lane	x	02/01/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Additions

			09/10/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Improvements
			09/29/09	Earth Investigations Consultants	Geotechnical Review, Proposed Relocations of Swimming Pool and Spa
			04/21/10	Earth Investigations Consultants	Geotechnical Review, Proposed Site Improvements
			06/06/17	Earth Investigations Consultants	Geotechnical Investigation, Proposed Guesthouse and Poolhouse
			08/30/18	Geosphere Consultants, Inc.	Geotechnical Update Study, Proposed Site Improvements
260 Mountain Wood Lane	x		11/16/01	Milstone Geotechnical	Geotechnical Investigation, Proposed Mohr Residence
			06/16/03	Milstone Geotechnical	Geotechnical Review, Garden Shed
			02/20/10	Milstone Geotechnical	Report Update, Geotechnical Investigation, Proposed Pool House and Swimming Pool, Mohr Residence
263 ? Mountain Wood Lane	x		09/02/86	Earth Systems Consultants	Soil Investigation, Addition to Caretaker's Quarters
			06/11/86	Peterson Architects	Site Plan, with annotations
			07/14/86	William Cotton and Associates	Geotechnical Review Sheet
			07/15/86	William Cotton and Associates	Preliminary Geologic review, Davis Addition to Cottage
			09/10/86	Earth Systems Consultants	Plan Review, Addition to Caretaker's Quarters
			10/02/86	William Cotton and Associates	Supplemental Geotechnical Review, Davis Addition to Cottage, AP #3149
265 Mountain Wood Lane	x		08/08/02	GeoForensics Inc.	Geotechnical Investigation, Proposed Barn, Liebeck Property
			11/07/02	GeoForensics Inc.	Retaining Wall Recommendations, Proposed Barn
NEUMAN LANE					
	15 Neuman Lane		12/17/15	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
17	25 Neuman Lane	x	11/26/02	Romig Engineers, Inc.	Geotechnical Investigation, New Residence
	45 Neuman Lane	x	10/20/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Pool, Game Room and Decks
			11/11/03	Earth Investigations Consultants	Geotechnical Plan Review, Proposed New Game Room and Decks
			03/18/04	Dodge Associates Surveying	Profile at Lands of Draeger
			07/12/17	Wayne Ting & Associates	Geotechnical Investigation, Proposed Addition
NOEL ROAD					
17	10 Noel Road	x	03/03/00	GeoQuest, Inc.	Geotechnical Investigation, Goldberg Residence Additions
			02/21/08	GeoQuest, Inc.	Preliminary Plan Review and Supplemental Recommendations, Goldberg Residence Backyard Additions
			02/21/10	ARA Engineering Company	Geotechnical Engineering Study, Proposed House Addition, Goldberg Residence
	11 Noel Road		0/0/89	William Cotton and Associates	Geotechnical Review Sheet - Anzelc
			08/24/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Anzelc Addition, PA #7409

			11/09/89	Baldwin-Wright, Inc.	Geotechnical Investigation
			12/09/89	Lea Engineering	Structural Calculations
			02/12/90	Baldwin-Wright, Inc.	Geotechnical Plan Review, Proposed Addition and Swimming Pool
			03/14/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Anzels Addition, PA #7409 and #7677
			03/21/90	Baldwin-Wright, Inc.	Response to Supplemental Geologic and Geotechnical Review, Proposed Addition and Swimming Pool
			04/12/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Anzels Addition, PA #7409 and #7677
			09/20/90	Baldwin-Wright, Inc.	Review of Revised Retaining Wall Design, Proposed Wall Behind the Addition
NORMANDY LANE					
17	115 Normandy Lane	x	04/10/11	Wayne Ting & Associates	Geotechnical Investigation, Proposed Pool House, Swimming Pool, and Pergola
			04/10/11	Wayne Ting & Associates	Geotechnical Investigation, Proposed Pool House, Swimming Pool, and Pergola
			4/10/11 (Revised)	Wayne Ting & Associates	Geotechnical Investigation, Proposed Pool House, Swimming Pool, and Pergola
			05/17/11	Wayne Ting & Associates	Respond to Town of Woodside
			06/10/11	Wayne Ting & Associates	Foundation Drain Recommendations
	120 Normandy Lane	x	07/09/07	Murray Engineers, Inc.	Geotechnical Investigation, Louie Residence
	140 Normandy Lane	x	08/16/00	Friar Associates, Incorporated	Geotechnical Investigation, Proposed Addition
	150 Normandy Lane	x	07/25/02	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Remodeling/Additions
			08/30/02	Town of Woodside	Engineering Geology Review Comments
			09/12/02	Cotton, Shires & Associates, Inc.	Geotechnical Engineering Review, Rosenthal Residence
			09/18/02	Town of Woodside	Engineering Geology Review Comments
			11/29/02	Carl W. Garbe, P.E.	Response to Review Comments
			02/02/09	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Landscaping/Pool
			03/16/09	Carl W. Garbe, P.E.	Pool Support
NORTHGATE DRIVE					
17	125 Northgate Drive	x	05/28/98	Nielsen Geotechnical Incorporated	Soil Report
	128 Northgate Drive	x	03/06/06	Romig Engineers, Inc.	Geotechnical Investigation, Heublein Residence
			11/30/06	Romig Engineers, Inc.	Supplemental Recommendations, Heublein Swimming Pool
NORTHRIDGE LANE					
17	110 Northridge Lane	x	05/09/06	Earth Investigations Consultants	Geotechnical Investigation
			05/01/07	Earth Investigations Consultants	Supplemental Recommendations, Landscape Wall

			07/27/07	Earth Investigations Consultants	Supplemental Geotechnical Recommendations, Proposed Trellis
	140 Northridge Lane	x	11/06/79	Purcell, Rhoades & Associates	Underpinning Recommendations
	150 Northridge Lane	x	10/28/91	Milstone Geotechnical	Geotechnical Investigation, Proposed Addition, Moseman Residence
				William Cottom and Associates	Geotechnical Review Sheet
			06/11/92	Milstone Geotechnical	Geotechnical Review, Moseman Residence
			12/22/15	Foundation Engineering Consultants Inc.	Geotechnical and Geological Engineering Report, Proposed New Residence
			06/12/92	William Cottom and Associates	Geologic and Geotechnical Review, Moseman Addition, BP-8797
	155 Northridge Lane	x	01/31/01	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residence
			06/24/04	Murray Engineers Inc	Geotechnical Evaluation, New Swimming Pool
			10/13/04	Murray Engineers Inc	Geotechnical Review of Plans, Swimming Pool and Spa
OAKFORD ROAD					
17	100 Oakford Road	x	05/25/06	Romig Engineers, Inc.	Geotechnical Investigation, Prael Residence
	115 Oakford Road	x	06/10/96	Romig Consulting Engineers	Geotechnical Investigation, Residence & Garage Addition
	215 Oakford Road	x	03/15/90	AC&H - Civi Engineers	Site Improvements - Lot 61 Woodside Hills - Unit 1
				William Cotton and Associates	Geotechnical Review Sheet
			08/08/96	Upp Geotechnology, Inc.	Geotechnical Investigation
			09/21/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Distressed Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204254					
Record Title & Contents					
GEOTECHNICAL REPORT FOR OAKHAVEN WAY - 227 OLD LA HONDA ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
OAKHAVEN WAY					
17A	7 Oakhaven Way	x	06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
	21 Oakhaven Way	x	05/31/00	Friar Associates, Incorporated	Geotechnical Investigation
			10/13/02	Hydro-Geo Consultants, Inc.	Preliminary Engineering Geologic Evaluation
	61 / 71 Oakhaven Way	x	07/05/83	William Cotton and Associates, Inc.	Geotechnical Investigation, Oakhaven Way Landslide
			09/22/83	Town - Owners	Agreement - Exhibit A
	71 Oakhaven Way	x	06/22/04	Buckley Engineering Associates	Geotechnical Investigation, Proposed Elevator Addition

			07/10/07	Wayne Ting & Associates, Inc.	Retaining Wall Recommendations
	81 Oakhaven Way		07/23/12	JF Consulting, Inc.	Geotechnical Study, New Deck Supports & Hot Tub Pad
	99 Oakhaven Way	x	05/13/75	Howard F. Donnelly & Associates	Foundation Investigation, Proposed Single Family Residence, Lot 6, Woodland Hills Unit 5
			08/11/77	Leighton and Associates	Review of 5/13/75 report
			10/04/77	Howard F. Donnelly & Associates	Supplemental Geotechnical Investigation, Proposed Single Family Residence, Lot 6, Woodside Hills Unit 5
			11/11/77		Site Photograph
			11/21/77	Leighton and Associates	Review of 10/4/77 report
			06/02/79	Gordon Dowsett, Architect	Site Plan with annotations
			06/27/79	Nordmo Associates	Consultation on Landslide, Lot 6, Woodside Hills Unit 5
			07/18/79	William Cotton and Associates	Geotechnical Review Sheet
			07/21/79	William Cotton and Associates	Geologic Review - Dowsett
			09/20/79	William Cotton and Associates	Geotechnical Review Sheet
OAKHILL DRIVE					
17A	7 Oakhill Drive	x	08/02/07	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
			09/24/15	Romig Engineers, Inc.	Geotechnical Investigation, Swimming Pool
	15, 20, 25 Oakhill Drive	x	09/09/82	Hallenbeck-McKay & Associates	Geotechnical Engineering Investigation, Landslide Oakhill Drive, Portions of Lots 17 (7), 8 (25), and 9 (20) - Tract 748
			01/03/83	William Cotton and Associates	Geotechnical Review Sheet
			01/18/83	William Cotton and Associates	Geologic Review, Landslide Repair
			10/03/83	Hallenbeck & Associates	Supplemental Recommendations, Oakhill Drive Landslide
			11/01/84	Hallenbeck & Associates	Engineering Observations of Landslide Winterization, Construction Sequence "A"
			5/0/1986	Tri State Engineering Company	Landslide Repair and Sections
			05/22/86	Hallenbeck & Associates	Review of Grading and Drainage Plan, Oakhill Drive Landslide Repair
			05/22/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Taylor Landslide Repair
			06/04/86	William Cotton and Associates	Supplemental Geotechnical Review, Taylor Landslide Repair
			07/24/86	Brobeck, Phleger & Harrison	Heeter/Grau, Rammner V. Taylor, et al.
			05/04/87	Hallenbeck & Associates	Engineering Observation of Grading, Landslide Repair, Oakhill Drive
	20 Oakhill Drive	x	12/07/87	Hallenbeck & Associates	Plan Review, 20 Oakhill Drive
			12/29/87	William Cotton and Associates	Geotechnical Review, Taylor Reconstruction, PA #4487, 20 Oakhill Drive
			01/18/88	W. & J. Lorell Structural Engineers	Structural Calculations, 20 Oakhill Drive
			03/01/88	Hallenbeck & Associates	Review of Plans, 320 Oakhill Drive

			03/15/88	William Cotton and Associates	Supplemental Geotechnical Review, Taylor Reconstruction, 20 Oakhill Drive PA #4487
			03/22/88	Hallenbeck & Associates	Review of Plans, 20 Oakhill Drive
			04/13/88	Hallenbeck & Associates	Engineering Observation of Pier Excavations, 20 Oakhill Drive
			04/18/88	Hallenbeck & Associates	Supplemental Letter, Engineering Observation of Pier Excavations, 20 Oakhill Drive
			03/25/08	Michelucci & Associates, Inc.	Geotechnical Evaluation, Proposed Addition to Residence
	25 Oakhill Drive	x	06/21/99	Soil Engineering Construction, Inc.	Geotechnical Evaluation and Letter Report, Stabilization of Failing Slope along Uphill Side of Entry Drive
			11/03/99	Earth Investigations Consultants	Geotechnical Investigation, Slope Repair of West Side of Driveway
			03/18/02	Earth Investigations Consultants	Geotechnical Evaluation, Landslide on West Side of Driveway
			10/21/02	Earth Investigations Consultants	Geotechnical Evaluation, Landslide on West Side of Driveway, Stability Analysis
			01/10/03	Earth Investigations Consultants	Geotechnical Plan Review, Repair of Landslide Complex on West Side of Driveway
			07/09/07	Earth Investigations Consultants	Geotechnical Update, Proposed Slope Stabilization, Upslope of Driveway
			03/24/10	Earth Investigations Consultants	Geotechnical Update, Proposed Landscape Terracing, Graham Residence
			03/11/14	Earth Investigations Consultants	Geotechnical Investigation, Proposed Lap Pool
	30 Oakhill Drive	x	08/17/71	Blomquist Engineering	Geology Study, Lot 10, Partition Road
			07/01/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Addition
			08/28/86	Elisabeth Vespremi, Architect	Site Plan, with annotations
			09/02/86	William Cotton and Associates	Geotechnical Review Sheet
			09/15/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Rammler Additions, AP#3269
			10/27/86	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation Plan, Proposed Garage and Addition
			11/25/86	William Cotton and Associates	Supplemental Geotechnical Review, Rammler Garage/Attic, AP#3269
OLD LA HONDA ROAD					
17A	Thornewood O S Preserve	x	10/09/07	Timothy C. Best, CEG	Engineering Geologic Revoew, Thornewood Ope Space Preserve Trail Upgrades
	8 Old La Honda Road	x	02/21/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Carport and Second-Story Studio
	11 Old La Honda Road	x	09/01/07	Earth Sciences Consultants	Geotechnical Investigation, Front East Deck and South Addition (APN 075-134-120)
	now 29 Preston Road		01/09/09	Romig Engineers, Inc.	Geologic Slope Evaluation

			01/26/09	Earth Sciences Consultants	Geotechnical Report Update and Seismic Factors, Front East Deck and South Addition
			08/10/10	Romig Engineers, Inc.	Geotechnical Recommendations, Site Retaining Wall
			03/18/11	Romig Engineers, Inc.	Geotechnical Investigation, 2,500 Gallon Water Tanks and Stabilization Wall
12 Old La Honda Road	x		08/06/90	Hydro-Geo Consultants, Inc.	Geotechnical Evaluation, Single-Family Residence
				William Cotton and Associates	Geotechnical Review Sheet
				William Cotton and Associates	Copy of Plot Plan with annotations
			04/08/92	Hydro-Geo Consultants, Inc.	Geologic Considerations, Improvements
			04/17/92	Hydro-Geo Consultants, Inc.	Geologic Considerations, Improvements
			05/11/92	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Gilchrist Guest House, 8708 and 8709
			05/29/92	Hydro-Geo Consultants, Inc.	Response to 5/11/92 Review Comments from WCA, Proposed Gilcrest Guest House
			06/26/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Gilchrist Guest House, 8708 and 8709
20 Old La Honda Road	x		07/24/87	Upp Geotechnology, Inc.	Geotechnical Investigation of Two Parcels (APN 075-134-210 & 220)
			06/02/87	Upp Geotechnology, Inc.	Limited Geotechnical Investigation of Landslide (APN 075-134-210 & 220)
			07/12/91	Upp Geotechnology, Inc.	Preliminary Geotechnical Investigation, Single-Family Homesite (APN 075-134-210 & 220)
			07/17/91	Upp Geotechnology, Inc.	Supplemental Information, Preliminary Geotechnical Investigation, Modified Slope Stability Analysis
			08/27/92	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Access Road Bridge, Slope Stabilization and Landslide Repair Options
			10/30/92	Upp Geotechnology, Inc.	Soil and Foundation Investigation, New Residence and Garage, Lands of Sedgwick
133 Old La Honda Road	x		05/03/79	PSC Associates, Inc.	Geologic and Soil Engineering Feasibility Investigation, Proposed Residence, 6-Acre Parcel (Lots 23-33), Old La Honda and Home Roads
			06/07/79	William Cotton and Associates	Geotechnical Review Sheet
			06/18/79	William Cotton and Associates	Geologic review
			07/24/90	Bay Area Geotechnical Group	Geotechnical Evaluation of Existing Graded Area with Retaining Walls
145 Old La Honda Road	x		08/31/77	Purcell, Rhoades & Associates	Results of Additional Subsurface Investigation, Proposed Residence
			05/02/79	PSC Associates, Inc.	Geotechnical Investigation Report, Proposed Residence Between Old La Honda and Home Road (Lots 34, 36 and 38) - APN 75-283-020
			06/07/79	William Cotton and Associates	Geotechnical Review Sheet
			06/18/79	William Cotton and Associates	Geologic Review, Lands of Design Developers
			07/03/79	PSC Associates, Inc.	References for 5/2/79 report

			10/03/79	PSC Associates, Inc.	Supplemental Stability Analyses, Proposed Residence Between Old La Honda and Home Roads (Lots 34, 36 & 38)
			12/17/79	William Cotton and Associates	Review of Supplemental Stability Analysis Report
			02/05/80	PSC Associates, Inc.	comments on responsibility for unpermitted grading
			04/04/80	J. Michael Cleary and Associates	Soil and Geologic Investigation, Lands of Design Developers (APN 075-283-020)
			02/23/81	F.R. Strathdee & Associates	Tredwell Property Improvements APN 075-283-020
			04/24/81	Perry R. Wood	Soil Percolation Tests, Lots 34, 36 and 38 (Parcel 075-283-020)
				F.R. Strathdee & Associates	Residence for Matt Younger, with annotations
			06/01/81	F.R. Strathdee & Associates	Yreadwell-Younger Variance Request
			06/10/81	Cleary Consultants, Inc.	Review of Development Plans, Lands of Design Developers
			07/24/81	Perry R. Wood	Soil Percolation Tests, Lots 34, 36 and 38, Parcel 075-283-020, Between Pld La Honda Road and Home Road
			08/11/81		Structural Calculations for Bridge and Retaining Walls
			08/11/81	Cleary Consultants, Inc.	Review of Foundation Plans, Driveway Bridge, Lands of Design Developers
			06/17/82	Cleary Consultants, Inc.	Site Inspection, Lands of Design Developers
			07/18/83	Cleary Consultants, Inc.	Soil Engineering Services During Installation of Drilled Pier Foundations, Younger Residence
			09/26/83	Cleary Consultants, Inc.	Soil Engineering Services Durig Backfilling of Retaining Wall at Home Road, Younger Residence,
			09/26/84	William Cotton and Associates	Soil Engineering Services Durig Backfilling at Rear of Home, Younger Residence,
			08/21/86	Cleary Consultants, Inc.	Geotechnical reconnaissance of House and Property
			09/25/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Lands of McSweeney
			03/08/07	Earth Investigations, Inc.	Geotechnical Investigation, Proposed Driveway Rehabilitation
			06/15/07	Holmes Cully	Structural Calculations
			12/01/07	Holmes Cully	Supplemental Structural Calculations
			03/12/08	Holmes Cully	Supplemental Structural Calculations
			03/13/08	Earth Investigations, Inc.	Geotechnical Plan Review
			05/01/08	Peter T. Mason	Home Road Photographs
171 Old La Honda	x		12/21/76	Purcell, Rhoades & Associates	Soil and Geologic Investigation, Lots 34, 36, 38, Portola Hills Subdivision
			01/03/77	Bill Campbell	General Conditions and Specifications
			02/07/77	Purcell, Rhoades & Associates	Revised Soil and Geologic Investigation, Lots 34, 36, 38, Portola Hills Subdivision

			02/11/77	Purcell, Rhoades & Associates	Addendum to Soil and Geologic Investigation for Tim O'Brian
			03/10/77	Leighton and Associates, Inc.	Review
			03/18/77	Purcell, Rhoades & Associates	Revised Site Plan
			03/29/77	Leighton and Associates, Inc.	Comments on Revised Site Plan
			03/31/77	Purcell, Rhoades & Associates	Discussion of Conclusions and Recommendation by Leighton and Associates, Inc. dated March 29, 1977
			04/07/77	Leighton and Associates, Inc.	Review Comments
			04/29/77	Purcell, Rhoades & Associates	Results of Additional Subsurface Investigation for Tim O'Obrian
			06/07/77	Leighton and Associates, Inc.	Review Comments
			08/31/77	Purcell, Rhoades & Associates	Results of Additional Subsurface Investigation and Summary Conclusions, Geotechnical Investigation, Proposed residence
			09/14/77	Leighton and Associates, Inc.	Review Comments
			04/17/78	Sigrid Lorenzen Rupp, Architect	Letter to Leighton and Associates, Inc.
207 Old La Honda Road	x		05/01/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Foundation Improvements, Mason-Dare Residence
			11/25/03	ASMO Consulting Engineers	Geotechnical Evaluation, Driveway Retaining Walls
			04/22/04	JF Consulting, Inc.	Geologic Letter Report, Proposed Driveway Retaining Walls, Lands of Mason
			06/04/04	ASMO Consulting Engineers	Response to Toen of Woodside Comments, Driveway Relocation and Associated Retaining Walls
			06/05/07	Earth Investigations Consultants	Geotechnical Investigation Up date, Proposed Parking Area & Garage Addition, Mason-Dare Residence
			06/05/07	Earth Investigations Consultants	Response to Town Comments, Proposed Parking Area & Garage Addition, Mason-Dare Residence
227 Old La Honda Road	x		02/06/84	Ronald A. Meschino	Caisson Design
					Photographs of Landslide
			05/15/84	William M. McMorrow	Geotechnical Engineering Evaluation, Landslide Stabilization-Retaining Wall, Brugos Property
			06/05/84	William Cotton and Associates	Landslide Stabilization - Retaining Wall Evaluation, Brugos Property
			08/13/84	William M. McMorrow	Supplemental Information Requested by Cotton & Associates, Landslide Stabilization-Retaining Wall, Brugas Property
			08/30/84	William Cotton and Associates	Landslide Stabilization - Retaining Wall Evaluation, Brugos Property
			09/04/84	William Cotton and Associates	Landslide Stabilization - Retaining Wall Evaluation, Brugos Property
			09/30/93	JCP Geologists - Engineers	Soil and Foundation Services for Proposed Swimming Pool
			05/14/96	Louis A. Richardson	Engineering Geologic Considerations, Residential Addition at Sinclair Residence
			05/22/96	William Cotton and Associates	Geotechnical Review Sheey

			06/04/96	William M. McMorrow	Geotechnical Engineering Evaluation & Plan Review, Single-Family Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204255					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 245 OLD LA HONDA ROAD - 736 OLD LA HONDA ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
OLD LA HONDA ROAD					
18	245 Old La Honda Road	x	10/11/84	Earth Sciences Associates	Existing/Proposed Retention Pond
			10/19/84	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Ordemann Dam Reconstruction, APN: 75-240-14
			06/03/85	Earth Sciences Associates	Proposed Retention Pond, Ordemann Property
			06/13/85	Atkinson Farasyn	Violations of the Woodside Municipal Code
			07/12/85	Atkinson Farasyn	Comments to Town Geologist
			07/22/85	Herbert Frahm	Transmittal of Revised Plan
			08/23/85	Herbert Frahm	Report on History of Dam and Effect of Dam Failure
			09/23/85	Michael T. Dukes	Ordemann Dam Reconstruction, APN #75-240-14
			10/10/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Ordemann Dam Reconstruction, APN 075-240-14
			10/25/85	Atkinson Farasyn	Letter to Mr. Ordemann
			12/20/85	Frahm Elder abd Cannis	Response to 10/10/85 WCA Comments
			04/18/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Ordemann Dam Reconstruction, APN 075-240-14
			11/18/87	County of San Mateo, Department of Health Services	Comments of Proposed Dam Reconstruction
			09/21/92	Hydro-Geo Consultants, Inc.	Preliminary Geological Evaluation, Two Proposed Single-Family Residence Sites
			01/15/96	Applied Earth Investigations Consultants	Geotechnical Investigation to Mitigate a Small Landslide at the Access Driveway, Schilling Estate
			09/03/09	Buckley Engineering Associates, Inc.	Geotechnical Investigation, Proposed Solar Array
			12/14/10	Buckley Engineering Associates, Inc.	Geotechnical Investigation Update, Proposed Solar Array

	302 Old La Honda Road	x	01/30/89	MS Geotechnical Consultants, Inc.	Geotechnical Engineering Study, Byrnes Residence
			10/19/89	William Cotton and Associates	Supplemental Geologic Review, Byrnes, Variance 451
	320 Old La Honda Road	x	10/07/96	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Single-Family Residence Between 302 and 360 Old La Honda Road
	355 Old La Honda Road		10/11/12	Romig Engineers, Inc.	Geotechnical Investigation, Shimer-Shelton Residence Addition
	360 Old La Honda Road	x	05/04/87	Applied Earth Investigations Consultants	Soil and Geologic Investigation, Single-Family Residence on APN 075-151-010
	370 Old La Honda Road	x	04/28/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Elder & Noble, Portion of Lot 12 - APN 075 151 020
			04/24/87	Questa Engineering Corporation	Sewage Disposal Site Plans, Old La Honda Road, APN 075-151-020
				William Cotton and Associates	Geotechnical Review Sheet
			12/08/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Elder, Variance #418
			06/27/89	Upp Geotechnology, Inc.	Addendum, Geotechnical Investigation, Proposed Water Tank, Lands of Elder/Noble
			08/30/89	Upp Geotechnology, Inc.	Review of Plan Revisions, Elder & Noble Residence
	375 Old La Honda Road	x	08/01/68	Crosby & Associates	Soil Investigation, Proposed Building Site
	385 Old La Honda Road	x	12/01/77	Cooper-Clark & Associates	Engineering Geologic Investigation, Lots 112 and 117, Subdivision No. 2, Woodside Country Club
			12/22/77	Cooper-Clark & Associates	Report to Mr. William Patrick
			12/27/77	Town of Woodside	Review of Cooper-Clark & Associates reports
			04/19/07	Earth Investigations Consultants	Geotechnical Investigation, Proposed Deck Replacement
	400 Old La Honda Road	x	06/17/75	Dunham & Associates	Soil Investigation, Proposed House, Woodside Country Club Properties (APN 075-261-010)
			02/02/77	Leighton and Associates	Review of 6/17/75 DA report
			02/21/77	Richard E. Rowland	Geologic Evaluation, Old La Honda Road Property
			03/07/77	Dunham & Associates	Plan Review, Proposed Home, Woodside Country Club Properties #2
			03/09/77	Leighton and Associates	Review of 2/21/77 RER report
			10/21/81	William Cotton and Associates	Property, with annotations
			11/09/81	William Cotton and Associates	Geotechnical Review Sheet
			11/30/81	William Cotton and Associates	Preliminary Geologic review, Corcoran - Proposed Guest House
			05/21/82	William Cotton and Associates	Geotechnical Review Sheet
			06/01/82	William Cotton and Associates	Geologic Review
			07/07/82	Site Characteristics Inc.	Geotechnical Investigation, Corcoran Guest House
				William Cotton and Associates	Figure 3 from SCI report, with annotations
			07/29/82	William Cotton and Associates	Geologic Review of SCI report

			10/16/03	Nielsen Geotechnical, Incorporated	Slope Stability Analysis
408 Old La Honda Road	x	08/25/89		Hydro-Geo Consultants, Inc.	Geotechnical Evaluation, Proposed Garage/Pool Site
				William Cotton and Associates	Geotechnical Review Sheet
		09/22/89		William Cotton and Associates	Preliminary Geologic Review. Mathews Car Barnm VAR #467
		11/01/89		Hydro-Geo Consultants, Inc.	Letter on Revised Site and Plot Plan
		11/01/89		William Cotton and Associates	Memo on Revised Site and Plot Plan
		06/11/90		Hydro-Geo Consultants, Inc.	Review of Plans and Specifications
		03/17/06		Murray Engineers, Inc.	Geotechnical & Engineering Geologic Investigation, Mathews Residence Improvements
431 Old La Honda Road	x	01/15/80		Terratech, Inc.	Geologic and Geotechnical Investigation, Lands of Eldredge (APN 075-272-030)
442 Old La Honda Road	x	04/22/77		Purcell, Rhoades & Associates	Soil and Geologic Investigation (APN 076-120-060)
		05/11/77		Town of Woodside	Review
		05/13/77		Purcell, Rhoades & Associates	Reply to Comments in Town Review
		05/18/77		Town of Woodside	Review of Reply to Comments in Town Review
		06/14/77		Purcell, Rhoades & Associates	Reply to Review of Reply to Comments in Town Review
		06/23/77		Town of Woodside	Review of Reply to Review of Reply to Comments in Town Review
		03/29/00		Terrasearch, Inc.	Preliminary Geologic Investigation, Recent Landslide
		08/08/02		Terrasearch, Inc.	Grading Plan Review
464 Old La Honda Road	x	12/17/86		Upp Geotechnology	Preliminary Geotechnical Investigation, Lands of Bolton (APN 076-102-040)
503 Old La Honda Road	x	02/04/11		Murray Engineers, Inc.	Geotechnical Evaluation, Thirty-Five Slopes, Serrurier Property
		06/17/11		Murray Engineers, Inc.	Geotechnical Investigation, Serrurier Residence
		07/06/11		Murray Engineers, Inc.	Supplemental Information, Proposed Demolition, Serrurier Property
		09/16/11		Murray Engineers, Inc.	Supplemental Information, Serrurier Residence
		09/23/11		Murray Engineers, Inc.	Supplemental Information, Serrurier Residence
548 Old La Honda Road	x	04/24/89		Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Residence, NW Corner APN 076-110-040
		10/10/91		Geotechnical Engineering Systems Co,	Slope Stability Analysis, Shaikh Residence
		10/19/91		Hydro-Geo Consultants, Inc.	Landslide Evaluation, Proposed Single-Family Residence Site (APN 076-110-040)
		02/18/92		Hydro-Geo Consultants, Inc.	Landslide Evaluation (APN 076-110-040)
		07/15/93		Hydro-Geo Consultants, Inc.	Response to Town Review, Proposed New Single-Family Residence
		10/27/94		Earth Investigation Consultants	Geotechnical Services, Proposed House

	560 Old La Honda Road	x	03/20/91	Carl W. Garbe, P.E.	Earthwork, Recreation Area
			01/21/92	Carl W. Garbe, P.E.	Supplemental Geotechnical Report, Recreation Area Earthwork
			09/20/93	Louis A. Richardson	Engineering Geologic Investigation, Existing Riding Ring
			10/25/93	Haro, Kasunich and Associates, Inc.	Slope Stability Analysis, Existing Riding Ring
			01/25/94	Louis A. Richardson	Review of Site Plan, Drainage and Grading for Riding Ring
	572 Old La Honda Road	x	02/13/02	Romig Engineers, Inc.	Geotechnical Investigation, White Residence Additions
	580 Old La Honda Road	x	01/19/81	J. Michael Cleary and Associates	Geotechnical Investigation, Lots 26, 27 & 29 (Map of Portola Hills, Book 7, Page 20, San Mateo County)
			1/0/81	Paul E. Nowack and Assoaites, Inc.	Grading Plan Lot No. 23, a Portion of Lot 29, with annotations
			02/27/81	Clearly Consultants, Inc.	Review of Grading Plan, Lot No. 29, Map of Portola Hills
			05/05/81	William Cotton and Associates	Geotechnical Review Sheet
			07/09/81	Clearly Consultants, Inc.	Geotechnical Plan Review, Lot 29, Map of Portola Hills
			12/13/83	Clearly Consultants, Inc.	Site Reconnaissance and Geotechnical Update, Lot 25, Lot 27, and Lot 29
			12/23/83	William Cotton and Associates	Geologic Review - Lands of Szabo, BPA 912
			09/12/85	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Szabo, BPA 912
	590 Old La Honda Road		07/25/17	Murray Engineers, Inc.	Geotechnical Investigation, Melanson Site Improvements
	630 Old La Honda Road	x	09/26/78	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Percolation Rate Testing, Lot Nos. 320 and 321, Woodside Country Club Subdivision
			07/30/79	Fisher Land Surveys	Topographic Map, with annotations
			08/20/79	William Cotton and Associates	Geotechnical Review Sheet
			11/01/79	Walter E. Eagle, Architect	Gradign Plan, with annotations
			01/16/80	Purcell, Rhoades & Associates	Soils/Foundation Investigation - Lots No. 320 and 321
			01/29/80	Town of Woodside	Review of Revised Site Grading Plan, (Lencioni/Hayes)
			02/22/80	William Cotton and Associates	Review - Lencioni Conformity/Variance 255
			03/02/81	Purcell, Rhoades & Associates	Plan Review, Lots 320 and 321, Woodside Country Club Subdivision
			03/05/80	William Cotton and Associates	Review of 1/16/80 PR&A report
			03/21/81	William Cotton and Associates	Geologic Review
			04/15/81	Purcell, Rhoades & Associates	Plan Review, Lots 320 and 321, Woodside Country Club Subdivision
			04/22/81	Purcell, Rhoades & Associates	Plan Changes - Lots 320 and 321, Woodside Country Club Subdivision
			04/27/81	William Cotton and Associates	Geologic Review
				Town of Woodside	Variance 255, Resolution 1980--121
	632 Old La Honda Road	x	02/24/04	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Thornton Additions
			08/12/04	Pacific Geotechnical Engineering	Retaining Wall Recommendations, Thornton Property

	736 Old La Honda Road	x	09/20/02	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Barn
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204256					
Record Title & Contents					
GEOTECHNICAL REPORT FOR OLIVE HILL ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
OLIVE HILL ROAD					
18A	131 Olive Hill Road	x	07/28/89	Upp Geotechnology, Inc.	Fault Location Investigation, Addition to Corfman Residence
			06/06/90	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Addition to Residence
				William Cotton and Associates	Geotechnical Review Sheet
			11/30/93	Harlan Tait Associates	Job Memorandum
			05/27/94	Upp Geotechnology, Inc.	Supplemental Recommendations. Addition to Corfman Residence
			06/03/94	Upp Geotechnology, Inc.	Supplemental Recommendations, Concrete Slab for Sunroom Addition to Corfman Residence
			10/16/03	Nielsen Geotechnical Incorporated	Geotechnical Recommendations
			07/01/04	Murray Engineers, Inc.	Geotechnical Services, Landscaping Improvements
			08/07/04	Murray Engineers, Inc.	New Engineer of Record, Corfman Swimming Pool
			01/11/16	Redwood Geotechnical Engineering, Inc.	Geotechnical Investigation, Addition to Smith Beal Residence
	140 Olive Hill Road	x	11/20/07	Connell Geotechnical, Inc.	Geotechnical Investigation, New Residence
	150 Olive Hill Lane	x	09/01/87	Earth Syatems Consultants	Foundation Recommendations, Proposed Addition to Residence
			01/21/04	Nielsen Geotechnical, Inc.	Geotechnical Recommendations
			02/01/05	Murray Engineers Inc.	Geotechnical Services, Bibbler Residence Improvements
	160 Olive Hill Road		08/09/88	Freeman-Kern Associates	Geotechnical Investigation, Addition to Existing House
		x	05/21/00	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed House Additions
	164 Olive Hill Lane	x	10/21/91	Hallenbeck & Associates	Geotechnical Engineering and Geologic Hazard Investigation, Proposed 2nd Story Addition

			06/09/93	Hallenbeck & Associates	Addendum to Geotechnical Engineering Evaluation and Geologic Hazard Investigation
165 Olive Hill Lane	x		01/04/94	Upp Geotechnology, Inc.	Fault Location Investigation
			01/14/94	Upp Geotechnology, Inc.	Supplemental Information, Fault Location Investigation
			01/25/94	Upp Geotechnology, Inc.	Supplemental Information, Site Plan Modification, Fault Location Investigation
			01/31/14	Murray Engineers, Inc.	Geotechnical Investigation, Ragatz Residence Improvements
166 Olive (Tree) Hill Lane	x		03/05/08	Romig Engineers, Inc.	Geotechnical Investigation, Dutta Residence
166 Olive Hill Lane			11/02/17	Romig Engineers, Inc.	Geotechnical Investigation, Larson Pool House
170 Olive Hill Lane	x		01/09/97	Steven F. Connelly	Fault Investigation, Conway Property
			01/17/97	Nielsen Geotechnical Incorporated	Soil Report
			01/29/96	Earth Investigations Consultants	Fault Investigation Waiver, Proposed improvements
187 Olive Hill Lane	x		11/20/97	Nielsen Geotechnical Incorporated	Geotechnical Report
210 Olive Hill Lane	x		01/17/74	Berlogar, Long & Associates	Soil Investigation, Proposed Single Family Residential Development, 3+/- Acre Parcel
			06/11/79	J. Michael Cleary and Associates	Soil and Foundation Investigation, Demonet House Addition
			05/19/00	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Wang/Pope
			06/03/05	Upp Geotechnology, Inc.	Supplemental Recommendations, Proposed Swimming Pool and Associated Improvements, Wang Property
214 Olive Hill Lane			08/31/15	Murray Engineers, Inc.	Geotechnical Investigation, Faul Landscape Improvements
222 Olive Hill Lane	x		05/21/99	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence, Rohlen Property
			04/24/02	GeoForensics, Inc.	Basement Design Parameters, Proposed New Residence
			07/17/00	GeoForensics, Inc.	Response to Town Review, Proposed New Residence
			12/20/10	GeoForensics, Inc.	Geotechnical Investigation, Motor Court Expansion
			12/22/10	Murray Engineers, Inc.	Geotechnical Investigation, New Swimming Pool
			06/01/11	Murray Engineers, Inc.	Geotechnical Investigation, New Pool House
			06/30/11	BKF	Storm Drain Design Discussion
			08/29/11	Murray Engineers, Inc.	Response to Town Geology Division Review Comments, New Swimming Pool & Pool House
300 Olive Hill Lane	x		07/24/01	Charles H. Hartsog	Soils and Geotechnical Report
			04/17/02	Charles H. Hartsog	Soils and Geotechnical Report
			05/28/03	Charles H. Hartsog	Soils/Geotechnical Report, Generator Structure

	306 Olive Hill Lane	x	01/18/00	Nielsen Geotechnical Incorporated	Soil Report
			04/28/08	Murray Engineers, Inc.	Supplemental Recommendations, New Swinning Pool
			06/09/08	Murray Engineers, Inc.	Alternative Swimming Pool Recommendations, New Swimming Pool
			02/23/09	Murray Engineers, Inc.	Alternative Exterior Slab Design Criteria, New Swimming Pool
	307 Olive Hill Lane	x	06/11/98	Steven F. Connelly	Geologic Investigation, Proposed Remodel, Roux Residence
			06/17/98	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Additions and Carport
	308 Olive Hill Lane	x	10/31/90	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Foundation Repair, Wiegand Residence
			04/04/05	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Barn
			10/30/15	Murray Engineers, Inc.	Geotechnical Investigation, Larson Residence
	310 Olive Hill Lane	x	08/29/77	Purcell, Rhoades & Associates	Reconnaissance Soil and Foundation Investigation and Recommendations, Foundation Design, Lot 5
			05/11/82	William Cotton and Associates	Geotechnical Review Sheet
			05/13/82	William Cotton and Associates	Geotechnical Review - Boles Pool
			04/14/82	Purcell, Rhoades & Associates	Pool Plan Review, Boles Residence
	500 Olive Hill Lane	x	12/05/80	PSC Associates, Inc.	Soil Engineering Investigation, Proposed House Addition
			10/08/93	Earth Investigations Consultants	Geotechnical Evaluation, Proposed Additions to Existing House

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204257

Record Title & Contents

**GEOTECHNICAL REPORT FOR
ORCHARD HILL ROAD - PARTITION ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
ORCHARD HILL ROAD					
19	15 Orchard Hill Road	x	07/30/86	Joseph M. Bauer, Structures & Engineering	Structural Calculations, Proposed Kilmer Guest Cottage
			06/30/86	JCP Geologists Engineers	Soil and Foundation Services, Proposed Guest House
			08/11/86	JCP Geologists Engineers	Addendum to Soil and Foundation Services, Proposed Guest House
			08/28/86	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation Plan, Proposed Guest House
			10/15/86	William Cotton and Associates	Geotechnical Review Sheet

			10/20/86	JCP Geologists Engineers	Addendum to Soil and Foundation Services, Proposed Guest House
			11/03/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kimler Guest House
OTIS AVENUE					
19	103 Otis Avenue	x	02/27/07	Romig Engineers, Inc.	Geotechnical Investigation, Lock Residence
	111 Otis Avenue	x	01/14/02	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Foundation Improvement
	128 Otis Avenue	x	10/03/74	Dunham and Associates	Soil Investigation, Proposed Home, Woodside Glens Unit 1
			01/15/86	Dunham & Associates	Proposed Improvements
			02/03/86	William Cotton and Associates	Geotechnical Review Sheet
			02/10/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Vaccaro Basement Floor and Spa Additions
	132 Otis Avenue	x	04/06/94	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Planned Foundation Repairs and Additions to Single-Family Residence
			10/18/95	Jo Crosby & Associates	Geotechnical Consultation, Residence
	135 Otis Avenue		03/11/16	Romig Engineers, Inc.	Geotechnical Investigation
	140 Otis Avenue	x	05/22/89	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Mitigation of Distress to Existing Residence, Proposed Detached Garage, Jensen Residence
			12/11/92	Upp Geotechnology, Inc.	Feasibility and Preliminary Plan Review, Proposed Foundation Repair and Detached Garage Addition, Nickell Residence
			07/29/93	Raleigh Engineering	Geological and Geotechnical Report
			01/23/07	PGSoils, Inc.	Geotechnical Investigation, Proposed Retaining Wall, Nickel Property
	143 Otis Avenue	x	04/25/03	Romig Engineers, Inc.	Geotechnical Investigation, Lewis Garage
			02/06/09	Romig Engineers, Inc.	Supplemental Recommendations, Lewis Garage
	no address	x	01/23/85	Howard F Donley & Associates	Potline of Geotechnical Report, Resubdivision of APN 73-061-200
			1/0/85	Rick Skierka	Concept Map, with annotations
			07/12/85	William Cotton and Associates	Geotechnical Review Sheet
			07/16/85	William Cotton and Associates	Preliminary Geologic Review, Lands of Drees, LD 287
			08/01/85	Town of Woodside	Subdivision Review Meeting - Land Division 287
			09/26/85	Howard F Donley & Associates	Geotechnical Investigation, Proposed New Residence
			10/16/85	Rick Skierka	Tentative Map
			11/04/85	William Cotton and Associates	
			05/29/86	Howard F Donley & Associates	Review of Architectural Drawings and Design Calculations, Proposed Single Family Residence
			08/08/86	William Cotton and Associates	Geotechnical Review Sheet
			08/11/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
	157 Otis Avenue	x	09/26/85	Howard F. Donley & Associates	Geotechnical Investigation, Proposed New Residence

			05/29/86	Howard F. Donley & Associates	Review of Architectural Drawings and Design Calculations, Proposed Single Family Residence
			08/11/86	William Cotton & Associates	Preliminary Geologic and Geotechnical Review, Drees, AP #3138
			02/11/87	Lawrence B. Karp	New Residence - Foundation Construction
			02/25/87	Wipson Incorporated	Construction Observation Letter
			04/17/08	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Kalinowski Property
			05/04/08	Murray Engineers, Inc.	Engineering Geologic & Geotechnical Investigation, Kalinowski Residence Improvements
	160 Otis Avenue	x	07/31/05	Wayne Ting & Associates, Inc.	Proposed Deck
			11/08/07	Wayne Ting & Associates, Inc.	Response to County Concerns
	163 Otis Avenue	x	02/05/93	Upp Geotechnology, Inc.	Geotechnical Investigation, Two Adjoining Undeveloped Parcels, Lands of Vellequette
			01/18/94	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation, Two Adjoining Undeveloped Parcels, Lands of Vellequette
	168 Otis Avenue	x	04/09/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Addition to Goldberg Residence
				William Cotton and Associates	Geotechnical Review Sheet
			09/21/88	Upp Geotechnology, Inc.	Review of Foundation Plans, Addition to Goldberg Residence
			10/03/88	Richard Hanson, Civil Engineer	Structural Calculations
			10/05/88	William Cotton and Associates	Preliminary Geotechnical and Geologic Review, Goldberg Additions, PA #4889
	172 Otis Avenue	x	07/31/00	Herzog Geotechnical Consulting Engineers	Geotechnical Investigation Report
			05/11/17	Romig Engineers, Inc.	Geotechnical Investigation Report Harvey Landslide Repair
			12/28/00	Herzog Geotechnical Consulting Engineers	Engineering Geologic Report/Supplemental Geotechnical Report
PALM CIRCLE					
19	8 Palm Circle	x	09/28/11	GeoForensics, Inc.	Geotechnical Evaluation, Garage Foundation Repairs
			05/16/14	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
	10 Palm Circle	x	08/29/00	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence
PARTITION ROAD					
19	3540 Partition Road	x	09/09/05	Romig Engineers, Inc.	Geotechnical Investigation, Wennblom Retaining Wall Replacement
			07/31/12	Murray Engineers, Inc.	Geotechnical Investigation-Residence Improvements
	3530 Partition Road	x	03/07/94	Dunham & Associates	Geotechnical Engineering Investigation
			04/16/12	Earth Investigations Consultants	Limited to Proposed Main Entry Remodel
			07/31/12	Murray Engineers, Inc.	Geotechnical Investigation Residence Improvements

	3555 Partition Road	x	05/25/83	Howard Donley Associates, Inc.	Landslide Investigation
			02/27/84	Howard Donley Associates, Inc.	Progress Report, Construction Inspection, Repair of Landslide
			09/15/93	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Underpinning and Additions
	3560 Partition Road	x	09/02/77	Terrasearch, Inc.	Geologic Investigation, Partition Road Property (Hanson)
			09/25/78	Purcell, Rhoades & Associates	Geotechnical Hazard Investigation, ≈ 2.7-Acre Parcel
			11/03/78	Robert Mahnoy	Foundation Design - 2.7-Acre Parcel
			01/29/79	Randlett & Foulk, Inc.	Site Development Plan, with annotations
			02/00/79	Washington - Jensen & Associates	Structural Calculations
			03/19/79	R.I. Whaley	Review of Site Development Plan, Johnson
			04/08/79	William Cotton and Associates	Geotechnical Review Sheet
			04/23/79	William Cotton and Associates	Review
			04/25/79	Soil Engineering Construction, Inc.	Leach Foeld Comments, Johnson Lot - Land Division Map 181
			07/23/79	Soil Engineering Construction, Inc.	Supplemental Investigations - Johnson Lot, Parcel A, Land Division Map 181
			10/05/79	Charles E, Randlett	Retaining Wall Desing / Calculations
			10/11/79	Soil Engineering Construction, Inc.	Landslide Area South of House, Johnson Lot, Parcel A, Land Division Map 181
			12/10/79	Soil Engineering Construction, Inc.	Soil & Geologic Investigation, Johnson Lot
			02/18/80	William Cotton and Associates	Geologic Review
			06/16/82	Soil Engineering Construction, Inc.	Comments on Grading and Landslide, APN 72-093-080
			01/22/85	Soil Engineering Construction, Inc.	Observations on Stability, Drainage, and Grading, APN 72-093-080
			00/00/85	William Cotton and Associates	Geotechnical Review Sheet
			05/01/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Johnson (B and J Construction)
	3600 Partition Road	x	04/29/80	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Percolation Testing, Approximat 3.5-Acre Oarcel
			07/14/80	William Cotton and Associates	Geotechnical Review Sheet
			07/18/80	William Cotton and Associates	Review of 4/29/80 PR&A report
			09/13/88	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, Lands of Taromi (APN 072-173-020)
			02/14/87	Arcturus Land Survey	Topographic Map

				William Cotton and Associates	Geotechnical Review Sheet
			07/29/92	William Cotton and Associates	Preliminary Geologic Review, Taroni Single Family Residence
		Rogers	01/17/01	Harlan Tait Associates	Preliminary Geologic Evaluation, Septic System
			11/19/01	Harlan Tait Associates	Geotechnical Feasibility Evaluation, Septic System
			08/20/02	Harlan Tait Associates	Geotechnical Investigation, Rogers Residence
			08/13/03	Harlan Tait Associates	Geologic Mapping, Rogers Property
			01/16/04	Harlan Tait Associates	Geotechnical Investigation, Rogers Residence
			05/21/04	Harlan Tait Associates	Supplemental Investigation and Response to Geologic Review Comments, Rogers Property
			06/17/05	Harlan Tait Associates	Geotechnical Consultation, Rogers Property
3635 Partition Road				Hardesty Associates	Layout and Lighting Plan
			08/30/88	Joseph M. Bauer, C.E.	Structural Calculations
			08/12/88	Charles H. Hartsog & Associates	Soil Report
				William Cortton and Associates	Geotechnical Review Sheet
			06/17/88	William Cortton and Associates	Preliminary Geologic and Geotechnical Review, Barker Exterior Improvements, PA #4684
3640 Partition Road		x	09/22/83	John T. O'Rourke & Associates	Landslide Evaluation
			10/28/83	John T. O'Rourke & Associates	Additional Subsurface Data
			07/18/84	John T. O'Rourke & Associates	Report of Horizontal Drains
			08/26/85	Kimand Associates	Retaining Wall Design Parameters. Ringold Residence
			09/11/85	Charles E. Phillips	Retaining Wall & Pavement Plan & Section
			09/24/85	John T. O'Rourke & Associates	Review of Driveway Improvements
			10/15/85	William Cotton and Associates	Geotechnical Review Sheet
			11/01/85	William Cotton and Associates	Preliminary Geologic Review, Lands of Ringold, Driveway Retaining Wall
			11/12/85	John T. O'Rourke & Associates	Response to Town Comments - Cross Sections
			11/21/85	John T. O'Rourke & Associates	Response to Town Comments - Cross Sections
			11/22/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Ringold Driveway Retaining Wall
			05/25/07	Michelucci & Associates, Inc.	Geotechnical and Geologic Investigation, Planned Site Improvements, Lars Ahlstrom Property
			03/12/08	Michelucci & Associates, Inc.	Proposed New Retaining Wall, Lars Ahlstrom Residence

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204258

Record Title & Contents					
GEOTECHNICAL REPORT FOR PATROL COURT - 660 PATROL ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
PATROL COURT					
19A	Patrol Court Landslide		06/04/05	Earth Sciences Associates	Patrol Road Landslide Investigation, Phases I & II
	20 Patrol Court	x	10/12/00	Romig Engineers, Inc.	Geotechnical Investigation, Plum Residence Addition
	25 Patrol Court	x	07/09/82	Clearly Consultants, Inc.	Landslide Repair Investigation
			08/05/86	Clearly Consultants, Inc.	Investigation of February, 1986 Landslide, Heyeck Property
			various	William Cotton and Associates ?	Mincellaneous photographs, mps, and sections
			09/25/86	William Cotton and Associates	Mitigation Recommendations, Heyeck Landslide
			04/28/98	Harlan Tait Associates	Patrol Court Crib Wall Mitigation/Repair Alternatives
	30 Patrol Court	x	12/14/95	Alan Kropp & Associates, Inc.	Geologic/Geotechnical Investigation, Moll Residence Landslide
			12/02/11	Upp Geotechnology, Inc.	Limited Soili and Foundation Study Report, Emergency Retaining Wall Replacement
PATROL ROAD					
19A	Patrol Road Landslide		06/04/85	Earth Sciences Associates	Patrol Road Landslide Investigation, Phases I & II
	518 Patrol Road	x	11/09/06	Murray Engineers, Inc.	Geotechnical Investigation, Joost Residence Underpinning
			09/20/17	Murray Engineers, Inc.	Geotechnical Investigation, Joost Landslide Mitigation
	532 Patrol Road	x	12/07/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence Repair & New Addition, Gordon Property
	558 Patrol Road	x	03/04/09	Romig Engineers, Inc.	Geotechnical Investigation, Wimmer Residence Addition
			09/13/10	Romig Engineers, Inc.	Geotechnical Response, Wimmer Property Drainage
			10/04/10	Romig Engineers, Inc.	Geotechnical Plan Review, Wimmer Residence Addition
	559 Patrol Road	x	09/24/01	Romig Engineers, Inc.	Geotechnical Investigation, Herbert Residence
	573 Patrol Road	x	08/09/07	Romig Engineers, Inc.	Geotechnical Investigation, New Retaining Wall and Deck Replacement
	580 Patrol Road	x	01/11/01	Geo Forensics, Inc.	Geotechnical Report Update, Proposed Residential Addition
			03/12/01	GeoForensics, Inc.	Report Supplement, Reed/Siegal Property
			07/02/01	GeoForensics, Inc.	Response (to review comments), Reed/Siegal Property
			03/18/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	581 Patrol Road	x	01/10/97	Michelucci & Assoicates, Inc.	Preliminary Geotechnical Evaluation
			02/17/06	Romig Engineers, Inc.	Geotechnical Investigation, Residence Underpinning
	587 Patrol Road	x	3/00/05	Romig Engineers, Inc.	Geotechnical Investigation, Yang Residence Addition

	617 Patrol Road	x	03/06/89	Baldwin-Wright, Inc.	Geotechnical Evaluation, Retaining Wall & Drainage Evaluation
			12/10/96	Steve Brooks, R.E.H.S.	Malfunctioning Sewage Disposal System Repair
			04/10/97	Earth Investigations Consultants	Geotechnical Investigation, Leachfield Stability Analysis
			06/13/97	Earth Investigations Consultants	Response to Initial Town Geologist Review (of 4/10/97 report)
	635 Patrol Road	x	11/20/79	Francis A. Stejer	Special Landslide Study, Proposed Garage
			01/14/80	William Cotton and Associates	Geotechnical Review Sheet
			02/18/80	William Cotton and Associates	Review of FAS 11/20/79 Report
			02/25/80	Francis A. Stejer	Addendum - Special Landslide Study, Proposed Garage
			03/05/80	William Cotton and Associates	Review Notes
			03/27/80	William Cotton and Associates	Review of Addendum Report
			10/03/06	Murray Engineers, Inc.	Geotechnical Investigation, Robbins Property Landslide
			05/26/15	Murray Engineers, Inc.	Geotechnical Investigation, Sebekos Residence Improvements
	640 Patrol Road	x	06/08/78	Purcell, Rhoades & Associates	Geotechnical Investigation, Proposed Swimming Pool, Murphy Residence
			01/23/87	C. S. Stewart Associates	Mitigation of House Distress
			09/18/87	C. S. Stewart Associates	Geotechnical Engineering Report, Murphy Residence Foundation Repair
				unknown	2 geologic sections through 1982 Patrol Court/Patrol Road landslide
			09/05/87	Engineering Systems Construction	Site Plan: New Retaining Wall and Foundations, Murphy Residence
				William Cotton and Associates	Geotechnical Review Sheet
			12/15/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Murphy Foundation repair, PA #4436
			01/07/88	Steve Deal Associates	Plan Review: Murphy Property Mitigation
	655 Patrol Road		08/29/12	Murray Engineers, Inc.	Geotechnical Investigation, Swimming Pool Distress
	660 Patrol Road	x	05/15/02	Romig Engineers, Inc.	Geotechnical Investigation, MacLeod Residence Addition
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204259					
Record Title & Contents					
GEOTECHNICAL REPORT FOR PATROL ROAD - 1307 PORTOLA ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
PATROL ROAD					
20	685 Patrol Road	x	05/17/83	Donald A. Meschino	Caisson Calculations

			06/18/83	William M. McMorrow & Associates	Geotechnical Engineering and Geologic Services, Landslide Stabilizations, Egli Residence
			06/22/83	Town of Woodside	Road Access Concerns
			08/09/85	Louis A. Richardsom	Landslide and Road Repair Investigation
			02/14/91	Town of Woodside	Town of Woodside vs. Robert Russell
			07/18/91	Michelucci & Associates	Geotechnical Investigation
			09/06/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Russell Additions
			10/09/91	Michelucci & Associates	Geotechnical Consultation
			03/09/92	Michelucci & Associates	Geotechnical Evaluation, Proposed Septic Leachfield
			04/13/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Russell Additions
			05/21/92	Lea & Sung Engineering, Inc.	Stitch Pier Design Structural Calculations
			05/22/92	Michelucci & Associates	Planned Modifications & Repairs
			06/01/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Russell Additions
			08/17/92	Lea & Sung Engineering, Inc.	Structural Calculations
			09/01/92	Michelucci & Associates	Review of Plans
			04/10/95	Harlan Tait Associates	Preliminary Evaluation, Landslide
			08/18/11	Murray Engineers, Inc.	Geotechnical Investigation, Furukawa Site Improvements
700 Patrol Road	x		07/14/99	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Milton
			02/14/03	Cotton, Shires & Associates, Inc.	Geotechnical Engineering Review
			08/11/03	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation and Response to Review Comments, Lands of Lovazzano
			11/07/03	Upp Geotechnology, Inc.	Supplemental Response to Review Comments, Lands of Lovazzano
			09/24/04	Upp Geotechnology, Inc.	Plan Review and Supplemental Response to Review Comments, Lands of Lovazzano
			10/04/04	Upp Geotechnology, Inc.	Supplemental Response to Review Comments, Lands of Lovazzano
			10/04/04	Upp Geotechnology, Inc.	Plan Review, Lands of Lovazzano
			01/05/05	Upp Geotechnology, Inc.	Plan Review, Lands of Lovazzano
			06/02/08	Upp Geotechnology, Inc.	Construction Observations, Site Drainage, Site Grading, Drilled Piers, Concrete Slabs-On-Grade
			10/12/09	Upp Geotechnology, Inc.	Limited Soil and Foundation Study Report, Proposed New Decks and Leachfield Relocation
			04/08/10	Upp Geotechnology, Inc.	Supplemental Recommendations and Discussion Proposed New Decks and Storage Area, Kerko Property
			05/05/10	Upp Geotechnology, Inc.	Plan Review and Response to Plan Comments by the Town of Woodside, Proposed New Decks and Leachfield Relocation, Kerko Property

	725 Patrol Road		05/22/12	Sigma Prime Geosciences, Inc.	Geotechnical Study, Retaining Wall Replacement
	760 Patrol Road	x	10/14/08	Romig Engineers, Inc.	Geotechnical Investigation, Hanson Residence Additions
	815 Patrol Road	x	11/29/99	Terrasearch, Inc.	Geologic and Geotechnical Investigation, Proposed Retaining Walls and Cutoff Trench
	830 Patrol Road	x	05/20/85	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed Lap Pool
				Freeman-Kern Associates, Inc.	Site Plan with annotations
			02/07/86	William Cotton and Associates	Geotechnical Review Sheet
			02/16/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Passal Pool
	850 Patrol Road	x	05/28/01	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Swimming Pool & Spa Site (APN 072-071-140)
			10/18/01	Hydro-Geo Consultants, Inc.	Geotechnical Report, Swimming Pool and Spa
			05/15/02	Questa Engineering Corporation	Geotechnical and Engineering Geologic Investigation, Proposed Swimming Pool
			06/18/08	Questa Engineering Corporation	Addendum for Addition and Deck Improvements (5/15/02 report)
			04/22/09	Questa Engineering Corporation	Revised Addendum for Addition and Deck Improvements (5/15/02 report)
	875 Patrol Road	x	04/09/85	JCP Geologists- Engineers	Soil and Foundation Study, Proposed Addition to Residence
	885 Patrol Road	x	05/07/07	Romig Engineers, Inc.	Geotechnical Investigation, Staats Site Improvements
			06/07/07	Romig Engineers, Inc.	Supplemental Recommendations, Staats Retaining Wall
PHILLIP ROAD					
20	100 Phillip Road	x	05/02/96	Earth Investigations Consultants	Fault Location Assessment, Proposed House
			05/07/96	Earth Investigations Consultants	Soil and Ground Water Exploration, Proposed On-Site Sewage Disposal
			07/11/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residence
			04/07/05	Earth Investigations Consultants	Geotechnical Supplement, Proposed Swimming Pool
	120 Phillip Road	x	10/21/97	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Guest House, Suber Property
			10/21/99	GeoForensics, Inc.	Addendum to Geotechnical Investigation Report
			02/06/01	GeoForensics, Inc.	Report Update, Proposed Residential Additions
	135 Phillip Road	x	02/15/11	Sigma Prime Geosciences, Inc.	Geotechnical Study, Proposed Detached Carport, Cooney Property
			05/24/11	Sigma Prime Geosciences, Inc.	Geotechnical Study, Proposed Detached Carport, Cooney Property
			07/18/11	Sigma Prime Geosciences, Inc.	Plan Review Letter, Proposed Carport, Remodeled Garage
			07/19/11	Sigma Prime Geosciences, Inc.	Addendum to Soils report, Proposed Carport and Garage Remodel
			07/25/11	Sigma Prime Geosciences, Inc.	Response to Geotechnical Comments, Proposed Carport, Remodeled Garage

	145 Phillip Road	x	05/30/94	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions, Nathan Residence
			12/21/95	GeoForensics, Inc.	Geotechnical Report Update, Proposed Pool House and Residential Additions
	160 Phillip Road	x	07/21/99	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Residence
			10/21/99	Earth Mechanics Consulting Engineers	Addendum to Geotechnical Investigation Report
			09/30/00	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Pool and Pool House
			03/13/02	Earth Mechanics Consulting Engineers	Response to Geotechnical Review Comments, Proposed Water Feature
	175 Phillip Road	x	07/17/91	Applied Soil Mechanics, Inc.	Preliminary Geologic and Soil Engineering Study, Proposed Giovenco Residence on 2 Acre Site
			01/16/92	Earth Systems Consultants - Northern California	Updated Construction Plan Review, Proposed Giovenco Residence
				William Cotton and Associates	Geotechnical Review Sheet
			02/10/92	Earth Systems Consultants - Northern California	Final Grading and Foundation Plan Review, Proposed Giovenco Residence
			02/27/92	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Giovenco New Residence, PA #8694, 8695, 8696
			05/13/92	William Cotton and Associates	Supplemental Geotechnical Review, Giovenco New Residence, PA #8694, 8695, 8696
			01/02/92	Mission Engineers, Inc.	Preliminary Grading and Drainage Plan, Lands of John Giovenco
			06/12/00	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Pool/Spa
			10/01/00	Carl W. Garbe, P.E.	Retaining Wall Section
	190 Phillip Road	x	10/07/74	Dunham & Associates	Soil Investigation, Proposed Addition (APN 075-292-130)
			05/09/86	Jo Crosby & Associates	Geotechnical Report, Landslide
PORTOLA ROAD					
20	1231 Portola Road	x	03/21/78	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, One-Acre Lot off Portola Road
			07/19/02	United Soil Engineering, Inc.	Geotechnical Investigation, Proposed Minor Additions and New Deck
	1239 Portola Road	x	11/20/97	Jo Crosby & Associates	Geotechnical Investigation, Planned Additions
			01/22/98	Jo Crosby & Associates	Addendum, Geotechnical Investigation, Planned Additions and Alterations
			03/30/98	Jo Crosby & Associates	Engineering Geology, Planned Additions and Alterations

			04/15/98	Jo Crosby & Associates	Response to Town Review Comments (4/3/98), Planned Additions and Alterations
			05/14/98	Jo Crosby & Associates	Response to Town Review Comments (5/7/98), Planned Additions and Alterations
			06/04/98	Jo Crosby & Associates	Response to HTA Review Letter (6/4/98) Comments
			06/04/98	Jo Crosby & Associates	Geotechnical Review of Plans, Additions
			08/27/98	Jo Crosby & Associates	Observation of Excavations for Foundations, Additions
			12/07/01	Jo Crosby & Associates	Response to Town Review Comments (10/19/01), Garage Foundations
			04/24/02	Jo Crosby & Associates	Response to Town Comments (1/22/02), Remodeling Garage
			03/11/03	Romig Engineers, Inc.	Geotechnical Investigation, Russell Garage Foundation Reconstruction
1301 Portola Road	x		08/04/00	Friar Associates, Incorporated	Geotechnical Investigation, Addition to Studio Building
			03/21/04	Amso Consulting Engineers (ACE)	Geotechnical Investigation, House Addition
			4/11/04 ?	Amso Consulting Engineers (ACE)	
1307 Portola Road	x		01/19/07	Sigma Prime Geosciences, Inc.	Geotechnical Report, Proposed Single Family Dwelling
			09/10/09	Sigma Prime Geosciences, Inc.	Geotechnical Report, House Remodel

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204260

Record Title & Contents

**GEOTECHNICAL REPORT FOR
1380 PORTOLA ROAD - 2095 PORTOLA ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
PORTOLA ROAD					
20A	1380 Portola Road	x		William Cotton and Associates	Geotechnical Review Sheet
					Topographic Map / Siye Plan, with annotations
			12/16/85	William Cotton and Associates	Preliminary Geologic Review, Thomas / Willow Tree Farm Use Permit, File #80-91
			03/10/86	William Cotton and Associates	Supplemental Geologic Review, Thomas/Willow Tree Farm Use Permit, File #80-19
	1400 Portola Road	x	02/09/87	Fowler & Associates	Geological Investigation, The Family Farm
				William Cotton and Associates	Geotechnical Review Sheet
			03/05/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Family Farm Fault Trenching, Use Permit 80-96
			12/31/87	Fowler & Associates	Geotechnical Investigation, Propsed Expansion of the Family Farm

			05/17/99	Treadwell & Rollo	Geotechnical/Geological Investigation, Family Farm Landslide
			12/30/11	Tharp & Associates, Inc.	Geotechnical Investigation- Design Phase, Repair of Damaged Bridge Abutment
1407 Portola Road	x		06/21/95	Buckley Engineering Associates	Geologic Investigation, Proposed Residential Additions
			06/23/95	Ting & Associates	Geotechnical Investigation, Proposed Additions
			08/26/96	Buckley Engineering Associates	Response to Review, Proposed Additions
			09/04/96	Ting & Associates, Inc.	Response to Review, Geologic and Geotechnical Investigation, Proposed Additions
			08/09/96	Harlan Tait Associates	Review - Geologic and Geotechnical Investigation, Proposed Additions
			09/12/96	Harlan Tait Associates	Supplementary Review - Geologic and Geotechnical Investigations, Proposed Additions
			07/03/96	Ting & Associates	Foundation Plan Review, Proposed Additions
			08/31/96	Buckley Engineering Associates	Response to Review - Leach Field, Proposed Additions
1439 Portola Road	x		SEE 1439 HOME ROAD		
1460 Portola Road	x		03/14/77	Francis A. Stejer	Engineering Geologic Study, Proposed Parcel No. 1 (APN 075-294-060)
			04/11/77	Dunham and Associates	Soil Investigation, Fragulia, Proposed Home
1475 Portola Road	x		06/19/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed Replacement Retaining Wall, King Property
1510 Portola Road	x		03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation (APN 075-294-160)
1530 Portola Road	x		07/20/09	Romig Engineers, Inc.	Geotechnical Investigation, Miller Residence
			11/09/10	Romig Engineers, Inc.	Updated Geotechnical Review, Miller Pool House
1543 Portola Road	x		02/14/77	Purcell, Rhodes & Associates	Soil and Geologic Investigation, Intersection of Portola Road and Old La Honda Road
			04/25/77	Town of Woodside	Review
			?	?	Plot Plan
			?	William Cotton and Associates	Geotechnical Review Sheet
			08/26/87	Lee Engineers	Swimming Pool Construction Soil Investigation
			09/18/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Berger Pool, P.A. #4186
1545 Portola Road	x		05/09/05	Connell Geotechnical, Inc.	Geotechnical Investigation Report, New Riding Arena, Portola Farms
			02/27/08	Connell Geotechnical, Inc.	Geotechnical Investigation Report, New Cover for Existing Riding Arena, Portola Farms
1800 Portola Road			11/02/11	Murray Engineers, Inc.	Geotechnical Investigation, Keith Residence Improvements
1820 Portola Road	x		06/13/05	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
			08/17/05	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Barn Addition
			09/14/05	Murray Engineers, Inc.	Supplemental Recommendations, Spa, Trellis & Site Retaining Walls

	1835 Portola Road		08/14/91	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Detached 3-Car Garage Addition
		x	06/17/05	Lawrence B. Karp	various documents addressing proposed remodel in fault zone
	1840 Portola Road	x	09/30/75	Richard E. Roland	Geologic Report, Mogensen Property (APN 075-291-050)
			07/27/78	Mattson and Mattson	Site Plan, Morey Residence, with Annotations
			08/30/78	William Cotton and Associates	Geotechnical review
	1909 Portola Road	x	09/28/84	Fowler & Associates	AP Special Studies Zone Investigation, Gilmore Residence
			09/16/84	Doug Thom	Sute Plan
			09/30/84	Susan Burr and Douglas Thom	Letter to Planning Commission
			10/11/84	William Cotton and Associates	Geotechnical Review Sheet
			10/11/84	?	Color Photographs of Trench Site (after backfill) and Creek
			10/16/84	William Cotton and Associates	Preliminary Geologic Review, Gilmore Addition, VAR 358
			ca 1984	?	Copies of Photographs of Property
			07/06/99	Fowler & Associates	Geotechnical Investigation, Proposed Addition
			05/09/06	Romig Engineers, Inc.	Geotechnical Review, Residence Remodel
			08/29/06	Romig Engineers, Inc.	Slope Reconstruction, Bridgman Residence
	1965 Portola Road	x	08/14/80	Howard Donley Associates, Inc.	Site Investigation, Proposed Swimming Pool
			08/19/80	William Cotton and Associates	Geotechnical Review Comments
			08/27/80	William Cotton and Associates	
			09/14/94	Earth Systems Consultants Northern California	Fault Evaluation Study
			12/20/94	Earth Systems Consultants Northern California	Soil Engineering Study, Proposed Facciola Residence Additions
			10/05/94	Earth Systems Consultants Northern California	Addendum, Fault Evaluation Study
	1990 Portola Road	x	04/01/77	Purcell, Rhoades & Associates	Geotechnical Invstigation, Property NE of Intersection of Phillips and Portola Road (APN 072-211-250)
				Design 2	Site Plan with trenches
			05/06/77	Town of Woodside	Review of Geotechnical Investigation
			05/24/77	Purcell, Rhoades & Associates	Response to Town Review
			06/01/77	Town of Woodside	Review of Response to Town Comments
			01/29/87	Purcell, Rhoades & Associates	Soil Engineering Study and Foundation Recommendations, Proposed Swimming Pool
	2083 Portola Road	x	05/18/05	Romig Engineers, Inc.	Geotechnical Investigation, Mohsenin Residence Additions
	2087 Portola Road	x	10/14/02	J. Yang and Associates	Geotechnical Site Investigation
			10/28/04	Hoexter Consulting, Inc.	Engineering Geologic Reconnaissance, New Residence
			11/20/04	J. Yang and Associates	Geotechnical Site Investigation, Revision 1

			11/20/04	J. Yang and Associates	Geotechnical Review Comments
			12/23/04	J. Yang and Associates	Geotechnical Review Comments
			06/27/05	Hoexter Consulting, Inc.	Response to Review Letter, Construction of New Residence
	2089 Portola Road	x	09/22/95	William Cotton and Associates	Geotechnical Investigation, Landslide Mitigation
	2091 Portola Road	x	09/22/95	William Cotton and Associates	Geotechnical Investigation, Landslide Mitigation
			06/08/13	GeoForensics, Inc.	Geotechnical Investigation, Proposed Repair and Remodeling of Residence
			08/03/16	GeoForensics, Inc.	Geotechnical Update for Proposed New Residential Remodel
			01/22/18	Michelucci & Associates, Inc.	Geotechnical Investigation Proposed Site Improvements
	2095 Portola Road	x	04/10/74	Richard Rowland	Geologic Report, Alembique Ceek Parcel, Ellis Property

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204261

Record Title & Contents

**GEOTECHNICAL REPORT FOR
3000 PORTOLA ROAD - PROSPECT AVENUE**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
PORTOLA ROAD					
21	3000 Portola Road	x	11/29/76	Leighton and Associates	Field Review of Trench
				Leighton and Associates	Field Review Notes
			12/02/76	Burkland and Associates	Schrool Property
			12/27/76	Applied Earth Sciences Consultants	Geologic and Seismic Hazards Evaluation, Schroll Property
			02/28/77	Town of Woodside	Memo - Review of Burkland & Associates Report dated 12/27/76
			03/03/77	Burkland and Associates	Schrool Property - Supplemental Data
			03/14/77	Leighton and Associates	Memo - Comment on Response to 2/28/77 Memo
			00/00/87	Earth Systems Consultants	Geologic abd Seismic Hazards Evaluation, The School Property
			06/06/00	Applied Earth Sciences Consultants	Comments on Meeting with Town Geologist
			07/13/00	Applied Earth Sciences Consultants	Supplemental Comments on Meeting with Town Geologist re. Fault Investigation
			07/14/00	Town of Woodside	Memo to Applied Earth Sciences Consultants re. Fault Investigation

			08/14/00	Applied Earth Sciences Consultants	Memo to Town Geologist re. Fault Investigation
			08/15/00	Town of Woodside	Memo to Applied Earth Sciences Consultants re. Fault Investigation re. Fault Investigation
			09/12/00	Town of Woodside	Memo to Applied Earth Sciences Consultants re. Fault Investigation re. Fault Investigation
			04/13/01	Applied Earth Sciences Consultants	A Geotechnical Investigation for Subdivision Feasibility, The Schroll Estate
			04/17/01	Town of Woodside	Pre-Application: Subdivision, Engineering Geology Comments
			05/09/01	Town of Woodside	Pre-Application: Subdivision, Engineering Geology Comments
			07/12/01	Town of Woodside	Subdivision Review Comments
			10/07/03	Upp Geotechnical, Inc.	Preliminary Findings, Geotechnical Investigation, Residence
			10/08/05	Town of Woodside	Pre-Application: Residence, Engineering Geology Comments
			11/14/03	Upp Geotechnology, Inc.	Geotechnical Investigation, Virtual Management Property
			05/10/05	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Phase 2A Improvements, Residence
			06/01/05	Upp Geotechnology, Inc.	Phase 2B On-Site Sewage Disposal System for Gym and Recreation Building
			06/01/05	Applied Earth Sciences Consultants	On-Site Sewage Disposal System, Siting, Construction, System Use and Maintenance (Phase 2B Permit SOW)
			06/03/05	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Phase 2B Improvements, Residence
			05/03/05	Applied Earth Sciences Consultants	On-Site Sewage Disposal Systems, Main Residence, Pool House and Cabana
			10/21/05	Applied Earth Sciences Consultants	On-Site Sewage Disposal Systems, Caretakers Residence, Maintenance Building, and Kennel
			11/03/05	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Phase 3 Improvements, Portola Road Residence
			01/28/08	Upp Geotechnology, Inc.	Supplemental Recommendations, Adobe House Renovation, Portola Road Residence
			04/29/08	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Adobe Road House, Portola Road Residence
PRESTON ROAD					
21	16 Preston Road				
	19 Preston Road	x	05/09/94	Nielsen Geotechnical Incorporated	Soil Report
			07/19/05	Murray Engineers, Inc.	Limited Geotechnical Evaluation & Foundation Recommendations, Residential Improvements

	22 Preston Road	x	07/11/97	Steven F. Connelly, C.E.G.	Geologic Investigation, Whalen Property
	25 Preston Road	x	06/20/78	Burkland and Associates	Geotechnical Investigation, Macie Property
			10/02/78	Burkland and Associates	Supplemental Geologic Investigation, Macie Property
			10/22/02	Earth Systems Consultants	Final Report on Construction Activity, Retaining Wall Plank Replacement Project, Thomas Residence
	27 Preston Road	x	01/07/80	William Cotton and Associates	Geotechnical Review Sheet
			03/06/80	Earth Systems Consultants	Progress Summary - Geotechnical Investigation, Proposed Lorenzini Residence
			04/04/80	Earth Systems Consultants	Draft Geotechnical Investigation, Lorenzini Property
			04/28/80	Earth Systems Consultants	Geotechnical Investigation, Lorenzini Property
			06/02/80	William Cotton and Associates	Review - Lorenzini
			04/10/85	Earth Systems Consultants	Foundation Plan Review
			04/15/85	James K. Bell	Site Plan, with annotations
			04/23/85	William Cotton and Associates	Geotechnical Review Sheet
			05/01/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of McMillen
	29 Preston Road		SEE 11 OLD LA HONDA ROAD		
	235 Preston Road		06/20/78	Burkland & Associates	Geotechnical Investigation, Nalie Property
			10/02/78	Burkland & Associates	Geotechnical Investigation, Malie Property
	359 Preston Road	x	07/16/98	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Retaining Wall Repair
			10/28/98	Upp Geotechnology, Inc.	Limited Soils and Foundation Investigation, Repair of Landslide Scar, Lands of Yoshida
PROSPECT AVENUE					
21	60 Prospect Avenue	x	04/03/81	Purcell, Rhoades & Associates	Preliminary Soils Investigation, Parcel 2, LD #223
			04/21/81	Perry R. Wood	Soil Percolation Tests, LD #273
			05/13/81	Town of Woodside	Review Comments, Sy LD #273, Preliminary Map Review
			05/15/81	William Cotton and Associates	Geotechnical Review Sheet
			06/16/81	William A. Bartlett	Preliminary Map. LD #273, Subdivision Portion of Parcel A
			08/12/81	Perry R. Wood	Soil Percolation Tests, Parcel 2, LD #273
			09/21/81	William Cotton and Associates	Geologic Review, LD #273
			04/17/86	Purcell, Rhoades & Associates	Geotechnical Engineering and Foundation Recommendations, Blick Residence
			04/02/03	Nielsen Geotechnical Incorporated	Soil Report
	80 Prospect Avenue	x	07/30/80	Applied Earth Consultants	Geotechnical Engineering, Proposed Swimming Pool, Lands of Enos
			0/0/80	William Cotton and Associates	Geotechnical Review Sheet

			06/23/81	William Cotton and Associates	Review of Pool Site - Enos (Pool) BP 1004
			08/10/81	Applied Earth Consultants	Geologic Inspection of Swimming Pool Excavation
			04/12/06	Buckley Engineering Associates, Inc.	Geotechnical Engineering, Proposed Foundation Improvement, Pool House
155 Prospect Avenue	x		12/15/75	Berloger, Lomg & Associates	Engineering Geologic Fault Investigation, Bryson Property
			10/27/97	Nielsen Geotechnical Incorporated	Geotechnical Report
			06/07/00	Nielsen Geotechnical Incorporated	Tennis Court
			09/05/01	Nielsen Geotechnical Incorporated	Plan Review, Tennis Court
			10/03/02	Nielsen Geotechnical Incorporated	Final Construction Report, Tennis Court
			01/13/06	Murray Engineers, Inc.	Geotechnical Investigation, Hartman Cottage
			05/16/07	Murray Engineers, Inc.	Supplemental Geotechnical Recommendations, Landscaping Improvements
169 Prospect Avenue	x		08/06/99	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence
169 Prospect Avenue			06/12/00	Fowler & Associates	Geotechnical Consultation and Plan Review
183 Prospect Avenue	x		03/28/95	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Garage
			06/13/95	Michelucci & Associates, Inc.	Geotechnical Evaluation of "Point Bar" Creek Bank Erosion Mitigation Project, Weinstein Property
185 Prospect Avenue	x		02/28/13	Romig Engineers, Inc.	Geotechnical Investigation, Skarakis Deck Addition and Carriage House Improvements
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204262					
Record Title & Contents					
GEOTECHNICAL REPORT FOR QUAIL MEADOWS COURT - 386 RAYMUNDO DRIVE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
QUAIL MEADOWS COURT					
21A	1 Quail Meadows Court	x	10/09/78	Purcell, Rhoades & Associates	Geotechnical Investigation
			05/08/86	Terrasearch Inc.	Soil Investigation, Proposed Residence, Quail Meadows (APN 073-270-070)
	3 Quail Meadows Court	x	06/28/86	Purcell, Rhoades & Associates	Soil Engineering and Foundation Design Report, Lot 2, Quail Meadows Court

	5 Quail Meadows Court	x	04/11/86	Dunham & Associates	Soil Investigation, Proposed Home (APN 073-270-050)
			04/04/86	?	Site Plan
			?	William Cotton and Associates	Geotechnical Review Sheet
			08/04/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Investigation - Moore
QUAIL MEADOWS DRIVE					
21A	Quail Meadows Subdivision		07/21/69	W. A. Wahler & Associates	Geologic and Soils Investigation, Vista Del Sol
			02/01/77	Leighton and Associates	Review of 7/21/69 Geologic and Soil Investigation report
	2 Quail Meadows Drive	x	04/25/86	Dunham & Associates	Soil Investigation, Proposed Home, Lot 9, Quail Meadows (APN 073-270-130)
			05/21/87	Melvin R. Hill Inc.	Pool Design
				William Cotton & Associates	Geotechnical Review Sheet
			07/08/87	William Cotton & Associates	Preliminary Geotechnical Review, Morey Swimmih Pool and Spa, PA #4188
			07/22/87	Melvin R. Hill Inc.	Pool Design
			08/26/87	William Cotton & Associates	Supplemental Geotechnical Review, Morey Swimming Pool and Spa, PA #4188
	4 Quail Meadows Drive	x	08/30/94	Fowler & Associates	Engineering Geologic Report, Proposed Chenevich Residence
			09/01/94	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Home
			10/26/07	Romig Engineers, Inc.	Geotechnical Investigation, Garage, Pool House, and Lap Pool
	6 Quail Meadows Drive	x	05/31/85	Purcell, Rhoades & Associates	Soil Engineering Study, Lot 7, Quail Meadows (APN 073-270-110)
			03/20/08	Terra Firma Engineering and Science	Geotechnical Investigation for Photovoltaic Array
	10 Quail Meadows Drive	x	06/10/86	Purcell, Rhoades & Associates	Soil Engineering and Foundation Design Report, Lot 5, Quail Meadows (APN 073-270-090)
			03/06/01	Jo Crosby & Associates	Geotechnical Investigation for Proposed Swimming Pool
	12 Quail Meadows Drive	x	12/04/85	Purcell, Rhoades & Associates	Soil Engineering and Foundation Design Report, Lot 4, Quail Meadows (APN 073-270-080)
			07/31/03	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Liu Residence
			07/31/03	Hoexter Consulting, Inc.	Engineering Geology Reconnaissance, New Residence
RANCH ROAD					
21A	25 Ranch Road	x	09/04/08	Romig Engineers, Inc.	Geotechnical Investigation, Snyder Residence Additions
	50 Ranch Road	x	07/24/92	Clearly Consultants, Inc.	Soil and Foundation Investigation, Residence Expansion
	55 Ranch Road	x	02/18/11	Geotechnical Engineering, Inc.	Soil Investigation, Planned Addition to existing Gian Residence

	75 Ranch Road	x	00/00/77	George L. Quick	Geologic Investigation, Lot 4, Block 6, Skywood Acres (APN 075-013-080)
			07/07/77	Geo-Ekta Laboratories	Foundation Soils Investigation, Lot 4, Block 6, Skywood Acres
	80 Ranch Road		07/28/77	Purcell, Rhoades and Associates	Soil and Geologic Investigation, Proposed Home, Lot 12, Block 3, Skywood Acres
		x	10/12/77	Purcell, Rhoades and Associates	Supplemental No. 2, Soil and Geologic Investigation of Proposed Home, Lot 12, Block 3, Skywood Acres
			10/14/77	Leighton and Associates	review of above report
	85 Ranch Road	x	12/23/86	Upp Geotechnology	Preliminary Investigation, Vasquez Property
			12/16/02	Earth Investigations Consultants	Engineering Geologic Evaluation
			01/23/03	Stimac Associates, Inc.	Geotechnical Investigation, Proposed Additions and Remodel
			01/23/04	Stimac Associates, Inc.	Geotechnical Investigation
			08/25/04	Stimac Associates, Inc.	Geotechnical Review of Plans, Residential Remodel for Griggs
	90 Ranch Road	x	09/09/02	Charles H. Hartsog	Soils Report
			12/26/02	Charles H. Hartsog	Geo Plan Review Comments, Proposed Remodeling
RAVINE DRIVE					
21A	165 Ravine Drive	x	03/21/02	Upp Geotechnology, Inc.	Reconnaissance Geotechnical Investigation, Proposed Barn, Darbonne Property
			10/03/02	Upp Geotechnology, Inc.	Construction Observations, Site Grading, Darbonne Property
RAYMUNDO DRIVE					
21A	141 Raymundo Drive	x	11/15/85	Upp Geotechnology	Soil and Foundation Investigation, Fontana Swimming Pool
				William Cotton and Associates	Geotechnical Review Sheet
				Val's Custom Pools	Site Plan, with annotations
			11/27/85	Upp Geotechnology	Plan Review, Fontana Swimming Pool
			12/16/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Fontana Pool
	166 Raymundo Drive	x	06/20/96	Upp Geotechnology, Inc.	Fault Location Investigation, Reese Trust Property
			12/04/06	Earth Investigations, Consultants	Geotechnical Evaluation, Equestrian Arena Improvements
			04/04/07	Earth Investigations, Consultants	Supplemental Geologic Data, Soil Exploration Logs & Hermit Fault, Equestrian Arena Improvements
	173 Raymundo Drive	x	09/21/84	Upp Geotechnology	Soil and Foundation Investigation, Swimming Pool
			08/31/89	JCP	Engineering Geologic Study, Proposed Barn, Guest House, Tennis Court, and Additions
	314 Raymundo Drive	x	01/09/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel
	317 Raymundo Drive	x	09/29/93	Earth Investigations Consultants	Engineering Geological Site Reconnaissance, Kaul Property (APN 072-032-010)

			10/24/94	Earth Investigations Consultants	Engineering Geological Site Reconnaissance, Proposed Drainfield - Kaul Property (APN 072-032-010)
			07/03/95	Earth Investigations Consultants	Engineering Geological Site Reconnaissance, Proposed Drainfield - Kaul Property (APN 072-032-010)
			09/29/97	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Single Family Residence
			7/0/98	Phillip A. Frame	Engineering Geology Report
			07/15/98	Milstone Geotechnical	Geotechnical Investigation, Proposed Thalapaneni Residence
	386 Raynundo Drive	x	09/04/99	North Coast Engineering	Geotechnical and Geologic Investigation of Landslide
			04/22/09	Earth Investigations Consultants	Geotechnical Investigation, Newly-Constructed Porches and Proposed Deck Expansion, McCauley Residence
			03/17/10	Earth Investigations Consultants	Geotechnical Investigation, Proposed Room Addition, McCauley Residence
			09/21/11	Earth Investigations Consultants	Geotechnical Investigation, After-The-Fact Construction, Remodeled Garage/Poolhouses, Pool, and Site Retaining Walls, McCauley Residence
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204263					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 416 RAYMUNDO DRIVE - 486 RAYMUNDO DRIVE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
RAYMUNDO DRIVE					
22	416 Raymundo Drive	x	11/05/03	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Williford Property
			11/20/03	Louis A. Richardson	Engineering Geologic Feasibility Considerations, New Residential Construction
			06/17/05	GeoForensics, Inc.	Geotechnical Recommendations, New Riding Rink
			06/30/05	GeoForensics, Inc.	Retaining Wall Alternative, Proposed Riding Rink
			07/20/05	GeoForensics, Inc.	Retaining Wall Calculations, Proposed Riding Rink
			09/01/05	GeoForensics, Inc.	Review of Civil Plan - Slide Impact, Proposed Riding Rink
			09/09/05	GeoForensics, Inc.	Commentary on "Retaining Walls", Proposed Riding Rink
	421 Raymundo Drive	x	01/21/81	William M. McMorrow & Associates	Accomplishment of Slope Rehabilitation

			07/13/96	William M. McMorrow	Geotechnical Engineering Investigation, Proposed Swimming Pool and Spa
			08/22/96	William M. McMorrow	Supplemental Geotechnical Data, Proposed Swimming Pool & Spa
			07/08/99	William M. McMorrow	Geotechnical Engineering Evaluation, Proposed New Pool House & Porch
			02/02/00	William M. McMorrow	Geotechnical Engineering Review, Proposed New Pool House
			05/05/00	Steven F. Connelly	Engineering Geologic Investigation, Proposed Pool House and Landslide Repair
			05/31/00	Frederick Maurer, Jr.	Geotechnical Investigation, Proposed Pool House and Landslide Repair, Poletti Residence
			08/04/00	Frederick Maurer, Jr.	Supplemental Recommendations and Slope Stability Analyses, Geotechnical Investigation, Proposed Pool House and Landslide Repair
			08/11/00	Geomatrix Consultants	Geotechnical Review, Proposed Pool House and Landslide Repair, Poletti Residence
			08/22/00	Frederick Maurer, Jr.	Geotechnical Plan Review and Response to Town Comments, Proposed New Pool House and Landslide Repair
			08/22/00	Frederick Maurer, Jr.	Response to Town Review Comments, Supplemental Slope Stability Analyses and Additional Recommendations
			01/19/01	Frederick Maurer, Jr.	Summary Report, Construction Observation Services, Proposed Pool House
			03/26/01	Frederick Maurer, Jr.	Final Geotechnical Plan Review, Proposed Pool House
			07/09/01	Frederick Maurer, Jr.	Final Geotechnical Plan Review, Proposed Pool House Revisions
			12/14/01	Frederick Maurer, Jr.	Final Report, Construction Observation Services, Proposed Pool House
460 Raymundo Drive	x		08/26/81	McMorrow & Associates/Francis A. Stejer, C.E.G.	Geologic Fault Study-Soils Foundation Investigation, Lot 12, Rancho Canada, Tract 567
			12/28/88	John Coyle & Associates, Inc.	Preliminary Engineering Geologic Investigation, Tuck Property
			11/16/88	Snyder & Associates	Geotechnical Investigation, Proposed Tuck Residence
			02/18/89	Snyder & Associates	Supplement to Geotechnical Investigation, Proposed Tuck Residence
			05/18/89	Snyder & Associates	Supplemental Information, Proposed Tuck Residence
			05/16/89	John Coyle & Associates, Inc.	Supplement Letter Report, Preliminary Engineering Geologic Investigation, Tuck Property
			04/09/93	Upp Geotechnology, Inc.	Geotechnical Review, Lands of Tuck
			11/29/95	Upp Geotechnology, Inc.	Plan Review, Preliminary Grading and Drainage Plans, Foundation Plans, Tuck Residence
			01/25/96	Upp Geotechnology, Inc.	Addendum Plan Review, Grading and Drainage Plans, Foundation Plan, Tuck Residence

			03/16/98	Upp Geotechnology, Inc.	Engineering Geologic and Fault Location Investigation Report, Lands of Storm
			09/11/00	Phillip A Frame	Fault Investigation Report
			05/09/01	Advance Soil Technology, Inc.	Soil and Foundation Investigation, Proposed Single Family Residence
			05/17/02	SPI Consulting	Creek Stabilization with Geoweb Cellular Confinement System, Design Calculations
			07/27/06	Phillip A Frame	Update of Fault Investigation Report
			07/28/06	Phillip A Frame	Engineering Geology Report, Storm Residence
			09/18/06	AST Advance Soil Technology, Inc.	Response to Plan Check Comments, Proposed Single Family Residence
			11/14/06	Phillip A. Frame	Existing Data on the Old Landslide Mapped on the Storm Property
			11/30/06	AST Advance Soil Technology, Inc.	Proposed Single Family Residence, Supplemental Information, Proposed Single Family Residence
			04/16/07	Phillip A Frame	Geologic Investigation, Old Mapped Landslide
			04/20/07	AST Geotechnical & Environmental Consulting Engineers	Slope Stability Analysis, Old Mapped Landslide, Storm Residence
			05/25/07	Schaaf & Wheeler	Storm Residence Driveway Drainage
			09/17/07	AST Advance Soil Technology, Inc.	Supplemental Data - Geotechnical Recommendations for the Proposed Dam Structure (Retaining Wall)
			10/10/07	Biggs Cardosa Associates, Inv.	Structural Calculations for Storm Residence Detention Basin
			10/15/07	AST Advance Soil Technology, Inc.	Plan Review (Detention Wall), Proposed Single Family Residence
463 Raymundo Drive	x		04/24/98	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Proposed Pool House, Lands of Clark
486 Raymundo Drive	x		05/23/85	William Cotton and Associates ?	Notes from Fault Trench Inspection
			05/31/85	Tim J. Manzagol	A Geologic Investigation
			06/16/85	Melinda Fitch, owner	Letter to William Cotton and Associates, with WCA annotations on attached map
			07/08/85	William Cotton and Associates	Preliminary Geologic Review, Lands of Fitch - Fault Investigation, proposed Residential Addition

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204264

Record Title & Contents

**GEOTECHNICAL REPORT FOR
RIDGE COURT - ROBLES DRIVE**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
RIDGE COURT					
22A	32 Ridge Court	x	09/25/95	Carl W. Garbe	Soils and Foundation Investigation
			01/15/96	Carl W. Garbe	Review - Geotechnical Investigation, Proposed Addition
			2/22/96	Carl W. Garbe	Supplemental Review - Geotechnical Investigation, Proposed Addition, Garage
	63 Ridge Court		09/30/05	Romig Engineers, Inc.	Geotechnical Investigation, Kravitz Residence
RIDGEWAY ROAD					
22A	Ridgeway Road		09/12/66	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Woodside Hills Unit No. 6
	130 Ridgeway Road	x	01/19/98	Nielsen Geotechnical Incorporated	Soil Report
			09/09/00	Nielsen Geotechnical Incorporated	Project Review & Soil Report Update
			05/15/01	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Swimming Pool
	140 Ridgeway Road	x	04/30/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Panscaping Improvements
			07/07/05	PGSoils, Inc.	Subsurface Conditions, proposed Back Yard Landscaping improvements
	150 Ridgeway Road	x	04/22/09	Romig Engineers, Inc.	Geotechnical Investigation, Huberty Residence Additions
	175 Ridgeway Road	x	02/01/91	JCP Geologist - Engineers	Soil and Foundation Study for Proposed Residence
				William Cotton and Associates	Geotechnical Review Sheet
			05/22/91	William Cotton and Associates	Supplemental Geotechnical Review, Stankovic, PA #8228, 8229, 8230
			02/13/91	Oakley and Associates	Site Plan, with annotations
	230 Ridgeway Road	x	04/14/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Additions
	255 Ridgeway Road	x	06/25/01	Ajay Singh	Geotechnical Engineering Recommendation, Proposed Schonfeld Residence Modifications
			10/10/01	Ajay Singh	Plan Review, Proposed Schoenfeld Residence Modifications
			12/04/01	Ajay Singh	Foundation Observations, proposed Schonfeld Residence Modifications
			11/11/02	Ajay Singh	Final Report, Proposed Schoenfeld Residence Modifications
	285 Ridgeway Road	x	01/29/10	Murray Engineers, Inc.	Geotechnical Investigation, Housser Residence Addition
	290 Ridgeway Road	x	06/30/06	PGSoils, Inc.	Geotechnical Conditions, Proposed Pool Area Accessory Building
	300 Ridgeway Road	x	04/05/07	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
			04/15/07	J. Yang and Associates	Response to the Concerns of Town of Woodside, Proposed Smythe Addition

			10/04/07	J. Yang and Associates	Geotechnical Review Commnets, Proposed In-Law Residence
	330 Ridgeway Road	x	04/03/08	Murray Engineers, Inc.	Limited Geotechnical Evaluation, Site Improvements
			03/16/09	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Bath/Spa Structure
	331 Ridgeway Road	x	09/24/99	GeoForensics Inc.	Geotechnical Investigation, Proposed New Guest House, Renski Property
ROAN PLACE					
22A	5 Roan Place	x	06/03/95	GeoForensics Inc.	Geotechnical Observations of Reported Residential Distress, Ahmed Residence
			09/22/99	GeoForensics Inc.	Geotechnical Investigation for Mitigation of Residential Distress. Ahmed Property
			11/01/99	GeoForensics Inc.	Report Correction
			01/06/00	GeoForensics Inc.	Review of Revised Plans
			03/30/00	GeoForensics Inc.	Response to Town Review
			07/15/07	GeoForensics Inc.	Review of Revised Plans #2
			09/14/00	GeoForensics Inc.	Report Supplement - Drainage
			09/14/00	GeoForensics Inc.	Review of Revised Plans #3
			10/13/00	GeoForensics Inc.	Response to Geomatrix Review
	25 Roan Place	x	02/17/90	Edward W. Baca	Survey Map, with annotations
			05/01/91	Earth Systems Consultants	Geotechnical Report, Landes Residence
			05/13/91	Earth Systems Consultants	Review of Grading Plans
			06/12/91	William Cottonand Associates	Preliminary Geologic and Geotechnical Review, Landes, VAR-499, XSD-77, Site Design 36
			06/04/92	William Cottonand Associates	Geologic and Geotechnical Review, Landes, Variance 517
	30 Roan Place	x	05/04/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
			06/02/06	Earth Investigations Consultants	Geotechnical Parameters, Proposed Retaining Wall
	45 Roan Place	x	12/14/71	Terrasearch, Inc. (Reynolds & Associates)	Soil & Geological Investigation, Benson Property
	75 Roan Place	x	09/30/93	JCP Engineers - Geologists	Geotechnical Causation and Mitigation Study, Distressed Home
			09/26/95	GeoForensics, Inc.	Geotechnical Investigation of Reported Residential Distress
			06/04/96	GeoForensics, Inc.	Response to Town Geotechnical Review, Partial Foundation Repais
			10/24/08	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence Remodel and New Second Story Addition
	80 Roan Place	x	12/05/91	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Proposed Addition Above Existing Garage
			01/24/92	Michelucci & Associates, Inc.	Review of Plans. Proposed Remodel and Addition, Barrett Residence

				William Cotton and Associates, Inc.	Geotechnical Review Sheet
				William Cotton and Associates, Inc.	Preliminary Geotechnical Review, Barrett Additions, #8652
			02/13/92	Michelucci & Associates, Inc.	response to Willam Cotton and Associates review comments
			02/14/92	Michelucci & Associates, Inc.	clarification to 2/13/92 letter
			02/19/02	Michelucci & Associates, Inc.	Supplemental Geotechnical Investigation, Planned Addition and Remodel Project
ROBERTA DRIVE					
22A	45 Roberta Drive	x	04/14/00	Romig Engineers, Inc.	Geotechnical Investigation, Congress Guest House
	75 Roberta Drive	x	07/28/94	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Addition to Existing Residence (APN 072-201-16)
			04/15/98	Hydro-Geo Consultants, Inc.	Response to Letter from Town's Geotechnical Consultant
	85 Roberta Drive	x	11/04/99	Nielsen Geotechnical Incorporated	Soil Report
			02/25/02	Nielsen Geotechnical Incorporated	Soil Report, Swimming Pool
			04/29/05	Murray Engineers, Inc.	New Engineer-of Record & Alternative Foundation Recommendations, Residence Additions
	170 Roberta Drive	x	11/01/73	United Soils Engineering, Inc.	Soil and Geological Investigation, Lot 2 Jacqueline Subdivision
	190 Roberta Drive	x	08/29/89	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Additions
			10/24/91	Michelucci & Associates, Inc.	Review of Plans, Proposed Addition and Accessory Building
				William Cotton and Associates	Geotechnical Review Sheet
			03/02/92	William Cotton and Associates	Geotechnical Review, Messmer Additions, PA #8700 and 8701
ROBLES DRIVE					
22A	45 Robles Drive	x	09/24/90	Fowler & Associates	Geotechnical Investigation, Proposed Exercise/Storage Building
	45 Robles Drive		01/18/06	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Landscape Improvements
	65 Robles Drive	x	06/29/93	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, Percolation Testing, Lands of O'Malley Trust (APN 072-201-042)
			01/03/94	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, Supplemental Percolation Testing, Expansion Field - Proposed Parcel 2
			7/25/2016	GeoForensics Inc.	Geotechnical Investigation for Proposed New Cottage
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204265					

Record Title & Contents					
GEOTECHNICAL REPORT FOR ROCKY WAY - SARGENT LANE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
ROCKY WAY					
23	514 Rocky Way	x	03/30/99	Upp Geotechnology, Inc.	Geotechnical Investigation, Additions to Carlson Residence
	529 Rocky Way	x	06/12/98	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence and Guest House
			09/05/00	Fowler & Associates	Geotechnical Consultation, Proposed Single Family Residence
			07/10/00	Fowler & Associates	Geotechnical Plan Review and Consultation, Proposed Single Family Residence
			04/24/07	PGSoils, Inc.	Geotechnical Investigation Report Update, Proposed Residence
			12/19/08	PGSoils, Inc.	Pier Hole Drilling Observation, BP07-266 & -267, Proposed Residence
			01/06/09	PGSoils, Inc.	Construction Observations, BO07-266 & -267, New Residence
			08/25/09	PGSoils, Inc.	Pier Hole Drilling Observation, BP07-266 & -267, Proposed Residence
			05/03/10	PGSoils, Inc.	Water Pipe Under Driveway, BO07-266 & -267, New Residence
			05/25/10	PGSoils, Inc.	Construction Observations Summary, BO07-266 & -267, New Residence
	546 Rocky Way	x	03/25/99	GeoForensics Inc.	Geotechnical Investigation, Hall Property
			11/03/99	GeoForensics Inc.	Review of Plans, Proposed New Residence
			09/18/01	GeoForensics Inc.	Construction Observations, New Residence and Accessory Building
ROMERO ROAD					
23	115 Romero Road	x	02/10/97	Nielsen Geotechnical Incorporated	Soil Report
	116 Romero Road	x	03/31/05	Murray Engineers, Inc.	Geotechnical Investigation, North Residence
	147 Romero Road	x	06/07/99	Nielsen Geotechnical Incorporated	Soil Report
			08/15/02	Nielsen Geotechnical Incorporated	Construction Report
	156 Romero Road	x	06/27/17	Earth Investigations Consultants, Inc.	Geotechnical Investigation, Propsoed Residential Development
	163 Romero Road	x	03/27/75	R. C. Harlan and Associates	Soil Investigation
			04/04/07	Romig Engineers, Inc.	Geotechnical Investigation, Mawson Residence Addition
			07/03/08	Romig Engineers, Inc.	Supplemental Design Parameters, Driveway Retaining Walls
			10/10/08	Romig Engineers, Inc.	Geotechnical Plan Review, Replacement Retaining Wall

			09/02/11	Romig Engineers, Inc.	Geotechnical Recommendations, Site Retaining Walls
	179 Romero Road	x	03/01/00	Nielsen Geotechnical Incorporated	Soil Report
	191 Romero Road	x	04/18/79	William Cotton and Associates	Geotechnical Review Sheet
			04/23/79	William Cotton and Associates	Geological Review - Giannone Variana
	198 Romero Road	x	02/28/03	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence
RUNNYMEDE ROAD					
23	880 Runnymede Road	x	12/30/82	Earth Sciences Associates	Phase I Assessment of Geologic Hazards, IASCO Property
			10/11/84	Earth Sciences Associates	Phase II Soil and Geologic Investigation IASCO Property
			08/16/90	Earth Sciences Associates	Update of Soil and Geologic Investigation Report for IASCO Property
			05/15/07	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Structure, Dearborn Stables
	922 Runnymede Road	x	10/14/74	Berloger, Long & Associates	Fault Investigation, Martines Property
			07/09/03	Steven A. Arnold	Geotechnical Evaluation
			10/22/03 rev	Steven A. Arnold	Geotechnical Evaluation
			10/21/03	Steven A. Arnold	Geotechnical Review Response
			9/3/03 rev	Steven A. Arnold	Geotechnical Evaluation
			08/25/05	PGSoils, Inc.	Geotechnical Investigation, Proposed Barn Modifications and "Hot Walker" Structure
			09/20/05	PGSoils, Inc.	Geotechnical Investigation, Proposed Deck and Trellis Additions
			09/08/06	PGSoils, Inc.	Geotechnical Report Update
	980 Runnymede Road	x	12/27/89	Tredwell & Associates, Inc.	Foundation Support - Cookhouse
			07/13/90	Tredwell & Associates, Inc.	Drilled Pier Installation - Cookhouse
			01/18/02	Tredwell & Rollo, Inc.	Geotechnical Consultation, Runnymede Farm Equipment Shed
			03/04/02	Tredwell & Rollo, Inc.	Plan Review, Runnymede Farm Equipment Shed
			04/25/02	Tredwell & Rollo, Inc.	Drilled Pier Installation, Farm Equipment Building, Runnymede Farm
			03/04/04	Tredwell & Rollo, Inc.	Geotechnical Design Parameters, Footbridge Replacement, Runnymede Farm
			12/21/04	Gilpin Geosciences, Inc.	Draft Fault Hazard Evaluation, Proposed Accessory Dwelling Unit
			01/07/05	Town of Woodside	Geology Departments Comments on 12/21/04 draft report
			02/23/05	Gilpin Geosciences, Inc.	Fault Hazard Evaluation, Proposed Accessory Dwelling Unit
			03/17/05	Tredwell & Rollo, Inc.	Geotechnical Consultation, Accessory Dwelling Unit, Runnymede Farm
			03/18/05	Town of Woodside	Geology Departments Comments on 1/23/05 final report
			03/24/05	Tredwell & Rollo, Inc.	Revised Report, Geotechnical Consultation, Accessory Dwelling Unit, Runnymede Farm
			10/16/07	Tredwell & Rollo, Inc.	Geotechnical Investigation, Vehicle Bridge

			11/05/07	Gilpin Geosciences, Inc.	Fault Hazard Evaluation, Caretaker's House
			11/14/07	Tredwell & Rollo, Inc.	Geotechnical Investigation, Cartaker's Residence
			12/21/07	Adolph S. Rosekrans, Inc. Architects	Project Manual for Caretaker's House
			03/16/10	Tredwell & Rollo, Inc.	Cookhouse Shade Structure
SAND HILL COURT					
23	10, 20, & 30 Sand Hill Court	x	11/12/80	Purcell Rhoades & Associates	Geotechnical Hazards Assessmant, APN 72-221-180, Sand Hill Road and Mountain Home Road
			01/09/81	Town of Woodside	Preliminary Map Review
			01/13/81	William Cotton & Associates	Geotechnical Review Sheet
			01/15/81	William Cotton & Associates	Geologic Review of PRA Hazards Assessmant dated 11/12/80
			01/16/81	Town of Woodside	Review of Preliminary Map, Capinvest, Inc., LD 271
				William Cotton & Associates	Geotechnical Review Sheet
			09/22/81	William Cotton & Associates	Memo on Conditions of Approval
			08/24/81	Purcell Rhoades & Associates	Preliminary Soil Report, APN 72-221-180, Sabd Hill Road and Mounrain Home Road
			09/24/81	Town of Woodside	Preliminary Map LD #271 Comments
			09/24/81	County of San Mateo, Department of Health Services	Rejection of Septic System for Proposed Parcels
			10/14/81	Purcell Rhoades & Associates	Addendum to 8/24/81 Report - Additional Percolation Studies, Preliminary Map LD #271
			11/11/81	William Cotton & Associates	Geologic Review of PRA Hazards Assessmant dated 11/12/80
			11/20/81	Edwin H. Smith	Preliminary Map, LD Capinvest, Inc., APN072-221-180
			12/11/81	William Cotton & Associates	Geotechnical Review Sheet
			02/17/87	William Cotton & Associates	Supplemental Geologic and Geotechnical Review, Capinvest, LD 271
			09/21/87	William Cotton & Associates	Supplemental Geologic and Geotechnical Review, Capinvest, LD 271
			11/17/87	William Cotton & Associates	Supplemental Geotechnical Review, Capinvest, LD 271
SAND HILL ROAD					
23	Sand Hill Road	x			
SARGENT LANE					
23	41 Sargent Lane	x	10/24/01	Romig Engineers, Inc.	Geotechnical Investigation, Judd Residence Addition
			12/14/10	BAAG Engineers	Geotechnical Engineering Investigation, Proposed Residential Remodel and Addition
			06/02/11	BAAG Engineers	Report Addendum, Geotechnical Engineering Investigation, Proposed Residential Remodel and Addition

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204266

Record Title & Contents

**GEOTECHNICAL REPORT FOR
SHADOWBROOK LANE - SOMERSET PLACE**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
SHADOWBROOK LANE					
23A	1 & 2 Shadowbrook Lane	x	11/22/74	Berloger, Long and Associates	Geologic and Soils Report
			01/24/78	Town Staff	Report to the Planning Commission
			09/15/87	Purcell, Rhoades & Associates	Preliminary Soil Analysis and Fluid Percolation Testing, Parcels 2 and 3
			09/28/87	Purcell, Rhoades & Associates	Soil Engineering and Geotechnical Study, Parcels 2 and 3
			10/07/87	Purcell, Rhoades & Associates	Notes on Observation of Trenches to Determine Groundwater Level
				William Cotton and Associates	Geotechnical Review Notes
			11/04/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Haas, PA #4345
			12/03/87	Purcell, Rhoades & Associates	Plan Review, Parcels 2 and 3
			12/23/87	Purcell, Rhoades & Associates	Potential for Seismic Failure of Proposed Pond, Parcel 3
			01/18/88	William Cotton and Associates	Supplemental Geotechnical Review, Haas, PA #4345
SHERIDAN WAY					
23A	115 Sheridan Way	x	11/20/97	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Additions, Kalkhoven House
	119 Sheridan Way	x	06/16/06	Murray Engineers, Inc.	Geotechnical Investigation, Hills Residence Improvements
			02/17/11	Murray Engineers, Inc.	Supplemental Site Retaining Wall Foundation Recommendations, Hills Property
	121 Sheridan Way	x	10/10/07	Romig Engineers, Inc.	Geotechnical Investigation, McBride Trellis
	130 Sheridan Way	x	07/02/03	Bay Area Geotechnical Group	Geotechnical Consultation, Webster Residence Flatwork Subgrade
			04/20/07	Henry Justiniano & Associates	Geotechnical Investigation, Proposed Reconstruction of Single Family Dwelling
	135 Sheridan Way	x	01/31/05	Romig Engineers, Inc.	Geotechnical Investigation, Burow/Sweeney Residence Additions
SKYLINE BOULEVARD					
23A	Vicinity of Skyline Boulevard		06/10/73	Deborah R. Harden	Engineering Geology and Slope Stability of Part (South) of the Town of Woodside
	Southwest Portion of Town			William Cotton and Associates	Draft Movement Potential Map ?
	Skyline Boulevard	x	12/20/85	William Cotton and Associates	Geotechnical Review Sheet - Skylonda Center
			12/0/85	ESA	Skylonda Center Environmental Assessment

			12/31/85	William Cotton and Associates	Preliminary Geologic Review, Skylonda Center
	17287 Skyline Boulevard		05/04/15	Earth Investigations Consultants	Geotechnical Investigation, Proposed Skylonda H2 Energy Center
			09/08/15	Earth Investigations Consultants	Supplemental Geotechnical Evaluation, Proposed Skylonda H2 Energy Center
			09/18/15	Earth Investigations Consultants	Geotechnical Plan Review, Structural Plans, Proposed Skylonda H2 Energy Center
	17288 Skyline Boulevard	x	01/26/94	ETIC	Site Characterization, Remedial Excavation, and Confirmation of Sampling - Unocal 76 Station - Alice's Restaurant
			09/14/95	Smith-Emery GeoServices	Workplan for Septic System Investigation, Alice's Restaurant
			10/20/95	Smith-Emery GeoServices	Septic System Recommendations, Alice's Restaurant
	17865 Skyline Boulevard	x	08/16/95	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Remodel Project
	18033 Skyline Boulevard	x	09/21/00	ADCO Engineering	Foundation Repair Investigation
			04/23/01	Nielsen Geotechnical Incorporated	Drainage Recommendations, Roof Drainage
			09/09/02	ADCO Engineering	Soil and Foundation Investigation, Proposed Addition
			02/07/03	Hydro-Geo Consultants, Inc.	Preliminary Geologic Engineering Assessment
			02/21/03	ADCO Engineering	Revised Soil and Foundation Investigation. Proposed Addition
			05/14/03	ADCO Engineering	Response to Town Comments, Proposed Addition
			10/27/04	ADCO Engineering	Update of Geotechnical Investigation Report, Proposed Addition
SKYWOOD WAY					
	20 Skywood Way		08/22/14	P. Whitehead and Associates	Geotechnical Investigation
23A	40 Skywood Way	x	11/21/80	Terrasearch, Inc.	Geologic Investigation, Proposed Residence (APN 072-035-050)
			11/01/82	Dunham & Associates	Soil Investigation, Alfred Residence
			06/02/83	William Cotton and Associates	Geotechnical Review Sheet
			09/01/83	Dunham & Associates	Plan Review, Proposed Home
			09/13/83	William Cotton and Associates	Geologic Review, Alfred Residence
			11/08/83	Dunham & Associates	Soil Engineering Recommendations, Proposed Pool
			11/09/83	William Cotton and Associates	Geotechnical Review Sheet
			12/02/83	William Cotton and Associates	Geotechnical Review, Algrid Swimming Pool
	65 Skywood Way	x	05/07/01	Cleary Consultants, Inc.	Geotechnical Investigation, Residence Addition
	85 Skywood Way	x	04/07/09	BAGG Engineers	Limited Geotechnical Investigation, Wood Deck Foundations
	90 Skywood Way	x	08/30/93	Fowler & Associates	Geotechnical Investigation, Proposed Swimming Pool
			02/07/94	Fowler & Associates	Geotechnical Consultation and Plan Review
			06/02/05	Fowler & Associates	Geotechnical Consultation, Proposed Addition
			03/29/06	Fowler & Associates	Construction Observation, Proposed Addition

95 Skywood Way	x	03/16/88	Clearly Consultants, Inc.	Soil and Geologic Investigation, Proposed Additions, William New Residence
			William Cotton and Associates	Geotechnical Skywood Way
		11/28/88	Clearly Consultants, Inc.	Soil and Geologic Investigation, Proposed Accessory Living Quarters and Carport
		4/0/1989	Nellie Ingraham Associates, Inc.	Structural Calculations - New Residence - Phase I, Accessory Living Quarters
		05/31/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, New, #7265
		06/29/89	Clearly Consultants, Inc.	Supplemental Geotechnical Engineering Analyses, Slope Stability of Dormant Slide
		07/12/89	Nellie Ingraham Associates, Inc.	Structural Calculations, New Residence
		07/14/89	Clearly Consultants, Inc.	Evaluation of Dormant Slide Stability
		07/24/89	Clearly Consultants, Inc.	Supplemental Geologic and Geotechnical Review, New, #7265
		08/04/89	Jacobson Silverstein Winslow, Architects	Geologic and Geotechnical Review, New, #7265
		08/23/89	William Cotton and Associates	Supplemental Geologic Review, New, PA #7265
		01/15/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		02/05/90	Clearly Consultants, Inc.	Supplemental Geotechnical Letter, William New Residence - Phase 2 Main House Addition
		02/07/90	Clearly Consultants, Inc.	Amalyzed Profiles for Stability Calculations, Main House Addition
		02/12/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		02/20/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		02/27/90	Clearly Consultants, Inc.	Main Residence and Detached Studio/Garage Addition, New Residence
		05/10/90	Hydro-Geo Consultants, Inc.	Proposed Addition to a Single-Family Residence
		05/15/90	William New, Jr., MD, PhD	Third Party Geotechnical Review, Extension of Main Residence with Detached Garage/Office, William New, PA #7617
		06/07/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		06/15/90	Clearly Consultants, Inc.	Supplemental Geotechnical Response, Additions to Main Residence and Detached Studio/Garage, William New Residence
		08/21/90	Clearly Consultants, Inc.	Progress Report, Soil Engineering Services During Site Grading and Foundation Installation Phases, House and Garage Additions
100 Skywood Way	x	03/26/75	William F. Jones	Soil Investigation, Proposed Spiller Residence, (APN 075-035-110)

			08/31/00	Upp Geotechnology, Inc.	Reconnaissance Geologic and Geotechnical Investigation, Addition to Residence, Bourgeois Property
			06/29/07	Upp Geotechnology, Inc.	Addendum Geotechnical Investigation and Plan Review, New Deck, Bourgeois Property
SMOKE TREE LANE					
23A	20 Smoke Tree Lane	x	01/07/97	Freeman-Kern Associates, Inc.	Fault Investigation, Baldwin Property
			02/26/99	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Lands of Baldwin
	25 Smoke Tree Lane	x	07/15/05	Romig Engineers, Inc.	Geotechnical Investigation, New Horse Barn
	57 Smoke Tree Lane	x	09/16/91	Nordmo Associates, Inc.	Geotechnical Investigation Report, Property Improvements & Remodeling
				William Cotton and Associates	Geotechnical Review Sheet
			12/04/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Hurlbut Additions, BP #8592, 8593, and 8602
			12/05/91	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
			12/09/91	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
			01/30/92	William Cotton and Associates	Memo with Comments on 1/30/92 Nordmo letter
			01/30/92	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
			01/31/92	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
			02/14/92	William Cotton and Associates	Supplemental Geotechnical Review, Hurlbut Additions, BP #8592, 8593, and 8602
			01/24/06	Nordmo Associates	Geotechnical Engineering Report, Proposed Master Bath Addition
	73 Smoke Tree Lane	x	02/25/09	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Pool House/Guesthouse
SOMERSET PLACE					
23A	10 Somerset Place	x	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision
			09/17/89	Cleary Consultants, Inc.	Estimated Maximum and Repeatable Ground Accelerations, Somerset Place Homes
			01/08/90	Alan Kropp & Associates, Inc.	Foundation Investigation, Rafanelli Residence
			05/11/90	Alan Kropp & Associates, Inc.	Plan Review, Rafanelli Residence
			05/18/93	Alan Kropp & Associates, Inc.	Geotechnical Update, Lot #2
			06/30/93	Alan Kropp & Associates, Inc.	Plan Review, Landes Residence
			08/05/93	Darwin Myers Associates	Geologic Hazards Reconnaissance
			07/31/17	Romig Engineers, Inc.	Geotechnical Investigation, Accessory Structure
	14 Somerset Place	x	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision on Godetia Drive
				William Cotton and Associates	Geotechnical Review Sheet
			03/15/89	Kwan & Associates	Structural Calculations

			09/15/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Fieber, PA #7381, Simba Lot 3
			09/20/89	The Russell Group, Architects	Site Plan with annotations
			09/25/89	Cleary Consultants, Inc.	Review of Grading and Foundation Plans, Lot 3, Somerset Place Luxury Homes
			09/26/89	Cleary Consultants, Inc.	Review of Landscaping Plans, Lot 3, Somerset Place Luxury Homes
			09/27/89	William Cotton and Associates	Supplemental Geotechnical Review, Fiebe, PA #7381, Simba Lot 1
18 Somerset Place	x		10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision on Godetia Drive
				William Cotton and Associates	Geotechnical review Sheet
			03/27/89	Kwan & Associates	Structural Calculations
			09/12/89	Cleary Consultants, Inc.	Review of Foundation Plan, Lots 4 and 5, Somerset Place
			09/15/89	William Cotton and Associates	Geologic and Geotechnical Review, Girouard, Lot 4 Simba Subdivision, PA #7373
			09/25/89	Cleary Consultants, Inc.	Review of Grading Plans, Lots 4 and 5, Somerset Place
			09/26/89	Cleary Consultants, Inc.	Review of Landscape Plans, Lots 4 and 5, Somerset Place Luxury Homes
			09/27/89	William Cotton and Associates	Supplemental Geotechnical Review, Girouard, Lot 4 Simba Subdivision, PA #7374
			09/29/89	Cleary Consultants, Inc.	Review of Grading Plans, 9/28/89 Revision, Lots 4 and 5, Somerset Place
			10/16/89	William Cotton and Associates	Supplemental Geotechnical Review, Girouard, Lot 4 Simba Subdivision, PA #7374
22 Somerset Place	x		10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigations, Lands of Simba Group, Five Lot Subdivision on Godetia Drive
				William Cotton and Associates	Geotechnical Review Sheet
			03/24/89	Kwan & Associates	Structural Calculations
			09/12/89	Cleary Consultants, Inc.	Review of Foundation Plans, Lots 4 and 5, Somerset Place
			09/15/89	William Cotton and Associates	Geologic and Geotechnical Review, Hirsch, Lot 5 Simba Subdivision, PA #7374(3)
			09/25/89	Cleary Consultants, Inc.	Review of Grading Plans, Lots 4 and 5, Somerset Place
			09/26/89	Cleary Consultants, Inc.	Review of Landscape Plans, Lots 4 and 5, Somerset Place
			09/27/89	William Cotton and Associates	Supplemental Geotechnical Review, Hirsch, Lot 5 Simba Subdivision, PA #7373
			09/29/89	Cleary Consultants, Inc.	Review of Grading Plans. 9/28/89 Revision, Lots 4 and 5, Somerset Place
			10/16/89	William Cotton and Associates	Supplemental Geotechnical Review, Hirsch, Lot 5 Simba Subdivision, PA #7373

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204267					
Record Title & Contents					
GEOTECHNICAL REPORT FOR SOUTHDALE WAY - STADLER DRIVE					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
SOUTHDALE WAY					
24	605 Southdale Way	x	09/11/89	Applied Earth Sciences Consultants	Summary Percolation Tests, 1.3 Acres addressed as 611 Southdale Way (APN 068-291-070)
	611 Southdale Way (APN 068-291-070)		02/21/91	Applied Earth Sciences Consultants	Soil and Geologic Investigation, 1.3 Acres addressed as 611 Southdale Way (APN 068-291-070)
			06/17/93	Applied Earth Sciences Consultants	Conceptual Site Plan Review, Two Lots on Southdale Way (APN 068-291-090 and APN 068-291-100)
			09/22/93	Applied Earth Sciences Consultants	Geotechnical Review of Revised Conceptual Site Plan, Two Lots on Southdale Way (APN 068-291-090 and APN 068-291-100)
			05/01/96	Applied Earth Sciences Consultants	Site Plan Review and Supplemental Field Investigation, Proposed On-Site Sewage Disposal System
			08/29/97	Applied Earth Sciences Consultants	Supplemental Geotechnical Report
			09/29/97	Applied Earth Sciences Consultants	On-Site Sewage Disposal System Design, Construction and Maintenance
			various	various	Town Council Agenda, November 5, 1996 Meeting
	605 Southdale Way		various	various	Town Council Agenda, February 11, 1997 Meeting
	636 Southdale Way	x	07/20/00	Nordmo Associates	Geotechnical Investigation, Proposed Residence
			06/21/01	Kern Consulting, Inc.	Geologic Investigation
			08/14/01	Nordmo Associates	Supplement and Plan Review, Proposed Perkins/Reed Residence
			09/24/01	Nordmo Associates	Supplement Two and Plan Review, Proposed Perkins/Reed Residence
			04/04/05	Nordmo Associates	Report Update, Proposed Residence
			06/13/05	Nordmo Associates	Geotechnical Review
			08/20/07	Nordmo Associates	Building Plan Review, Replacement Retaining Wall
			11/27/07	Nordmo Associates	Proposed Retaining Extension Downhill of Structures

			03/08/08	Nordmo Associates	Geotechnical Investigation of Slope Western Side of Driveway/Residence
			03/10/08	Nordmo Associates	Supplemental Geotechnical Investigation of Slope Western Side of Driveway/Residence
			05/24/08	Nordmo Associates	Response to Town Memo, Proposed Retaining Walls
			07/22/08	Nordmo Associates	Regarding Proposed Retaining Walls
	651 Southdale Way	x	02/28/06	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Addition
	659 Southdale Way	x	03/22/02	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Addition
			09/29/03	Dunham & Associates	Geotechnical Engineering Recommendations, Proposed Pool
			10/16/03	Neil O. Anderson & Associates, Inc.	Freidenrich Residence Pool
	711 Southdale Way	x	05/23/06	JF Consulting, Inc.	Geotechnical Study, New Driveway, Lands of Milne
SOUTHGATE DRIVE					
24	11 Southgate Drive	x	02/26/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
			08/04/08	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Site Improvements
			09/24/08	Earth Investigations Consultants	Geotechnical Review. Proposed Garden Retaining Wall
			04/18/11	Earth Investigations Consultants	Geotechnical Update, Proposed Backyard Landscape Improvements
SOUTHVIEW WAY					
24	North of Southview Way in RC	x	03/08/88	Edward W. Baca	Pre-Zoning Map
				William Cotton and Associates	Geotechnical Review Sheet
			04/11/88	William Cotton and Associates	Preliminary Annexation and Pre-Zoning, Vicinity of Southview Way and Summit Way
	746 Southview Way	x	04/24/08	ACRE Soil Engineering	Soil and Foundation Investigation, Residential Additions
			05/14/08	ACRE Soil Engineering	Foundations for the Storage Addition, Residential Additions
STADLER DRIVE					
24	1, 10, 16 and 18 Stadler Drive	x	01/14/77	Cooper Clark & Associates	Compilation fo Reports & Correspondence, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
			07/19/76	Cooper Clark & Associates	Geotechnical Investigation, Proposed Sites for Residences, Portion of Stadler Subdivision
			10/08/76	Cooper Clark & Associates	Response to 7/16/76 Review (missing)
			12/10/76	Cooper Clark & Associates	Supplemental Consultation, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
			01/07/77	Cooper Clark & Associates	Comments on Leighton and Associates Memo Dated 12/29/76
			01/14/77	Cooper Clark & Associates (John O'Rourke)	Septic Tank Drainfielsd, Proposed Sites for Residences, 28-Acre Portion of Stadler Suddivision
	10 Stadler Drive		04/09/76	Geo-Ekta Laboratories	Foundation Soils Investigation at Lot 8, Block 6 Skywood Acres

		x	08/24/76	Geo-Ekta Laboratories	Response to Review by Leighton and Associates
	16 Stadler Drive	x	10/22/03	Signa Prime Geosciences, Inc.	Geotechnical Study, Proposed Detached Structure
	35 Stadler Drive		06/15/21	Signa Prime Geosciences, Inc.	Geotechnical Study Proposed Retaining Walls
	50 Stadler Drive	x	06/23/93	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Home Reconstruction and Garage-Guest House Structure
	55 Stadler Drive		11/12/15	Romig Engineers, Inc.	Geological Investigation, Residence Improvements
	60 Stadler Drive	x	05/06/05	JF Consulting, Inc.	Geotechnical Investigation, Lands of Stronck, Remodel & Additions to Residence
			12/21/07	JF Consulting, Inc.	Geotechnical Comments, Proposed Spa and Low Retaining Walls, Lands of Stronck
	70 Stadler Drive	x	05/12/97	Fowler & Associates	Geotechnical Investigation, Proposed Remodeling
	75 Stadler Drive	x	02/24/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	99 Stadler Drive	x	12/08/03	Nielsen Geotechnical Incorporated	Geotechnical Recmmendations, Deck Remodel
			07/21/04	Murray Engineers, Inc.	Geotechnical Investigation, Weiss Residence Addition
			09/13/05	Murray Engineers, Inc.	Supplemental Recommendations, Weiss Residence
	115 Stadler Drive	x	11/15/05	Murray Engineers, Inc.	Geotechnical Investigation, Carter Residence Improvements
			02/10/06	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Carter Residence Improvements
	125 Stadler Drive	x	05/30/76	Howard F. Donley & Associates	Geologic-Soils Investigation, Proposed Single-Family Residence, Lot 3, Section 103, Skywood Acres, Sky Londa No. 1
			05/30/76	Howard F. Donley & Associates	Design details and Structural Caculations
			10/26/76	Howard F. Donley & Associates	Clarification, Geologic-Soils Investigation Report dated May 30, 1976
			06/01/77	Town of Woodside	Review Comments
			06/09/77	Howard F. Donley & Associates	Response to Town Review Comments
			06/30/77	Town of Woodside	Review of Response to Town Review Comments
			05/24/17	Romig Engineers, Inc.	Geotechnical Investigation, Scarlett Residence Improvements

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204268

Record Title & Contents

**GEOTECHNICAL REPORT FOR
STILL CREEK ROAD - STOCKBRIDGE AVENUE**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
-------	---------	------------------	------	-------------	-------

STILL CREEK ROAD					
24A	3 Still Creek Road	x	06/30/98	Michelucci & Associates, Inc.	Temporary Clearing of Access Driveway
			07/09/98	Michelucci & Associates, Inc.	Geotechnical Investigation, Landslide Problem, Job Memorandums
			06/21/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Retaining Wall and Existing Deck Foundation Improvement
	7 Still Creek Road	x			Job Memorandums, Work Authorization Form, HTA Project Set-Up & Data Sheet
SOME OF THE FOLLOWING REPORTS ADDRESS THE ORIGINAL 4-LOT SUBDIVISION AND/OR 35 STILL CREEK ROAD (LOT 4) - SEE ALSO 1/14/77 COOPER CLARK & ASSOCIATES WITH STADLER DRIVE					
INCLUDES COTTON AND ASSOCIATES FILE MATERIALS NOT INDIVIDUALLY REFERENCED FOR 45 STILL CREEK AND FOR THE 4-LOT SUBDIVISION (ID 228)					
	45 Still Creek Road	x	07/19/76	Cooper-Clark & Associates	Geotechnical Investigation, Proposed Sites for Residences, Portion of Stadler Subdivision
			pre 8/19/76	Cooper-Clark & Associates	Proposed Subdivision Parcel D (APN 075-020-01 and 075-020-09)
			08/19/76	Leighton and Associates	Review of pre 8/19/76 report
			10/08/76	Cooper-Clark & Associates	Response to 7/16/76 Review (missing)
			12/10/76	Cooper-Clark & Associates	Supplemental Consultation, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
			12/29/76	William Cotton and Associates	Review of 12/10/76 Report
			12/29/76	Leighton and Associates	Review of 12/10/76 Report
			02/03/77	Cooper-Clark & Associates	Review of Supplemental Data, Dr. New, et.al. Property, Portion of Stadler Subdivision
			02/22/77	Leighton and Associates	Review of 2/3/77 Report
			06/17/77	George L. Quick	Engineering Geologic Investigation of Access Road and Proposed Building Sites, Lots 2 and 3, Lands of Seittle, Et Al
			06/28/77	Leighton and Associates	Review of pre 6/28/77 Report
			07/14/77	George L. Quick	Memo Response to 7/28/77 Review by Leighton and Associates
			07/20/77	Cooper-Clark & Associates	Letter Response to 6/28/77 Review by Leighton and Associates
			03/31/82	Cooper-Clark & Associates	Consultation Services, Review of Revised House and Garage Locations, Lot 4 (3), Land Division #228
			08/16/77	Leighton and Associates	Review of 7/14/77 memo and 7/28/77 reports
			04/15/91	Hydro-Geo Consultants, Inc.	Preliminary Review of Geologic Conditions, Lot 3, Lands of Seittle
			05/16/91	William Cotton and Associates	Review of 4/15/91, 7/19/76, and 6/17/77 reports
			09/12/95	Romig Consulting Engineers	Workscope for Geotechnical Services, Proposed Burton Residence
			10/10/95	Romig Consulting Engineers	Field, Laboratory and Stability Results, Proposed Burton Residence
			10/20/95	Romig Consulting Engineers	Geotechnical Investigation, Proposed Burton Residence

			02/02/96	Louis A.Richardson	Supplemental Geologic Information for Geotechnical Investigation, Proposed Burton Residence
			02/07/96	Romig Consulting Engineers	Supplemental Geologic and Geotechnical Information, Proposed Burton Residence
			04/23/96	Romig Consulting Engineers	Supplemental Geologic and Geotechnical Information, Proposed Burton Residence
			04/25/96	Louis A.Richardson	Additional Supplementary Geologic Information for Geotechnical Investigation, Proposed Burton Residence
			07/17/96	Louis A.Richardson	Proposed Septic Drainfield Site, Burton Residence
STOCKBRIDGE AVENUE					
24A	2120 Stockbridge Avenue	x	06/26/00	J. Yang and Associates	Geotechnical Site Investigation, Proposed Residence
			04/30/01	J. Yang and Associates	Geotechnical Review, Proposed Residence
	2170 Stockbridge Avenue	x	07/01/96	Fowler & Associates	Geotechnical Investigation, Two Proposed Single Family Residences
			04/10/17	Romig Engineerers, Inc.	Geotechnical Innvestigation, Marlow Swimming Pool
	2180 Stockbridge Avenue	x	07/01/96	Fowler & Associates	Geotechnical Investigation, Two Proposed Single Family Residences
	2210 Stockbridge Avenue	x	01/30/96	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Additions and House Remodel
			02/13/97	Michelucci & Associates, Inc.	Supplemental Recommendations and Design Criteria, proposed Swimming Pool and Master Bedroom Wood Deck
	2220 Stockbridge Avenue	x	07/21/92	William Cotton and Associates	Geotechnical Investigation, Pivnicka Residence
			10.17/05	Earth Mechanics Consulting Engineers	Geotechnical Reconnaissance, Planned Pool
			01/17/07	Earth Mechanics Consulting Engineers	Geotechnical Consultation, Planned Improvements
	2290 Stockbridge Avenue	x	03/08/02	PGSoils, Inc.	Geotechncial Investigation, Proposed Residential Upgrade
	2298 Stockbridge Avenue	x	06/30/05	Eddy's Engineering & Construction Services	Soil Investigation, Including Geologic Reconnaissance and Recommendations for Construction of Retaining Walls
			07/15/09	Romig Engineerers, Inc.	Site Improvements
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204269					
Record Title & Contents					
GEOTECHNICAL REPORT FOR SUMMERHILL LANE - SUMMIT SPRINGS ROAD					

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
SUMMERHILL LANE					
25	110 Summerhill Lane	x	07/08/96	Earth Mechanics Consulting Engineers	Geotechnical Reconnaissance Report, Planned Additions and Improvements to Residence
			09/26/96	Earth Mechanics Consulting Engineers	Results of Exploration Program and Plan Review, Additions and Alterations
	135 Summerhill Lane	x	10/19/06	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Addition & Remodel
	140 Summerhill Lane	x	07/12/07	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
SUMMIT ROAD					
25	9 Summit Road	x	09/27/87	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, 7 Lots (APN 076-052-001), Woodside Country Club Sub. No. 4
			10/05/87	PSC Associates, Inc.	Geotechnical Engineering Investigation, Proposed Residence and Garage, 4 Lots
			11/20/02	PSC Associates, Inc.	Review and Update of 10/5/87 Report
			10/21/92	PSC Associates, Inc.	Retaining Walls at Carver Mead Residence, Summit Road
			04/19/93	PSC Associates, Inc.	Supplemental Foundation Engineering Investigation, Proposed Retaining Walls, Mead Residence
			04/29/93	PSC Associates, Inc.	Addendum to the Foundation Recommendations
	Summit Road	x	01/09/81	J. Michael Cleary and Associates	Soil and Foundation Investigation, Combined Lots APN 076-052-020 and 076-082-010
			03/13/81	William Cotton, Town Geologist	Geotechnical Review Sheet
			03/23/81	William Cotton, Town Geologist	Review Comments
			11/21/05	Pacific Geotechnical Engineering	Geologic Feasibility Investigation, Mead/Smith Property APN 076-052-020 and 076-082-010
			12/14/05	San Mateo County Environmental Health	Septic Test Pits
			12/15/05	Langley Hill Quarry	Perc Test Results
			05/26/05	Woodside Fire Protection District	Requirements
					Easement Grant
			06/06/06	Stoecker and Northway Architects, Inc.	APN 076-052-020 and 076-082-010
			06/15/06	Town	Pre-Application Geology Department Comments
	135 Summit Road	x	09/17/02	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Garfinkle Residence
	145 Summit Road	x	08/31/00	Romig Engineers, Inc.	Geotechnical Investigation, Residence Remodel
SUMMIT SPRINGS ROAD					

25	Summit Springs Road at Partition		10/01/85	William Cotton and Associates	Proposal for Geotechnical Services, Slope Monitoring and Geotechnical Evaluation of Road Distress at SST/PR Intersection
			03/13/86	William Cotton and Associates	Geologic Map and Section, SSR/PR Landslide
			03/19/86	William Cotton and Associates	Proposal for Geologic Monitoring of Landslide, SSR/PR Landslide
	450 Summit Springs Road	x	05/22/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed Site Improvements, Steenkamp Property
			02/18/02	GeoForensics, Inc.	Review of Drainage Plans (#3)
	460 Summit Springs Road		12/16/76	R.C. Harlan and Associates	Soil Investigation APN 072-081-130
		x	10/02/02	Steven A. Arnold	Deck Repair and Deck Expansion, Lonergan Residence
			05/21/03	Steven A. Arnold	Deck Repair / Expansion
	470 Summit Springs Road	x	05/25/77	J. Walter Hoskins	Soil Investigation
			07/11/77	Francis A. Stejer	Engineering Geology Study, Lot 9, Block, Woodside Oaks Unit No. 2 (APN 072-081-120)
			09/16/77	J. Walter Hoskins	Revised Soil Investigation
			12/30/77	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Lot 9, Block 1, Woodside Oaks Unit No. 2
			02/10/78	Town of Woodside	Review of Purcell, Rhoades & Associates report
			11/06/84	Tim J. Manzagol	Soil and Geologic Investigation
			11/16/84	William Cotton and Associates	Landslide Repair
			11/19/84	William Cotton and Associates	Landslide Repair
			11/24/84	Town of Woodside	Memo from Town Engineer to Town Manager on Landslide Repair
			?	William Cotton and Associates	Geotechnical Review Sheet
			12/14/84	William Cotton and Associates	Preliminary Geologic and Geotechnical Review. Home Equity - Landslide Repair
	475 Summit Springs Road	x	07/13/73	Geo-Ekta Laboratories / Goss & Associates, Inc.	Slope Stability Analysis, Lot 8, Tract 714, Woodside Oaks II
			11/28/90	Hydro-Geo Consultants, Inc.	Preliminary Geologic Review (Lands of Wang)
			03/31/91	Frank Lee & Associates	Soil and Foundation Investigation, Proposed Two-Story Single-Home
			11/22/91	Hydro-Geo Consultants, Inc.	Supplement to Preliminary Geologic Report
			09/07/99	McLeod and Associates	35% Slope Analysis
	480 Summit Springs Road	x	06/28/63	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Parcels 7 (490) and 8 (480), Block 1, Tract 714
			01/13/75	Daniel J. Rhoades & Associates	Soil Report
			09/02/76	Purcell, Rhoades & Associates	Site Inspection and Consultation, 480 Summit Springs Road
			11/17/76	Soil Engineering Construction, Inc.	Slope & Structural Repairs

			11/22/76	Purcell, Rhoades & Associates	Comments on Slide Repair Design
			11/30/76	Purcell, Rhoades & Associates	Soil and Geological Engineering Report
			12/02/76	Leighton and Associates	Comments on Slide Repair
			12/06/76	Randlett & Foulk, Inc.	Slide Repair
			12/06/76	Randlett & Foulk, Inc.	Structural Calculations
			12/08/76	Leighton and Associates	Review of Revised Slide Repair
			03/13/02	Ting & Associates, Inc.	Geotechnical Investigation, Proposed Garage
			03/23/04	Ting & Associates, Inc.	Deck Recommendations, Proposed Decks
			08/30/04	Louis A. Richardson	Engineering Geologic Reconnaissance Study (APN 072-081-110)
			05/08/05	Ting & Associates, Inc.	Proposed Remodeling, Garage, and Deck Recommendations (DRAFT)
			05/08/05	Ting & Associates, Inc.	Proposed Remodeling, Garage, and Deck Recommendations
485 Summit Springs Road	x		05/19/67	Crosby & Associates	Slide Repair
			07/03/68	Hawke Engineers	Soil Investigation and Consultation, Single Family Residence
			05/26/69	Technical Services Company, LTD.	Site Plan, Sections, Logs, Etc. for Proposed Design for Correction of Slide Damage
			08/22/69	Technical Services Company, LTD.	Existing Conditions, Proposed Septic Tank System
			08/26/69	Technical Services Company, LTD.	Letter to Town
			12/16/74	Civil & Construction Consultants, Inc.	Foundation Piers Boring Logs for Driveway Structure
			02/23/77	Civil & Construction Consultants, Inc.	Addition to Cramer Residence
			03/18/77	Leighton and Associates	Review of References
			03/14/83	William Cotton and Associates	Summit Springs Road - Kramer Landslide
			06/09/83	Civil & Construction Consultants, Inc.	Proposed Retaining Wall Construction Adjacent to the Public Roadway
			06/29/83	William Cotton and Associates	Geotechnical Review Sheet
			07/13/83	William Cotton and Associates	Cramer Retaining Wall
490 Summit Springs Road	x		06/28/63	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Parcels 7 (490) and 8 (480), Block 1, Tract 714
			04/22/05	Upp Geotechnology, Inc.	Limited Geotechnical Investigation
550 Summit Springs Road	x		11/02/78	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Lot 5, Block 3, Woodside Oaks Unit No, 2
			12/15/78	Gary L. Holmes, Architect	Site Plan with annotations
			01/05/79	William Cotton and Associates (?)	Summary of Field Review on 1/3/78
			01/26/79	William Cotton and Associates (?)	Geologic Review - Holmes Conformity

	555 Summit Springs Road	x	04/17/68	Cooper-Clark & Associates	Soil Investigation Report, Proposed Residence, Lot 1, Blook 2, Woodside Oaks Unit 2 (APN 072-083-160)
			03/30/88	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Swimming Pool and Deck Addition, Flood Residence
	560 Summit Springs Road	x	11/02/78	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Lot 5, Block 3, Woodside Oaks Unit 2 (APN 072-082-050)
			04/18/02	GeoForensics Inc.	Geotechnical Investigation of Fireplace Distress, Matthews Property
	575 Summit Springs Road	x	05/04/77	Purcell, Rhoades & Associates	Soil and Geologic Investigation, Lot 2
			06/01/77	Town of Woodside	Review
			06/02/77	Purcell, Rhoades & Associates	Plan Review
	580 Summit Springs Road	x	03/31/99	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Addition & Remodeling
			12/03/99	Hydro-Geo Consultants, Inc.	Engineering Geologic Assessment, Proposed Remodeling of Single-Family Residence
			12/22/99	American Soil Testing, Inc.	Supplemental Recommendations, Proposed Addition & Remodeling
			11/30/06	Romig Engineers, Inc.	Geotechnical Investigations, Greening Residence Addition
			06/25/07	Romig Engineers, Inc.	Geotechnical Report Update, Greening Residence Remodel
			01/19/09	Romig Engineers, Inc.	Geotechnical Recommendations, Driveway Retaining Walls
	600 Summit Springs Road	x	06/09/61	Woodward-Clyde-Sherard and Associates	Preliminary Soil Investigation, Proposed Summit Springs Subdivision
			06/16/81	Donald A Wollfe & Associates	Environmental Assessment, Summit Springs Property
			03/23/79	Howard Donley Associates, Inc.	Preliminary Terrain Analysis Report, Proposed 625 acre Housing Development, Summit Springs Property
			06/23/97	Pacific Geotechnical Engineering	Preliminary Geologic Feasibility Evalustion, Keenan Project, MPROSD Property
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204270					
Record Title & Contents					
GEOTECHNICAL REPORT FOR SUMMIT SPRINGS SUBDIVISION - TOYON COURT					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
SUMMIT SPRINGS SUBDIVISION					
25A	Summit Springs Subdivision		08/04/86	William Cotton and Associates	Geotechnical Review Sheet
			08/12/10	William Cotton and Associates	Summit Springs Grading for Access Road
			07/06/08	Brian Kangas Foulk	Map - Grading Permit Application - Summit Springs Testing Program

SUNRISE DRIVE					
25A	105 Sunrise Drive	x	09/13/84	Melvin R. Hill, Inc.	Soil Investigation
				William Cotton and Associates	Geotechnical Review Sheet
			10/31/84	Baronian & Danielson	Location Plan, with annotations
			07/24/85	William Cotton and Associates	Preliminary Geologic Review and Geotechnical Investigation Evaluation, Lands of Bastel, #2730
			07/06/89	Melvin R. Hill, Inc.	Plan Review
			09/28/89	SOHA	Structural Calculations
			08/10/89	William Cotton and Associates	Review Comments - Soil Investigation (9/84)
			08/14/89	Melvin R. Hill, Inc.	Response to Town Review Comments
			0/0/89	William Cotton and Associates	Geotechnical Review Sheet - Bastl
	125 Sunrise Drive	x	09/08/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Clausen
				William Cotton and Associates	Geotechnical Review Sheet
			10/26/87	Soil Engineering Construction, Inc.	Retainin Wall Calculations
			11/02/87	Soil Engineering Construction, Inc.	Site Plan
			11/16/87	Upp Geotechnology, Inc.	Review of Retaining Wall Plans, Clausen Residence
			11/24/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Causen Landslide Mitigation, PA #4443
					Photographs
			12/17/87	Upp Geotechnology, Inc.	Addendum Geotechnical Investigation of Landslide, Lands of Clausen
			01/11/88	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Clausen Landslide Mitigation, PA #4443
			03/24/88	Upp Geotechnology, Inc.	Construction Monitoring: Drainage System, Landslide Mitigation, Clausen Residence
			05/04/89	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Adition to Stockdale Residence
	140 Sunrise Drive	x	01/01/85	William Cotton and Associates	Preliminary Geologic Review, Anderson Pool, Variance 368
			01/11/85	Lifetime Pools	Site Plan, with annotations
			01/21/85	William Cotton and Associates	Geotechnical Review Sheet
			02/22/90	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Addition
	150 Sunrise Drive	x	09/30/97	Romig Consulting Engineers	Geotechnical Investigation, Braunstein Residence Slide Repair
			12/16/93	Nielsen Geotechnical Incorporated	Soil Report, Residential Additions
	155 Sunrise Drive	x	09/16/88	Upp Geotechnology, Inc.	Geotechnical Investigation, Slope Stabilization
			09/16/02	Upp Geotechnology, Inc.	Geotechnical Investigation Report Update and Plan Review, Muller Property
			10/22/02	Upp Geotechnology, Inc.	Response to Town Comments and Supplemental Plan Review, Slope Stabilization

			01/30/03	Upp Geotechnology, Inc.	Construction Observation, Retaining Wall and Deck, Muller Property
			12/03/04	Upp Geotechnology, Inc.	Supplemental Recommendations, Deck Piers, Muller Property
			12/22/04	Upp Geotechnology, Inc.	Supplemental Recommendations, Deck Piers, Muller Property
	160 Sunrise Drive	x	07/25/95	Earth Investigations Consultants	Geotechnical Consultation, Garage Foundation Rehabilitation
			07/31/95	Earth Investigations Consultants	Geotechnical Consultation, Proposed Leachfield Rehabilitation
			08/08/95	Earth Investigations Consultants	Geotechnical Consultation, Addendum to Report, Proposed Leachfield Rehabilitation
			08/31/95	Nielsen Geotechnical Incorporated	Geotechnical Review, Leach Field Repair - Deep Sumps
			09/12/95	Nielsen Geotechnical Incorporated	Response to Town's Review, Deep Sumps Septic System
	165 Sunrise Drive	x	04/17/07	Applied Earth Investigations Consultants	Single Family Residential Site Development Feasibility (Geotechnical) - Lot 9
	170 Sunrise Drive	x	09/20/76	Terrasearch, Inc.	Soil Investigation, Proposed Additions
			07/12/10	Murray Engineers, Inc.	Engineering Geologic & Geotechnical Investigation, Pre-Purchase Evaluation
	175 Sunrise Drive	x	08/11/80	Nordmo Associates	Soil Engineering Services, Proposed Recreational Facility
TANDIN LANE					
25A	1502 Tandin Lane	x	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation
			01/22/88	William F. Jones, Inc.	Site Investigation, Proposed Residence, Corner of Tandin Lane and Portola Road
			12/02/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kelley, Permit Application #5073
			01/10/89	William F. Jones, Inc.	Responses to Town Geologist's Review Letter
			02/14/89	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Kelley, Permit Application #5073
	1510 Tandin Lane	x	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation
	1518 Tandin Lane	x	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation
TODO EL MUNDO					
25A	100 Todo El Mundo	x	02/05/73	Crosby & Associates	Foundation Investigation, Jacobs Site, Oakhaven Way and Woodside Drive
			02/15/73	Town of Woodside	Question to Town Attorney
			02/21/73	Jon C. Cummings, Town Geologist	Review of 2/5/73 CA Addendum Report
			03/20/73	Joe Crosby & Associates	Addendum to Report Dated February 5, 1979, Supplemental Geologic Investigation
			4/0/78	Edwin H. Smith	Preliminary Map, Resubdivision of Parcel 1, Land Division Map No. 189
			04/28/73	Jon C. Cummings, Town Geologist	Review of 4/28/73 JCA Report

			06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
			07/25/78	Leighton and Associates, Inc.	Review of 6/29/78 PRA report
			08/08/78	William Cotton and Associates	Geotechnical Review - Coleman Land Division
150	Todo El Mundo	x	06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
			11/11/85	Michael S. Helm - Architect	Site Plan, with annotations
			03/21/86	Washington - Jensen & Associates	Structural Calculations for Residence
			04/23/86	Purcell, Rhodes & Associates	Soil Engineering and Geology Report Update, Proposed Residence
			06/12/86	William Cotton and Associates	Geotechnical Review Sheet
			06/19/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Erlin
			05/14/87	Purcell, Rhodes & Associates	Plan Review, Proposed Swimming Pool
			07/02/87	William Cotton and Associates	Supplemental Review, Erlin Pool, P.A. #4161
200	Todo El Mundo		06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
210	Todo El Mundo	x	03/11/85	Jo Crosby & Associates	Geotechnical Investigation, Proposed Addition to Garage
			11/14/02	Soil Engineering Construction Inc.	Soil and Foundation Report, Home Remodeling
			07/24/03	Soil Engineering Construction Inc.	Minimum Geotechnical Report, Remodeling Work
			09/29/03	Soil Engineering Construction Inc.	Geotechnical Engineering Review
220	Todo El Mundo	x	06/23/89	Shen & Associates	Geotechnical Investigation, Proposed Addition
			04/24/08	Sigma Prime Geosciences, Inc.	Geotechnical Study, Merwin Property
			03/13/09	Sigma Prime Geosciences, Inc.	Geotechnical Study, Merwin Property
			03/18/09	Sigma Prime Geosciences, Inc.	Response Letter, Remodel
230	Todo El Mundo	x	12/12/01	Romig Engineers, Inc.	Geotechnical Investigation, Upton Residence
			10/10/03	Romig Engineers, Inc.	Supplemental Recommendations, Residence Addition
TOYON COURT					
25A	103 Toyon Court	x	12/03/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
			03/04/97	Earth Investigations Consultants	Supplemental Geotechnical Parameters, Proposed Foundation Retaining Wall, Room Addition
			01/14/98	PGSoils, Inc.	Geotechnical Investigation, Proposed Additions
			04/14/99	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Remodel
			07/10/01	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Addition
			09/04/01	Earth Investigations Consultants	Supplemental Geotechnical Information, Seismic Design Parameters, Residential Remodel
			09/17/01	Earth Investigations Consultants	Geotechnical Update and Plan Review

	115 Toyon Court	x	05/23/84	Earth Systems Consultants	Summary Report - Geotechnical Study, Adams Residence
			07/23/84	William Cotton and Associates	Geotechnical Review Sheet
			07/27/84	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Adams Residence - Remedial Repairs
			08/06/84	Earth Systems Consultants	Response to Review Consultants Comments, Adams Residence
			08/16/84	William Cotton and Associates	Geologic Review, Adams Residence - Remedial Repairs
			08/20/84	Earth Systems Consultants	Response to Review Consultants Comments Letter of August 16, 1984
			08/23/84	William Cotton and Associates	Supplemental Geologic/Geotechnical Review, Adams Residence - Remedial Repairs
			01/10/85	Upp Geotechnology	Geotechnical Investigation of Distressed Property, Adams Residence
			04/18/85	Harrison, Teasley & Associates, Inc.	Structural Calculations, Adams Residence
			05/10/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review, Adams Repairs for Distressed Residence, APN 73-033-28
	118 Toyon Court	x	12/26/95	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Addition
	120 Toyon Court	x	10/29/89	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Addition
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204271					
Record Title & Contents					
GEOTECHNICAL REPORT FOR TRAIL LANE - TRIPP ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
TRAIL LANE					
26	20 Trail Lane	x	02/15/06	Murray Engineers, Inc.	Preliminary Fault Location Evaluation
	30 Trail Lane	x	02/02/77	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Proposed New Structures
			09/12/00	Louis A Richardson	Fault Trenching Investigation
			09/14/00	Nielsen Geotechnical Incorporated	Transmittal of 9/12/00 report
			08/28/02	Nielsen Geotechnical Incorporated	Soil Report
			07/03/03	Nielsen Geotechnical Incorporated	Recommendations, Marks House

			07/17/03	Nielsen Geotechnical Incorporated	Geotechnical Review Response
			07/29/03	Nielsen Geotechnical Incorporated	Geotechnical Review Response
			08/11/03	Northwest Hydraulic Consultants	100-Year Flood Elevations
			08/28/03	Nielsen Geotechnical Incorporated	Soil Report, New Marks House
			01/08/04	RJ Dailey Construction Co.	Settlement Monitor Log
			09/16/04	Murray Engineers Inc	Supplemental Geotechnical Recommendations, Marks Swimming Pool
TRIPP COURT					
26	10 Tripp Court	x	04/26/00	Nielsen Geotechnical Incorporated	Soil Report
	30 Tripp Court	x	06/02/80	Howard Donley Associates, Inc.	Site Investigation, Residential Swimming Pool
			06/12/80	William Cotton and Associates	Review of Geotechnical Letter report - Sudano Pool Site
			07/21/80	Howard Donley Associates, Inc.	Soil Investigation, Swimming Pool
			08/19/80	William Cotton and Associates	Geotechnical Review Sheet
			08/27/80	William Cotton and Associates	Geotechnical Review Sheet
			06/08/94	JCP - Engineers and Geologists	Soil and Foundation Study, Proposed Addition and Retaining Wall
			11/29/94	GeoForensics, Inc.	Geotechnical Report, Proposed Study Addition, Bowles Residence
	35 Tripp Court	x	01/14/08	Murray Engineers, Inc.	Geotechnical Services, Ahern Residence
	40 Tripp Court	x	05/23/00	Cyme. Inc.	Geotechnical Investigation, Addition and Remodel, Begun Residence
			02/14/01	Cyme. Inc.	Geotechnical Review of Final Design Plans and Response to Town Review Comments
	45 Tripp Road	x	07/07/05	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
	55 Tripp Court	x	03/17/01	Nielsen Geotechnical Incorporated	Soil Report
			08/11/03	Nielsen Geotechnical Incorporated	Construction Report, Basement Addition
	60 Tripp Court	x	06/29/65	San Mateo County Public Health & Welfare	Letter to Dr. Daniel Liebovitz
			04/20/77	Soil Engineering Construction, Inc.	Soil and Geologic Investigation
			05/11/77	Leighton and Associates	Review of 4/20/77 SEC report
				Soil Engineering Construction, Inc.	Logs of Test Pits 1 dn 2

	65 Tripp Court	x	08/17/94	Nielsen Geotechnical Incorporated	Soil Report
TRIPP ROAD					
26	3301 Tripp Road	x	05/15/91	Michelucci & Associates, Inc.	Fault-Hazard Investigation, Proposed Garage-Guest House
			08/19/96	Clearly Consultants, Inc.	Fault Location Investigation, Residence Addition
			01/14/97	Nielsen Geotechnical Incorporated	Soil Report
	3366 Tripp Road	x	04/13/89	Design Plus	Site Plan with annotations
				William Cotton and Associates	Geotechnical Review Sheet
			06/07/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Pederson #7284
	3460 Tripp Road		08/03/15	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
	3490 Tripp Road		04/26/17	Romig Engineers, Inc.	Geotechnical Investigation, Schembri Residence
	3530 Tripp Road	x	08/02/79	PSC Associates. Inc.	Geologic and Soil Engineering Investigation, Proposed Swimming Pool
			08/28/00	Nielsen Geotechnical Incorporated	Soil Report
			09/05/02	Nielsen Geotechnical Incorporated	Construction Report
	3573 Tripp Road	x	10/01/70	County of San Mateo	Letter on Percolation Test Results
			05/15/71	William G. Rummel	2 letters with this date on Septec Systemtest Results
			04/25/75	Daniel J. Rhoades & Associates	Soil and Geologic Hazard Study, Portion of Lot 4, tract 3, greer Partition
			09/24/76	Purcell, Rhoades & Associates	Review of 4/25/75 Report
			10/04/76	Town of Woodside	Review of 4/25/75 and 9/24/76 Reports
			11/19/76	Town of Woodside	Review of Revised Building Location
			02/28/77	Purcell, Rhoades & Associates	Fault Location on a Portion of Lot 4, Tract 3, Greer Partition (APN 072-141-030)
			3/0/77	Fisher Land Surveying	Preliminry Map
			03/22/77	Town of Woodside	Fault Location , Portion of Lot 4, Tract 3, Greer Partition
			09/06/83	Purcell, Rhoades & Associates	Soil and Geologic Study, APN 072-141-030
			03/20/85	Purcell, Rhoades & Associates	Soils Report Update (APN 072-141-030)
			04/02/85	Purcell, Rhoades & Associates	Plam Review - APN 072-141-030
			04/09/85	William Cotton and Associates ?	Geotechnical Review Sheet
			04/12/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
			04/30/85	Purcell, Rhoades & Associates	Plan Review Update - APN 072-141-030

			05/14/85	William Cotton and Associates ?	Notes on Fault Trench Inspection
			05/16/85	William Cotton and Associates ?	Notes on Fault Trench Inspection
			0/0/85	William Cotton and Associates	Photographs of Fault Trench
					Plat Plan, with annotations
			06/17/85	Purcell, Rhoades & Associates	Fault Evaluation Study (APN 072-141-030)
			07/03/85	William Cotton and Associates	Supplemental Geologic Review, Lands of Bullock (Schlosser), Fault Investigation
			08/13/03	Earth Investigations Consultants	Soil Investigation, Existing Carrage House
3577 Tripp Road	x		08/23/74	Geolabs - Northern California, Inc.	Magnetometer and Subsurface Investigation, Portion of Lot 4, Tract 3
			09/10/74	Town of Woodside	Review of Geolabs Report
			09/24/74	Town of Woodside	Review of Geolabs Report
			10/16/74	Town of Woodside	Approval Letter
3585 Tripp Road	x		06/06/00	Romig Engineers, Inc.	Geotechnical Investigation, Witter Residence Addition
3590 Tripp Road	x		05/24/00	John H. Dailey	Geotechnical Investigation, Proposed Residential Additions
			09/27/00	John H. Dailey	Response to Town Comments
3600 Tripp Road	x		04/07/99	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Addition, Existing Residence & Swimming Pool
			04/27/11	PGSoils, Inc.	Geotechnical Conditions, Fox Residence Remodeling
3615 Tripp Road	x		08/16/10	Romig Engineers, Inc.	Geotechnical Investigation, Pilch Residence Addition
3635 Tripp Road	x		10/27/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Pool House
			06/04/02	Earth Investigations Consultants	Geotechnical Site Review, Proposed Garage Expansion
			01/19/09	Earth Investigations Consultants	Geotechnical Investigation, Proposed Covered Porch
3660 Tripp Road	x		12/14/00	Romig Engineers, Inc.	Geotechnical Investigation, Patterson Residence Addition
			05/19/09	Connell Geotechnical, Inc.	Geotechnical Investigation, Dearing Residence Addition
			05/15/09	Louis A. Richardson	Engineering Geologic Reconnaissance Study
			10/05/11	Connell Geotechnical, Inc.	Supplemental Geotechnical Engineering Recommendations, Detached Accessory Structure
3710 Tripp Road	x		08/25/03	Alliance Environmental and Soil Engineering	Soil and Foundation Investigation, Residential Addition and Remodeling
			01/30/04	Alliance Environmental and Soil Engineering	Clarification, Residential Second Story Addition

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204272

Record Title & Contents

GEOTECHNICAL REPORT FOR

TUM SUDEN WAY - VALLEY COURT/ROAD

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
TUM SUDEN WAY					
26A	67 Tum Suden Way	x	12/29/89	Shen & Associates	Geotechnical Investigation, Proposed Addition and New Garage
			09/12/89	ARC Associates	Site Plan , Tum Suden Residence
				William Cotton and Associates	Geotechnical Review Sheet
			04/07/98	Earth Invstigations Consultants	Geotechnical Investigation, Stoker Residence
	70 Tum Suden Way	x	10/16/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed New Front Porch and Deck
	71 Tum Suden Way	x	03/17/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Wood Deck Replacement
	82 Tum Suden Way	x	10/03/86	Ling Chen Associates	Site Plan, with annotations
			10/12/86	SJK Structural Design	Soil and Geologic Investigation, Proposed Residence, Parcel 19 and 20, Block 602
				William Cotton and Associates	Geotechnical Review Sheet
			12/10/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kohl Residence, PA #3347
	91 Tum Suden Way	x	11/13/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
			09/23/03	Earth Investigations Consultants	Engineering Geological Site Review, Proposed 2-Lot Residential Subdivision, Parcel B, 91 Tum Suden Way
			12/23/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Detached Garage and Driveway
TURKEY FARM LANE					
26A	1 Turkey Farm Lane	x	05/05/86	TransPacific Geotechnical Engineers, Inc.	Geotechnical Investigation, Proposed Pool House and Swimmimg Pool, Ellison's Residence
			07/03/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Ellison Pool and Pool House
			10/11/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Pool House
			01/27/97	GeoForensics, Inc.	Report Update and Plan Review, Proposed New Pool and Spa
	25 Turkey Farm Lane	x	07/25/96	Earth Investigations Consultants	Geotechnical Services, Soil and Foundation Investigation, Proposed Second-Story Addition
			01/13/97	Earth Investigations Consultants	Geotechnical Services, Response to Town Comments on Soil and Foundation Investigation
	45 Turkey Farm Lane	x	07/21/89	Cleary Consultants, Inc.	Geotechnical and Geologic Investigation, Kitchen Addition
			07/24/98	Cleary Consultants, Inc.	Geotechnical Investigation, Pool House Addition
UPENUF ROAD					
26A	25 Upenuf Road	x	05/27/86	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Parcel 076-102-040

			7/0/86	Brian Kangas Foulk & Associates	Topographic Survey, Lot 267-271 Woodside Country Club Subdivision 3, with septic system annotations
			08/07/86	County of San Mateo	Letter to Mr. Bolton
			09/15/86	County of San Mateo	Letter to Mr. Woods
			09/24/86	Upp Geotechnology	Trenching, Bolton Site
			11/06/86	Perry R. Wood	Letter to San Mateo County Department of Health Services
			12/04/86	Perry R. Wood	Letter to Mr. Bolton
			12/17/86	Upp Geotechnology	Preliminary Geotechnical Investigation, Lands of Bolton (APN 076 102 040), Old La Honda Road
				William Cotton and Associates	Geotechnical Review Sheet
			01/23/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review. Bolton Building Site feasibility
			06/19/87	Upp Geotechnology	Geotechnical Investigation, Lands of Bolton (APN 076 102 040), Old La Honda Road
			07/13/87	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Parcel 076-102-040
			07/17/87	William Cotton and Associates	Supplemental Geotechnical Review, Bolton Building Site Feasibility, APN 076-102-040
			03/22/88	Perry R. Wood	Letter to Mr. Bolton
			10/12/89	Upp Geotechnology, Inc.	Geologic Update, Lands of Perry, Old La Honda Road, APN 076 102 040
			10/0/90	Brian Kangas Foulk & Associates	Topographic Survey, Lot 267-271 Woodside Country Club Subdivision 3, with > 35% slope annotations
			02/27/90	Questa Engineering Corporation	Sewage Disposal Evaluation
			08/16/90	Upp Geotechnology, Inc.	Review of Foundation Plans, Perry Residence, Old La Honda Road, APN 076 102 040
			02/01/91	Upp Geotechnology, Inc.	Review of Foundation Plans, Perry Residence, Old La Honda Road, APN 076 102 040
			05/20/91	William Cotton and Associates	Preliminary Geotechnical Review, Perry, PA #8215
87 Upenuf Road	x		01/06/78	Purcell, Rhoades & Associates	Preliminary Soils and Geologic Investigation, Proposed Pool
			02/17/78	Leighton and Associates	Review
			04/24/78	Purcell, Rhoades & Associates	Reply to Conclusions in Review By Leighton and Associates
			06/26/78	Purcell, Rhoades & Associates	Plan Review and Request for Additional Information for Proposed Swimming Pool
			07/13/78	Leighton and Associates	Review
			09/01/71	Sandis and Associates	Contour Map
33 Upper Big Tree Road			12/22/99	Upp Geotechnology, Inc.	Geotechnical Investigation Proposed New Residence and Leachfield

UPPER LAKE ROAD					
26A	15 Upper Lake Road	x	01/15/80	Terratech, Inc.	Geologic and Geotechnical Investigation, Lands of Eldredge
			01/15/80	Terratech, Inc.	Proposed Road Improvements
			01/17/80	Terratech, Inc.	Plan Review, Lands of Eldredge
			02/14/80	William Cotton and Associates	Geologic Review - Eldridge Property
			05/20/80	Terratech, Inc.	Plan Review - Alternative Access Roads, APN 75-272-030
			05/22/80	Fischer Land Surveying	Tree Loss Estimates and Grading Quantities
			06/12/80	William Cotton and Associates	Geologic Review - Eldridge Property
			07/08/80	Terratech, Inc.	Alternate Homesite, APN 75-272-030
			08/18/80	William Cotton and Associates	Geologic Review - Eldridge Property
			05/30/85	Terratech, Inc.	Geotechnical Information - Nusbaum Residence
			07/10/85	William Cotton and Associates	Geotechnical Review Sheet - Nusbaum
			07/12/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review - Nusbaum
			08/02/85	Terratech, Inc.	Update of Geologic and Geotechnical Investigation - Nusbaum Property
			08/02/85	Hoskins Engineering, Inc.	Structural Calculations - Nusbaum Water Tank
			08/08/85	Donald W. Nusbaum	Nusbaum Property - Supplemental Geologic/Geotechnical Review
			08/26/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review - Lands of Nusbaum
			03/11/86	William Cotton and Associates	Supplemental Geologic Review - Nusbaum Water Tank Variance
			04/25/16	Michelucci & Associates, Inc.	Geotechnical Investigation-Proposed Improvements
			12/15/16	Lea & Braze Engineering, Inc	Hydrology Study
	17 Upper Lake Road	x	12/06/77	Purcell Rhoades & Associates	Soil and Geologic Investigation
			04/03/78	Town of Woodside	Review of Soil and Geologic Investigation and Plans
			04/17/85	Frahm Elder Cannis	Site Drainage / Water Supply / Septec Tank-Leachfield Plan, with annotations
			05/01/85	various	Application fo Variance Necessary to Construct a Single Family Residence APN 075-240-110
			05/02/85	William Cotton and Associates	Geotechnical Review Sheet
			05/15/85	William Cotton and Associates	Preliminary Geologic / Geotechnical Review, Lands of Thayer, Variance 376
			05/20/85	Purcell Rhoades & Associates	Addendum to Soil and Geologic Investigation
			06/02/85	Mr. Thayer	Letter to Town responding to request for additional information
			06/06/85	Town of Woodside	Review by Town Engineer
			06/09/85	Mr. Thayer	Comments on alternative schemes for new residence
			06/11/85	William Cotton and Associates	Supplemental Geologic / Geotechnical Review, Lands of Thayer, Variance 376

			06/16/85	Mr. Thayer	Letter to Town responding to request for additional information
			06/19/85	Mr. Thayer	Letter to Town responding to William Cotton and Associates reviewq
			06/19/85	Purcell Rhoades & Associates	lternative Site Plan Review
			07/03/85	Donald W. Nusbaum	Letter to Thayer OK road widening
			07/31/85	Frahm Elder Cannis	Upper Lake Road Improvements, Lands of Thayer
			08/23/85	Purcell Rhoades & Associates	Plan Review
			09/18/85	William Cotton and Associates	Supplemental Geologic / Geotechnical Review, Lands of Thayer
			11/01/85	Purcell Rhoades & Associates	Plan Rewview - Upper Lake Road Improvements
			11/15/85	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Thayer
VALLEY COURT / ROAD					
26A	Valley Court	x	06/19/87	Terratech, Inc	Geologic Feasibility Evaluation, Lands of Halperin
			09/16/88	Terratech, Inc	Geotechnical Investigation, Lands of Halprin
	45 Valley Court		01/24/92	Louis A. Richardson	Engineering Geologic Considerations, Residential Construction (APN 073-141-220)
			02/19/92	William McMorrow	Geotechnical Engineering Evaluation, Proposed New Home Construction (APN 073-141-220)
			08/18/93	William McMorrow	Geotechnical Engineering Plan Review & Response to Review Comments on 2/19/92 Report, Single-Family Residence
			10/25/93	Louis A. Richardson	Response to Review Comments and 1/24/92 Report
	50 Valley Court	x	02/12/08	Romig Engineers, Inc.	Geotechnical Investigation, Medina Residence
			02/12/08	Romig Engineers, Inc.	Geotechnical Investigation, Medina Residence
			09/25/09	Romig Engineers, Inc.	Supplemental Recommendations, Medina Residence
			01/22/10	Romig Engineers, Inc.	Response to Town Comments, Medina Residence
			04/01/10	Michelucci & Associates, Inc.	Planned New Rock Walls, Medina Residence
	60 Valley Court	x	05/31/98	Nielsen Geotechnical Incorporated	Soil Report (APN 073-141-350)
			09/22/01	Nielsen Geotechnical Incorporated	Construction Report, Berry House and Cottage (APN 073-141-350)
			03/17/08	Murray Engineers, Inc.	Geotechnical Recommendations, New Barn & Swimming Pool
			11/25/08	Murray Engineers, Inc.	Supplemental Recommendations, Site Retaining Walls, Newton Barn
	70 Valley Court	x	08/31/98	Frederick Maurer, Jr.	Geotechnical Investigation, Chuter Residence
			04/19/01	Frederick Maurer, Jr.	Supplemental Report, Geotechnical Investigation, Proposed Chuter Residence Barn
	80 Valley Court	x	07/06/95	Terratech, Inc	Geologic and Geotechnical Update and Review of Initial Foundation Plans, Proposed Dow Residence
			04/24/97	Terratech, Inc	Geotechnical Recommendations, Proposed Dow Residence Pool and Pool House
			10/09/01	Bay Area Geotechnical Group	Limited Geotechnical Investigation, Dow Property

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204274					
Record Title & Contents					
GEOTECHNICAL REPORT FOR VINEYARD HILL ROAD - WEST CALIFORNIA WAY					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
VINEYARD HILL ROAD					
27	3 Vineyard Hill Road	x	04/12/77	Cooper Clark & Associates	Investigation of Potential Geologic Hazards, Parcel 1, LD #153
			04/11/77	Perry Wood	Soil Percolation Test for Septic Drain Facilities- Mountain Home Road & Vineyard
			06/02/78	Dunham & Associates	Soil Investigation, Proposed Home, Parcel 3, Land Division 237 (APN 072-211-680)
	7 Vineyard Hill Road	x	04/12/77	Cooper Clark & Associates	Investigation of Potential Geologic Hazards, Parcel a, LD#153
			4/13,/96	Nielsen Geotechnical Incorporated	Soil Report
	10 Vineyard Hill Road	x	08/08/97	Jo Crosby & Associates	Geotechnical Review, Planned Grading and Drainage
			09/18/97	Jo Crosby & Associates	Geotechnical Review, Planned Grading and Drainage
			10/17/97	Jo Crosby & Associates	Revised Geotechnical Analysis, Planned Grading and Drainage
			07/27/99	Applied Earth Sciences Consultants	Geotechnical Report, Backyard Drainage Control and Landscape Pond Construction
			10/08/99	Applied Earth Sciences Consultants	Response to Town of Woodside Questions re: Proposed Landscape Pond
			03/05/00	Applied Earth Sciences Consultants	Response to Geotechnical Review Letter dated 1/7/00 re: Proposed Landscape Pond
			10/11/00	Geomatrix Consultants, Inc.	Hydrologic/Seismic Review, Proposed Drainage Control and Landscape Pond
			various	provided by Applied Earth Sciences Consultants	Attachmanrs 1 - 8 for Pond Project
	12 Vineyard Hill Road	x	11/15/91	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Walsh Additions/Remodel
VINTAGE COURT					
27	1, 3, and 5 Vintage Court	x	03/02/70	Jo Crosby and Associates	Geologic Investigation, Land Division 146
			08/07/70	Ben Page	Field Observations of San Andreas Fault trenches
			08/25/70	Reynolds and Associates	Soil Engineering and Geologic Investigation
			10/20/70	Willard Somers	Owners Response

			10/31/70	Ben Page	Supplemental Comments on Observations
			10/12/77	Brian Kangas Foulk & Associates	Preliminary Site Development Plan
			03/20/78	Terrasearch, Inc.	Soils and Geologic Investigation, Goumas Property. Parcel M, Land Division Map No. 22
			06/06/78	Terrasearch, Inc.	Percolation Test Results , Goumas Property
			8/0/78	Brian Kangas Foulk & Associates	Preliminary Map - Land Division No. 248
			08/15/78	William Cotton and Associates	Review Comments on 3/20/78 report
			08/29/78	William Cotton and Associates	Geotechnical Reviews - Goumas Land Division
			11/06/78	William Cotton and Associates	Geotechnical Review - Goumas Land Division
1 Vintage Court			07/02/01	GeoForensics Inc.	Geotechnical Investigation, Proposed New Pool and Tennis Court
			09/09/04	J. Yang and Associates	Geotechnical Site Investigation, Proposed Retaining Wall Repair
			12/23/04	J. Yang and Associates	Geotechnical Site Investigation, Revision 1, Proposed Retaining Wall Repair
			04/12/08	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Barn
3 Vintage Court	x		05/20/85	Terrasearch, Inc.	Update of Soil Investigation, Lot 2, Soficon Way
			02/20/90	Terrasearch, Inc.	Update Geotechnical and Geological Investigation and Supplemental Recommendations, Lot 2, Soficon Way
				William Cotton and Associates	Geotechnical Review Sheet
			05/04/90	William Cotton and Associates	Preliminary Geologic Review, Hooper Site Development, 2 Soficon Way
			05/22/90	Terrasearch, Inc.	Supplemental Geologic Investigation, Lot 2, Soficon Way (Vintage Court)
			08/31/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Hooper, PA #7978
			09/13/90	Terrasearch, Inc.	Grading and Foundation Plan Review, Lot 2, Soficon Way
			09/24/90	Wm. Jay Hammond, Civil Engineer	Structural Calculations, Hooper Residence, PA #7978, 2 Soficon Way
			03/04/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Site Improvements
			04/16/13	JF Consulting, Inc.	Geotechnical Investigation-Barn and Stables-Lands of Kehring
			04/03/15	JF Consulting, Inc.	Geotechnical Investigation-Golf Pool House-Lands of Kehring
5 Vintage Court	x		03/20/78	Terrasearch, Inc.	Soil and Geologic Investigation, Goumas Property, Parcel M, Land Division Map No. 22
			09/21/78	Terrasearch, Inc.	Addendum, Soils and Geologic Investigation, Goumas Property, Parcel M, Land Division Map No.22
			11/19/84	Terrasearch, Inc.	Swimming Pool Recommendations, Storm Residence
			03/25/85	Elmore Design	Site Plan
			04/19/85	August E. Waegmann	Structural Calculations
			05/20/85	William Cotton and Associates	Preliminary Geologic Review, Storm Swinning Pool, Variance 377

			11/01/94	Terrasearch, Inc.	Foundation Plan Review, Pejcha Residence
			01/12/95	Harlan Tait Associates	Review - Geologic / Geotechnical Investigation, Proposed Addition
			01/25/95	Terrasearch, Inc.	Response to Geologic/Geotechnical Review and Supplemental Foundation Plan Review
			03/20/95	Harlan Tait Associates	Review - Response to Geologic /Geotechnical Review and Supplemental Foundation Plan Review Letter, Proposed Addition
WARD WAY					
27	2145 Ward Way	x	06/11/08	Murray Engineers, Inc.	Geotechnical Investigation, Foundation Improvements
			07/22/14	Geo Forensics, Inc.	Geotechnical Investigation for proposed new swimming pool
	2155 Ward Way		04/15/16	Geo Forensics, Inc.	Geotechnical Investigation for Proposed New Residence Addition
	2165 Ward Way	x	09/22/03	William M. McMorrow	Geotechnical Engineering Evaluation & Plan Review, Proposed Masonry Block Retaining Wall
	2175 Ward Way	x	03/13/08	Murray Engineers, Inc.	Geotechnical Investigation, Epstein Residence Improvements
WEST CALIFORNIA WAY					
27	710 West California Way	x	04/24/78	Purcell, Rhoades & Associates	
			01/26/82	Francis A. Steiger	Engineering Geologic Study APN 068-134-010 & -060
			05/01/84	Rick Skierka	Concept Map with annotations
			06/08/84	William Cotton and Associates	Geotechnical Review Letter
			06/14/84	William Cotton and Associates	Preliminary Geologic Review, Welz, LD 286
			07/30/84	Hallenbeck & Associates	Proposed Leach Field - Parcel 1, APN 068-134-010 & -060
			08/15/84	William Cotton and Associates	Review of Welz, LD 286
			11/08/95	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Additions to Gibson Residence
			04/02/96	Upp Geotechnology, Inc.	Plan Review and Response to Woodside Town Review, Additions to Gibson Residence
			11/05/96	Upp Geotechnology, Inc.	Supplemental Soil and Foundation Recommendations, Gibson Residence
			11/20/96	Upp Geotechnology, Inc.	Plan Review, Drilled Pier Foundation, Gibson Residence
			06/28/00	Upp Geotechnology, Inc.	Update Soil and Foundation Investigation, New Swimming Pool, Elfisaway Property
	729 West California Way	x	08/08/05	Romig Engineers, Inc.	Geotechnical Investigation, Toddart Basement Addition
	730 West California Way	x	07/13/06	Treadwell & Rollo	Geotechnical Investigation, Cropper Residence
	740 West California Way	x	05/26/95	William Cotton and Associates	Geotechnical Investigation, Fisher Residence Additions
			03/14/02	Cotton, Shires & Associates, Inc.	Geotechnical Investigation, Proposed Swimming Pool
	756 West California Way	x	10/01/06	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
	757 West California Way	?	4/24/2015	Romig Engineers, Inc.	

760 West California Way	x	04/19/89	JCP Geologists Engineers	Soil and Foundation Serices, Proposed Residence and Swimming Pool
		06/12/89	JCP Geologists Engineers	Addendum to Soil and Foundation Study and Review of Soil and Foundation Engineering Aspects of Foundation and Grading Plans
		08/05/89	JCP Geologists Engineers	Soil and Foundation Serices, Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		03/20/90	JCP Geologists Engineers	Soil and Foundation Study
		04/02/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans, Proposed Residence, Lot 17
		06/11/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kolnes, PA-7711
764 West California Way	x	04/19/89	JCP Geologists Engineers	Soil and Foundation Study, Proposed Residence and Swimming Pool
			William Cotton and Associates	Geotechnical Review Sheet
		06/12/89	JCP Geologists Engineers	Addendum to Soil and Foundation Study
		02/26/90	Joseph Parello, Civil Rngineer	Structural Calculations
		03/21/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans for Two Proposed Residences on Lots 18 and 19
		04/02/90	JCP Geologists Engineers	Foundation and Grading Plan Review
		06/11/90	William Cotton and Associates	Preliminary Geologic and Geotecnical Review, Kolnes, PA-7765
		08/20/90	William Cotton and Associates	Memo with Comments
		09/12/90	JCP Geologists Engineers	Response to Preliminary Geologic and Geotechnical Review Letter
768 West California Way	x		William Cotton and Associates	Geotechnical Review Sheet
		03/06/90	Joseph Parello, Civil Engineer	Structural Calculations, Custom Residence @ Lot 19
		03/21/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans for Two Proposed Residences on Lots 18 & 19
		06/11/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kolnes, PA 7766
		08/20/90	William Cotton and Associates	Review Notes
806 West California Way	x	06/19/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Additions
844 West California Way	x	12/29/77	Purcell, Rhoades & Associates	Geotechnical Investigation, Lot on Northwest Corner of West California and Jefferson Streets (APN 068-241-180)

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204275

Record Title & Contents

**GEOTECHNICAL REPORT FOR
WEST GLEN WAY - 310 WHISKEY HILL ROAD**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
WEST GLEN WAY					
27A	622 West Glen Way	x	07/07/78	Dunham & Associates	Soil Report
			05/26/98	Nicholas Engineering Consultants	Geotechnical Update, Proposed Residential Addition
			10/15/98	Nicholas Engineering Consultants	Supplemental Information, Proposed Residential Addition
			02/16/04	J. Yang and Associates	Geotechnical Site Investigation, Proposed Residence Remodel
			07/28/04	J. Yang and Associates	Revision, Geotechnical Report, Proposed Residence Remodel and New Barn
			08/03/09	Murray Engineers, Inc.	Geotechnical Investigation, Site Improvements
	622 West Glen Way		08/03/09	Murray Engineers, Inc.	Geotechnical Investigation, Site Improvements
	625 West Glen Way	x	06/13/84	Purcell, Rhoades & Associates	Percolation Test Results, Lot 44
			12/01/85	Purcell, Rhoades & Associates	Engineering Geologic and Foundation Recommendations Report, Lot 44
			12/20/85	William Cotton and Associates	Geotechnical Review Sheet
			01/03/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Habenicht, New Home Site
	638 West Glen Way	x	05/10/07	Romig Engineers, Inc.	Geotechnical Investigation, Brauner Residence Additions
	643 West Glen Way	x	02/20/78	Howard Donley Associates	Geotechnical and Drainfield Investigation, Single Family Residence, Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
			08/19/87	Thakore D. Sunderwala, Civil - Structural Engineer	Structural Calculations
			09/22/87	Purcell, Rhodes & Associates	Soils Report Update and Plan Review - Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
				William Cotton and Associates	Geotechnical Review Sheet
			12/14/87	Purcell, Rhodes & Associates	Plan Review - Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
			01/11/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Frank, Emerald lake Subdivision, PA #4422
			03/02/88	Purcell, Rhodes & Associates	Plan Review, Single-Family Residence, Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
			03/03/88	Thakore D. Sunderwala, Civil - Structural Engineer	Supplemental Structural Calculations
			04/14/88	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Frank, Variance and PA #4422
	650 West Glen Way	x	01/08/78	William Cotton and Associates	Field Review
			09/15/78	Steve J. Kilimowski	Foundation Investigation, Lot 23 Block 3

			12/20/78	Steve J. Kilimowski	Site Plan, Lot 23, Block 3 Estates of Emerald Lake - Parcel 068-282-030
			01/20/79	William Cotton and Associates	Geologic Review
	657 West Glen Way	x	11/08/78	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Soil Foundation Investigation, Lots 53 and 36, Block 2, Emerald Lakes Subdivision One
	659 West Glen Way	x	12/19/06	Romig Engineers, Inc.	Geotechnical Evaluation, Slopes on Chappelle Property
			04/21/08	Romig Engineers, Inc.	Updated Geotechnical Investigation, Chappelle Residence
				Romig Engineers, Inc.	Updated Figure 2 from 4/21/08 Report Showing Grading and Slopes >35%
			08/11/09	Romig Engineers, Inc.	Updated Geotechnical Report, Chappelle Residence
			08/10/09	Romig Engineers, Inc.	Swimming Pool Recommendations, Chappelle Residence
	662 West Glen Way	x	08/16/12	Rock Solid Engineering, Inc.	Claims of Defective Grading and Repair Recommendations
	713 West Glen Way	x	07/12/05	Murray Engineers, Inc.	Geotechnical Invrstigation, McDevitt Site Improvements
			07/23/09	Murray Engineers, Inc.	Geotechnical Investigation, McDivitt Residence Improvements
	732 West Glen Way		06/18/18	Geosphere Consultants, Inc.	Limited Geotechnical Study, Proposed Solar Panel Array
	740 West Glen Way	x	07/11/95	Earth Investigations Consultants	Geotechnical Design Parameters, Proposed Foundation Rehabilitation, Existing House and Attached Carport
	742 West Glen Way	x	12/23/05	Earth Investigations Consultants	Limited Soil & Foundation Investigation, Proposed Remodel and Addition
WEST MAPLE WAY					
27A	447 West Maple Way	x	02/27/03	Romig Engineers, Inc.	Geotechnical Investigation, Bareket Residence Addition
			06/27/03	Romig Engineers, Inc.	Geotechnical Plan Review, Bareket Rsidence Addition
	470 West Maple Way	x	12/16/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Site Improvements
			09/14/04	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Site Improvements
	481 West Maple Way	x	09/30/09	Romig Engineers, Inc.	Removal of Undocumented Fill, Fanfelle Property
			11/12/09	Romig Engineers, Inc.	Backfilling of Buker
			05/25/12	Romig Engineers, Inc.	Geotechnical Investigation Fanfelle Residence
	482 West Maple Way	x	12/02/86	Carl W. Garbe, P.E.	Soils and Foundation Report, Proposed Residence
				William Cotton and Associates	Geotechnical Review Sheet
			02/19/88		Structural Calculations
			04/01/88	San Mateo County	Soil Percolation Test Report
			07/25/88	Neil Moore & Associates	Plan Check Comments
			09/26/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Tsukushi, PA #4790
			11/22/88	Carl W. Garbe, P.E.	Geologic and Geotechnical Review, Soils and Foundation Report of December 1987, Proposed Residence
			12/22/88	William Cotton and Associates	Supplemental Geotechnical Review, Tsukushi, PA #4790

	489 West Maple Way	x	09/21/93	JCP Geologists-Engineers	Soil and Foundation Study, Proposed Additions
			10/25/93	JCP Geologists-Engineers	Addendum, Soil and Foundation Services, Proposed Additions
WHISKEY HILL ROAD					
27A	225 Whiskey Hill Road	x	07/03/02	Gilpin Geosciences, Inc.	Preliminary Ground-Rupture Hazard Evaluation
			05/22/03	Gilpin Geosciences, Inc.	Draft Surficial Geology Map
			06/10/03	Treadwell & Rollo	Geotechnical Investigation, Hawk Hill Residence
			07/03/03	Gilpin Geosciences, Inc.	Preliminary Ground-Rupture Hazard Evaluation
			01/15/04	Gilpin Geosciences, Inc.	Driveway Fill Slope
			11/15/04	Murray Engineers Inc.	Supplemental Geotechnical Investigation, Hawk Hill Residence
			04/07/05	Murray Engineers Inc.	Supplemental Pier Foundation Recommendations, Hawk Hill Swimming Pool
			06/10/03	Treadwell & Rollo	Geotechnical Investigation, Hawk Hill Residence
	270 Whiskey Hill Road	x	06/11/03	Steven F. Connelly	Engineering Geology Investigation, Proposed Bridge Upgrade, Balkanski Property
			07/09/03	Nielsen Geotechnical, Inc.	Soil Report
			07/11/03	Nielsen Geotechnical, Inc.	Foundation Recommendations, Bridge Upgrade
			12/05/03	Steven F. Connelly	Fault Investigation, Proposed Cottage, Balkanski Property
			01/08/04	Steven F. Connelly	Response Letter to Town Review of Fault Investigation, Proposed Cottage, Balkanski Property
			02/25/04	Nielsen Geotechnical, Inc.	Revised Drainage Recommendations, Balkanski House
			07/10/04	Murray Engineers Inc	Geotechnical Recommendations, Phase 2 Development, Creekside House
			10/25/04	Murray Engineers Inc	Supplemental Foundation Recommendations, Phase 3 Development, Creekside House
	290 Whiskey Hill Road	x	05/23/84	Terrasearch, Inc.	Soil and Geologic Investigation, Proposed Marshall Residence Addition
			01/13/87	JCP Geologists-Engineers	Soil and Foundation Study, Proposed Tennis Court
			11/16/87	Harding Lawson Associates	Geotechnical Investigation, Marshall Residence
			11/17/87	Walker & Moody Architects	Site Plan: Caretakers House
				William Cotton and Associates	Geotechnical Review Sheet
			12/14/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review , Lands of Marshall, PA #4462 and #4462
			01/13/09	Harding Lawson Associates	Post-Report Consultation, Geotechnical Investigation, Marshall Residence
			01/29/88	Harding Lawson Associates	Post-Report Consultation, Geotechnical Investigation, Marshall Residence (Draft)
			02/01/88	Harding Lawson Associates	Post-Report Consultation, Geotechnical Investigation, Marshall Residence

			02/02/88	William Cotton and Associates	Geologic and Geotechnical Review, Marshall, PA #4429 and #4462
	300 Whiskey Hill Road	x	04/20/79	Nordmo Associates	Soil Engineering Services, Proposed Swimming Pool
			12/18/95	Michelucci & Associates, Inc.	Geotechnical Investigation, Landslide, Gates Property
			09/22/03	Nielsen Geotechnical Incorporated	Soil Report
			06/04/04	Murray Engineers	Geotechnical Services, Site Retaining Walls
			04/07/06	Michelucci & Associates, Inc.	Update to 1995 Geotechnical Investigation, Landslide Above Tennis Court
	303 Whiskey Hill Road	x	07/12/74	Berloger, Long & Associates	Soils Engineering and Engineering Geologic Investigation, Proposed Parcel Split, Single Family Residential Development
			02/15/74	Edwin H. Smith	Preliminary Map, Land Division No. 204, Lands of Chamberlain
			03/08/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed House and Swimming Pool (APN 073-090-540)
	310 Whiskey Hill Road	x	12/01/01	Nielsen Geotechnical Incorporated	Soil Report, New (Replacement) Residence
			10/21/03	Nielsen Geotechnical Incorporated	Soil Report, Proposed Replacement Garage
			04/27/07	Romig Engineers, Inc	Geotechnical Recommendations, Koppl Garage Remodel

TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00224397

Record Title & Contents

**GEOTECHNICAL REPORT FOR
410 WHISKEY HILL ROAD - 645 WOODSIDE DRIVE**

BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
WHISKEY HILL ROAD					
28	410 Whiskey Hill Road	x	06/30/05	Murray Engineers, Inc.	Geotechnical Investigation, Dressel Barn Renovation
			05/25/07	Murray Engineers, Inc.	Geotechnical Investigation, Dressel Residence
	411 Whiskey Hill Road		09/16/05	Applied Earth Sciences Consultants	Investigation of a failing on-site sewage disposal system
	437 Whiskey Hill Road		12/29/15	Murray Engineers, Inc.	Geotechnical Investigation, Boyce Swimming Pool
	441 Whiskey Hill Road	x	07/07/77	Dunham & Associates	Soil Investigation, Lot 3, Land Division Map 232 (APN 073-090-450)
			04/12/99	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed Smythe Residence
			02/01/05	Ting & Associates, Inc.	(Geotechnical Investigation) Proposed Smythe Addition

			04/25/05	Ting & Associates, Inc.	Response to the Concerns of the Town of Woodside, Proposed Smythe Addition
			11/09/09	Ting & Associates, Inc.	Geotechnical Investigation, Proposed Arbor, Pool Remodel, Decks, and Fence Walls
443 Whiskey Hill Road	x		08/27/87	Purcell, Rhoades & Associates	Soil Engineering and Foundation Study
			09/28/93	Jo Crosby & Associates	Geotechnical Investigation, Proposed Guest House Site
			04/30/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Rosendin Property
445 Whiskey Hill Road	x		09/27/10	Murray Engineers, Inc.	Geotechnical Investigation, New Detached Garage, Paterson Family Trust Property
447 Whiskey Hill Road			02/17/91	GeoForensics, Inc.	Subsurface Investigation, Wolfenden Residence
	x		05/05/08	Romig Engineers, Inc.	Geotechnical Investigation. Bates Outdoor Arena and Storage Building
			05/11/09	Romig Engineers, Inc.	Geotechnical Response Bates Barn Renovation
			05/12/09	Romig Engineers, Inc.	Piers for Site Retaining Wall Bates Barn Renovation
449 Whiskey Hill Road	x		02/08/07	Neil O. Anderson	Geotechnical Investigation Addendum
			02/17/07	Neil O. Anderson	Geotechnical Investigation Addendum
450 Whiskey Hill Road	x		06/08/81	Earth Systems Consultants	Geotechnical Investigation, Pool House Addition, Blokker Residence
			08/09/04	Murray Engineers Inc.	Geotechnical Investigation, Deck Reconstruction, Blokker Residence
			05/13/08	Murray Engineers Inc.	Limited Geotechnical Investigation, Residence Addition
457 Whiskey Hill Road	x		10/13/06	Murray Engineers, Inc.	Geotechnical Investigation, New Residence
			06/15/09	Murray Engineers, Inc.	Geotechnical Report Update, New Residence
485 Whiskey Hill Road	x		02/28/07	Murray Engineers, Inc.	Geotechnical Investigation, Peterson Residence
			02/27/04	Town	Aerial and Ground Photos
490 Whiskey Hill Road	x		10/26/09	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
510 Whiskey Hill Road			05/27/15	ARA Engineering Company	Geotechnical Engineering Study, Proposed House Addition
550 Whiskey Hill Road	x		06/10/08	Clearly Consultants, Inc.	Geotechnical Investigation, New Residence
580 Whiskey Hill Road	x		05/22/86	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Kahl
				William Cotton and Associates	Geotechnical Review Sheet
			07/20/86	SEDCO Structural Engineering & Development	Structural Calculations
			12/05/86	Upp Geotechnical, Inc.	Review of Foundation Plans, Single Family Home, Lands of Kahl
			01/16/97	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kahl Residence, PA 3225
590 Whiskey Hill Road	x		03/13/99	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Dali Property
610 Whiskey Hill Road	x		06/27/79	PSC Associates, Inc.	Geologic and Soil Engineering and Foundation Investigation, Hewes
			07/20/79	PSC Associates, Inc.	Remodeling Plan Review - Proposed Building Additions

			07/26/79	William Cotton and Associates	Geotechnical Review Sheet
			07/27/79	William Cotton and Associates	Hewes - Geotechnical Review
			06/18/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Additions to Hewes Residence
			06/08/04	Charles H. Hartzog	Soils Report
			09/07/04	Charles H. Hartzog	Soil / Geotechnical Report Only
	760 Whiskey Hill Road		05/01/13	Foundation Engineering Counsultants	Geotechnical & Engineering Geology Report, Proposed new room addition
WHY WORRY LANE					
28	Why Worry Subdivision #148	x	08/01/86	Upp Geotechnology, Inc.	Geotechnical Feasibility Investigation
	20 Why Worry Lane	x	06/26/90	Upp Geotechnology, Inc.	Geotechnical Investigation, Lot 2 - Why Worry Farm Subdivision
	100 Why Worry Lane	x	05/09/00	Bay Area Geotechnical Consultants	Geologic Evaluation & Geotechnical Investigation, Proposed Building Remodel, Liautaud Residence
			09/14/02	Bay Area Geotechnical Consultants	Geotechnical Consultation, Proposed Generator Vault, Kelley
			05/04/07	Bay Area Geotechnical Consultants	Update to Geotechnical Engineering Investigation
			02/25/09	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Pool House/Guesthouse
WILDWOOD WAY					
28	115 Wildwood Way	x	10/26/11	Milstone Geotechnical	Geotechnical Investigation, Proposed Ferrari Residence
WINDING WAY					
28	101 Winding Way	x	06/14/99	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residential Addition
			08/26/03	Bay Area Geotechnical Group	Addendum to Geotechnical Engineering Investigation, Proposed Swimming Pool, Ballinger Residence
	140 Winding Way		05/19/08	Murray Engineers, Inc.	Geotechnical Services, Burnap Residence
	201 Winding Way	x	06/06/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
			08/02/99	Earth Investigations Consultants	Geotechnical Report Update and Plan Review, Proposed House Addition
	225 Winding Way	x	10/29/85	Earth Investigations Consultants	Geotechnical Study, Williams Property
			05/08/85	Town of Woodside	Letter to Owner Williams regarding problems with landslide and repair activities and associated erosion
			11/15/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Williams Landslide Repair
			01/15/86	William Cotton and Associates	Notes of Site inspection and conversations with geotec and landscape architect - repair not inspected by geotec.
			01/20/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Williams Landslide Repair
			11/22/93	John W. Leonard	Preliminary Geotechnical Engineering Study, Proposed Tennis Court

			08/01/11	Neil O. Anderson	Geotechnical Investigation, Kissick Swimming Pool Renovation
			09/19/12	Applied Earth Sciences Consultants	5,000 Gallon Underground Irrigation Water Storage Tank Installation
	231 Winding Way		04/24/12	Romig Engineers, Inc.	Geotechnical Investigation, Vannini Residence
			10/31/12	Romig Engineers, Inc.	Fault Rupture Evaluation
	233 Winding Way	x	08/20/74	Berloger, Long & Associates	Fault Investigation, Vaughn Property (APN 072-221-230)
			04/11/97	Pacific Geotechnical Engineering	Geotechnical Investigation, Proposed Improvements, Lacob Property
			10/28/04	Westfall Engineers, Inc.	Structural Calculations, New Barn
			04/26/10	Murray Engineers, Inc.	Geotechnical Investigation, Andrews Residence
	235 Winding Way	x	06/05/09	Romig Engineers, Inc.	Geotechnical Investigation, Juelsgaard Residence
	250 Winding Road	x	02/22/08	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Residential Storage Shed
			03/11/08	Michelucci & Associates, Inc.	Review of Plans, Proposed New Storage Shed
			08/18/08	Michelucci & Associates, Inc.	Pavement Recommendations, Adjacent to Proposed New Storage Shed
			08/28/08	Michelucci & Associates, Inc.	Summary Review of Plans, Proposed New Storage Shed
	290 Winding Way	x	10/27/86	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed Addition
			08/08/89	BFL	Entrance Gate
WOODHILL DRIVE					
28	75 Woodhill Drive	x	03/07/08	Murray Engineers, Inc.	Geotechnical Investigation, Dearborn Residence Improvements
WOODSIDE DRIVE					
28	135 Woodside Drive	x	06/16/10	Romig Engineers, Inc.	Geotechnical Investigation, Schemers Swimming Pool, Pool House, and Addition
	150 Woodside Drive		10/30/15	Romig Engineers, Inc.	Geotechnical Investigation, Chad Residence
	170 Woodside Drive	x	05/24/11	Romig Engineers, Inc.	Geotechnical Investigation, Lashkoff Residence Addition, Garages, and InLaw Unit
	215 Woodside Drive	x	05/13/02	Nielsen Geotechnical Incorporated	Soil Report
	225 Woodside Drive	x	05/20/96	Nielsen Geotechnical, Incorporated	Soil Report
	235 Winding Way	x	06/05/09	Romig Engineers, Inc.	Geotechnical Investigation, Juelsgaard Residence
	245 Woodside Drive	x	02/04/91	Michelucci & Associates, Inc.	Geotechnical Investigation, Distressed Goodmanson Residence
			03/03/93	Michelucci & Associates, Inc.	Geotechnical Investigation, Distressed Goodmanson Residence
	265 Woodside Drive	x	01/30/02	GeoForensics Inc.	Geotechnical Investigation, Proposed Residential Additions
			10/06/06	Romig Engineers, Inc.	Geotechnical Investigation, Residence Improvements
			09/07/10	Romig Engineers, Inc.	Supplemental Geotechnical Recommendations, Van Der Linde Residence

			07/29/11	Romig Engineers, Inc.	Geotechnical Plan Review, Residence Repair Plans
			09/20/11	Romig Engineers, Inc.	Supplemental Recommendations, Residence Repair Plans
275 Woodside Drive	x		06/22/99	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Additions and Garage
285 Woodside Drive	x		04/11/94	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Single-Family Residence
			01/03/11	Romig Engineers, Inc.	Geotechnical Investigation, Livermore Exercise Studio
			05/12/11	Romig Engineers, Inc.	Response to Geologic Review, Livermore Exercise Studio
315 Woodside Drive	x		04/12/05	Frank Lee & Associates	Soil and Foundation Investigation, Proposed Two-Story Addition
			06/06/05	Frank Lee & Associates	Supplemental Design and Construction Recommendations, Swimming Pool
			10/03/05	Frank Lee & Associates	Addendum to Soils and Foundation Report, Proposed Two-Story Additions
			05/03/06	Frank Lee & Associates	Addendum 2 to Soils and Foundation Report, Proposed Two-Story Additions
			12/20/05	Frank Lee & Associates	Driveway Recommendations, Proposed Two-Story Additions
			12/19/06	Frank Lee & Associates	Foundation Plan Review
335 Woodside Drive	x		03/10/97	Steven A. Arnold	Site Inspection
			06/06/97	Cleary Consultants, Inc.	Geotechnical Investigation, Planned Master Bedroom Addition
435 Woodside Drive	x		10/31/96	Nielsen Geotechnical Incorporated	Soil Report, Gabion Retaining Wall
			11/22/99	Earth Investigations Consultants	Geotechnical Investigation, Fill Slope Stability Improvements
			05/06/00	GeoForensics, Inc	Geotechnical Investigation to Address Slope Stability, Dorsey Property
			10/15/02	GeoForensics, Inc	Response to Town Review, Proposed Slope Repair
			05/07/03	Baker - CEG	Engineering Geologic Evaluation Response to Comment #1), Proposed Slope Restoration
			06/06/03	GeoForensics, Inc	Response to Town Review (#3)
			07/29/03	GeoForensics, Inc	Plans (Drawings GF-1 to 3)
			09/25/03	GeoForensics, Inc	Plate 2 Transmittal
475 Woodside Drive			12/17/13	Murray Engineers, Inc.	Geotechnical Investigation, Newby Residence Improvements
520 Woodside Drive	x		11/16/04	Friar Associates, Incorporated	Soil Bearing Capacity, Existing Garage Structure
			08/01/05	Friar Associates, Incorporated	Foundation Design Information, Existing Garage Structure
			12/15/05	Friar Associates, Incorporated	Response Letter, Proposed Tennis Court
			11/06/06	Friar Associates, Incorporated	Proposed Garage Structure
			04/30/08	Friar Associates, Incorporated	Proposed Garage Addition
565 Woodside Drive	x		05/20/95	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions

	625 Woodside Drive		06/27/13	Frank Lee & Associates	Soil and Foundation Investigation, Proposed Two-Story Residential Building
	640 Woodside Drive	x	07/27/93	Lowney Associates	Geotechnical Investigation, Hepper Residence
			03/19/19	Romig Engineers, Inc.	Geotechnical Investigation Hepper Swimming Pool
	645 Woodside Drive	x	02/02/96	Romig Consulting Engineers	Geotechnical Study, Pool House Addition
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204277					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 650 WOODSIDE DRIVE - 2891 WOODSIDE ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
WOODSIDE DRIVE					
29	650 Woodside Drive	x	12/23/97	Alcon Engineering	Response to Plan Check Comments
	665 Woodside Drive	x	09/26/94	Nielsen Geotechnical Incorporated	Soil Report
			04/08/96	Nielsen Geotechnical Incorporated	Supplemental Geotechnical Information, Proposed Additio/Remodel and Retaining Wall
	710 Woodside Drive	x	08/14/03	Ting & Associates, Inc.	Foundation Recommendations, Proposed Addition
			07/07/06	Murray Engineers, Inc.	Geotechnical Investigation, Louie Residence
			08/14/06	Murray Engineers, Inc.	Supplemental Recommendations, Driveway Pavement, Louie Residence
	746 Woodside Drive	x	09/04/90	Jo Crosby & Associates	Geotechnical Investigation, Distress to the Residence
			10/24/90	Robert Lyon Associates	Plans, with annotations
			12/11/90	Jo Crosby & Associates	Foundation Repair Plan Review, Shaw Residence
				William Cotton and Associates	Geotechnical Plan Review
	757 Woodside Drive		11/18/17	Frank Lee & Associates	Soil and Foundation Investigation, Proposed One-Story Addition Residence
	765 Woodside Drive		06/17/13	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Remodel
	805 Woodside Drive	x	05/03/94	Haro, Kasunich and Associates, Inc.	Geotechnical Reconnaissance (APN 069-150-056)
			08/12/94	Haro, Kasunich and Associates, Inc.	Geotechnical Investigation
			03/15/17	Murray Engineers, Inc.	Geotechnical Investigation, Toy Residence Improvements

	809 Woodside Drive	x	01/22/08	Buckley Engineering Associates, Inc.	Geotechnical Investigation, Proposed New Residence
	811 Woodside Drive	x	11/22/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed Basement Addition
			12/31/11	Earth Investigations Consultants	Proposed Pool and Deck
		x	06/11/13	Earth Investigations Consultants	Slope Analysis
	850 Woodside Drive	x	05/21/02	Nielsen Geotechnical Incorporated	Soil Report
	851 Woodside Drive	x	11/05/01	Nielsen Geotechnical Incorporated	Foundation Recommendations
			10/20/03	Nielsen Geotechnical Incorporated	Review of Foundation Conditions
			12/03/03	Nielsen Geotechnical Incorporated	Construction Report, House Remodel
WOODSIDE ROAD					
29	Village Hill	x	02/28/74	Whisler-Patri	Exhibits to Application for Conditional Use Permit for Village Hill Property
			01/21/74	Lowney-Kaldveer Associates	Preliminary Geotechnical Investigation, Lincoln Hill Office Building
			03/10/74	William R. Cotton	Review of Village Hill Preliminary Geotechnical Investigation Report
	Woodside Road		07/12/13	Treadwell & Rollo	Revised Geotechnical Investigation, PG&E Substation Expansion
	2300 Woodside Road	x	10/11/02	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Terrace Remodel, Menlo Country Club
			12/02/11	Romig Engineers, Inc.	Geotechnical Investigation, Golf Course Improvements, Menlo Country Club
	2360 Woodside Road	x	12/27/95	Lee Engineers	Geotechnical Investigation, Guest House
			02/07/96	Lee Engineers	Addendum to Geotechnical Investigation, Guest House
			05/24/03	Lee Engineers	Soil Investigation, House Addition
	2879 Woodside Road	x	10/08/02	Sigma Prime Geosciences, Inc.	Engineering Geologic and Geotechnical Report for Proposed Residence
HALDEN / HAWK HILL SUBDIVISION - 2883 and 2884 Woodside Road					
	2883 Woodside Road	x	10/06/88	Applied Earth Sciences Investigations	Location of Existing On-Site Sewage Disposal System and Preparation of Recommendations to Upgrade the System
			04/02/89	Applied Earth Sciences Investigations	Soil and Geologic Investigation, Proposed New Garage Location
			04/19/89	Applied Earth Sciences Investigations	Foundation Addition for the Remodel of the Existing Single Family Residence
			04/25/89	Applied Earth Sciences Investigations	Observation of Pier Drilling, New Pier and Grade Beam Foundations, New Additions to Existing Residence

			05/29/90	Applied Earth Sciences Investigations	Final Inspection, New Foundation Construction, Remodel to Existing Residence
			08/31/91	Brian Kangas Foulk	Conceptual Map - Tentative Map, Lands of Haldan
				William Cotton and Associates	Geotechnical Review Sheet
			09/10/91	Brian Kangas Foulk	Natural Land Feature Study
			11/11/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Halden, Subdivision #151
			12/08/91	GeoForensics Inc.	Geotechnical Observations of Leach Field Test Excavations, Four Proposed Lots
			12/12/91	GeoForensics Inc.	Geotechnical Investigation for Proposed Subdivision
			01/14/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Halden / Hawk Hill Subdivision #151
				Cultural Resource Planning	Cultural Resource Assessment
			02/17/92	GeoForensics Inc.	Geotechnical and Geologic Response to Issues Raised by Town Geologist, Proposed Residential Site
			03/30/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Halden / Hawk Hill Subdivision #151
			04/07/92	GeoForensics Inc.	Report Clarification, Proposed Residential Sites
			07/20/92	Oswald G. Villard	Letter to Planning Commission regarding Halden Subdivision
			09/01/93	Mills Associates	Draft Focused Environmental Impact Report, Hawk Hill Subdivision
			11/01/93	Mills Associates	Response to Comments, Hawk Hill Subdivision EIR
			08/01/94	Mills Associates	Addendum, Hawk Hill Subdivision EIR
	2887 Woodside Road	x	04/07/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Remodeling and Seismic Upgrade Project
			05/11/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed House Modifications and New Spa
			06/11/07	Michelucci & Associates, Inc.	Supplemental Recommendations and Design Criteria, Proposed Swimming Pool and Related Exterior Improvements
	2891 Woodside Road	x	07/29/98	Nielsen Geotechnical Incorporated	Foundation Recommendations, Barn
			02/15/99	John Coyle & Associates, Inc.	Limited Geologic Reconnaissance, Lower Area, Maroney Property
			03/08/99	Nielsen Geotechnical Incorporated	Soil Report
			06/29/07	Murray Engineers, Inc.	New Engineer of Record & Supplemental Recommendations, New Cabana
			05/15/18	Murray Engineers, Inc.	Geotechnical Investigation, Lynch Residence Improvements

	2893 Woodside Road	x	9/2/1993	Earth Science Consultants	Geotchnical Investigation New Pool and Pool House-Byers Residence
	2934 Woodside Road	x	6/12/2005	Ting & Associates, Inc.	Foundation Recommendations
	Highway 280 & Woodside Road	x	10/2/2007	Krazan & Associates	Geotechnical Engineering Investigation-Verizon Wireless Communicstion Tower Site
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204278					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 2905 WOODSIDE ROAD - 3445 WOODSIDE ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
WOODSIDE ROAD					
29A	2905 Woodside Road	x	05/07/92	JCP Geologists - Engineers	Letter Geologic and Soil & Foundation Study, Proposed Home (APN 073-090-170)
			03/12/93	JCP Geologists - Engineers	Additional Recommendations, Pier Foundation Design, Proposed Home
			04/22/93	JCP Geologists - Engineers	Addendum - Letter Geologic and Soil & Foundation Study, Proposed Home (APN 073-090-170)
	2907 Woodside Road	x	11/03/09	Sigma Prime Geosciences, Inc.	Geotechnical Study, Kamara Property
	2909 Woodside Road	x	10/01/02	Carl W. Garbe, P.E.	Soil & Foundation Report, Proposed Emergency Generator
		x	05/07/92	JCP Geologists - Engineers	Soil and Foundation Study
			02/05/10	Romig Engineers, Inc.	Geotechnical Investigation, Residence Remodel & Site Improvements
	2915 Woodside Road	x	07/18/97	Associated Terra Consultants, Inc.	Soils and Foundation Investigation, Lands of Siebel
	2925 Woodside Road	x	05/13/94	Earth Investigations Consultants	Geotechnical Evaluation, Proposed Additions to Pioneer Building
	2934 Woodside Road	x	06/12/05	Wayne Ting & Associates, Inc.	Foundation Recommendations, Proposed Remodeling
			08/24/05	Wayne Ting & Associates, Inc.	Supplemental Desing Recommendations
	2955 Woodside Road	x	08/30/00	Nielsen Geotechnical Incorporated	Soil Report, Community House
			09/25/03	Nielsen Geotechnical Incorporated	Construction Report, Woodside Community House
	2955 Woodside Road	x	08/23/89	William Cotton and Associates	Geotechnical Investigation, Town Hall Site
			11/11/89	Town of Woodside	Building Requirements, Contract Conditions, and Specifications
	2965 Woodside Road	x	08/02/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed 2-Story Office Building (APN-073-112-320)
	2967 / 2969 Woodside Road	x	07/21/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel and Expansion
			07/22/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel and Expansion

	2991 / 2995 Woodside Road	x	01/18/79	Geoconsultants, Inc.	Geological Reconnaissance and Geophysical Survey, Proposed Commercial Complex
			01/24/79	Howard Donley Associates, Inc.	Geotechnical Investigation, Fault Investigation of Canada Fault
			02/15/80	Donald A. Woolfe and Associates	Environmental Impact Report, Gilbert Project: Retail, Office and Service Facilities
			03/18/80	William Cotton and Associates	Review of Preliminary Site Plan - Gilbert Center
			10/06/80	Howard Donley Associates, Inc.	Soil and Foundation Investigation, Proposed Shopping Center - Gilbert Center
			10/29/80	William Cotton and Associates	Geotechnical Review Sheet
			11/11/80	William Cotton and Associates	Review of 10/6/80 HD&A report
	3015 Woodside Road	x	07/25/85	JCP Geologists Engineers	Soil and Foundation Services, Proposed Addition to Robert's Grocery
	3050 Woodside Road	x	08/27/76	Howard F. Donley & Associates	Feasibility Level Geotechnical Investigation, Proposed Canada Corners Shopping Complex and Land to North
			09/09/76	Leighton and Associates, Town of Woodside	Geotechnical Review of above
			01/24/78	Town Staff	Report to Planning Commission, Conditional Use Permit 80-81 - Canada Corners
	3100 Woodside Road	x	06/13/95	Michelucci & Associates. Inc.	Geotechnical Evaluation of "Point Bar" Creek Bank Erosion Mitigation Project, Weinstein Property
			08/15/16	Michelucci & Associates. Inc.	Geotechnical Investigation. Proposed New Residence, Swimming Pool Guesthouse and Other Site Improvements
	3105 Woodside Road	x	02/15/08	Romig Engineers, Inc.	Geotechnical Investigation, Ehikian Residence Improvements
	3110 Woodside Road	x	12/07/11	Romig Engineers, Inc.	Geotechnical Investigation
	3111 Woodside Road	x	06/13/90	J. V. Lowney & Associates	Geotechnical Investigation, Woodside Fire Station
	3140 Woodside Road	x	04/06/11	PGSoils, Inc.	Geotechnical Investigation, Proposed Upgrades, Woodside Library Building
	3145 Woodside Road	x	05/31/00	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition
	3180 Woodside Road	x	06/24/94	Robert B. Rogers, P.E., M. Eng.	Foundation Investigation, New Residence and Garage
	3195 Woodside Road	x	09/01/88	William F. Jones, Inc.	Soil Investigation, Proposed Relocation, Woodside School Library
			10/11/93	Lowney Associates	Geotechnical Investigation, Woodside Elementary Classroom Addition
			11/25/97	Lowney Associates	Geotechnical Investigation, Multi-purpose and Classroom Buildings, Woodside Elementary School
			03/23/00	Lowney Associates	Supplemental Geotechnical Investigation and Geologic Hazards Evaluation, Woodside Elementary School Improvements
	3204 Woodside Road	x	05/29/00	Nielsen Geotechnical Incorporated	Soil Report

			03/07/01	Nielsen Geotechnical Incorporated	Plan Review, Jenkins House Restoration & Addition
			04/15/01	Nielsen Geotechnical Incorporated	Footing Observations, Addition
			09/15/01	Nielsen Geotechnical Incorporated	Plan Review - 2
			09/16/04	Nielsen Geotechnical Incorporated	Construction Report
	3308 Woodside Road	x	08/21/14	American Soil Testing, Inc,	Soil and Foundation Investigation of Proposed addition and swimming pool
	3323 Woodside Road	x	05/08/14	Murray Engineers, Inc.	Geotechnical Investigation-Residence Improvements
	3324 Woodside Road	x	09/02/99	Romig Engineers, Inc.	Geotechnical Investigation, Brown Residence Improvements
			05/09/08	Romig Engineers, Inc.	Geotechnical Investigation, Brown Swimming Pool
	3370 Woodside Road	x	05/23/97	Upp Geotechnology, Inc.	Geotechnical Investigation, New Residence and Office, Thieriot Property
	3373 Woodside Road	x	12/10/09	Murray Engineers, Inc.	Geotechnical Investigation, Sculley Residence
	3383 Woodside Road	x	09/16/04	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Addition
	3411 & 3417 Woodside Road	x	02/27/07	Murray Engineers, Inc.	Geotechnical Investigation, Bear Gulch Creek Partners Property
			11/06/07	Murray Engineers, Inc.	Supplemental Recommendations, Proposed Swimming Pool, Bear Gulch Creek Partners Property
	3445 Woodside Road	x	09/28/78	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Soils Foundation Investigation, Parcel Fronting Woodside Road, Bear Gulch and West Union Creeks
			7/0/78	Fred Blomquist & Associates	Site Plan
			10/16/78	William Cotton and Associates	Field Review Notes
			11/07/78	William Cotton and Associates	Geotechnical Review: Martinez - Conformity
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204282					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 3480 WOODSIDE ROAD - 3875 WOODISDE ROAD					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
WOODSIDE ROAD					
30	3480 Woodside Road	x	12/06/96	Earth Investigations Consultants	Geologic Investigation, Fault Location, Proposed Single Family Residence Development

			05/09/97	Earth Investigations Consultants	Geological Services, Supplemental Fault Investigation, Proposed New Residence
			05/15/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Residence
			05/18/99	Earth Investigations Consultants	Wet Weather Test Hole Locations, Proposed House
			06/10/99	Earth Investigations Consultants	Subdrain and Observation Well Abandonment
			04/26/00	Earth Investigations Consultants	Supplemental Geotechnical Investigation, Proposed House
			01/30/02	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Pool and Spa
			05/09/03	Earth Investigations Consultants	Geotechnical Investigation Update
			10/06/03	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Site Improvements
			03/09/04	Earth Investigations Consultants	Geotechnical Clarification, Proposed Pool and Adjoining Terrace
			05/20/04	Earth Investigations Consultants	Geotechnical Parameters, Mat Slab for Proposed Barn and Conservatory
3500 Woodside Road	x		06/17/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
			11/28/00	GeoForensics, Inc.	Pool Recommendations
			06/07/04	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Water Feature and Meditation Structure
3555 Woodside Road	x		08/11/87	Upp Geotechnology, Inc.	Fault Location Study, Additions to Residence, Lands of Alexander
			08/21/87	Upp Geotechnology, Inc.	Supplemental Information, Fault Location Study, Additions to Residence, Lands of Alexander
3585 Woodside Road	x		09/25/98	Upp Geotechnology, Inc.	Geotechnical Investigation, Proposed New Residence, Lands of Alexander
			08/22/01	Upp Geotechnology, Inc.	Supplemental Recommendations, Proposed Swimming Pool, Alexander Property
			10/25/01	Upp Geotechnology, Inc.	Construction Observation, Residence and Garage, Alexander Property
			06/14/02	Upp Geotechnology, Inc.	Construction Observation, Swimming Pool, Alexander Property
3610 Woodside Road	x		05/02/84	Edward Dominion	Plot Plan and Details, with annotations
			05/22/84	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield
			05/30/84	Terratech, Inc.	Geologic Investigation, Lands of Jelinich
			05/31/84	Terratech, Inc.	Review of Foundation Plans, Additions to Jelincich Residence
			06/06/84	William Cotton and Associates	Geotechnical Review Sheet
			06/11/84	Terratech, Inc.	Supplemental Information and Addendum to Plans, Jelincich Property
			06/14/84	William Cotton and Associates	Preliminary Geologic Review, Jelincich Additions
			10/10/84	Freeman-Kern Associates, Inc.	Geologic and Geotechnical Investigation, 4.98 Acres
			10/17/10	Edward Dominion	Structural Calculations
			11/24/84	Freeman-Kern Associates, Inc.	Plan Review
			11/08/84	William Cotton and Associates	Preliminary Geologic Review, Jelincich

			11/27/84	Freeman-Kern Associates, Inc.	Plan Review, Drainage Plans
3620 Woodside Road	x		03/22/99	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Guest House and Residence, Cromwell & Chiaro Property
			04/26/00	GeoForensics, Inc.	Basement Design Parameters, Proposed New Residence
			05/01/02	GeoForensics, Inc.	Recommendations for Landscaping Walls, Proposed New Residence
			11/11/02	GeoForensics, Inc.	Recommendations for Pool Construction, Proposed New Residence
3665 Woodside Road	x		09/23/83	Purcell, Rhoades & Associates	Soils and Foundation Study - Swimming Pool, Hoffacker Residence
			07/15/83	Anthony Pools	Site Plan, with annotations
			08/30/83	William Cotton and Associates	Geotechnical Review Sheet
			09/13/83	William Cotton and Associates	Geologic Review, Hoffacker Pool
			10/18/83	William Cotton and Associates	Engineering Geologic Review, Hoffacker Pool
Woodside Road at Oakhill Drive	x		03/10/09	William Cotton and Associates	Geotechnical Investigation, California Water Service Company, Station 16, Woodside Reservoir
3784 Woodside Road	x		11/29/84	Jo Crosby & Associates	Geotechnical Report, Slope Failure
			09/09/85	Jo Crosby & Associates	Preliminary Plan Review. Proposed Addition
			10/03/85	Robelo / Kocjan Associates, Inc.	Structural Calculations
			10/31/85	Jo Crosby & Associates	Completion Report - Consultation and Slope Support Recommendations
			11/05/85	William Cotton and Associates	Geotechnical Review Sheet
			11/22/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Braniff
			02/25/11	Romig Engineers, Inc	Geotechnical Study, Sadlier Site Retaining Walls
3787 Woodside Road	x		09/13/96	GeoForensics, Inc.	Geotechnical Investigation, New Residence, Lego Property
3789 Woodside Road	x		11/14/01	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Remodel of Existing Barn
			11/11/02	Nielsen Geotechnical Incorporated	Soil Report
			03/11/03	Nielsen Geotechnical Incorporated	Construction Report, Barn Remodel
			06/25/04	Nielsen Geotechnical Incorporated	Review of Project Plans, Jordan-Bennett House
			08/03/04	Nielsen Geotechnical Incorporated	Construction Report, Grading
			08/09/04	Murray Engineers, Inc	New Engineer of Record, New Residence
			09/15/04	Murray Engineers, Inc	Supplemental Information, Geotechnical Investigation, Proposed Guest House
3799 Woodside Road	x		06/26/98	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Proposed Creek Bank Stabilization, Momsen Property
			03/28/07	Murray Engineers, Inc.	Geotechnical Investigation, Open Water South Property Improvements

			01/10/08	Murray Engineers, Inc.	Supplemental Liquefaction Evaluation, Open Water South Property Improvements
			06/26/08	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Open Water South Property Improvements
	3810 Woodside Road		09/05/91	Tim J. Manzagol	Geotechnical Recommendations For a Proposed Addition
	3860 Woodside Road	x	03/30/11	Romig Engineers, Inc.	Geotechnical Recommendations, Clabert Residence Remodel
			04/13/11	Romig Engineers, Inc.	Response to Geologic Review, Calbert Residence Remodel
			08/24/11	Romig Engineers, Inc.	Geotechnical Recommendations, Pool Heaters and Propane Tanks
	3875 Woodside Road	x	04/21/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions
			12/31/97	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation, New Guest House, Lands of Solomon
			02/10/98	Upp Geotechnology, Inc.	Response to Geological and Geotechnical Review, New Guest House, Lands of Salomon
TOWN OF WOODSIDE RECORD TRACKING NOTICE (RTN) Barcode/Box # SJ00204283					
Record Title & Contents					
GEOTECHNICAL REPORT FOR 3970 WOODSIDE ROAD - YOSEMITE COURT					
BOX #	ADDRESS	PLOTTED FIRE MAP	DATE	PREPARED BY	TITLE
WOODSIDE ROAD					
30A	3970 Woodside Road	x	10/15/99	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Residence
			03/05/01	Terrasearch, Inc.	Supplemental Letter/Report, proposed New Residence
	3985 Woodside Road	x	02/17/99	GeoForensics, Inc.	Geotechnical Investigation for Proposed New Residential Aditions
	4105 Woodside Road	x	11/10/69	Crosby & Associates	Soil and Geologic Investigation, Proposed Forest Glade Estates
			04/16/74	Geolabs - Northern California, Inc.	Magnetometer Survey, Proposed Forest Glade Estates
			06/21/74	Geolabs - Northern California, Inc.	Subsurface Investigation of Splinter Fault Trace
			07/25/77	Richard E. Rowland	Geologic Report, Portion of Hume Property
			09/14/77	Dunham & Associates	Soil Investigation, Hume, Woodside Road, Woodside
			11/02/77	Leighton and Associates	Review of above 2 reports
			11/22/77	Town Staff	Report to Planning Comission on Hume
			10/14/97	Lowney Associates	Geotechnical and Geologic Hazard Investigation, Hume Residence
			01/22/99	Jo Crosby & Associates	Review of the Geological and Geotechnical Data, Proposed Parcel B, 3 Lot Subdivision, Gilo and Hume Subdivision

			02/05/99	Lowney Associates	Geologic Review of Potential Fault Rupture Hazards, Hume Residence
4155 Woodside Road	x		07/24/78	Cooper Clark & Associates	Evaluation of an Inferred Type "C" Fault Trace, Portion of Land Division #227
			01/07/81	Cooper Clark & Associates	Discussion of 1978 Fault Investigation
			07/05/84	Perry R. Wood	Potential Geologic Hazard Posed by Sliver Fault of the San Andreas Fault System, and Potential Erosion Hazard Along Drainage Courses
			10/18/85	Testing Engineers, Inc.	Compaction Test Results
			04/10/86	PSC Associates, Inc.	Geotechnical Engineering Investigation, Lot 1, Land Division No. 265
			07/14/86	PSC Associates, Inc.	Foundation Plan Review Letter, Proposed Residence, Lot 1, Land Division 265
			07/18/86	PSC Asspciates, Inc.	Geotechnical Observation of Foundation Pier Drilling, Lot 1
			02/02/87	PSC Associates, Inc.	Geotechnical Observation of Site Drainage and Results of Density Testion Services for Paved Areas, Lot 1
			4/31/88	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Swimming Pool, Tennis Court, Cabana
				William Cotton and Associates	Geotechnical Review Sheet
			05/24/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Feeney Pool, Tennis Court and Cabana, PA #4652, #4924, and #4671
			06/08/88	Carl W. Garbe, P.E.	Review of Plans, Proposed Swimming Pool
			06/21/88	Carl W. Garbe, P.E.	Daily Field Report (Compaction Tests)
			06/30/88	Carl W. Garbe, P.E.	Preliminary Geologic & Geotechnical Review, Proposed Pool, Tennis Court, Cabana
4175 Woodside Road	x		07/24/78	Cooper Clark & Associates	Evaluation of an Inferred Type "C" Fault Trace, Portion of Land Division #227
			01/07/81	Cooper Clark & Associates	Discussion on Additional Fault Investigation
			03/26/81	PSC Associates, Inc.	Soil Engineering Investigation, Proposed Residence, Parcel 2 (Land Division No. 265)
				Frederick R. Strathdee	Site/Grading Plan
			04/10/86	PSC Associates, Inc.	Geotechnical Engineering Report Update, Lot 2, (Land Division No. 265
			07/31/86	PSC Associates, Inc.	Grading and Foundation Plan Review for Lot 2 (Land Division No, 265)
			08/26/86	PSC Associates, Inc.	Letter Report - Geologic Fault Investigation, Lot 2 (Land Division No. 265)
			10/01/86	William Cotton and Associates	Geotechnical Review Sheet
			10/20/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Wilson Development
5000 Woodside Road	x		09/11/90	Jo Crosby & Associates	Remedial Work, Coral Area

			09/12/90	Gene Kunit & Associates	Grading & Drainage Plan
			09/13/90	David Allen Henderson	description of proposed project
			09/14/09	David Allen Henderson	grading quantities
			08/03/04	Milstone Geotechnical	Geotechnical Investigation, Proposed Improvements, McDade Residence
			07/16/15	Murray Engineers, Inc.	Guest House and Tennis Court
			09/29/04	Milstone Geotechnical	Response to Town of Woodside Geotechnical Review Comments, Proposed Improvements
	5001 Woodside Road	x	02/22/08	Murray Engineers, Inc.	Geotechnical Investigation, Dearborn Stables
WOODSIDE WAY					
30A	610 Woodside Way	x	04/14/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel/New House
			08/31/00	Earth Investigations Consultants	Engineering Geologic Evaluation, Proposed Leachfield, Proposed New Residence
	620 Woodside Way	x	01/15/81	Purcell, Rhoades & Associates	Results of Percolation Tests, Lot 17, Block 201, Emerald Lake Estates
			01/26/96	Bay Area Geotechnical Group	Foundation Investigation, Proposed Single-Family Residence
			10/24/97	Bay Area Geotechnical Group	Proposed Septic System and Existing French Drain
			11/21/97	Bay Area Geotechnical Group	Proposed French Drain Collection of Shallow Subsurface Seepage
			07/06/98	Questa Engineering Corporation	Septic System Review
			08/11/98	Questa Engineering Corporation	Drainage Plans
			04/23/99	Bay Area Geotechnical Group	Geotechnical Review of Development Plans
			07/17/03	Bay Area Geotechnical Group	Geotechnical Report Update and Plan Review, Proposed Deck and Cabana
	623 Woodside Way	x	02/26/80	Purcell, Rhoades & Associates	Percolation Test Results, Combined Lots 11, 12, and 13, and Combined Lots 9 and 10, Estates of Emerald Lake
			04/25/85	TransPacific Geotechnical Engineers, Inc.	Geotechnical Investigation, Proposed Hurley Residence
			8/0/85	Monarch Associates, Inc.	Plot Plan for Robert Hurley, with annotations
			08/13/85	Purcell, Rhoades & Associates	Site Evaluation and Percolation Field Update for Lots 9 and 10
			08/20/85	County of San Mateo, Department of Health Services	Comments on 8/13/85 PRA letter
			09/16/85	Steve Deal Associates	Supplemental Subsurface Study
			09/20/85	William Cotton and Associates	Geotechnical Review Sheet
			09/20/11	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Hurley, Variance 388
			10/02/85	Purcell, Rhoades & Associates	Leachfield Evaluation Update for Lots 9 and 10

			10/15/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Lands of Hurley, Variance 388
			06/02/86	Arthur Keyes Architect	Letter to Town Staff Regarding Change in Drainfield Location
			07/18/94	Earth Investigations Consultants	Geotechnical Investigation
	629 Woodside Way	x	02/26/80	Purcell, Rhoades & Associates	Percolation Test Results, Combined Lots 11, 12, and 13, and Combined Lots 9 and 10, Estates of Emerald Lake
		x	04/25/85	TransPacific Geotechnical Engineers, Inc.	Geotechnical Investigation-Proposed Hurley Residence
	635 Woodside Way	X	02/26/80	Purcell, Rhoades & Associates	Percolation Test Results, Combined Lots 11, 12, and 13, and Combined Lots 9 and 10, Estates of Emerald Lake
	638 Woodside Way	x	10/28/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Garage and Deck Additions
	642 Woodside Way	x	06/06/94	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation
	643 Woodside Way	x	12/09/10	Earth Investigations Consultants	Geotechnical Investigation, Proposed Lower Story Room Addition
WOODVIEW LANE					
30A	5 Woodview Lane	x	11/05/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence and Pool, Andrighetto Property
			08/14/97	GeoForensics, Inc.	Response to Town Geotechnical Review, Andrighetto Property
			05/01/98	GeoForensics, Inc.	Supplementary Evaluation, Andrighetto Property
	15 Woodview Lane	x	10/19/90	Purcell, Rhoades & Associates	Evaluation of the Hazards of Surface Rupture, Proposed Home Conversions
	35 Woodview Lane	x	08/15/85	Raymond Pestrong	Geologic Investigation, Gamble Property
			09/25/85	Purcell, Rhoades & Associates	Soil and Foundation Study, Pool House
			09/04/85	William Cotton and Associates	Geotechnical Review Sheet
			09/18/85	William Cotton and Associates	Preliminary Geologic Review, Gamble, APN 076-302-110
			10/11/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Gamble Pool House, APN 076-302-110
			04/23/07	William M. McMorrow	Geotechnical Engineering Evaluation & Plan Review, Proposed Additions & Alterations, Hanham Residence
			07/15/07	William M. McMorrow	Response to Town of Woodside Review Letter dated 6/26/07
			09/16/07	William M. McMorrow	Response to Second Town of Woodside Review Letter dated 8/8/07
YOSEMITE COURT					
30A	629 Yosemite Court	x	08/28/92	Upp Geotechnology, Inc.	Soil and Foundation Investigation, New Residence, Lands of McHugh